

## Wylfa Newydd Project

6.7.27 ES Volume G - A5025 Off-line  
Highway Improvements App G9-6 - A5025  
Route Improvement Contract EIA: Hedgerow  
Survey Results

---

PINS Reference Number: EN010007

---

Application Reference Number: 6.7.27

---

June 2018


Revision 1.0

Regulation Number: 5(2)(a)

Planning Act 2008

Infrastructure Planning (Applications: Prescribed Forms and Procedure) Regulations 2009

[This page is intentionally blank]



# A5025 Route Improvement Contract EIA

Hedgerow Survey Results

May 2014

Horizon Nuclear Power

# A5025 Route Improvement Contract EIA

Hedgerow Survey Results

May 2014

Horizon Nuclear Power

5210 Valiant Court, Gloucester Business Park, Delta Way, Gloucester, GL3 4FE

## Issue and revision record

<b>Revision</b>	<b>Date</b>	<b>Originator</b>	<b>Checker</b>	<b>Approver</b>	<b>Description</b>	<b>Standard</b>
A	April 2014	L. Hill	T. Crabb	C. Probert	First Issue	[REDACTED]

This document is issued for the party which commissioned it and for specific purposes connected with the above-captioned project only. It should not be relied upon by any other party or used for any other purpose.

We accept no responsibility for the consequences of this document being relied upon by any other party, or being used for any other purpose, or containing any error or omission which is due to an error or omission in data supplied to us by other parties.

This document contains confidential information and proprietary intellectual property. It should not be shown to other parties without consent from us and from the party which commissioned it.

# Contents

<b>Chapter</b>	<b>Title</b>	<b>Page</b>
1	Introduction	1
1.1	A5025 Background	1
1.2	Ecology Background	2
1.3	Scope of the Report	2
1.4	Survey Limitations	2
2	Methodology	3
2.1	Desk study	3
2.2	Field Surveys	3
3	Results	5
3.1	Clawdd Walls	6
4	Recommendations	7
5	References	8
	Appendices	9
	Appendix A. A5025 Online and Offline Works	10
	Appendix B. Hedgerow Maps	11
	Appendix C. Results of 'None Important' Hedgerows	12

# 1 Introduction

## 1.1 A5025 Background

Horizon Nuclear Power Ltd (a subsidiary of Hitachi Ltd) is proposing to build a new nuclear power station on land beside the existing operational Magnox nuclear power station on Wylfa Peninsula, Anglesey, North Wales. Horizon Nuclear Power (HNP) are currently preparing a Development Consent Order (DCO) application for the proposed power station, which will include nuclear reactors with a minimum generating capacity of up to 2,700 Mega Watts (MW) of electricity which will be submitted to The Planning Inspectorate for review.

In order to facilitate the construction and operation of the new power station, the project will require a number of additional components (which fall outside the DCO application) and these are termed 'associated developments'. One of which relates to the upgrade of the existing transport infrastructure and is termed the A5025 Route Improvement Contract (RIC). The purpose of the upgrade is to facilitate the movement of the workforce materials, and minimise the impact of the movements on local communities.

Mott MacDonald (MM) has been commissioned by HNP to undertake a Preliminary Ecological Appraisal (PEA) to identify any potential ecological impacts and constraints associated with the proposed development.

The proposed route, hereby referred to as the 'scheme', follows a 22 km length of the A5025 between National Grid references: SH4171093260; and SH3004078890. A plan showing the extent of the scheme is provided in Appendix A. The route starts at the junction of the A5 trunk road at the village of Valley, and runs in a north easterly direction towards the existing power station at Wylfa Head to the east of the Village of Cemaes. The scheme includes a small section of the un-graded road Pen-yr-Orsedd. This is located to the west of the A5025 and is situated approximately 2 km to the north of the village of Llanrhuddlad. The A5025 runs through a number of villages and small rural communities.

The scheme design is yet to be defined and a number of options are currently being considered in consultation with the Isle of Anglesey County Council (IoACC), the Highways Authority (North and Mid Wales Trunk Road Agency) and other stakeholders. It is anticipated that the majority of the works will be undertaken within the existing highway boundary (known as on-line works); however at a number of locations, works outside of the highway boundary (off-line works) may be required, which may include minor road straightening, by-passes, roundabouts and junction improvements as detailed below.

The following areas for possible offline route improvements are:

- The Valley crossroads which may require bypassing;
- Llanfachraeth where a bypass to the east of the village is being considered;
- Llanfaethlu where bends at the Black Lion Inn and Llanfaethlu may need to be straightened;
- Cefn Coch where the existing route between Bod-Hedd and Cefn Coch may need to be straightened;
- Tregele where modifications to the site access are being considered. Alternatively, a by-pass as well as potential changes to the access to Cemlyn may be required; and
- Improvements along the A5025, between the construction site and Amlwch, to the proposed new workers village.

A map is provided in Appendix A highlighting both the online and offline works proposed along the A5025.

## **1.2 Ecology Background**

Extended Phase 1 Habitat Surveys were carried out by Mott MacDonald between August 2011 and March 2014. To fully utilise land access, protected species and habitat data was gathered simultaneously during the initial habitat surveys. This included carrying out surveys on all hedgerows within 100 m of the road scheme.

## **1.3 Scope of the Report**

A new framework was set up in running from the 1<sup>st</sup> of April 2014 and Jacobs Engineering Group Inc. were commissioned to continue with the ecological surveys for the A5025 RIC. This report aims to summarise the information pertaining to reptiles that has been collated by Mott MacDonald to date, and provide a seamless mechanism to transfer the data in order for any further recommendations and/or surveys to be undertaken.

The objectives of this report are as follows:

- To present the methodology used for all reptile work;
- To present the results of the desk study & field survey work; and
- To provide brief recommendations for further survey work.

## **1.4 Survey Limitations**

It was not possible to survey some areas within the survey extent; this was largely due to limited and/or irregular land access. This had implications for timing and duration of the surveys, whereby the Extended Phase 1 surveys were conducted over a longer period of time and subsequently covered a spectrum of optimal and non-optimal time for assessment. Adverse weather conditions in particular had a negative effect on the survey timings in 2013. All sites with granted land access have had hedgerow surveys carried out. Site specific details and results can be found within Section 3.

## 2 Methodology

All ecological works followed up to date best practice guidelines provided by the Chartered Institute of Ecology and Environmental Management (CIEEM). In addition, further specific highway guidance was also followed. This is provided by The Design Manual for Roads and Bridges (DMRB), specifically Volume 10 (Environmental Design and Management) and Volume 11 (Environmental Assessment), along with relevant Interim Advice Notes (IANs), such as IAN 130/10 Ecology and Nature Conservation: Criteria for Impact Assessment which supplements DMRB Volume 11, SECTION 3 Part 4 'Ecology and Nature Conservation'.

### 2.1 Desk study

The aims of the desk study with specific regards to hedgerows, was to identify all hedgerows within 100 m of the A5025 using aerial photography. All hedgerows were then individually numbered in order to identify hedgerows for surveying. Hedgerows less than 20 m in length or with gaps of more than 20 m in length, were not classed as hedgerows and were recorded as such and were not surveyed.

The following databases were used to extract the required information outlined above:

- Google Maps: (<https://maps.google.co.uk/>); and
- Multi-Agency Geographic Information for the Countryside (MAGIC) website: (<http://magic.defra.gov.uk/>).

Maps detailing hedgerow locations can be found in Appendix B and results of the surveys are discussed further within Section 3.

### 2.2 Field Surveys

The definition of a hedgerow used for the purpose of the surveys follows the description within the Hedgerow Survey Handbook, produced by the Department for Environment, Food and Rural Affairs (Defra, 2007).

The guidance document states that a hedgerow is defined as:

*'Any boundary line of trees or shrubs over 20 m long and less than 5 m wide between major woody stems at the base';*

and

*'The end of a hedge will be classed as where it joins another hedge or feature (a node)'.*

Species-rich hedgerows were defined as such:

*Where the structural species making up the 30 m survey section of the hedgerow includes at least four woody species. Climbers and brambles do not count towards the total except for roses.*

The survey was carried out on all hedgerows within the survey buffer area of 100 m, and each hedgerow was surveyed according to methods outlined above.

Using the guidance the following lengths of hedgerow were surveyed:

- Hedgerows under 30 m (but greater than 20 m): whole hedge surveyed;
- Hedgerow between 30 m and 100 m: 30 m in the centre was surveyed;
- Hedgerows between 100 m and 200 m: hedge divided into two and the 30 m in the centre of each section was surveyed; and
- Hedgerows over 200 m: divided into 3 and the 30 m in centre of each section was surveyed.

The hedge survey involved inspection of the prescribed lengths as detailed above to record the following features. It should be noted that due to the number of hedgerows on site, hedgerows were surveyed from one side. The side to be surveyed was selected randomly to avoid bias surveys:

- Width, height, and length (between nodes) were recorded;
- Woody species in the survey section were recorded;
- Ground flora species within 1 m of the outermost edges of the hedge were recorded along a 30 m survey length (or entirety of hedge if less than 30 m);
- Additional features such as ditches, walls and banks were recorded;
- Connections with other hedges and habitats were recorded; and
- Management and adjacent land use were recorded.

## 3 Results

Approximately 530 native and non-native hedgerows were recorded within the survey area. Hedgerows were predominantly categorised as intact species-poor and were occasionally recorded growing on earth banks. Defunct species poor hedgerows covered approximately 13% of the total hedgerow extent. Species poor hedgerows with trees were also frequently recorded. Intact native rich species hedgerows were recorded in approximately 2% of the total extent.

The dominant species documented by the survey was hawthorn (*Crataegus monogyna*) with frequent or scattered pedunculate oak (*Quercus robur*), dog-rose (*Rosa canina*), English elm (*Ulmus procera*), blackthorn (*Prunus spinosa*) and elder (*Sambucus nigra*) with occasional willow (*Salix* sp.) and gorse (*Ulex europaeus*). The ground flora was generally species poor and dominated by bramble (*Rubus fruticosa*), ivy (*Hedera* sp.) and common nettle (*Urtica dioica*).

The following table outlines all hedgerows that were classified as 'Important' as defined by the Hedgerow Regulations 2007.

Table 3.1: Important Hedgerow Results

Hedgerow Number	Hedgerow Location (x and y coordinates)	Hedgerow Description
457	239968 393658	Mainly hawthorn and blackthorn with some ash, ground flora includes cleavers, nettle, docks, bramble and hearts tongue fern.
311	234254 390915	Shrubby hedgerow with trees, consisting of silver birch, ash, beech, gorse, hawthorn and hazel. Has a connection with broadleaved woodland.
144	231738 383845	Line of trees with hawthorn and privet. Two connections with other hedgerows, ivy, cleaver, nettle and cow parsley ground flora.
148	231489 384498	Shrubby hedgerow adjacent to a road with a parallel hedge and less than 10% gaps.
155	231650 384622	This shrubby hedgerow has less than 10% gaps and at least 5 woody species; it is also bordering a bank and a wall.
180	232024 385342	Trimmed and dense shrubby hedgerow with gorse, willow, blackthorn, hawthorn and rose. There is a ditch along at least half the length of the hedgerow.
66	231722 381029	A shrubby hedgerow with a line of trees. Species include laurel, hawthorn, blackthorn and poplar. It has numerous additional features including a parallel hedge; it is adjacent to a road, at least 1 standard tree and less than 10% gaps.
252	232580 388176	Shrubby hedgerow with a line of trees, has a bank, ditch and a wall along at least half its length and at least 1 standard tree.

Source: Mott MacDonald 2013 / 2014

Appendix C details the remaining hedgerows surveyed within 100 m of the A5025. While these hedgerows were not classified as important they still had characteristic features worthy of note.

### **3.1 Clawdd Walls**

Clawdd walls are known to be present in Anglesey and these were recorded at a number of locations, most importantly at locations along the A5025. Clawdd walls are an ancient form of boundary that are built in areas where stone is scarce; these are stone faced earth banks with a hedge planted on top and often a ditch on one side. Wales is a strong hold for these types of wall, however due to changes in farming many of them have fallen into disrepair.

## 4 Recommendations

A confirmed scope of works should be provided to ensure all hedgerows within 100 m of all works (i.e. both offline and online works) have been surveyed.

Data for all hedgerows categorised as 'important' should be provided to HNP to ensure these hedgerows are captured within the planning application.

It would be expected that all other hedgerows present have appropriate mitigation and protection recommended within the working construction documents.

## 5 References

Chartered Institute of Ecology and Environmental Management – Sources of Survey Methods website: <http://www.cieem.net/sources-of-survey-methods-sosm->;

Department for Environment, Food and Rural Affairs (2007) Hedgerow Survey Handbook. A standard procedure for local surveys in the UK. Defra, London;

Dry Stone Walling association website: [http://www.dswns.org.uk/English\\_Index.html](http://www.dswns.org.uk/English_Index.html);

Google Maps: <https://maps.google.co.uk/>;

Highways Agency's Design Manual for Roads and Bridges (DMRB) (1993), Volume 10;

Highways Agency's Design Manual for Roads and Bridges (DMRB) (1993), Volume 11, Section 3, Part 4 Ecology and Nature Conservation;

Highways Agency's Design Manual for Roads and Bridges (DMRB) (1993), Volume 11, Section 3, Part 10, HD 45/09 Road Drainage and the Water Environment;

Highways Agency Interim Advice Note 130/10 (2011), Ecology and Nature Conservation: Criteria for Impact Assessment;


Mott MacDonald (2014) A5025 Upgrade Wylfa, Preliminary Ecological Appraisal;

Multi-Agency Geographic Information for the Countryside (MAGIC) website: (<http://magic.defra.gov.uk/>)

# Appendices



Appendix A. A5025 Online and Offline Works	10
Appendix B. Hedgerow Maps	11
Appendix C. Results of 'None Important' Hedgerows	12

## Appendix A. A5025 Online and Offline Works



## Appendix B. Hedgerow Maps





**Legend**

- Important Hedgerows (Numbered)
- Not important Hedgerows (Numbered)
- Indicative site extent - 100m buffer
- Jacobs survey area

This document is issued for the party which commissioned it and for specific purposes connected with the captioned project only. It should not be relied upon by any other party or used for any other purpose. We accept no responsibility for the consequences of this document being relied upon by any other party, or being used for any other purpose, or containing any error or omission which is due to an error or omission in data supplied to us by other parties.

**Mott MacDonald**


Fitzalan House  
Fitzalan Road  
Cardiff  
CF24 0EL  
Tel +44 (0) 2920 467800  
Fax +44 (0) 2920 467801  
Web [www.mottmac.com](http://www.mottmac.com)


Title: A5025 Road Improvements Contract  
Hedgerow Survey Results

Page 2 of 9

0 125 250 500  
Metres

Drawn	JW	Checked	TC
Approved	ECP	Rev No	P1
Date: 24/04/2014		Scale: 1:10,000	@ A3
Drawing No: MMD-320831-L-DR-XX-3461			





### Legend

- Important Hedgerows (Numbered)
- Not important Hedgerows (Numbered)
- Indicative site extent - 100m buffer
- Jacobs survey area

This document is issued for the party which commissioned it and for specific purposes connected with the captioned project only. It should not be relied upon by any other party or used for any other purpose. We accept no responsibility for the consequences of this document being relied upon by any other party, or being used for any other purpose, or containing any error or omission which is due to an error or omission in data supplied to us by other parties.





Fitzalan House  
Fitzalan Road  
Cardiff  
CF24 0EL  
Tel +44 (0) 2920 467800  
Fax +44 (0) 2920 467801  
Web [www.mottmac.com](http://www.mottmac.com)

Title: A5025 Road Improvements Contract  
Hedgerow Survey Results  
Page 4 of 9

0 125 250 500  
Metres

Drawn	JW	Checked	TC
Approved	ECP	Rev No	P1
Date: 24/04/2014	Scale: 1:10,000	@ A3	

Drawing No: MMD-320831-L-DR-XX-3463



### Legend

- Important Hedgerows (Numbered)
- Not important Hedgerows (Numbered)
- Indicative site extent - 100m buffer
- Jacobs survey area

This document is issued for the party which commissioned it and for specific purposes connected with the captioned project only. It should not be relied upon by any other party or used for any other purpose. We accept no responsibility for the consequences of this document being relied upon by any other party, or being used for any other purpose, or containing any error or omission which is due to an error or omission in data supplied to us by other parties.


  
**Mott MacDonald**


Fitzalan House  
Fitzalan Road  
Cardiff  
CF24 0EL  
Tel +44 (0) 2920 467800  
Fax +44 (0) 2920 467801  
Web [www.mottmac.com](http://www.mottmac.com)


Title: A5025 Road Improvements Contract  
Hedgerow Survey Results  
Page 5 of 9


0 125 250 500  
Metres

Drawn	JW	Checked	TC
Approved	ECP	Rev No	P1
Date: 24/04/2014		Scale: 1:10,000	@ A3
Drawing No: MMD-320831-L-DR-XX-3464			









## Appendix C. Results of 'None Important' Hedgerows

Table C.1: Non Important Hedgerow Results

Hedgerow Number & location (x & y coordinates)	Scoping	Category									
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/byway/bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species
1: 229565 379432	Defunct	0	0	0	0	0	0	0	0	0	0
2: 229601 379406	Defunct	0	0	0	0	0	0	0	0	0	0
3: 229690 379535	Defunct	0	0	0	0	0	0	0	0	0	0
4: 229693 379535	Defunct	0	0	0	0	0	0	0	0	0	0
5: 229552 379276	Surveyed	0	0	0	1	0	0	1	0	0	2
6: 229620 379394	Surveyed	0	0	0	1	1	0	0	0	0	2
7: 229715 379459	Not a hedge	0	0	0	0	0	0	0	0	0	0
8: 229728 379412	Not a hedge	0	0	0	0	0	0	0	0	0	0
9: 229754 379399	Not a hedge	0	0	0	0	0	0	0	0	0	0
10: 234254 391024	Not a hedge	0	0	0	0	0	0	0	0	0	0
11: 234257 391215	Not a hedge	0	0	0	0	0	0	0	0	0	0

<sup>1</sup> Connections being features such as a pond (2 points) and/or broadleaved woodland (2 points).

Hedgerow Number & location (x & y coordinates)	Scoping	Category									
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/byway/bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species
12: 229815 379568	Not a hedge	0	0	0	0	0	0	0	0	0	0
14: 229887 379528	Not a hedge	0	0	0	0	0	0	0	0	0	0
15: 229929 379571	Surveyed	0	0	0	1	0	0	0	1	0	1
16: 229886 379589	Surveyed	0	0	0	0	1	1	0	1	0	2
18: 229880 379680	Surveyed	0	0	0	1	1	0	1	0	0	2
19: 230029 379735	Not a hedge	0	0	0	0	0	0	0	0	0	0
20: 230073 379829	Defunct	0	0	0	0	0	0	0	0	0	0
21: 230063 379815	Defunct	0	0	0	0	0	0	0	0	0	0
23: 230209 379874	Surveyed	0	0	0	1	0	0	0	0	1	2
25: 230316 380022	Surveyed	0	0	0	0	0	0	1	0	0	2
26: 230432 380007	Surveyed	0	0	0	1	1	0	1	0	1	2
31: 230511 380162	Defunct	0	0	0	0	0	0	0	0	0	1
32: 230543 380127	Surveyed	0	0	0	1	1	0	0	0	0	1
33: 230562 380181	Surveyed	0	0	0	0	1	0	1	0	0	1
34: 230589 380126	Surveyed	0	1	0	1	1	1	1	0	0	2
35: 230731 380250	Surveyed	0	0	0	0	1	0	1	0	0	3

Hedgerow Number & location (x & y coordinates)	Scoping	Category										
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/byway/bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species	
36: 230703 380286	Surveyed	0	0	0	1	1	0	1	0	1	3	Not important
46: 231097 380657	Surveyed	1	0	0	1	0	0	1	0	0	5	Not important
47: 231201 380665	Surveyed	0	0	0	1	1	0	1	0	1	3	Not important
50: 231323 380779	Surveyed	0	0	0	1	0	1	1	0	0	3	Not important
51: 231275 380799	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
52: 231299 380820	Surveyed	1	0	0	1	0	0	1	0	1	2	Not important
53: 231158 380651	Line of trees	1	0	0	0	0	0	0	0	0	0	Not important
54: 231191 380694	Surveyed	0	1	0	0	1	0	1	0	0	1	Not important
55: 231217 380728	Surveyed	0	0	0	0	0	0	1	0	0	3	Not important
56: 231242 380755	Surveyed	0	0	0	0	0	0	0	0	1	3	Not important
58: 231410 380860	Surveyed	1	0	0	1	0	0	0	0	1	1	Not important
59: 231369 380926	Surveyed	0	0	0	1	1	0	1	1	0	2	Not important
61: 231451 380959	Surveyed	0	0	0	1	0	0	0	0	0	3	Not important
62: 231494 381006	Not a hedge	0	0	0	1	0	0	0	0	0	1	Not important
67: 231762 381099	Surveyed	0	0	0	1	1	1	1	0	1	2	Not important
68: 231649 381141	Surveyed	0	0	0	1	0	1	1	0	1	1	Not important

Hedgerow Number & location (x & y coordinates)	Scoping	Category										
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/byway/bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species	
69: 231655 381144	Surveyed	0	0	0	1	1	1	1	0	1	1	Not important
70: 231719 381196	Surveyed	0	0	0	1	0	1	1	0	1	2	Not important
71: 231673 381310	Surveyed	0	0	0	1	0	0	1	0	0	2	Not important
72: 231681 381500	Surveyed	0	0	0	1	1	0	1	0	1	3	Not important
73: 231672 381776	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
74: 231615 381964	Surveyed	0	0	0	1	1	0	1	0	0	2	Not important
75: 231739 381237	Surveyed	1	0	0	1	0	1	0	0	1	2	Not important
76: 231793 381326	Surveyed	0	0	0	1	1	0	0	0	0	1	Not important
77: 231800 381477	Defunct	0	0	0	0	0	0	0	0	0	0	Not important
78: 231767 381538	Surveyed	0	0	0	1	0	0	1	0	0	2	Not important
79: 231812 381593	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
80: 231751 381680	Surveyed	0	0	0	1	1	0	1	1	0	3	Not important
81: 231786 381755	Defunct	0	0	0	0	0	0	0	0	0	0	Not important
82: 231802 381933	Surveyed	0	0	0	1	0	0	1	0	0	2	Not important
83: 231853 381837	Defunct	0	0	0	0	0	0	0	0	0	0	Not important
85: 231855 382055	Defunct	0	0	0	0	0	0	0	0	0	0	Not important

Hedgerow Number & location (x & y coordinates)	Scoping	Category										
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/byway/bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species	
99: 231825 382612	Surveyed	0	0	0	1	0	0	1	0	1	1	Not important
101: 231790 382575	Surveyed	1	0	0	1	1	0	0	0	0	3	Not important
102: 231747 382572	Surveyed	0	1	0	1	0	0	1	0	1	1	Not important
103: 231748 382613	Surveyed	0	0	0	1	1	0	0	0	0	3	Not important
105: 231788 382670	Surveyed	0	1	0	1	0	0	0	0	0	2	Not important
108: 231684 382813	Defunct	0	0	0	0	0	0	0	0	0	0	Not important
110: 231594 382776	Surveyed	0	0	0	1	0	1	0	0	0	2	Not important
111: 231633 382849	Defunct	0	0	0	0	0	0	0	0	0	0	Not important
112: 231660 382937	Surveyed	0	1	0	1	0	0	0	1	0	1	Not important
113: 231654 382953	Defunct	0	0	0	0	0	0	0	0	0	0	Not important
114: 231579 383069	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
115: 231516	Defunct	0	0	0	0	0	0	0	0	0	0	Not important

Hedgerow Number & location (x & y coordinates)	Scoping	Category									
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/ byway/ bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species
382953											
116: 231446 383024	Surveyed	1	0	0	0	1	0	0	1	0	4
117: 231433 382948	Surveyed	1	0	0	1	1	0	1	0	0	3
118: 231431 382909	Surveyed	0	0	0	1	0	0	1	0	1	1
119: 231379 382943	Surveyed	0	0	0	1	0	0	0	0	0	1
120: 231362 383121	Surveyed	1	0	0	1	0	0	0	0	0	2
121: 231440 383097	Surveyed	0	0	0	0	0	0	0	0	0	2
122: 231407 383190	Surveyed	1	0	0	1	0	0	1	0	0	3
123: 231484 383141	Surveyed	1	0	0	1	1	0	1	0	0	3
124: 231523 383213	Not a hedge	0	0	0	0	0	0	0	0	0	0
125: 231393 383173	Line of trees	1	0	0	0	0	0	0	0	0	0
126: 231468 383285	Not a hedge	0	0	0	0	0	0	0	0	0	0

Hedgerow Number & location (x & y coordinates)	Scoping	Category										
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/byway/bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species	
127: 231562 383321	Surveyed	0	0	0	1	0	1	1	1	1	2	Not important
128: 231590 383220	Surveyed	0	0	0	1	1	1	1	0	0	1	Not important
129: 231599 383276	Surveyed	1	1	0	1	1	0	1	1	0	2	Not important
130: 231498 383418	Surveyed	0	1	0	1	0	0	1	0	1	1	Not important
131: 231526 383431	Surveyed	0	0	0	1	0	0	1	0	1	1	Not important
132: 231595 383560	Surveyed	0	0	0	1	0	0	0	0	1	2	Not important
133: 231696 383516	Surveyed	0	0	0	1	0	1	1	0	1	1	Not important
134: 231674 383540	Defunct	0	0	0	0	0	0	0	0	0	0	Not important
137: 231521 384289	Line of trees	1	0	0	0	0	0	0	0	0	0	Not important
138: 231518 384295	Line of trees	1	0	0	0	0	0	0	0	0	0	Not important
139: 231644 384226	Surveyed	0	0	0	1	0	0	0	0	0	3	Not important
140:	Surveyed	1	0	0	1	0	1	1	0	1	3	Not important

Hedgerow Number & location (x & y coordinates)	Scoping										Category
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/byway/bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	
231678											
384055											
145: 231762 383798	Surveyed	0	0	0	1	0	0	0	1	1	2 Not important
146: 231529 384430	Surveyed	1	0	0	0	1	0	1	0	0	3 Not important
149: 231645 384484	Surveyed	0	0	0	1	0	0	0	0	0	2 Not important
150: 231559 384483	Surveyed	0	0	0	1	0	0	1	0	0	2 Not important
152: 231528 384556	Surveyed	0	0	0	0	0	0	1	0	0	2 Not important
153: 231561 384519	Surveyed	0	0	0	1	0	0	1	0	0	2 Not important
154: 231591 384570	Surveyed	0	0	0	1	0	0	1	0	0	2 Not important
156: 231726 384635	Surveyed	0	0	0	1	0	0	0	0	0	2 Not important
157: 231643 384709	Surveyed	0	0	0	1	0	0	1	0	1	3 Not important
158: 231731 384765	Surveyed	0	0	0	1	0	1	1	0	1	2 Not important
161: 231728	Surveyed	0	0	0	0	0	1	0	0	1	2 Not important

Hedgerow Number & location (x & y coordinates)	Scoping	Category									
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/ byway/ bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species
384855											
162: 231731	Surveyed	1	0	0	1	0	1	1	0	1	2
384863											
163: 231845	Surveyed	0	0	0	1	0	0	1	0	0	3
384849											
164: 231796	Surveyed	0	0	0	1	0	0	0	0	1	4
384892											
166: 231771	Surveyed	0	0	0	1	0	1	1	0	1	3
384945											
167: 231779	Surveyed	0	0	0	1	0	1	1	0	1	3
384951											
168: 231850	Surveyed	0	0	0	1	0	0	1	0	1	3
384997											
169: 231829	Surveyed	0	0	0	1	0	0	1	0	0	3
385067											
170: 231876	Surveyed	0	0	0	1	0	0	1	0	1	3
385210											
171: 231878	Surveyed	0	0	0	1	0	0	1	0	1	3
385216											
172: 231906	Surveyed	0	0	0	1	0	0	1	0	1	3
385120											
173: 231921	Surveyed	0	0	0	1	0	0	1	0	1	3
385111											

Hedgerow Number & location (x & y coordinates)	Scoping	Category										
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/byway/bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species	
174: 231932 385023	Surveyed	0	0	0	1	1	0	0	0	1	3	Not important
175: 231935 385037	Surveyed	0	0	0	1	1	0	0	0	1	3	Not important
176: 231918 385038	Surveyed	0	0	0	1	1	0	1	0	0	3	Not important
177: 231966 385371	Surveyed	0	0	0	0	0	0	1	0	0	3	Not important
178: 231957 385271	Surveyed	0	0	0	1	1	0	1	0	0	4	Not important
179: 231894 385201	Surveyed	0	0	0	1	0	0	1	0	0	3	Not important
181: 231769 385351	Surveyed	0	0	0	1	0	0	1	0	0	3	Not important
182: 232003 385477	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
183: 232062 385606	Surveyed	0	0	0	1	0	0	1	0	0	2	Not important
184: 231955 385521	Defunct	0	0	0	1	0	0	1	0	0	3	Not important
185: 231962 385694	Defunct	0	0	0	0	0	0	0	0	0	0	Not important
186:	Defunct	0	0	0	0	0	0	0	0	0	0	Not important

Hedgerow Number & location (x & y coordinates)	Scoping										Category
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/byway/bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	
231966											
385701											
187: 232072 385684	Surveyed	0	0	0	1	1	1	1	0	1	3 Not important
188: 232031 385762	Surveyed	0	0	0	1	0	0	1	0	0	3 Not important
189: 232066 385859	Defunct	0	0	0	0	0	0	0	0	0	0 Not important
190: 231981 385970	Surveyed	0	0	0	1	1	0	1	0	0	3 Not important
191: 231912 386054	Surveyed	0	0	0	1	0	0	1	0	0	1 Not important
192: 231885 386039	Defunct	0	0	0	0	0	0	0	0	0	0 Not important
193: 231867 386113	Surveyed	0	0	0	1	1	0	0	0	0	0 Not important
194: 231844 386224	Surveyed	0	0	0	1	0	0	0	0	0	0 Not important
195: 231969 386087	Defunct	0	0	0	0	0	0	0	0	0	0 Not important
196: 231926 386147	Defunct	0	0	0	0	0	0	0	0	0	0 Not important
197: 231949	Surveyed	1	0	0	1	1	0	0	1	0	3 Not important

Hedgerow Number & location (x & y coordinates)	Scoping	Category									
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/byway/bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species
386235											
198: 231978	Surveyed	0	0	0	1	1	0	1	0	0	3
386330											Not important
204: 231943	Surveyed	0	0	0	1	0	0	0	0	1	1
386479											Not important
205: 231834	Defunct	0	0	0	0	0	0	0	0	0	0
386437											Not important
206: 231837	Defunct	0	0	0	0	0	0	0	0	0	0
386476											Not important
207: 231798	Not a hedge	0	0	0	0	0	0	0	0	0	0
386550											Not important
208: 231817	Not a hedge	0	0	0	0	0	0	0	0	0	0
386634											Not important
209: 231703	Defunct	0	0	0	0	0	0	0	0	0	0
386765											Not important
210: 231656	Surveyed	1	0	0	1	0	0	0	0	0	3
386734											Not important
211: 231505	Surveyed	0	0	0	1	1	0	1	0	1	3
386851											Not important
212: 231614	Surveyed	0	0	0	1	1	0	1	0	0	2
386860											Not important
213: 231683	Surveyed	0	0	0	1	1	0	1	0	0	3
386871											Not important

Hedgerow Number & location (x & y coordinates)	Scoping	Category										
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/byway/bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species	
214: 231634 386934	Surveyed	0	0	0	1	1	0	1	0	0	3	Not important
215: 231640 386993	Surveyed	0	0	0	1	1	0	1	0	0	2	Not important
217: 231493 387126	Surveyed	0	0	0	1	1	0	1	0	0	2	Not important
218: 231483 387032	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
219: 231568 386913	Surveyed	0	0	0	1	1	0	1	0	0	3	Not important
220: 231568 387011	Surveyed	0	0	0	1	1	0	1	0	0	0	Not important
221: 231577 387117	Surveyed	1	0	0	1	0	0	1	0	1	2	Not important
222: 231599 387200	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
226: 231713 387427	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
227: 231669 387506	Surveyed	0	0	0	1	0	0	0	0	1	3	Not important
228: 231669 387513	Surveyed	0	0	0	1	0	0	0	0	1	3	Not important
229:	Surveyed	0	0	0	1	1	0	0	0	0	2	Not important

Hedgerow Number & location (x & y coordinates)	Scoping										Category
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/byway/bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	
231669											
387573											
230:	Surveyed	0	0	0	1	0	0	0	0	0	2 Not important
231727											
387659											
231:	Surveyed	0	0	0	1	1	0	0	0	1	2 Not important
231734											
387723											
232:	Surveyed	0	0	0	1	1	0	0	0	1	2 Not important
233624											
392897											
233:	Defunct	0	0	0	0	0	0	0	0	0	0 Not important
231847											
387783											
234:	Surveyed	0	0	0	1	0	0	0	1	0	3 Not important
231880											
387675											
238:	Surveyed	0	0	0	1	1	0	0	0	0	3 Not important
231999											
387894											
242:	Not a hedge	0	0	0	0	0	0	0	0	0	0 Not important
232137											
387826											
243:	Surveyed	0	0	0	1	0	0	0	0	1	1 Not important
232245											
387963											
244:	Not a hedge	0	0	0	0	0	0	0	0	0	0 Not important
232091											
387933											
245:	Surveyed	0	0	0	1	1	0	0	0	1	2 Not important
232237											
387981											
246:	Not a hedge	0	0	0	0	0	0	0	0	0	0 Not important
232391											

Hedgerow Number & location (x & y coordinates)	Scoping	Category									
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/ byway/ bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species
388167											
247: 232398	Surveyed	0	0	0	1	1	0	0	0	1	3
388174											
248: 232471	Surveyed	0	0	0	1	1	0	0	0	1	2
388175											
249: 232481	Not a hedge	0	0	0	0	0	0	0	0	0	0
388113											
250: 232518	Surveyed	0	0	0	1	1	0	1	0	0	2
388133											
251: 232550	Surveyed	0	0	0	1	1	0	1	0	0	2
388133											
253: 232586	Surveyed	0	0	0	1	1	1	1	0	0	2
388199											
254: 232556	Surveyed	0	0	0	1	1	0	1	0	0	4
388398											
255: 232601	Surveyed	1	0	0	1	1	0	0	0	0	3
388315											
256: 232682	Surveyed	0	0	0	1	1	0	0	0	0	1
388513											
257: 232752	Surveyed	1	0	0	1	1	0	0	0	1	4
388505											
258: 232760	Surveyed	0	0	0	1	1	0	1	0	0	3
388600											

Hedgerow Number & location (x & y coordinates)	Scoping	Category									
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/byway/bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species
259: 232813 388601	Surveyed	0	0	0	1	1	0	0	0	1	3
260: 232814 388695	Not a hedge	0	0	0	0	0	0	0	0	0	Not important
262: 232957 388660	Not a hedge	0	0	0	0	0	0	0	0	0	Not important
263: 233031 388803	Surveyed	0	1	0	1	0	0	1	0	0	3
264: 233058 388869	Surveyed	0	0	0	1	0	0	0	0	0	1
265: 233082 388827	Surveyed	0	1	0	1	0	0	0	0	0	1
266: 233103 388927	Defunct	0	0	0	0	0	0	0	0	0	0
267: 233158 388937	Surveyed	0	0	0	1	0	0	0	0	0	2
269: 233282 389003	Not a hedge	0	0	0	0	0	0	0	0	0	0
270: 233331 389054	Surveyed	0	0	0	1	0	0	0	0	0	2
271: 233437 389110	Not a hedge	0	0	0	0	0	0	0	0	0	0
272:	Surveyed	0	0	0	1	0	1	0	0	0	2

Hedgerow Number & location (x & y coordinates)	Scoping	Category										
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/ byway/ bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species	
233310												
389156												
274:	Surveyed	0	0	0	1	1	0	0	0	1	2	Not important
233024												
388996												
277:	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
233428												
389194												
278:	Surveyed	0	0	0	1	1	0	0	0	0	3	Not important
233492												
389161												
279:	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
233571												
389359												
280:	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
233586												
389372												
281:	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
233556												
389465												
282:	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
233696												
389548												
283:	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
233713												
389663												
284:	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
233793												
389751												
285:	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
233846												
389708												
286:	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
233909												

Hedgerow Number & location (x & y coordinates)	Scoping	Category									
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/ byway/ bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species
389721											
290: 233934	Not a hedge	0	0	0	0	0	0	0	0	0	0
389828											
291: 233945	Not a hedge	0	0	0	0	0	0	0	0	0	0
389912											
292: 234041	Surveyed	1	0	0	1	1	0	0	0	1	3
389946											
293: 233704	Line of trees	1	0	0	0	0	0	0	0	0	0
389721											
294: 233697	Line of trees	1	0	0	0	0	0	0	0	0	0
389712											
301: 234130	Not a hedge	0	0	0	0	0	0	0	0	0	0
390195											
302: 234117	Surveyed	1	0	0	0	1	0	0	0	0	5
390289											
304: 234213	Not a hedge	0	0	0	0	0	0	0	0	0	0
390225											
305: 234078	Not a hedge	0	0	0	0	0	0	0	0	0	0
390246											
306: 234157	Surveyed	1	0	0	0	1	0	0	0	0	3
390429											
307: 234163	Surveyed	0	0	0	1	1	0	1	0	0	4
390589											

Hedgerow Number & location (x & y coordinates)	Scoping	Category									
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/byway/bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species
308: 234137 390990	Line of trees	1	0	0	0	0	0	0	0	0	0
309: 234118 391028	Line of trees	1	0	0	0	0	0	0	0	0	0
310: 234254 391024	Surveyed	0	0	0	1	0	0	0	0	0	2
312: 234219 390779	Defunct	0	0	0	0	0	0	0	0	0	0
313: 234296 390646	Scrub	0	0	0	0	0	0	0	0	0	0
314: 234255 390608	Surveyed	0	0	0	1	0	0	1	0	1	2
315: 234282 390541	Surveyed	0	0	0	1	0	0	1	0	0	3
316: 234252 390380	Defunct	0	0	0	0	0	0	0	0	0	0
317: 234136 391064	Line of trees	1	0	0	0	0	0	0	0	0	0
318: 234257 391215	Surveyed	0	0	0	1	0	0	0	0	0	3
319: 234181 391167	Surveyed	0	0	0	1	1	0	1	0	1	2
321:	Surveyed	0	0	0	0	0	0	0	0	0	0

Hedgerow Number & location (x & y coordinates)	Scoping	Category									
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/ byway/ bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species
233435											
392582											
337: 233837 391469	Not a hedge	0	0	0	0	0	0	0	0	0	Not important
338: 233697 391443	Not a hedge	0	0	0	0	0	0	0	0	0	Not important
339: 233490 391555	Not a hedge	0	0	0	0	0	0	0	0	0	Not important
340: 233449 391564	Not a hedge	0	0	0	0	0	0	0	0	0	Not important
341: 233520 391742	Defunct	0	0	0	0	0	0	0	0	0	Not important
344: 233466 392095	Defunct	1	0	0	1	0	1	0	0	2	Not a hedge
350: 233553 392191	Not a hedge	0	0	0	0	0	0	0	0	0	Not important
352: 233414 392278	Defunct	0	0	0	0	0	0	0	0	0	Not important
355: 233624 391849	Surveyed	0	0	0	1	0	0	0	0	2	Not important
356: 233818 391481	Defunct	0	0	0	0	0	0	0	0	0	Not important
357: 233936	Surveyed	0	0	0	1	0	0	0	0	3	Not important

Hedgerow Number & location (x & y coordinates)	Scoping	Category										
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/ byway/ bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species	
391506												
367: 234547	Scrub	0	0	0	0	0	0	0	0	0	Not important	
391369												
371: 234938	Not a hedge	0	0	0	0	0	0	0	0	0	Not important	
391403												
372: 235017	Not a hedge	0	0	0	0	0	0	0	0	0	Not important	
391528												
373: 235133	Not a hedge	0	0	0	0	0	0	0	0	0	Not important	
391689												
376: 235314	Surveyed	0	0	0	1	1	0	1	0	0	Not important	
391903												
377: 235339	Surveyed	0	0	0	1	0	0	1	0	1	Not important	
392015												
378: 235254	Surveyed	0	0	0	1	0	0	0	0	3	Not important	
391931												
380: 235530	Not a hedge	0	0	0	0	0	0	0	0	0	Not important	
392210												
383: 235590	Surveyed	0	0	0	1	1	0	1	0	0	4	Not important
392446												
384: 235527	Surveyed	0	0	0	0	0	1	1	0	0	2	Not important
392599												
396: 235986	Not a hedge	0	0	0	0	0	0	0	0	0	Not important	
392935												

Hedgerow Number & location (x & y coordinates)	Scoping	Category										
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/byway/bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species	
402: 236327 393117	Surveyed	0	0	0	0	0	0	1	0	0	1	Not important
410: 236596 392992	Surveyed	1	0	0	1	0	1	0	0	0	3	Not important
411: 236683 393024	Surveyed	1	0	0	1	0	0	0	0	0	4	Not important
414: 236686 393051	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
415: 236749 393013	Surveyed	1	0	0	1	0	0	1	0	0	3	Not important
416: 236759 393042	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
419: 237180 393041	Defunct	0	0	0	0	0	0	0	0	0	0	Not important
423: 237607 393584	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
424: 237783 393597	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
425: 237868 393672	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
426: 237877 393667	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
427:	Defunct	0	0	0	0	0	0	0	0	0	0	Not important

Hedgerow Number & location (x & y coordinates)	Scoping	Category									
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/ byway/ bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species
237940											
393638											
428: 238055 393673	Not a hedge	0	0	0	0	0	0	0	0	0	Not important
429: 238110 393686	Not a hedge	0	0	0	0	0	0	0	0	0	Not important
430: 238310 393702	Not a hedge	0	0	0	0	0	0	0	0	0	Not important
432: 238177 393550	Defunct	0	0	0	0	0	0	0	0	0	Not important
433: 238476 393681	Not a hedge	0	0	0	0	0	0	0	0	0	Not important
434: 238474 393575	Not a hedge	0	0	0	0	0	0	0	0	0	Not important
435: 238770 393564	Defunct	0	0	0	0	0	0	0	0	0	Not important
436: 238891 393585	Not a hedge	0	0	0	0	0	0	0	0	0	Not important
441: 239257 393617	Not a hedge	0	0	0	0	0	0	0	0	0	Not important
442: 239165 393556	Defunct	0	0	0	0	0	0	0	0	0	Not important
443: 239152	Not a hedge	0	0	0	0	0	0	0	0	0	Not important

Hedgerow Number & location (x & y coordinates)	Scoping	Category									
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/ byway/ bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species
393606											
445: 239251	Defunct	0	0	0	0	0	0	0	0	0	0
393559											
446: 239339	Surveyed	0	0	0	1	0	1	1	1	1	2
393613											
447: 239446	Not a hedge	0	0	0	0	0	0	0	0	0	0
393607											
448: 239478	Surveyed	0	0	0	1	0	0	0	0	0	0
393580											
449: 239674	Surveyed	0	0	0	0	0	0	1	0	0	2
393638											
450: 239568	Surveyed	0	0	0	1	1	0	0	0	0	2
393726											
451: 239785	Not a hedge	0	0	0	0	0	0	0	0	0	0
393744											
452: 239707	Not a hedge	0	0	0	0	0	0	0	0	0	0
393684											
454: 239860	Not a hedge	0	0	0	0	0	0	0	0	0	0
393689											
455: 239842	Not a hedge	0	0	0	0	0	0	0	0	0	0
393681											
456: 239942	Not a hedge	0	0	0	0	0	0	0	0	0	0
393612											

Hedgerow Number & location (x & y coordinates)	Scoping	Category									
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/byway/bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species
458: 240087 393695	Not a hedge	0	0	0	0	0	0	0	0	0	0
459: 240105 393692	Not a hedge	0	0	0	0	0	0	0	0	0	0
460: 240287 393613	Defunct	0	0	0	0	0	0	0	0	0	0
461: 240316 393654	Defunct	0	0	0	0	0	0	0	0	0	0
462: 240346 393600	Defunct	0	0	0	0	0	0	0	0	0	0
463: 240494 393622	Defunct	0	0	0	0	0	0	0	0	0	0
464: 240727 393590	Not a hedge	0	0	0	0	0	0	0	0	0	0
465: 240763 393601	Not a hedge	0	0	0	0	0	0	0	0	0	0
466: 240940 393603	Not a hedge	0	0	0	0	0	0	0	0	0	0
467: 240947 393603	Not a hedge	0	0	0	0	0	0	0	0	0	0
468: 240993 393621	Surveyed	0	0	0	1	0	0	1	0	0	2
469:	Not a	0	0	0	0	0	0	0	0	0	0

Hedgerow Number & location (x & y coordinates)	Scoping	Category									
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/ byway/ bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species
240157 393569	hedge										
471: 240561 393506	Not a hedge	0	0	0	0	0	0	0	0	0	0
472: 240851 393507	Not a hedge	0	0	0	0	0	0	0	0	0	0
473: 240920 393536	Defunct	0	0	0	0	0	0	0	0	0	0
474: 240996 393483	Not a hedge	0	0	0	0	0	0	0	0	0	0
475: 241071 393496	Surveyed	0	0	0	1	0	0	0	0	0	5
477: 241375 3923820	Defunct	0	0	0	0	0	0	0	0	0	0
478: 241345 392494	Surveyed	1	0	0	1	0	0	1	0	0	4
479: 241377 392593	Surveyed	0	0	0	0	0	0	1	0	0	5
480: 241394 392511	Not a hedge	0	0	0	0	0	0	0	0	0	0
482: 241452 392133	Surveyed	0	0	0	0	0	0	0	0	0	0
483: 241442	Surveyed	0	0	0	1	0	1	1	0	1	1

Hedgerow Number & location (x & y coordinates)	Scoping	Category									
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/ byway/ bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species
392692											
484: 241446	Surveyed	0	0	0	1	0	1	1	0	1	1 Not important
392699											
485: 241509	Defunct	0	0	0	0	0	0	0	0	0	0 Not important
392875											
486: 241486	Not a hedge	0	0	0	0	0	0	0	0	0	0 Not important
393200											
487: 241462	Surveyed	0	0	0	1	0	0	0	0	0	1 Not important
393296											
488: 241540	Defunct	0	0	0	0	0	0	0	0	0	0 Not important
393033											
492: 241620	Defunct	0	0	0	0	0	0	0	0	0	0 Not important
392941											
493: 241634	Not a hedge	0	0	0	0	0	0	0	0	0	0 Not important
392890											
494: 241631	Not a hedge	0	0	0	0	0	0	0	0	0	0 Not important
392864											
495: 241611	Not a hedge	0	0	0	0	0	0	0	0	0	0 Not important
392806											
496: 241606	Surveyed	0	0	0	1	0	0	1	0	0	2 Not important
392789											
497: 241566	Surveyed	0	0	0	1	0	0	1	0	0	2 Not important
392686											

Hedgerow Number & location (x & y coordinates)	Scoping	Category									
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/byway/bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species
498: 241496 392571	Surveyed	0	0	0	1	0	0	1	0	0	4
499: 241481 392387	Defunct	0	0	0	0	0	0	0	0	0	0
500: 241509 392310	Surveyed	0	0	0	0	0	0	0	1	0	1
501: 241535 392276	Surveyed	0	0	0	0	0	0	1	1	0	1
503: 241555 392200	Defunct	0	0	0	0	0	0	0	0	0	0
504: 241526 392105	Defunct	0	0	0	0	0	0	0	0	0	0
505: 241592 392093	Defunct	0	0	0	0	0	0	0	0	0	0
506: 241530 392000	Defunct	0	0	0	0	0	0	0	0	0	0
507: 241528 391992	Defunct	0	0	0	0	0	0	0	0	0	0
508: 241473 391880	Surveyed	1	0	0	1	1	0	1	0	0	3
509: 241470 391873	Surveyed	1	0	0	1	1	0	1	0	0	3
510:	Defunct	0	0	0	0	0	0	0	0	0	0

Hedgerow Number & location (x & y coordinates)	Scoping	Category										
		At least 1 standard tree	Connections scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/ byway/ bridleway	Gap less than 10%	At least 3 woodland ground flora species	Parallel hedge	Number of Woody species	
241457												
391950												
511: 241415 391918	Not a hedge	0	0	0	0	0	0	0	0	0	Not important	
512: 241352 391875	Not a hedge	0	0	0	0	0	0	0	0	0	Not important	
513: 241350 391833	Not a hedge	0	0	0	0	0	0	0	0	0	Not important	
514: 241386 391799	Not a hedge	0	0	0	0	0	0	0	0	0	Not important	
516: 241465 391784	Defunct	0	0	0	0	0	0	0	0	0	Not important	
517: 241582 391770	Defunct	0	0	0	0	0	0	0	0	0	Not important	
519: 241726 391712	Defunct	0	0	0	0	0	1	1	0	1	3	Not important
520: 241828 391619	Surveyed	1	0	0	1	1	0	0	0	0	2	Not important
521: 241863 391587	Defunct	0	0	0	0	0	0	0	0	0	0	Not important
522: 241874 391575	Defunct	0	0	0	0	0	0	0	0	0	0	Not important
523: 241647	Surveyed	0	0	0	1	0	1	1	0	1	3	Not important

Hedgerow Number & location (x & y coordinates)	Scoping								At least 3 woodland ground flora species	Parallel hedge	Number of Woody species	Category
	At least 1 standard tree	Connectio ns scoring 4 or more points <sup>1</sup>	Lime/black poplar /wild service tree	Bank or wall	Ditch	Footpath/ byway/ bridleway	Gap less than 10%					
391703												
524: 241751 391632	Not a hedge	0	0	0	0	0	0	0	0	0	0	Not important
526: 241923 391455	Defunct	0	0	0	0	0	0	0	0	0	0	Not important
527: 242007 391310	Defunct	0	0	0	0	0	0	0	0	0	0	Not important

Source: Mott MacDonald 2013/20