Light Valley Solar

Environmental Statement Volume 3

Appendix 16.2: Arboricultural Impact Assessment

Document Reference: EN0110012/APP/LVS/06.03.16.02

February 2026

Planning Inspectorate Reference: EN0110012
APFP Regulation 5(2)(a)

Light Valley Solar

Infrastructure Planning

Planning Act 2008

The Infrastructure Planning
(Applications: Prescribed Forms and Procedure) Regulations 2009

Light Valley Solar

DCO Submission

Appendix 16.2: Arboricultural Impact Assessment

Regulation Reference	APFP Regulation 5(2)(a)
Planning Inspectorate Case Reference	EN0110012
Application Document Reference	EN0110012/APP/LVS/06.03.16.02
Author	Light Valley Solar Limited

Version	Date	Status of Version
1.0	February 2026	DCO Submission

Treework Environmental Practice

Arboricultural Impact Assessment

Light Valley Solar

Report Reference Number: EN0110012/APP/LVS/06.03.16.02

On behalf of

Light Valley Solar Limited

February 2026

Document Control Sheet

Project Name: **Light Valley Solar**

Report Ref: **EN0110012/APP/LVS/06.03.16.02**

Report Title: **Arboricultural Impact Assessment**

	Name	Position	Date
Prepared by:	Claire Harbinson	Principal Arboricultural Consultant	January 2025
Surveyed by:	Claire Harbinson Mike Wood Callum Throw Ben Watkins James Butler-White Nick Ball	Principal Arboricultural Consultant Senior Arboricultural Consultant Arboricultural Surveyor Arboricultural Surveyor Senior Arboricultural Consultant Arboricultural Surveyor	October 2024; January, June, October 2025

Table of Contents

Executive summary 1

1 Introduction 3

1.1 Brief and context 3

1.2 Purpose of this report 4

1.3 The Proposed Development 4

2 Existing tree population and constraints 5

2.2 Site descriptions 6

2.3 Tree/hedge quality and value 17

2.4 Statutory protection and designations 17

3 Arboricultural impacts from the Proposed Development 20

3.1 Design Principles – embedded mitigation 20

3.2 Tree removal and retention 20

3.3 Facilitative tree works 24

3.4 Tree protection during construction 25

3.5 Special technical measures 27

3.6 Tree protection and management during the operation phase (including maintenance) 29

4 Arboricultural compensation and enhancement 29

5 References 30

Annex A - Tree Schedule 31

Annex B - Tree Protection Plan 32

Annex C - Tree Protection Specifications 33

Annex D - Tree Survey Method and Limitations 34

Executive summary

- This Arboricultural Impact Assessment (AIA) report provides an assessment of the impact of the Proposed Development on trees, woodlands and hedges within and within influencing distance of, the Order Limits. The Proposed Development is made up of the Solar Development Sites, the Cable Route Corridor connecting the Solar Development Sites with one another and to the National Grid at Monk Fryston where the Proposed Development will connect to the National Grid, Highways Improvements Areas and access points for the Cable Route Corridor and the Solar Development Sites.

- 1685 individual trees, 257 groups of trees, 25 woodland blocks, and 440 hedges have been surveyed as falling within or within influencing distance of the Order Limits. Each of these features has been assigned a quality and value category from A (high) to U (low) according to *BS5837:2012: Trees in relation to design, planning and construction*. The tree survey data is presented within the Tree Schedule at Annex A.

- Within, or within influencing distance of the Order Limits, there is potential for the removal of 60 individual trees, 5 entire tree groups, 19 entire hedges (with a total length of 1543 m), and parts of 2 tree groups to facilitate the Proposed Development, of which 0 are category A, 9 are Category B, 64 are Category C and 3 are Category U. These trees and hedges are enumerated in Table 3-1 of this report. Parts of hedges of an approximate total length of 1715.5 m will also be removed in addition to the entire hedges identified above. Tree and hedge removals represent the worst-case scenario, and the actual loss may be less than the figures quoted in this report.

- All other trees within the Order Limits will be retained and integrated into the Proposed Development. Sufficient space and adequate protection measures will be put in place to ensure that retained trees are not damaged during the construction, operational, or decommissioning phases. Retained tree protection measures are discussed throughout this report and illustrated on the Tree Protection Plan at Annex B.

- 141 trees and tree groups may require lateral pruning and/or crown raising to accommodate construction plant/vehicles that will facilitate the Proposed Development. These works are summarised in Section 3.3 and on the Tree Schedule at Annex A.

- The Root Protection Areas (RPAs) of 9 trees within or within influencing distance of the Solar Development Sites fall within the internal proposed access

tracks. Special measures are specified at Section 3.5 to ensure that damage to these trees is avoided.

- The online planning map of North Yorkshire Council (NYC) (former Selby District) indicates that no Tree Preservation Orders or Conservation Areas are present within the Solar Development Sites. One tree, T2309, within influencing distance of the wider Order Limits is covered by TPO 5/2003. There is one ancient woodland (Gilbertson's Wood) within influencing distance of Solar Development Site 1 that is identified on the government Magic portal. Nine veteran/ancient trees were identified during the survey. No trees with statutory protection or ancient or veteran trees will be removed to facilitate the Proposed Development. T2309 may require minor pruning to facilitate construction access. Site access will pass beneath one veteran tree (T475); measures are proposed in this report at paragraph 3.5.2 to prevent the tree being damaged during construction.

1 Introduction

1.1 Brief and context

1.1.1 Treework Environmental Practice was instructed on behalf of the Applicant, in July 2024, June 2025 and October 2025 to provide a survey of trees across the Order Limits of the Proposed Development and to produce an AIA, in accordance with British Standard BS5837: 2012 Trees in *Relation to Design, Demolition and Construction – Recommendations* (), of the effect of the Proposed Development on trees, woodlands and hedges. The entirety of the Order Limits is within the administrative area of NYC and falls within what was Selby district.

1.1.2 This report covers trees, woodlands and hedges within and within influencing distance of the Order Limits, comprising the Solar Development Sites, Cable Route Corridor (with associated access points and visibility splays) and highways improvements areas.

1.1.3 British Standard BS 5837:2012 *Trees in Relation to Design, Demolition and Construction* sets out the principles and procedures to be applied to achieve a harmonious and sustainable relationship between trees and new developments. In the context of a Development Consent Order (DCO), this procedures involves an a tree survey to qualify and quantify the trees on site and establish the arboricultural constraints to development (above- and below-ground) to inform the design in an iterative process, and continues with an assessment of the arboricultural impacts of the Proposed Development covering the construction, operation and decommissioning phases to inform the Environmental Statement (ES), with measures to mitigate such impacts should they be negative. Detailed technical specifications for mitigation and protection measures are devised in the design phase that follows, which may also require further on-site surveys, and are presented in a final arboricultural assessment presented as part of the ES. The implementation of those measures once consent is granted may be guided by Arboricultural Method Statements and professional guidance where appropriate.

1.1.4 This final AIA reports on the likely direct and indirect impacts of the Proposed Development on trees in the construction, operation and decommissioning phases.

1.1.5 This report has been prepared to support the ES based on the design, construction and decommissioning information as presented in Chapter 2: The Proposed Development (ES Volume 1) [**EN0110012/APP/LVS/06.01.02**]. The impacts have been assessed on a worst-case scenario basis in terms of tree and hedge removals to facilitate construction accesses and visibility splays. It may be possible

to reduce tree and hedge removals from the quantities detailed in this report once detailed construction plans have been finalised.

1.2 Purpose of this report

1.2.1 This AIA, and accompanying Tree Schedule and Tree Protection Plan, is provided to support the ES. It highlights areas of conflict between trees, the design and construction facilitation for the Proposed Development, and suggests solutions and mitigation for any negative impacts.

1.2.2 It sets out the likely arboricultural impacts of the Proposed Development using the following considerations as a framework:

1. Trees and hedges to be removed and retained.
2. Remedial work to retained trees and hedges to allow development and ensure that retained vegetation will form a harmoniously integrated component of the Proposed Development.
3. Suitable measures to protect retained trees, woodlands and hedges.
4. Special construction or engineering measures required to enable trees, woodlands and hedges to be harmoniously integrated into the Proposed Development.

1.3 The Proposed Development

1.3.1 The Proposed Development comprises a solar photovoltaic (PV) electricity generating station of over 100 megawatts (MW) and 'associated development' comprising a Battery Energy Storage System (BESS), grid connection infrastructure and other infrastructure integral to the construction, operation and maintenance, and decommissioning phases.

1.3.2 The main element of the Proposed Development comprises seven Solar Development Sites (Solar Development Sites 1-4 and 6-8) that will accommodate the Solar PV Panels. A BESS Compound will be located within Solar Development Site 2.

1.3.3 The Cable Route Corridor is the area within which the export connection cables (hereafter referred to as the 'Grid Connection Cables') would be located to connect the Solar PV Sites to the National Grid at the existing Monk Fryston Substation (hereafter referred to as the 'Existing National Grid Monk Fryston Substation') and the area within which cables connecting the Solar Development Sites would be located (hereafter referred to as 'Interconnecting Cables') (refer to Figure 2.1: Illustrative Site Layout Plan (ES Volume 2) [**EN0110012/APP/LVS/06.02.02.01**].

1.3.4 Further details of the Proposed Development are presented in Chapter 2: The Proposed Development [**EN0110012/APP/LVS/06.01.02**] and the design envelope for the Proposed Development is set out in the Design Parameters and Commitments Document [**EN0110012/APP/LVS/05.06**] and the limits of deviation shown on the Works Plans [**EN0110012/APP/LVS/02.03**]. The entirety of the Order Limits fall within the NYC administrative area.

2 Existing tree population and constraints

2.1.1 A survey covering trees within the Solar Development Sites and trees on adjacent land close enough to be affected by the Solar Development Sites was undertaken in October 2024 and January 2025. A survey of the Cable Route Corridor and access points for the Cable Route Corridor and the Solar Development Sites was completed in June 2025. A further survey of the Highways Improvements Areas and areas of land added to the Order Limits was conducted in October 2025. The full survey results are presented in the Tree Schedule at Annex A.

2.1.2 The survey was undertaken based on trees plotted using an OS Mastermap base map as reference in Treework Environmental Practice's specialist tree management software: MyTrees. The basemap contained a topographical survey of the trees for limited portions of Solar Development Site 1 only. Trees and hedges were plotted on the basemap using a combination of topographical survey, onsite measurement, GPS and aerial photos as references, and their positions are therefore approximate.

2.1.3 The Solar Development Sites and Cable Route Corridor currently comprise arable and grazing farmland, arranged in fields bounded by hedges. As is typical of agricultural fields, trees are located around the field boundaries either singly, within hedges or within woodland blocks, with only very occasional instances of trees within the fields. Some of the proposed highways improvements areas are in villages and small towns, where trees are mainly ornamental.

2.1.4 Ash dieback (also known as chalara, caused by the fungus *Hymenoscyphus fraxineus*) is present within the Order Limits and surrounding countryside, but where observed currently seems to be in the early stages. However, the disease progression can change quite rapidly, and it can be anticipated that a proportion of the surveyed ash trees will succumb to the disease and eventually need to be removed.

2.2 Site descriptions

Solar Development Site 1

2.2.1 Solar Development Site 1 comprises the field parcels around Mount Pleasant Farm and Manor Farm. The fields are all bordered by early mature and mature hedges interspersed with large mature or early mature oak (*Quercus robur*) of high (Category A) or moderate (Category B) quality, with occasional mature specimens of field maple (*Acer campestre*) and willow (*Salix* sp.). Many of the field boundaries are bordered by deep, wet ditches, and the trees are growing on one bank. Some veteran trees and likely future veteran trees have been identified from among this population.



Photo 1 Typical managed hedge field boundaries with mature oak



Photo 2 Typical mature oak growing on deep ditch bank



Photo 3 Typical unmanaged hedge with mature oak



Photo 4 Veteran (possibly ancient) willow





Photos 4 and 5 Occasional early mature and mature oak in field

2.2.2 There are also occasional mature ash (*Fraxinus excelsior*) along the field boundaries. The ash have been ravaged by ash dieback, which has shortened their life expectancy and, in many places, has lowered their quality and retention value to a Category C or Category U (see paragraph 2.2.19 for a definition of the categories).





Photos 6 and 7 Field boundary ash showing signs of ash dieback

2.2.3 Hedges are all mostly managed, with periodic cutting to keep their height at between 1 and 2 m and have a fairly low species diversity commensurate with hedges planted around the time of Enclosure or thereafter, being predominantly comprised of hawthorn (*Crataegus monogyna*) and blackthorn (*Prunus spinosa*). Some hedges are thick and more or less continuous; these have been assigned a Category B. Others have been over-managed and are now thin and gappy; these have been assigned a Category C. The Escrick Park Estate has implemented a programme to coppice some of the poorer condition hedgerows to rejuvenate them over the winters of 2024/25 and 2025/26 as part of their long-cycle hedgerow management.



Photo 8 Entire typical managed hedge



Photo 9 Typical gappy managed

2.2.4 Small plantations of oak and sycamore (*Acer pseudoplatanus*) and occasionally of conifers such as Sitka spruce (*Picea sitchensis*) have been planted in various pockets and field corners across the site. These plantations have presumably all been planted as crops to be harvested in the future. Easterby's Plantation to the north of Mount Pleasant Farm was being harvested at time of survey. These plantations are all outside of the Order Limits but are within influence of the Proposed Development in terms of crown overhang, RPAs, and shade.



Photo 9 Typical conifer plantation



Photo 10 Typical broadleaf plantation

2.2.5 The boundary to the northeast of Solar Development Site 1 is bordered by an ancient semi-natural woodland (Gilbertson's Wood) of mixed broadleaves (predominantly ash, oak and sycamore). This feature is off-site on the east side of the track but is within influencing distance in terms of crown overhang. Category A edge groups of this woodland have been included in the survey.



Photo 11 Gilbertson's Wood (ancient woodland)

Solar Development Site 2

2.2.6 Solar Development Site 2 comprises four large rectangular fields to the south of Monk Fryston Common Lane and a small field parcel to the north of it. The northern boundary of the southern rectangular fields is largely devoid of trees or hedges. To the east of Siddle Farm House the northern boundary is lined with a short group of young and early mature oak, with one large mature Category A oak of high quality. To the east of these trees is a plantation of tall, mature hybrid black poplar (Populus x canadensis) of moderate quality and value (Category B).



Photo 12 Boundary oak



Photo 13 Mature poplar plantation

2.2.7 The remainder of the eastern boundary has only scattered hedge trees and short lengths of remnant hedge. The southern boundary with the road is interspersed with semi-mature ash. All of these trees are showing sign of ash dieback and likely have a limited lifespan as a result (Category C).



Photo 13 Roadside ash with incipient ash dieback



Photo 14 Degraded hedge

2.2.8 The western boundary is bordered to the south with a high-quality linear shelterbelt of mature oak with hawthorn, hazel (*Corylus avellana*) and blackthorn understorey, growing around an eroded bank and ditch. The northern part of the western boundary with Fryston Common Farm is bordered by a tall category B hedge of hazel, hawthorn, elder (*Sambucus nigra*) and dogwood (*Cornus sanguinea*) planted with semi-mature field maple (*Acer campestre*) and ash of low quality and value (Category C).



Photo 15 Mature oak shelterbelt



Photo 16 Mature hedge with semi-mature field maple

2.2.9 The small parcel to the north of the road is bordered to the east and west by discontinuous hedge remnants. The eastern side contains early mature trees of oak (Category B) and ash (Category C) with willow (Category C) in a wet flush to the northeast. A large Category B goat willow (*Salix caprea)* grows adjacent to the field entrance to the southwest.

Solar Development Site 3

2.2.10 Solar Development Site 3 comprises three fields on Hillam Common bordered by deep ditches with occasional oak (Category B) and ash with varying severities of ash dieback (Category C) growing on the banks. Short lengths of remnant hedges of hawthorn and hazel are scattered around the boundaries.



Photo 17 Central oak group



Photo 18 Boundary oak

Solar Development Site 4

2.2.11 Solar Development Site 4 comprises a series of fields north of Birkin Road set around a central farmhouse.





Photos 19 and 20 Field oak and ash along eastern

2.2.12 Fields to the north are large, open field parcels bordered by tracks with sparse trees and hedge remnants. Small pockets of boundary trees of oak, sweet chestnut (*Castanea sativa*), poplar and sycamore are dotted around the boundaries. These are mostly of moderate quality and value (Category B). Farm buildings are surrounded by small plantations of early mature mixed broadleaves of high (Category A) and moderate (Category B) quality and value.





Photo 21 and 22 Central plantations of broadleaves



Photo 23 Typical field boundary with deep ditches and early mature oak



Photo 24 Typical remnant group of boundary trees

Solar Development Site 6 – Land South of Common Lane

2.2.13 This Solar Development Site comprises four fields to south of Common Lane. Trees are sporadically distributed around the field boundaries. The easternmost field only has trees along the southern boundary; these comprise semi- and early mature oak, ash, alder (*Alnus glutinosa*) and willow of either low (Category C) or moderate (Category B) quality. There are also discontinuous hedges of predominantly hawthorn and elm (*Ulmus* sp.) of low quality (Category C). The large central field contains only one tree, a Category B oak on the northern boundary. The southwestern field has scattered trees along of field maple (*Acer campestre*), ash and lime (*Tilia x vulgaris*) along the northern boundary with Turpin Lane, and a small group of early mature sycamore of moderate quality (Category B) to the south. The boundary with adjacent properties in the southwest corner is bordered by B Category sycamore trees and a hawthorn/goat willow hedge. The small field to the east of Turpin Lane is bordered by hawthorn hedges and contains a Category B oak tree on each of the northern and western boundaries. The adjacent offsite field contains a group of early mature willow that overhang the central field.





Photos 25 and 26 Field boundary of eastern field with occasional oak and ash



Photo 27 Lone oak growing on deep ditch bank in the central field



Photo 28 Group of sycamore in south-west field



Photo 29 Sycamore along southwestern boundary of south-west field



Photo 30 Sporadic ash, oak and lime to north of south-west field





Photos 31 and 32 Lone oaks along boundaries of field west of Turpin

Solar Development Site 7 Land North of Common Lane

2.2.14 This Solar Development Site comprises a single field between Common Lane and the railway embankment. There is an area of willow in the southwest; there was a large mature willow here, but it failed in a recent storm. Young alder, birch (*Betula pendula*) and Scots pine (*Pinus sylvestris*) have been sporadically planted along the western boundary. The western half of the northern boundary with the railway contains occasional early mature trees of field maple (Category B) and ash (Category C). The remaining boundary has recently been planted with saplings to form a hedge. Low quality (Category C) blackthorn hedges line the eastern field boundary, with occasional Category C semi-mature ash and oak.



Photo 33 Eastern boundary



Photo 34 Willow group to southwest



Photo 35 View along western boundary towards railway

Solar Development Site 8 Land North of the Railway

2.2.15 This large single field has almost no trees. It is bordered by a sinuous dyke to the west, a track to the east and the railway to the south. The boundary with the small piece of railway land to the southwest that is currently farmed as part of the field has three mature trees of ash, oak and white poplar (*Populus alba*), all Category B. The dyke in this corner is lined with white poplar of moderate quality (Category B). The small nub of rough land to the northwest contains a Category B ash and is bordered to the north by remnants of an old hedge of oak, myrobalan plum (*Prunus cerasifera*) and elder (*Sambucus nigra*). A blackthorn hedge and thicket can be found in the northeastern corner. The area behind the railway fence contains some goat willow that have been hard pruned to the field boundary (Category C).



Photo 36 Individual trees on railway land




Photo 37 View towards dyke to southwest



Photo 38 Individual ash in rough land to northeast



Photo 39 View north

Cable Route Corridor (CRC) 1-4 (from Solar Development Site 1 to Solar Development Site 4)

2.2.16 The Cable Route Corridor between Solar Development Sites 1 and 4 traverses roughly 18.5 km of agricultural fields bordered by hedges and rows of trees. The route crosses the A19, the River Ouse, Selby Dam, National Rail lines, the A63 and other smaller roads. In character these are broadly similar to the fields in Solar Development Site 1, and the species assemblage is comparable; trees are chiefly oak and ash, with willow and alder on wetter land; hedges are predominantly hawthorn and blackthorn. Hedges are in compact form due to regular management. In the more northerly half of the route some field boundaries, notably where ditches are large, comprise dense linear groups of trees, and individual trees are larger and older; retention categories are on average higher (A and B). In in the more southerly half of the route hedges are shorter and often gappy and depleted.



Photo 40 – Typical field boundary vegetation in northern half of Cable Route Sites 1-4



Photo 41 – Typical depleted field boundary vegetation in southern half of Cable Route Sites 1-4

Cable Route Corridor 1-4a (from Solar Development Site 1 to Solar Development Site 4)

2.2.17 This alternative Cable Route Corridor from Solar Development Site 1 to Solar Development Site 4, which crosses over Fox Lane and Hillam Common Lane. This corridor also connects into Cable Route Corridor 2-4 for the most southern section. There are no trees or hedges in this section.

Cable Route Corridor 2-4 (from Solar Development Site 2 to Solar Development Site 4); Cable Route Corridor 2-6 (from Solar Development Site 2 to Solar Development Site 6); Cable Route Corridor 3-4 and 3-4a (from Solar Development Site 3 to Solar Development Site 4); Cable Route Corridor 6-7 (from Solar Development Site 6 to Solar Development Site 7) and Cable Route Corridor 2-8 (between Solar Development Sites 2 and 8)

2.2.18 The cable routes between Solar Development Sites 4 and 2, Sites 2 and 6, and Sites 2 and 8 and Sites 3 and 4 traverse large fields with unvegetated boundaries save for some remnant hedges along the main roads, a belt of higher value trees just east of Ingthorne Lane, some low quality hedges either side of the railway to the north of Solar Development Site 6 and some moderate quality trees on the south side of Common Lane south of Solar Development Site 7.

Cable Route Corridor 4-POC (from Monk Fryston Substation to Solar Development Site 4)

2.2.19 The route between Solar Development Site 4 and Monk Fryson Substation traverses large fields where the boundary vegetation is patchy and mostly of low quality and value (Category C), with occasional individual trees of moderate quality and value (Category B). The National Grid substation is bordered to the east by a belt of semi-mature plantation woodland of predominantly ash; due to its condition it is of low quality and value (Category C)*.*

2.3 Tree/hedge quality and value

BS5837: 2012 recommends classifying trees into four quality and value categories to determine their relative retentive worth. A summary of the relative retentive worth of the trees on site as recorded during the tree survey and expressed by their categories is given in Table 2-1. Annex A explains the BS 5837:2012 tree categorisation process.

Table 2-1: Trees/groups in each retention category

Category	Total	Tree	Group	Hedgerow	Woodland
A	124	115	6		3
B	938	748	105	71	16
C	1274	763	142	369	6
U	63	59	4		
Total	**2407**	**1685**	**257**	**440**	**25**

2.3.1 Trees present constraints to development both above and below ground. The above-ground constraints comprise the physical extent of tree crowns. The below-ground constraints comprise the roots and are expressed in terms of the RPA, which is the minimum rooting area that a tree needs to sustain itself in reasonable health. These constraints, as established by the tree survey, inform this assessment of the impact of the Proposed Development.

2.3.2 The full results of the tree survey on which this report is based are given in the Tree Schedule at Annex A, and the above- and below-ground constraints are illustrated on the Tree Protection Plan at Annex B. Each tree (T), tree group (G), woodland, (W) and hedge (H) has been allocated an individual number to which it is referred in this report and all associated documents. The survey method and limitations are set out in Annex D.

2.4 Statutory protection and designations

2.4.1 ***Tree Preservation Orders and Conservation Areas***

A review of the online planning map of NYC (former Selby District) indicates that none of the Solar Development Sites lie within a Conservation Area. One tree, T2309, within influencing distance of the wider Order Limits is covered by TPO 5/2003.

2.4.2 ***Ancient and Veteran Trees***

Veteran and ancient trees are afforded special protection in the planning system as irreplaceable habitat (Ref 2, para 5.4.54). Normally, policy dictates that development plans that involve the destruction of irreplaceable habitat will not be granted consent unless there are wholly exceptional circumstances. Nine veteran/ancient trees have been identified across the Solar Development Sites, 7 in Solar Development Site 1 and 2 along the Cable Route Corridor, as shown in Table 2-2 below. An additional buffer zone, calculated as 15 times the stem diameter as opposed to 12 times for an RPA, has been considered as the minimum offset between these trees and development proposals, in accordance with the Natural England Standing Advice on Ancient Woodland, Ancient Trees and Veteran Trees (Ref 3). This buffer is shown on the Tree Protection Plan at Annex B.

Table 2-2: Veteran Trees identified within the Order Limits

Object ID	Species	Location	Retention Category
T159	*Quercus robur* (English oak)	Western boundary of field 1.21	A13
T188	*Quercus robur* (English oak)	Western boundary of field 1.21	A13
T475	*Quercus robur* (English oak)	Southern boundary of field 1.28	A13
T535	*Fraxinus excelsior* (Ash)	Eastern boundary of field 1.43	B13
T947	*Quercus robur* (English oak)	Eastern boundary of field 1.31	A13
T1174	*Quercus robur* (English oak)	Southern boundary of field 1.12	A3
T1340*	*Salix fragilis* (Crack willow)	Southwestern boundary of field 1.16	A3
T1894	*Quercus robur* (English oak)	Southern boundary of CR51	B3
T1939	*Fraxinus excelsior* (Ash)	Southern boundary of CR467	B3

** Possibly also an ancient tree*

2.4.3 A further 24 trees within or within influencing distance of the Order Limits were identified as having some veteran habitat characteristics but were not judged to have a sufficient number of habitat features, longevity of habitat and/or age and size to qualify for veteran status.

2.4.4 One tree is identified as veteran on the Ancient Tree Inventory dataset managed by the Woodland Trust. This tree appears to correspond with tree T310 (category A) on our survey. This has not been identified as a veteran tree in the survey due to its lack of habitat features, and it is noteworthy that the girth of the tree as recorded on the Inventory is much larger than the girth that was measured during the survey.

2.4.5 ***Ancient Woodland***

Gilbertson's Wood to the northeast of Solar Development Site 1 is designated as ancient semi-natural woodland according to the government Magic portal. Woodland groups W1253, W1256 and W1257 on the survey, which form the western edge of this wood and are outside of the Order Limits but within influencing distance of them, are therefore designated as ancient woodland, which is also classed as irreplaceable habitat (Ref 2) and the additional buffer zone of 15 mhas been considered as the minimum offset between the woodland and the development proposals as part of the embedded mitigation, as per Natural England Standing Advice (Ref 3). This is illustrated on the Tree Protection Plan at Annex B.

2.4.6 ***Important Hedgerows***

Three hedges (H1.16, H1.65, and H6.10) as identified in the ecology survey, which correspond to hedges H476 (H1.16), H309, H312, H316 and H317 (H1.65) and H1770 (H6.10) as identified in the arboricultural survey, have been identified in Chapter 8: Cultural Heritage (ES Volume 1) [**EN0110012/APP/LVS/06.01.08**] as being Important under the criteria of the Hedgerow Regulations 1997.

3 Arboricultural impacts from the Proposed Development

3.1 Design Principles – embedded mitigation

3.1.1 As embedded mitigation, when setting the parameters for land suitable for solar development and BESS development, a 15 m buffer was put in place around ancient woodland, a 10 m buffer was put in place around non-ancient woodland, a buffer of 15 times the stem diameter as measured at 1.5 m was put in place around ancient/veteran trees and a 5 m buffer was put in place for non-ancient/non-veteran trees. This mitigation is embedded as a Design Principle and as set out in the Design Parameters and Commitments Document **[EN0110012/APP/LVS/05.05.01]** and the Outline Construction Environmental Management Plan (oCEMP) **[EN0110012/APP/LVS/07.02]**. Following the establishment of more precise constraints in the form of RPAs and canopy extents from the tree survey, the buffers or the RPA, whichever is greater, have been applied. In rare cases where the buffers cannot be applied, alternative mitigation has been proposed to reduce the impacts on retained trees (see Section 3.5 of this report). The Design Principles for ancient woodland and ancient and veteran trees are also applicable to the Cable Route Corridor and highway improvement areas, but the RPAs/canopy extents have been used to establish suitable distances between construction activity and retained trees, tree groups, hedges and non-ancient woodland.

3.2 Tree removal and retention

3.2.1 The removal of 1 individual tree and the removal of parts of 13 hedges up to a total of 81 m of hedge will be required within the Solar Development Sites to facilitate the Proposed Development.

3.2.2 Three entire hedges, and short lengths of 2 hedges will be removed to facilitate ornithology enhancements and permissive path creation adjacent to the Solar Development Sites.

3.2.3 To facilitate the Cable Route Corridor or to maintain appropriate visibility splays for direct accesses to either the Cable Route Corridor or the Solar Development Sites, 54 individual trees, 11 entire tree groups, 19 entire hedges (with a total length of 1501 m), small parts of 1 tree group (c. 6 trees) and 1 woodland group (2-3 trees) and parts of 55 hedges with a combined approximate total length of around 1715.5 m will need to be removed in the worst-case scenario.

3.2.4 Identification of vegetation removals to facilitate the cable installation have been based on a working width along the Cable Route Corridor of 25 m to accommodate the cable trench, the haul road, which will run adjacent, and spoil from the trenching. Where horizontal directional drilling (HDD) has been specified the launch and receptor pits will adopt a 10 m standoff from watercourses and 50 m

from Canal and River Trust watercourses. Therefore, they will be outside of AVT buffer zones, RPAs and canopy spreads of trees, tree groups, woodlands and hedges.

3.2.5 Removals for visibility splays and accesses are based on a worst-case scenario Design Manual for Roads and Bridges (DMRB) criteria using the maximum criteria or One Step Below criteria. It may be possible to reduce the number of trees and lengths of hedges lost to visibility splay facilitation in the final construction plan by using alternative acceptable criteria or by using banksmen to ensure vehicle ingress/egress safety where high-value trees might otherwise be lost, but this assessment assumes a worst-case of loss.

3.2.6 Within or within influencing distance of the Order Limits, 59 Category U trees and 4 tree groups have been identified that are in poor structural and/or physiological condition such that they would not have an anticipated remaining lifespan of greater than 10 years. Where there is a need to remove these trees to facilitate the Proposed Development their removal has been recommended and is recorded in Table 3-1 below. Elsewhere, it may not be necessary to remove Category U features unless they pose a high risk to infrastructure or construction personnel. This can be assessed on a case-by-case once the details of the construction programme have been finalised and in agreement with the Arboricultural Clerk of Works, as set out in the oCEMP [**EN0110012/APP/LVS/07.02**].

3.2.7 No veteran or ancient trees or trees in ancient woodlands will be removed to facilitate the Proposed Development.

Table 3-1: Trees/Entire Tree Groups/Entire Hedges for Removal by BS Category

Category A Trees/Groups/Hedges/ Woodland	**Category B Trees/Groups/Hedges/ Woodland**	**Category C Trees/Groups/Hedges/ Woodland**	**Category U Trees/Groups/Hedges/ Woodland**
-	T149, H465, H466, H614, T1554, T1555, G1623, T2502, T2503	T353, T354, T837, H1058, H1060, T1097, T1186, T1187, T1188, T1546, T1547, T1548, T1549, T1550, T1638, T1639, H1676, T1677, T1678, T1679, T1690, T1691, T1696, T1697, T1698, T1701, T1702,	T2177, G2347, T2365

Category A Trees/Groups/Hedges/ Woodland	Category B Trees/Groups/Hedges/ Woodland	Category C Trees/Groups/Hedges/ Woodland	Category U Trees/Groups/Hedges/ Woodland
		H1704, H1705, T1826, G1827, H1958, T1960, T1961, H1962, T1963, T1964, T1965, H1993, T2005, T2006, T2019, H2020, H2025, T2037, T2038, H2039, H2041, T2140, G2148, T2178, T2189, T2190, T2227, T2247, T2248, G2344, H2432, H2459, T2460, H2467, T2489, T2491, H2496, T2501, T2504	
0	9	66	3

Table 3-2: Lengths of Hedges for Removal

Object ID	Location	BS Category	Hedge Length Removed (m)
Entire Hedges			
H465	Solar Development Site 1	B	293
H466	Solar Development Site 1	B	18
H614	Solar Development Site 1	B	421
H1058	CRC 3-4	C	6
H1060	CRC 3-4	C	17
H1676	CRC 1-4	C	197
H1704	CRC 1-4	C	62
H1705	CRC 1-4	C	95
H1958	CRC 1-4	C	17
H1962	CRC 1-4	C	17
H1993	CRC 1-4	C	41
H2020	CRC 1-4	C	15
H2025	CRC 1-4	C	27
H2039	CRC 4-POC	C	28
H2041	CRC 4-POC	C	8

Object ID	Location	BS Category	Hedge Length Removed (m)
H2432	CRC 2-4	C	7
H2459	CRC 4-POC	C	126
H2467	CRC 4-POC	C	50
H2496	CRC 1-4	C	98
Total length of entire hedges to be removed (m)			**1543**
Partial Hedges			
H148	Solar Development Site 1	B	3
H207	Solar Development Site 1	C	4
H221	Solar Development Site 1	B	2
H260	Solar Development Site 1	B	3
H348	Solar Development Site 1	B	5
H467	Solar Development Site 1	B	3
H479	Solar Development Site 1	B	8
H482	Solar Development Site 1	B	7
H507	CRC 1-4	B	25
H626	Solar Development Site 1	B	5
H960	Solar Development Site 1	C	4
H1217	Solar Development Site 1	C	5
H1389	Solar Development Site 1	C	5
H1425	Solar Development Site 6	C	15
H1462	Solar Development Site 6	C	7
H1540	CRC 1-4	C	25
H1542	CRC 1-4	C	25
H1544	CRC 1-4	C	16
H1551	CRC 1-4	C	176
H1562	CRC 1-4	C	245
H1565	CRC 1-4	C	242
H1570	CRC 1-4	C	10
H1584	CRC 1-4	B	20
H1612	CRC 1-4	C	190
H1643	CRC 4-POC	C	25
H1668	CRC 1-4	C	25
H1674	CRC 1-4	C	103
H1708	CRC 1-4	C	25
H1715	CRC 1-4	C	25
H1718	CRC 1-4	C	25
H1770	Solar Development Site 6	C	10
H1866	CRC 1-4	C	45
H1868	CRC 1-4	C	25
H1870	CRC 1-4	C	25
H1878	CRC 1-4	C	25
H1881	CRC 1-4	C	10
H1882	CRC 1-4	C	25

Object ID	Location	BS Category	Hedge Length Removed (m)
H1892	CRC 1-4	C	25
H1898	CRC 1-4	C	25
H1956	CRC 2-6	C	13.5
H1978	CRC 1-4	C	25
H2002	CRC 1-4	C	122
H2025	CRC 1-4	C	27
H2068	CRC 1-4	C	51
H2072	CRC 1-4	C	25
H2073	CRC 1-4	C	25
H2074	CRC 1-4	C	25
H2079	CRC 1-4	C	25
H2151	CRC 1-4	C	12
G2164	CRC 1-4	B	99
H2354	CRC 1-4	C	26
H2364	CRC 1-4	C	18
H2370	CRC 1-4	C	8
H2371	CRC 1-4	C	22
H2483	CRC 1-4	C	115
H2584	CRC 1-4	B	15
Total length of partial hedges to be removed (m)			**1715.5**
Total length of hedges to be removed (m)			**3258.5**

3.2.8 A 10 m span of one Important Hedgerow H1770 (H6.10) in Solar Development Site 6 will be removed to facilitate the Proposed Development. The two other Important Hedgerows will be retained,

3.2.9 All trees, tree groups, woodlands and hedges other than those in Table 3-1 and Table 3-2 will be retained and protected during the lifetime of the Proposed Development (see Section 3.4).

3.3 Facilitative tree works

3.3.1 No tree works are likely to be required to facilitate installation of the panels, as trees within the Solar Development Sites fields are around the field boundaries and the panels will be installed internally to the fields, with generous offsets. Minor pruning such as crown lifting or removal of selected small branches may be required to provide suitable clearance for construction and maintenance vehicles using the access tracks within the Sites.

3.3.2 Seven groups of trees, 3 hedges and 2 trees will require minor lateral pruning to provide suitable clearance along access tracks.

3.3.3 Crown raising to achieve clearance above the highway of 5 m will be required to an estimated 111 trees, 12 tree groups and the edges of 7 woodland blocks to facilitate the passage of large construction vehicles and abnormal indivisible loads (AILs) that will be using minor roads or access tracks unused to high-sided vehicles. The exact number of trees that will require pruning will be identified once construction access plans have been finalised, and thus the currently identified work represents the worst-case scenario.

3.3.4 All of the tree work cited above is specified in the Tree Schedule at Annex A.

3.3.5 The oCEMP [**EN0110012/APP/LVS/07.02]** provides that hedges that are currently managed will be trimmed to the usual extents immediately prior to the commencement of construction to minimise the risk of conflict with construction plant and to avoid the need for maintenance during construction. Once construction is complete, the hedges can be allowed to grow out if desired.

3.4 Tree protection during construction

3.4.1 The oCEMP [**EN0110012/APP/LVS/07.02]**, provides for the following.

3.4.2 ***RPAs and Construction Exclusion Zones (CEZ)***
Retained trees will be protected during construction by establishing a CEZ around their RPAs. RPAs are a layout design tool, indicating the minimum area around a tree deemed to contain sufficient roots and soil to maintain the tree's viability. RPAs should be treated as a precautionary area within which activities such as ground compaction, excavation, the storing of materials, ground level changes and other construction activity that are likely to cause damage to trees should be excluded. This CEZ can be achieved by the erection of barriers. Tree protection barriers must be installed before any demolition or construction works start and should remain in place until all construction activity has been completed. Final specifications for all tree protection measures will be set out in the detailed Construction Environmental Management Plan (CEMP).

3.4.3 Across most of the Solar Development Sites, the permanent security fencing will serve as the tree protection fencing. The security fencing is likely to be deer wire mesh fencing of around 2.5 m in height, affixed with wooden posts driven into the ground. This will form a barrier that is immovable and braced against accidental impact. The security fencing will be installed before the arrival of plant and materials and any other form of construction taking place. The fencing will be sited

outside of RPAs and tree canopies and can be installed using plant of a similar size to the agricultural vehicles that typically traverse the fields and tracks. Nevertheless, all vehicles, materials and personnel required to install the fencing will operate on the field side of the fence line to avoid traversing RPAs. These commitments are included in the oCEMP [**EN0110012/APP/LVS/07.02**].

3.4.4 Indicative locations of the dual-purpose security fencing/tree protection fencing are shown on the Tree Protection Plan at Annex B, but this will be confirmed in an updated version of this plan submitted with the detailed CEMP.

3.4.5 Where the security fencing does not protect RPAs and cannot be adjusted (e.g., for retained trees located within fields and trees/hedges along the Cable Route Corridor), temporary tree protection fencing will be installed to protect trees during the construction and decommissioning phases. The fencing will be erected to a specification similar to drawing 3 in BS 5837:2012 (Ref 1) (reproduced at Annex C) where construction activity is close to vegetation, and can be of a lower specification (e.g., ski netting secured with road pins; see Annex C) where construction activity is more distant. All temporary tree protection fencing will carry identifying signs that state its purpose and proscribe its removal until all construction or decommissioning work is complete.

3.4.6 ***Transport access and access tracks***

Transport access into the Solar Development Sites will be from existing roads and farm access tracks, using existing entrances or new entrances that have been selected to avoid boundary vegetation; therefore, the impact on trees and hedges of the access tracks will be minor. Vehicles traversing the fields in the Solar Development Sites will use the internal access roads, which will either be existing farm tracks or formed of new tracks where farm tracks are unavailable. Access tracks will be a maximum of 6 m wide, which may require upgrading existing tracks to accommodate the size and weight of plant being brought onto site.

3.4.7 ***BESS/Substations***

The BESS will be located at the eastern end of the southwestern field of Solar Development Site 2 as shown on Figure 2.1 Illustrative Site Layout Plans (ES Volume 2) **[EN0110012/APP/LVS/06.02.02.01]**. The maximum extents of the BESS are at least 20 m from any retained trees or hedges. Substations will be constructed in Sites 1, 2 and 4 at least 20 m from any retained trees or hedges. No trees or hedges will be affected by their construction, and the facilities will be separated from trees and hedges by the site security fencing.

3.4.8 ***Construction compounds***

All temporary Solar Development Site Construction Compounds are located in fields where there is no vegetation, either centrally or peripherally. The Cable Construction Compounds are either located in fields with no vegetation, or the maximum extents have been reduced to leave sufficient separation between the compounds and boundary trees, tree groups and hedges.

3.4.9 ***Cable installation***

The cable will be installed in an excavated trench along the majority of the routes, except where natural obstacles such as roads, railways, rivers and buried services require the cable to be installed using HDD. The current trajectory of the cable has been selected to avoid high value (Category A and B) trees and hedges. However, the precise siting of the cable trench, which will be around 2 m wide, within the Cable Route Corridor will be determined by physical constraints that will be identified during the works and may deviate within the Order Limits from the currently planned trajectory.

3.4.10 In principle, the cable trench, which will be between 2 and 7 m wide, should be sited to avoid the RPAs of all retained trees, but particularly the higher value category A and B trees, tree groups and hedges. Where the cable trench requires partial hedge removals the precise position of the trench along the hedge may vary, but the length identified for removal will be similar to that calculated in this report, as the assessment has been based on the principle of a 25 m span to accommodate the trench, haul road and additional working area (e.g., for temporary spoil deposition). Minor encroachments on the periphery of RPAs may be tolerable, but major encroachments could require trees to be removed. Where HDD is used, the launch and receptor pit will be sited outside of the RPAs, canopy extents and buffers of retained trees, tree groups and hedges to ensure that impacts are minimal. All trees and hedges immediately adjacent to the 25 m wide working area will be protected by temporary tree protection fencing; however, it would not be reasonable to extend the protection to all trees/hedges in the field being traversed, as these trees will not be affected by the construction activities. All plant/vehicle movements and materials storage will take place outside of the RPAs/canopy extents/buffer zones of retained trees, tree groups, hedges and woodland.

3.5 Special technical measures

3.5.1 Conflicts between retained trees and aspects of the Proposed Development that cannot be dealt with by CEZs, tree protection or remedial tree work can be mitigated by the use of special technical measures. General recommendations for these measures are presented in the sections that follow based on the information that is currently available. The specific details must be carefully planned once

detailed construction information is available to avoid tree damage. An Arboricultural Method Statement will be produced before construction starts and prior to decommissioning to guide sensitive works around trees, with provision for supervision by a qualified arboriculturist where necessary. The requirement for an Arboricultural Method Statement is committed to in the oCEMP.

3.5.2 ***No-dig access track construction***

In two locations in Solar Development Site 1 and one location in Solar Development Site 6, the internal site access tracks cross the RPAs of retained trees (T472, T473, T474, T475 (a veteran tree), T477, T478 and T1266 in Solar Development Site 1; T1450 and T1455 in Solar Development Site 6). These access tracks will be formed of existing farm tracks; however, the size and weight of plant and frequency of trips may be greater than would usually traverse the current tracks. These tracks may therefore need to be upgraded to accommodate the construction plant. Where the tracks cross RPAs, track upgrading must be carried out on a "no-dig" basis; that is, there must be no excavation into the existing track where tree roots may be growing to avoid root severance. Upgrades must be achieved by building up on existing levels. To avoid compaction of soil within and below the existing tracks, the chosen solution must have a suitable load-spreading specification sufficient for the maximum loads anticipated to avoid compacting any existing ground within the RPA, which may contain tree roots. This could comprise a cellular matrix of sufficient depth for the proposed use with granular infill or similar no-ground penetrating specification, or steel trackway of the appropriate rating. Alternatively, the span of the affected RPAs could be bridged to avoid any contact with the ground below.

3.5.3 ***Utilities and services***

Full information on the location of ancillary utility and service runs for the Proposed Development was not available at time of writing. In principle, any traditional trench-installed utilities that may be required to facilitate construction (e.g., temporary electricity, water or sewage supply) should be routed outside of the RPAs of retained trees, woodlands and hedges to avoid root damage, and should utilise existing hedge gaps to route ancillary services that may be required during construction into the Solar Development Sites. Where routing utility runs within RPAs is unavoidable, all work should comply with the measures set out in paragraph 3.4.4 or the National Joint Utilities Volume 4, and advice should be sought from the project Arboricultural Consultant before commencement.

3.6 Tree protection and management during the operation phase (including maintenance)

3.6.1 Planned tree maintenance work is likely to be required during the operational phase of the Proposed Development. This is likely to include:

1. Removal of trees succumbing to ash dieback or other disease;
2. Removal or pruning of trees experiencing partial or total structural failure due to storm damage, where that failure threatens to damage infrastructure;
3. Hedge trimming and maintenance.

3.6.2 Trees and hedges requiring maintenance will be accessed via the proposed access tracks or existing farm tracks; temporary removal of the security fencing to access boundary trees and hedges may be required, but the fencing will be re-erected immediately after works are completed.

3.6.3 Trees will be adequately protected during any maintenance of the solar farm infrastructure by the permanent security fencing, as all of the infrastructure will be sited within the fenced panel areas outside of the canopies and RPAs of retained trees. No access is likely to be required to the Cable Route Corridor once the cable has been installed.

4 Arboricultural compensation and enhancement

4.1.1 Extensive planting of native woodland blocks, native woodland belts and hedges with and without individual trees planted within them will be carried out across all seven Solar Development Sites as compensation for trees and hedges lost to the Proposed Development, and to enhance canopy cover and hedge provision across the Solar Development Sites. Opportunities will also be taken to reinforce existing hedges by gapping up, increasing widths and hedge tree planting. Indicative locations of these enhancements are shown on the Outline Environmental Masterplan **[EN0110012/APP/LVS/02.12].** Trees and hedges lost to the cable installation will be replanted wherever possible in the Cable Route Corridor subject to further detailed design works, as set out in the detailed CEMP.

5 References

Ref 1. British Standards Institution, “BS5837: 2012 Trees in Relation to Design, Demolition and Construction – Recommendations,” 2012.

Ref 2. UK Government, “Overarching National Policy Statement for Energy (EN-1),” 2025, [Online]. Available at: https://www.gov.uk/government/publications/overarching-national-policy-statement-for-energy-en-1-2025

Ref 3. Natural England and Forestry Commission. “Ancient woodland, ancient trees and veteran trees: advice for making planning decisions,” 2022. [Online]. Available at: https://www.gov.uk/guidance/ancient-woodland-ancient-trees-and-veteran-trees-advice-for-making-planning-decisions

Annex A - Tree Schedule

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1	1	*Cerasus avium* Wild Cherry	11.0	1	32	N 6.0 E 5.0 S 5.0 W 5.0	1.0	1.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	46.3	3.8	20-40	B	2
T2	1	*Cerasus avium* Wild Cherry	10.0	1	31	N 5.0 E 5.0 S 5.0 W 5.0	1.5	1.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	43.5	3.7	20-40	B	2
T3	1	*Cerasus avium* Wild Cherry	10.0	1	28	N 5.0 E 5.0 S 5.0 W 5.0	1.5	1.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	35.5	3.4	20-40	B	2
T4	1	*Cerasus avium* Wild Cherry	10.0	1	23	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	23.9	2.8	20-40	B	2
T5	1	*Crataegus monogyna* Common Hawthorn/Quick/May	10.0	7	39	N 3.5 E 3.5 S 3.5 W 3.5	2.0	2.0	Mature	Good		71.3	4.8	20-40	B	1
T6	1	*Cerasus avium* Wild Cherry	9.0	1	21	N 4.0 E 5.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	Decay / structural defect - Localised. Decay / structural defect - Principal stems. Forms part of a linear group, along the edge of the farm driveway.	20.0	2.5	20-40	C	2
T7	1	*Cerasus avium* Wild Cherry	10.0	1	29	N 4.0 E 5.0 S 4.0 W 4.0	2.5	2.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	38.0	3.5	20-40	B	2
T8	1	*Cerasus avium* Wild Cherry	11.0	1	42	N 5.0 E 5.0 S 5.0 W 5.0	1.5	1.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	79.8	5.0	20-40	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T9	1	*Cerasus avium* Wild Cherry	10.0	1	30	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	40.7	3.6	20-40	B	2
T10	1	*Cerasus avium* Wild Cherry	10.0	1	12	N 3.0 E 3.0 S 3.0 W 3.0	1.0	1.0	Early Mature	Fair	Epicormic growth - Base. Forms part of a linear group, along the edge of the farm driveway. 3m epicormic shoots at base.	6.5	1.4	20-40	C	2
T11	1	*Cerasus avium* Wild Cherry	10.0	1	30	N 4.0 E 4.0 S 4.0 W 4.0	1.5	1.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	40.7	3.6	20-40	B	2
T12	1	*Cerasus avium* Wild Cherry	10.0	1	23	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	23.9	2.8	20-40	B	2
T13	1	*Cerasus avium* Wild Cherry	11.0	1	25	N 3.0 E 3.0 S 3.0 W 3.0	3.0	3.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	28.3	3.0	20-40	B	2
T14	1	*Cerasus avium* Wild Cherry	10.0	1	25	N 4.0 E 4.0 S 4.0 W 4.0	1.5	1.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	28.3	3.0	20-40	B	2
T15	1	*Cerasus avium* Wild Cherry	9.0	1	23	N 4.0 E 4.0 S 4.0 W 4.0	2.5	2.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	23.9	2.8	20-40	B	2
T16	1	*Cerasus avium* Wild Cherry	10.0	1	26	N 4.0 E 4.0 S 4.0 W 4.0	2.5	2.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	30.6	3.1	20-40	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T17	1	*Cerasus avium* Wild Cherry	10.0	1	30	N 5.0 E 5.0 S 5.0 W 5.0	1.5	1.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	40.7	3.6	20-40	B	2
T18	1	*Cerasus avium* Wild Cherry	10.0	1	29	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Fair	Forms part of a linear group, along the edge of the farm driveway.	38.0	3.5	20-40	B	2
T19	1	*Cerasus avium* Wild Cherry	10.0	1	39	N 6.0 E 6.0 S 6.0 W 6.0	1.5	1.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	68.8	4.7	20-40	B	2
T20	1	*Cerasus avium* Wild Cherry	9.0	1	13	N 2.0 E 2.0 S 2.0 W 2.0	1.5	1.5	Early Mature	Good	Epicormic growth - Base. No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	7.6	1.6	20-40	C	2
T21	1	*Cerasus avium* Wild Cherry	9.5	1	26	N 6.0 E 4.0 S 4.0 W 4.0	1.5	1.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	30.6	3.1	20-40	B	2
T22	1	*Cerasus avium* Wild Cherry	9.5	1	33	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	49.3	4.0	20-40	B	2
T23	1	*Cerasus avium* Wild Cherry	10.0	1	19	N 3.0 E 3.0 S 3.0 W 3.0	2.0	2.0	Early Mature	Poor	Forms part of a linear group, along the edge of the farm driveway.	16.3	2.3	10-20	C	2
T24	1	*Cerasus avium* Wild Cherry	10.0	1	37	N 6.0 E 6.0 S 6.0 W 4.0	1.5	1.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	61.9	4.4	20-40	B	2
T25	1	*Cerasus avium* Wild Cherry	11.0	1	32	N 2.0 E 2.0 S 2.0 W 2.0	3.0	3.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	46.3	3.8	20-40	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T26	1	*Cerasus avium* Wild Cherry	11.0	1	41	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	76.0	4.9	20-40	B	2
T27	1	*Cerasus avium* Wild Cherry	10.0	1	30	N 5.0 E 5.0 S 5.0 W 3.0	3.0	3.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	40.7	3.6	20-40	B	2
T28	1	*Cerasus avium* Wild Cherry	9.0	1	24	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	26.1	2.9	20-40	B	2
T29	1	*Cerasus avium* Wild Cherry	9.0	1	16	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	11.6	1.9	20-40	B	2
T30	1	*Cerasus avium* Wild Cherry	9.0	2	26	N 4.0 E 5.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	31.2	3.1	20-40	B	2
T31	1	*Cerasus avium* Wild Cherry	9.0	1	25	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	28.3	3.0	20-40	B	2
T32	1	*Cerasus avium* Wild Cherry	9.0	2	23	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Fair	Forms part of a linear group, along the edge of the farm driveway.	25.2	2.8	20-40	B	2
T33	1	*Cerasus avium* Wild Cherry	10.0	1	35	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	55.4	4.2	20-40	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T34	1	*Cerasus avium* Wild Cherry	9.5	1	24	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	26.1	2.9	20-40	B	2
T35	1	*Cerasus avium* Wild Cherry	10.0	1	39	N 4.5 E 4.5 S 4.5 W 4.5	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	68.8	4.7	20-40	B	2
T36	1	*Cerasus avium* Wild Cherry	8.0	1	21	N 3.0 E 3.0 S 3.0 W 3.0	2.0	2.0	Early Mature	Fair	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	20.0	2.5	20-40	C	2
T37	1	*Cerasus avium* Wild Cherry	10.0	1	28	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	35.5	3.4	20-40	B	2
T38	1	*Cerasus avium* Wild Cherry	10.0	1	36	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	58.6	4.3	20-40	B	2
T39	1	*Cerasus avium* Wild Cherry	9.5	1	24	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	26.1	2.9	20-40	B	2
T40	1	*Cerasus avium* Wild Cherry	10.0	1	33	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	49.3	4.0	20-40	B	2
T41	1	*Cerasus avium* Wild Cherry	10.0	1	23	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	23.9	2.8	20-40	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T42	1	*Cerasus avium* Wild Cherry	10.0	1	44	N 5.0 E 5.0 S 5.0 W 5.0	2.5	2.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	87.6	5.3	20-40	B	2
T43	1	*Cerasus avium* Wild Cherry	10.0	1	34	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	52.3	4.1	20-40	B	2
T44	1	*Cerasus avium* Wild Cherry	10.0	1	29	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	38.0	3.5	20-40	B	2
T45	1	*Cerasus avium* Wild Cherry	10.0	1	44	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	87.6	5.3	20-40	B	2
T46	1	*Cerasus avium* Wild Cherry	10.0	1	21	N 3.5 E 3.5 S 3.5 W 3.5	3.0	3.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	20.0	2.5	20-40	C	2
T47	1	*Cerasus avium* Wild Cherry	10.0	1	37	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	61.9	4.4	20-40	B	2
T48	1	*Cerasus avium* Wild Cherry	9.0	1	16	N 2.0 E 2.0 S 2.0 W 2.0	1.6	1.6	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	11.6	1.9	20-40	C	2
T49	1	*Cerasus avium* Wild Cherry	10.0	1	33	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	49.3	4.0	20-40	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T50	1	*Cerasus avium* Wild Cherry	8.0	1	21	N 2.5 E 2.5 S 2.5 W 2.5	3.0	3.0	Early Mature	Fair	Forms part of a linear group, along the edge of the farm driveway.	20.0	2.5	20-40	C	2
T51	1	*Cerasus avium* Wild Cherry	9.5	1	37	N 4.0 E 4.0 S 4.0 W 4.0	1.5	1.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	61.9	4.4	20-40	B	2
T52	1	*Cerasus avium* Wild Cherry	6.0	1	5	N 1.0 E 1.0 S 1.0 W 1.0	2.5	2.5	Early Mature	Fair	Forms part of a linear group, along the edge of the farm driveway.	1.1	0.6	20-40	C	2
T53	1	*Cerasus avium* Wild Cherry	9.0	1	15	N 3.0 E 3.0 S 3.0 W 3.0	2.0	2.0	Early Mature	Fair	Forms part of a linear group, along the edge of the farm driveway.	10.2	1.8	20-40	C	2
T54	1	*Cerasus avium* Wild Cherry	9.5	3	28	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	36.1	3.4	20-40	B	2
T55	1	*Cerasus avium* Wild Cherry	9.0	1	24	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	26.1	2.9	20-40	B	2
T56	1	*Cerasus avium* Wild Cherry	9.0	1	45	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	91.6	5.4	20-40	B	2
T57	1	*Cerasus avium* Wild Cherry	10.0	1	24	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	26.1	2.9	20-40	B	2
T58	1	*Cerasus avium* Wild Cherry	10.0	1	30	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	40.7	3.6	20-40	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T59	1	*Cerasus avium* Wild Cherry	11.0	1	33	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	49.3	4.0	20-40	B	2
T60	1	*Cerasus avium* Wild Cherry	11.0	1	37	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	61.9	4.4	20-40	B	2
T61	1	*Cerasus avium* Wild Cherry	9.0	1	21	N 2.5 E 2.5 S 2.5 W 2.5	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	20.0	2.5	20-40	C	2
T62	1	*Cerasus avium* Wild Cherry	10.0	1	37	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	61.9	4.4	20-40	B	2
T63	1	*Cerasus avium* Wild Cherry	10.0	2	24	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	Stems - Co-dominant. Forms part of a linear group, along the edge of the farm driveway.	27.7	3.0	20-40	C	2
T64	1	*Cerasus avium* Wild Cherry	9.5	1	18	N 3.0 E 3.0 S 3.0 W 3.0	2.0	2.0	Early Mature	Fair	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	14.7	2.2	20-40	C	2
T65	1	*Cerasus avium* Wild Cherry	10.0	1	24	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	26.1	2.9	20-40	B	2
T66	1	*Cerasus avium* Wild Cherry	11.0	1	33	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	49.3	4.0	20-40	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T67	1	*Cerasus avium* Wild Cherry	10.0	1	24	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	26.1	2.9	20-40	B	2
T68	1	*Cerasus avium* Wild Cherry	10.0	1	25	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	28.3	3.0	20-40	B	2
T69	1	*Cerasus avium* Wild Cherry	11.0	1	32	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	46.3	3.8	20-40	B	2
T70	1	*Cerasus avium* Wild Cherry	11.0	1	34	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	52.3	4.1	20-40	B	2
T71	1	*Cerasus avium* Wild Cherry	10.0	1	31	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	43.5	3.7	20-40	B	2
T72	1	*Cerasus avium* Wild Cherry	10.0	1	24	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	26.1	2.9	20-40	B	2
T73	1	*Cerasus avium* Wild Cherry	10.0	1	24	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	26.1	2.9	20-40	B	2
T74	1	*Cerasus avium* Wild Cherry	9.0	1	28	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	35.5	3.4	20-40	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T75	1	*Cerasus avium* Wild Cherry	9.0	2	23	N 4.0 E 4.0 S 4.0 W 4.0	1.5	1.5	Early Mature	Good	Stems - Co-dominant. Forms part of a linear group, along the edge of the farm driveway.	24.8	2.8	20-40	B	2
T76	1	*Cerasus avium* Wild Cherry	10.0	1	33	N 3.0 E 3.0 S 3.0 W 3.0	1.5	1.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	49.3	4.0	20-40	B	2
T77	1	*Cerasus avium* Wild Cherry	10.0	1	29	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	38.0	3.5	20-40	B	2
T78	1	*Cerasus avium* Wild Cherry	10.0	1	32	N 4.5 E 4.5 S 4.5 W 4.5	2.5	2.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	46.3	3.8	20-40	B	2
T79	1	*Cerasus avium* Wild Cherry	6.0	1	12	N 3.0 E 3.0 S 3.0 W 3.0	2.5	2.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	6.5	1.4	20-40	C	2
T80	1	*Cerasus avium* Wild Cherry	10.0	1	30	N 3.0 E 3.0 S 3.0 W 3.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	40.7	3.6	20-40	B	2
T81	1	*Cerasus avium* Wild Cherry	10.0	1	32	N 4.0 E 4.0 S 4.0 W 4.0	1.5	1.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	46.3	3.8	20-40	B	2
T82	1	*Cerasus avium* Wild Cherry	10.0	1	38	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	65.3	4.6	20-40	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T83	1	*Cerasus avium* Wild Cherry	10.0	1	35	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	55.4	4.2	20-40	B	2
T84	1	*Cerasus avium* Wild Cherry	9.5	1	38	N 4.0 E 4.0 S 4.0 W 4.0	1.5	1.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	65.3	4.6	20-40	B	2
T85	1	*Cerasus avium* Wild Cherry	9.5	1	18	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	14.7	2.2	20-40	C	2
T86	1	*Cerasus avium* Wild Cherry	10.0	1	36	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	58.6	4.3	20-40	B	2
T87	1	*Cerasus avium* Wild Cherry	10.0	1	29	N 4.0 E 4.0 S 4.0 W 4.0	1.5	1.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	38.0	3.5	20-40	B	2
T88	1	*Cerasus avium* Wild Cherry	11.0	1	38	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	65.3	4.6	20-40	B	2
T89	1	*Cerasus avium* Wild Cherry	10.0	1	31	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	43.5	3.7	20-40	B	2
T90	1	*Cerasus avium* Wild Cherry	9.5	1	27	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	33.0	3.2	20-40	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T91	1	*Cerasus avium* Wild Cherry	9.0	1	33	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	49.3	4.0	20-40	B	2
T92	1	*Cerasus avium* Wild Cherry	10.0	1	31	N 5.0 E 5.0 S 5.0 W 5.0	1.5	1.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	43.5	3.7	20-40	B	2
T93	1	*Cerasus avium* Wild Cherry	5.0	1	13	N 1.5 E 1.5 S 1.5 W 1.5	1.5	1.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	7.6	1.6	20-40	C	2
T94	1	*Cerasus avium* Wild Cherry	10.0	1	36	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	58.6	4.3	20-40	B	2
T95	1	*Cerasus avium* Wild Cherry	10.0	1	23	N 5.0 E 4.0 S 3.0 W 5.0	2.0	2.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	23.9	2.8	20-40	B	2
T96	1	*Cerasus avium* Wild Cherry	10.0	1	40	N 5.0 E 5.0 S 5.0 W 5.0	1.0	1.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	72.4	4.8	20-40	B	2
T97	1	*Cerasus avium* Wild Cherry	5.0	1	16	N 3.0 E 3.0 S 3.0 W 3.0	1.5	1.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	11.6	1.9	20-40	C	2
T98	1	*Cerasus avium* Wild Cherry	9.5	3	52	N 4.0 E 4.0 S 4.0 W 4.0	1.0	1.0	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	126.1	6.3	20-40	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T99	1	*Cerasus avium* Wild Cherry	10.0	1	23	N E S W 4.0 4.0 4.0 4.0	1.5	1.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	23.9	2.8	20-40	B	2
T100	1	*Cerasus avium* Wild Cherry	10.0	1	29	N E S W 4.0 4.0 4.0 4.0	1.5	1.5	Early Mature	Good	No significant faults observed. Forms part of a linear group, along the edge of the farm driveway.	38.0	3.5	20-40	B	2
T101	1	*Acer pseudoplatanus* Sycamore	10.0	1	37	N E S W 5.0 5.0 5.0 5.0	3.0	3.0	Early Mature	Good	No significant faults observed. Hedgerow tree. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	61.9	4.4	40+	B	1
T102	1	*Acer pseudoplatanus* Sycamore	10.0	1	36	N E S W 5.0 5.0 5.0 5.0	3.0	3.0	Early Mature	Good	No significant faults observed. Hedgerow tree. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	58.6	4.3	40+	B	1
T103	1	*Acer pseudoplatanus* Sycamore	10.0	1	30	N E S W 4.5 4.5 4.5 4.5	3.0	3.0	Early Mature	Good	No significant faults observed. Hedgerow tree. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	40.7	3.6	40+	B	1
T104	1	*Acer pseudoplatanus* Sycamore	10.0	1	34	N E S W 3.5 3.5 3.5 3.5	3.0	3.0	Early Mature	Good	No significant faults observed. Hedgerow tree. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	52.3	4.1	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T105	1	*Acer pseudoplatanus* Sycamore	10.0	1	43	N 4.5 E 4.5 S 4.5 W 4.5	3.5	3.5	Early Mature	Good	No significant faults observed. Hedgerow tree. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	83.6	5.2	40+	B	1
T106	1	*Acer pseudoplatanus* Sycamore	9.0	1	29	N 4.5 E 4.5 S 4.5 W 4.5	4.5	4.5	Early Mature	Good	No significant faults observed. Hedgerow tree. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	38.0	3.5	40+	B	1
T107	1	*Acer pseudoplatanus* Sycamore	10.0	1	30	N 4.5 E 4.5 S 4.5 W 4.5	4.5	4.5	Early Mature	Good	No significant faults observed. Hedgerow tree. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	40.7	3.6	40+	B	1
T108	1	*Acer pseudoplatanus* Sycamore	12.0	1	34	N 5.0 E 5.0 S 5.0 W 5.0	4.0	4.0	Early Mature	Good	No significant faults observed. Hedgerow tree. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	52.3	4.1	40+	B	1
T109	1	*Acer pseudoplatanus* Sycamore	12.0	1	25	N 4.0 E 4.0 S 4.0 W 4.0	4.0	4.0	Early Mature	Fair	Hedgerow tree. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	28.3	3.0	20-40	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T110	1	*Acer pseudoplatanus* Sycamore	11.0	1	26	N 5.0 E 5.0 S 5.0 W 5.0	4.0	4.0	Early Mature	Good	No significant faults observed. Hedgerow tree. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	30.6	3.1	40+	B	1
H111	200 50 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Sambucus sp.* Elder sp.	3.0	1	5	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge. 06/10/25 Hedge has been felled and chipped. Some plants have sprouted back.	1.1	0.6	40+	B	2
H112	100	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	5	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge.	1.1	0.6	40+	B	2
T113	1	*Acer pseudoplatanus* Sycamore	12.0	1	32	N 4.5 E 4.5 S 4.5 W 4.5	4.0	4.0	Early Mature	Good	No significant faults observed. Hedgerow tree.	46.3	3.8	40+	B	1
T114	1	*Acer pseudoplatanus* Sycamore	13.0	1	33	N 5.0 E 5.0 S 5.0 W 5.0	4.5	4.5	Early Mature	Good	No significant faults observed. Hedgerow tree.	49.3	4.0	40+	B	1
T115	1	*Acer pseudoplatanus* Sycamore	13.0	3	51	N 5.0 E 5.0 S 5.0 W 5.0	4.5	4.5	Early Mature	Good	Access to inspect base - Not possible. No significant faults observed. Pruning wounds - Recent. Hedgerow tree. DBH estimated.	122.1	6.2	40+	B	1
T116	1	*Acer pseudoplatanus* Sycamore	11.0	2	42	N 4.0 E 4.0 S 4.0 W 4.0	4.0	4.0	Early Mature	Good	Access to inspect base - Not possible. No significant faults observed. Hedgerow tree. DBH estimated.	81.4	5.1	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T117	1	*Acer pseudoplatanus* Sycamore	10.0	2	39	N 4.0 E 4.0 S 4.0 W 4.0	4.0	4.0	Early Mature	Good	Access to inspect base - Not possible. No significant faults observed. Hedgerow tree. DBH estimated.	69.0	4.7	40+	B	1
T118	1	*Acer pseudoplatanus* Sycamore	9.0	1	41	N 4.0 E 4.0 S 4.0 W 4.0	4.0	4.0	Early Mature	Dead	Dead tree / trees. Tree in 1.5m gap in hedge.			0-10	U	
T119	1	*Acer pseudoplatanus* Sycamore	12.0	1	59	N 4.0 E 4.0 S 4.0 W 4.0	4.0	4.0	Early Mature	Good	No significant faults observed. Pruning wounds - Suspected compartmentalised. Pruning wounds - Historic. Hedgerow tree. Tree in 1.5m in hedge.	157.5	7.1	40+	B	1
H120	60	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	5	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge.	1.1	0.6	40+	B	2
T121	1	*Acer pseudoplatanus* Sycamore	11.0	3	45	N 5.0 E 5.0 S 5.0 W 5.0	4.0	4.0	Early Mature	Good	No significant faults observed. Pruning wounds - Recent. Hedgerow tree. Tree in 2.5m gap in hedge.	91.8	5.4	20-40	B	1
H122	20	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	5	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge.	1.1	0.6	40+	B	2
T123	1	*Acer pseudoplatanus* Sycamore	11.0	3	44	N 5.0 E 5.0 S 5.0 W 5.0	4.0	4.0	Early Mature	Fair	Die-back - Upper crown. Pruning wounds - Recent. Hedgerow tree. Tree in 1m gap in hedge.	89.8	5.3	10-20	C	1
H124	20	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	5	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge.	1.1	0.6	40+	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T125	1	*Acer pseudoplatanus* Sycamore	11.0	1	32	N 4.0 E 4.0 S 4.0 W 4.0	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed. Pruning wounds - Recent. Hedgerow tree.	46.3	3.8	40+	B	1
T126	1	*Acer pseudoplatanus* Sycamore	10.0	1	33	N 4.0 E 4.0 S 4.0 W 4.0	4.0	4.0	Early Mature	Fair	Access to inspect base - Restricted / obscured. Epicormic growth - Base. Pruning wounds - Recent. Hedgerow tree.	49.3	4.0	20-40	C	1
T127	1	*Acer pseudoplatanus* Sycamore	11.0	1	53	N 5.0 E 5.0 S 5.0 W 5.0	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Pruning wounds - Recent. Hedgerow tree.	127.1	6.4	40+	B	1
T128	1	*Acer pseudoplatanus* Sycamore	13.0	1	36	N 4.0 E 4.0 S 4.0 W 4.0	4.0	4.0	Early Mature	Good	Access to inspect base - Not possible. Pruning wounds - Recent. Hedgerow tree.	58.6	4.3	40+	B	1
T129	1	*Acer pseudoplatanus* Sycamore	10.0	2	32	N 2.0 E 2.0 S 2.0 W 2.0	4.0	4.0	Early Mature	Dead	Dead tree / trees. Hedgerow tree.			0-10	U	
T130	1	*Acer pseudoplatanus* Sycamore	7.0	1	21	N 2.0 E 2.0 S 2.0 W 2.0	3.0	3.0	Early Mature	Dead	Dead tree / trees. Hedgerow tree.			0-10	U	
T131	1	*Acer pseudoplatanus* Sycamore	9.0	2	24	N 4.0 E 4.0 S 4.0 W 4.0	4.0	4.0	Early Mature	Fair	Access to inspect base - Not possible. Pruning wounds - Recent. Hedgerow tree. Tree in 1m gap in hedge.	27.9	3.0	10-20	C	1
H132	150 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Cornus sp.* Dogwood sp.	3.0	1	5	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge.	1.1	0.6	40+	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T133	1	*Acer pseudoplatanus* Sycamore	11.0	2	33	N 5.0 E 5.0 S 5.0 W 5.0	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed. Pruning wounds - Recent. Hedgerow tree.	50.0	4.0	20-40	B	1
T134	1	*Acer pseudoplatanus* Sycamore	10.5	1	33	N 5.0 E 5.0 S 5.0 W 5.0	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed. Pruning wounds - Recent. Hedgerow tree.	49.3	4.0	20-40	B	1
T135	1	*Acer pseudoplatanus* Sycamore	10.0	1	42	N 6.0 E 6.0 S 6.0 W 6.0	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed. Pruning wounds - Recent. Hedgerow tree.	79.8	5.0	20-40	B	1
T136	1	*Acer pseudoplatanus* Sycamore	10.0	1	35	N 5.0 E 5.0 S 5.0 W 5.0	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed. Pruning wounds - Recent. Hedgerow tree.	55.4	4.2	20-40	B	1
T137	1	*Acer pseudoplatanus* Sycamore	12.0	1	38	N 4.5 E 4.5 S 4.5 W 4.5	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed. Hedgerow tree.	65.3	4.6	20-40	B	1
T138	1	*Acer pseudoplatanus* Sycamore	13.0	1	28	N 5.0 E 5.0 S 5.0 W 5.0	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed. Hedgerow tree.	35.5	3.4	20-40	B	1
T139	1	*Acer pseudoplatanus* Sycamore	13.0	1	36	N 5.0 E 5.0 S 5.0 W 5.0	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed. Hedgerow tree.	58.6	4.3	20-40	B	1
T140	1	*Acer pseudoplatanus* Sycamore	11.0	1	36	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Fair	Access to inspect base - Restricted / obscured. Decline - Suspected. Hedgerow tree.			0-10	U	

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T141	1	*Acer pseudoplatanus* Sycamore	12.0	1	38	N 6.0 E 6.0 S 6.0 W 6.0	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed. Hedgerow tree.	65.3	4.6	20-40	B	1
T142	1	*Acer pseudoplatanus* Sycamore	12.0	1	34	N 4.5 E 4.5 S 4.5 W 4.5	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed. Hedgerow tree.	52.3	4.1	20-40	B	1
T143	1	*Acer pseudoplatanus* Sycamore	12.0	1	32	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed. Hedgerow tree.	46.3	3.8	20-40	B	1
T144	1	*Acer pseudoplatanus* Sycamore	14.0	1	31	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed. Hedgerow tree.	43.5	3.7	20-40	B	1
T145	1	*Acer pseudoplatanus* Sycamore	11.0	1	28	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed. Hedgerow tree.	35.5	3.4	20-40	B	1
T146	1	*Acer pseudoplatanus* Sycamore	11.0	1	27	N 5.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Fair	Access to inspect base - Restricted / obscured. Decline - Suspected. Hedgerow tree.			0-10	U	
T147	1	*Acer pseudoplatanus* Sycamore	11.0	1	30	N 4.0 E 4.0 S 4.0 W 4.0	4.0	4.0	Early Mature	Fair	Access to inspect base - Restricted / obscured. No significant faults observed. Hedgerow tree.	40.7	3.6	0-10	B	1
H148	400	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	5	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge. **Fell - Ground level.** Remove a 3-m span. To facilitate development.	1.1	0.6	40+	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T149	1	*Quercus robur* English Oak	11.0	1	22	N 5.0 E 5.0 S 5.0 W 5.0	3.5	3.5	Early Mature	Good	No significant faults observed. Pruning wounds - Historic. End of hedgerow. **Fell - Ground level.** To facilitate development.	21.9	2.6	40+	B	1
T150	1	*Quercus robur* English Oak	10.0	1	24	N 5.0 E 5.0 S 5.0 W 5.0	3.5	3.5	Early Mature	Good	No significant faults observed. Pruning wounds - Historic. Hedgerow tree.	26.1	2.9	40+	B	1
T151	1	*Quercus robur* English Oak	11.0	1	30	N 6.0 E 6.0 S 6.0 W 6.0	5.0	5.0	Early Mature	Good	No significant faults observed. Pruning wounds - Historic. Hedgerow tree.	40.7	3.6	40+	B	1
T152	1	*Quercus robur* English Oak	11.0	1	27	N 5.0 E 5.0 S 5.0 W 5.0	5.0	5.0	Early Mature	Good	No significant faults observed. Pruning wounds - Historic. Hedgerow tree.	33.0	3.2	40+	B	1
T153	1	*Quercus robur* English Oak	12.0	1	31	N 6.0 E 6.0 S 6.0 W 6.0	3.0	3.0	Early Mature	Good	Ivy or climbing plant. No significant faults observed. Pruning wounds - Historic. Hedgerow tree.	43.5	3.7	40+	B	1
T154	1	*Quercus robur* English Oak	9.0	1	18	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Good	Ivy or climbing plant. No significant faults observed. Hedgerow tree.	14.7	2.2	40+	B	1
T155	1	*Quercus robur* English Oak	10.0	1	20	N 4.5 E 4.5 S 4.5 W 4.5	3.0	3.0	Early Mature	Good	Ivy or climbing plant. No significant faults observed. Pruning wounds - Historic. Hedgerow tree.	18.1	2.4	40+	B	1
T156	1	*Quercus robur* English Oak	13.0	1	82	N 7.0 E 7.0 S 7.0 W 7.0	2.5	2.5	Mature	Good	Deadwood - Major. Habitat - High value. Ivy or climbing plant. Pruning wounds - Historic. Hedgerow tree.	304.2	9.8	40+	B	1
T157	1	*Quercus robur* English Oak	10.0	1	18	N 3.0 E 3.0 S 3.0 W 3.0	3.0	3.0	Semi Mature	Good	Ivy or climbing plant. No significant faults observed. Hedgerow tree.	14.7	2.2	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T158	1	*Quercus robur* English Oak	11.0	1	21	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Good	No significant faults observed. Pruning wounds - Historic. Hedgerow tree.	20.0	2.5	40+	B	1
T159	1	*Quercus robur* English Oak	16.0	1	92	N 7.0 E 9.0 S 7.0 W 7.0	2.5	2.5	Ancient or Veteran	Good	Branch - Broken. Deadwood - Major. Habitat - High value. Hollow trunk - Open cavity. Ivy or climbing plant. Pruning wounds - Historic. Hedgerow tree (veteran).	382.9	11.0	40+	A	1 3
T160	1	*Quercus robur* English Oak	11.0	1	17	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Good	No significant faults observed. Pruning wounds - Historic. Hedgerow tree.	13.1	2.0	40+	B	1
T161	1	*Quercus robur* English Oak	11.0	1	38	N 5.5 E 5.5 S 5.5 W 5.5	3.0	3.0	Early Mature	Good	No significant faults observed. Hedgerow tree.	65.3	4.6	40+	B	1
T162	1	*Quercus robur* English Oak	11.0	1	28	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Good	No significant faults observed. Hedgerow tree.	35.5	3.4	40+	B	1
T163	1	*Quercus robur* English Oak	11.0	1	29	N 5.0 E 5.0 S 5.0 W 5.0	2.5	2.5	Early Mature	Good	No significant faults observed. Hedgerow tree.	38.0	3.5	40+	B	1
T164	1	*Quercus robur* English Oak	11.0	1	25	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed. Hedgerow tree.	28.3	3.0	40+	B	1
T165	1	*Quercus robur* English Oak	11.0	1	27	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Good	No significant faults observed. Hedgerow tree.	33.0	3.2	40+	B	1
T166	1	*Quercus robur* English Oak	8.0	1	15	N 2.0 E 2.0 S 2.0 W 2.0	3.0	3.0	Early Mature	Good	No significant faults observed. Hedgerow tree.	10.2	1.8	40+	B	1
T167	1	*Quercus robur* English Oak	10.0	1	35	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Good	No significant faults observed. Hedgerow tree.	55.4	4.2	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T168	1	*Quercus robur* English Oak	11.0	1	21	N E S W 4.0 4.0 4.0 4.0	3.0	3.0	Early Mature	Good	No significant faults observed. Hedgerow tree.	20.0	2.5	40+	B	1
T169	1	*Quercus robur* English Oak	11.0	1	29	N E S W 5.0 5.0 5.0 5.0	4.0	4.0	Early Mature	Good	No significant faults observed. Hedgerow tree.	38.0	3.5	40+	B	1
H170	100 80 50 40	*Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple *other* Other *Acer pseudoplatanus* Sycamore	3.0	1	5	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. Staked tree / trees. Field boundary hedge.	1.1	0.6	40+	B	2
H171	20	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	5	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Boundary hedge, bounding early mature off site woodland copse.	1.1	0.6	40+	B	2
T172	1	*Quercus robur* English Oak	7.0	1	17	N E S W 2.0 2.0 2.0 2.0	2.0	2.0	Early Mature	Good	Bark wound - Physical damage or vandalism. Retention category downgraded due to size. Adjacent field opening/gap.	13.1	2.0	10-20	C	1
T173	1	*Quercus robur* English Oak	5.5	1	90	N E S W 0.0 0.0 0.0 0.0	0.0	0.0	Mature	Dead	Habitat - High value. High decaying Oak stump with niche habitat opportunity. RPA not applicable therefore U category.			10-20	U	
T174	1	*Quercus robur* English Oak	5.0	1	17	N E S W 5.0 5.0 5.0 5.0	0.5	0.5	Early Mature	Good	No significant faults observed. Pruning wounds - Historic.	13.1	2.0	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T175	1	*Quercus robur* English Oak	7.0	2	33	N 4.0 E 5.0 S 5.0 W 2.0	2.5	2.5	Early Mature	Good	No significant faults observed. Pruning wounds - Historic.	50.5	4.0	40+	C	1
T176	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	20	N 2.0 E 2.0 S 2.0 W 2.0	0.5	0.5	Early Mature	Good	No significant faults observed.	18.1	2.4	40+	B	1
T177	1	*Quercus robur* English Oak	12.0	1	45	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Good	Pruning wounds - Recent.	91.6	5.4	40+	B	1
T178	1	*Quercus robur* English Oak	12.0	1	38	N 5.0 E 5.0 S 5.0 W 3.0	3.0	3.0	Early Mature	Good	Pruning wounds - Recent.	65.3	4.6	40+	B	1
T179	1	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	1	8	N 2.0 E 2.0 S 2.0 W 2.0	0.5	0.5	Early Mature	Good	No significant faults observed.	2.9	1.0	40+	C	1
T180	1	*Quercus robur* English Oak	10.0	1	37	N 4.0 E 4.0 S 5.0 W 4.0	2.5	2.5	Early Mature	Good	Epicormic growth - Crown. Pruning wounds - Historic.	61.9	4.4	40+	B	1
T181	1	*Quercus robur* English Oak	10.0	1	43	N 5.0 E 5.0 S 5.0 W 4.0	3.0	3.0	Early Mature	Good	Epicormic growth - Crown. Pruning wounds - Historic.	83.6	5.2	40+	B	1
H182	12	*Prunus spinosa* Blackthorn/Sloe	4.0	1	5	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Fair	Hedge remnant.	1.1	0.6	10-20	C	2
T183	1	*Quercus robur* English Oak	10.0	1	48	N 5.0 E 5.0 S 5.0 W 5.0	2.5	2.5	Early Mature	Good	Epicormic growth - Crown. Pruning wounds - Historic.	104.2	5.8	40+	B	1
T184	1	*Quercus robur* English Oak	7.0	1	33	N 5.0 E 5.0 S 5.0 W 5.0	2.5	2.5	Early Mature	Good	Epicormic growth - Crown.	49.3	4.0	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T185	1	*Quercus robur* English Oak	15.0	1	106	N 5.0 E 5.0 S 5.0 W 5.0	1.5	1.5	Mature	Good	Decay entry points. Decay / structural defect - Base. Decay / structural defect - Open cavity / cavities. Epicormic growth - Crown. Pruning wounds - Historic. Mature Oak, with High habitat value.	508.3	12.7	40+	A	1
T186	1	*Quercus robur* English Oak	7.0	1	20	N 3.0 E 3.0 S 3.0 W 3.0	1.5	1.5	Early Mature	Good	Branch - Broken.	18.1	2.4	10-20	C	1
T187	1	*Quercus robur* English Oak	7.0	1	26	N 1.5 E 4.0 S 4.0 W 4.0	1.5	1.5	Early Mature	Good	Competition - Adjacent trees. Deadwood - Minor.	30.6	3.1	10-20	C	1
T188	1	*Quercus robur* English Oak	15.0	1	135	N 7.0 E 7.0 S 7.0 W 7.0	1.5	1.5	Ancient or Veteran	Good	Decay entry points. Deadwood - Minor. Epicormic growth - Crown. Pollard - Regrown. Pruning wounds - Suspected compartmentalised. Pruning wounds - Historic. Mature Oak, with High habitat value. Major stem hollowing.	706.9	15.0	40+	A	1 3
H189	12	*Prunus spinosa* Blackthorn/Sloe	4.0	1	5	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Fair	Hedge remnant.	1.1	0.6	10-20	C	2
T190	1	*Quercus robur* English Oak	7.0	1	24	N 4.0 E 4.0 S 4.0 W 4.0	1.5	1.5	Early Mature	Good	Deadwood - Minor.	26.1	2.9	40+	C	1
T191	1	*Quercus robur* English Oak	9.5	1	45	N 6.0 E 6.0 S 6.0 W 6.0	1.5	1.5	Early Mature	Good	Deadwood - Minor.	91.6	5.4	40+	B	1
T192	1	*Quercus robur* English Oak	7.0	1	30	N 4.5 E 4.5 S 4.5 W 4.5	1.5	1.5	Early Mature	Good	Access to inspect base - Not possible. Deadwood - Minor.	40.7	3.6	40+	B	1
T193	1	*Quercus robur* English Oak	7.0	1	20	N 2.5 E 2.5 S 2.5 W 2.5	1.5	1.5	Early Mature	Good	Access to inspect base - Not possible.	18.1	2.4	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T194	1	*Quercus robur* English Oak	10.0	1	20	N 1.5 E 3.0 S 4.5 W 3.0	1.5	1.5	Early Mature	Good	Access to inspect base - Not possible. Branch - Broken.	18.1	2.4	40+	C	1
T195	1	*Fraxinus excelsior* Ash	9.0	1	55	N 4.5 E 4.5 S 4.5 W 4.5	1.5	1.5	Early Mature	Good	Decay / structural defect - Extensive. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Principal stems. Major decay and Ash die back suspected.	136.8	6.6	40+	C	1
H196	12	*Prunus spinosa* Blackthorn/Sloe	4.0	1	5	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Fair	Hedge remnant.	1.1	0.6	10-20	C	2
T197	1	*Quercus robur* English Oak	10.0	1	35	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	Access to inspect base - Not possible.	55.4	4.2	40+	B	1
T198	1	*Quercus robur* English Oak	9.5	1	23	N 3.5 E 3.5 S 3.5 W 3.5	1.0	1.0	Early Mature	Good	Access to inspect base - Not possible.	23.9	2.8	40+	B	1
H199	12	*Prunus spinosa* Blackthorn/Sloe	4.0	1	5	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Fair	Hedge remnant.	1.1	0.6	10-20	C	2
T200	1	*Quercus robur* English Oak	12.0	1	52	N 6.0 E 6.0 S 6.0 W 6.0	1.5	1.5	Early Mature	Good	Access to inspect base - Not possible. Epicormic growth - Crown.	122.3	6.2	40+	B	1
T201	1	*Quercus robur* English Oak	12.5	1	51	N 7.0 E 7.0 S 7.0 W 7.0	1.0	1.0	Early Mature	Good	Epicormic growth - Crown.	117.7	6.1	40+	B	1
T202	1	*Quercus robur* English Oak	6.5	1	24	NW 5.0 NE 4.0 SE 4.0 SW 4.0	1.5	1.5	Early Mature	Good	Competition - Adjacent trees.	26.1	2.9	40+	C	1
T203	1	*Quercus robur* English Oak	10.5	1	32	N 5.0 E 5.0 S 5.0 W 5.0	1.0	1.0	Early Mature	Good	Epicormic growth - Crown.	46.3	3.8	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T204	1	*Quercus robur* English Oak	7.5	1	32	N E S W 4.0 4.0 4.0 4.0	1.5	1.5	Early Mature	Good	Deadwood - Minor.	46.3	3.8	40+	B	1
T205	1	*Fraxinus excelsior* Ash	12.0	1	50	N E S W 5.0 5.0 5.0 5.0	2.0	2.0	Early Mature	Fair	Pollard - Regrown. Pollarded at hedge height and regrown. Split into 2.0	113.1	6.0	10-20	C	1
H206	225 10	*Crataegus monogyna* Common Hawthorn/Quick/May *other* Other	2.5	1	4	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge.	0.7	0.5	40+	B	2
H207	7 6	*Sambucus sp.* Elder sp. *Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	4	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Gappy section of field boundary hedge. **Fell - Ground level.** Remove a 4-m span. To facilitate development.	0.7	0.5	20-40	C	2
H208	8 7	*Sambucus sp.* Elder sp. *Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	4	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Gappy section of field boundary hedge.	0.7	0.5	20-40	C	2
H209	4 2 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Malus sp.* Apple sp. *Sambucus sp.* Elder sp.	2.5	1	4	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Gappy section of field boundary hedge.	0.7	0.5	20-40	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T210	1	*Quercus robur* English Oak	9.0	1	20	N E S W 4.0 4.0 4.0 4.0	2.5	2.5	Early Mature	Good	Branch - Broken.	18.1	2.4	40+	B	1
H211	10 8	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus sp.* Elder sp.	2.5	1	4	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Gappy section of field boundary hedge.	0.7	0.5	20-40	C	2
T212	1	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	1	25	N E S W 3.0 3.0 3.0 3.0	1.5	1.5	Early Mature	Good	Competition - Adjacent trees.	28.3	3.0	20-40	C	1
T213	1	*Quercus robur* English Oak	14.5	1	68	N E S W 6.0 6.0 6.0 6.0	2.0	2.0	Early Mature	Good	Deadwood - Major. Decay / structural defect - Localised. Pruning wounds - Historic.	209.2	8.2	40+	B	1
T214	1	*Quercus robur* English Oak	10.0	1	25	N E S W 5.0 5.0 5.0 5.0	2.5	2.5	Early Mature	Good	Branch - Broken.	28.3	3.0	40+	B	1
H215	10	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	4	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Section of field boundary hedge.	0.7	0.5	20-40	C	2
T216	1	*Quercus robur* English Oak	9.0	1	21	N E S W 4.0 4.0 4.0 4.0	1.6	1.6	Early Mature	Good	Epicormic growth - Crown.	20.0	2.5	40+	B	1
H217	12	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	9	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Section of field boundary hedge.	3.7	1.1	20-40	C	2
T218	1	*Quercus robur* English Oak	6.5	1	8	N E S W 1.5 1.5 1.5 1.5	3.0	3.0	Early Mature	Good	Access to inspect base - Not possible. Young established tree in hedgerow.	2.9	1.0	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T219	1	*Quercus robur* English Oak	6.0	1	10	N E S W 1.8 1.8 1.8 1.8	3.0	3.0	Early Mature	Good	Access to inspect base - Not possible. Young established tree in hedgerow.	4.5	1.2	40+	C	1
T220	1	*Quercus robur* English Oak	8.5	1	16	N E S W 4.0 4.0 4.0 4.0	3.0	3.0	Early Mature	Good	Access to inspect base - Not possible.	11.6	1.9	40+	C	1
H221	150 20 5	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash	2.5	1	10	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Section of field boundary hedge. **Fell - Ground level.** Remove a 2-m span. To facilitate development.	4.5	1.2	20-40	B	2
T222	1	*Quercus robur* English Oak	4.0	1	7	N E S W 1.0 1.0 1.0 1.0	2.0	2.0	Early Mature	Good	Access to inspect base - Not possible. Young tree in hedgerow.	2.2	0.8	40+	C	1
T223	1	*Quercus robur* English Oak	5.5	1	7	N E S W 1.0 1.0 1.0 1.0	3.0	3.0	Early Mature	Good	Access to inspect base - Not possible. Young tree in hedgerow.	2.2	0.8	40+	C	1
T224	1	*Quercus robur* English Oak	5.0	1	10	N E S W 1.0 1.0 1.0 1.0	2.0	2.0	Early Mature	Good	Access to inspect base - Not possible. Young tree in hedgerow.	4.5	1.2	40+	C	1
T225	1	*Acer pseudoplatanus* Sycamore	10.0	1	32	N E S W 4.0 4.0 4.0 4.0	4.0	4.0	Early Mature	Good	No significant faults observed.	46.3	3.8	40+	B	1
T226	1	*Acer pseudoplatanus* Sycamore	11.0	1	42	N E S W 4.0 4.0 4.0 4.0	4.0	4.0	Early Mature	Good	No significant faults observed.	79.8	5.0	40+	B	1
T227	1	*Acer pseudoplatanus* Sycamore	12.0	1	38	N E S W 4.0 4.0 4.0 4.0	4.0	4.0	Early Mature	Good	No significant faults observed.	65.3	4.6	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T228	1	*Quercus robur* English Oak	19.0	1	98	N 10.0 E 12.0 S 10.0 W 10.0	4.0	4.0	Mature	Good	Access to inspect base - Restricted / obscured. Deadwood - Minor. No significant faults observed.	434.5	11.8	40+	A	1
T229	1	*Acer pseudoplatanus* Sycamore	12.0	1	38	N 3.5 E 3.5 S 3.5 W 3.5	4.5	4.5	Early Mature	Good	Ivy or climbing plant. No significant faults observed.	65.3	4.6	40+	B	1
T230	1	*Acer pseudoplatanus* Sycamore	12.0	1	23	N 5.0 E 5.0 S 5.0 W 5.0	4.5	4.5	Early Mature	Good	No significant faults observed.	23.9	2.8	40+	C	1
T231	1	*Acer pseudoplatanus* Sycamore	18.0	1	21	N 4.5 E 4.5 S 4.5 W 4.5	4.0	4.0	Early Mature	Good	No significant faults observed.	20.0	2.5	40+	B	1
T232	1	*Acer pseudoplatanus* Sycamore	9.0	1	26	N 4.0 E 4.0 S 4.0 W 4.0	4.0	4.0	Early Mature	Good	No significant faults observed.	30.6	3.1	40+	B	1
T233	1	*Acer pseudoplatanus* Sycamore	9.5	1	27	N 4.5 E 4.5 S 4.5 W 4.5	4.5	4.5	Early Mature	Good	No significant faults observed.	33.0	3.2	40+	B	1
T234	1	*Quercus robur* English Oak	20.0	1	138	N 10.0 E 12.0 S 10.0 W 10.0	4.0	4.0	Mature	Good	Access to inspect base - Restricted / obscured. Bark wound - Mechanical. Deadwood - Minor. No significant faults observed.	706.9	15.0	40+	A	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H235	20 10 5 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Fraxinus excelsior* Ash *Ilex aquifolium* Holly	2.5	1	10	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge.	4.5	1.2	20-40	B	2
T236	1	*Acer pseudoplatanus* Sycamore	7.0	1	16	N 3.5 E 3.5 S 3.5 W 3.5	3.0	3.0	Semi Mature	Good	Access to inspect base - Not possible. Young established tree in hedgerow.	11.6	1.9	40+	C	1
T237	1	*Acer pseudoplatanus* Sycamore	8.0	1	15	N 4.0 E 3.5 S 3.5 W 3.5	3.0	3.0	Semi Mature	Good	Access to inspect base - Not possible. Young established tree in hedgerow.	10.2	1.8	40+	C	1
T238	1	*Acer pseudoplatanus* Sycamore	8.0	1	15	N 4.0 E 3.5 S 3.5 W 3.5	3.0	3.0	Semi Mature	Good	Access to inspect base - Not possible. Young established tree in hedgerow.	10.2	1.8	40+	C	1
T239	1	*Acer pseudoplatanus* Sycamore	10.0	1	23	N 3.0 E 3.0 S 3.0 W 3.0	4.0	4.0	Early Mature	Good	Access to inspect base - Not possible. Young established tree in hedgerow.	23.9	2.8	40+	C	1
T240	1	*Quercus robur* English Oak	14.5	1	72	N 6.0 E 6.0 S 6.0 W 6.0	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Epicormic growth - Crown. Young established tree in hedgerow.	234.5	8.6	40+	A	1
T241	1	*Acer pseudoplatanus* Sycamore	11.0	1	22	N 3.0 E 3.0 S 3.0 W 3.0	3.0	3.0	Early Mature	Good	Access to inspect base - Not possible.	21.9	2.6	40+	C	1
T242	1	*Acer pseudoplatanus* Sycamore	11.0	1	14	N 3.5 E 3.5 S 3.5 W 3.5	3.0	3.0	Early Mature	Good	Access to inspect base - Not possible.	8.9	1.7	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T243	1	*Acer pseudoplatanus* Sycamore	13.0	1	34	N 6.0 E 6.0 S 6.0 W 6.0	3.0	3.0	Early Mature	Good	Pruning wounds - Historic.	52.3	4.1	40+	B	1
T244	1	*Acer pseudoplatanus* Sycamore	13.0	1	26	N 6.0 E 6.0 S 6.0 W 6.0	3.0	3.0	Early Mature	Good	Pruning wounds - Historic.	30.6	3.1	40+	B	1
T245	1	*Acer pseudoplatanus* Sycamore	14.0	1	40	N 6.0 E 6.0 S 6.0 W 6.0	3.0	3.0	Early Mature	Good		72.4	4.8	40+	B	1
T246	1	*Acer pseudoplatanus* Sycamore	15.0	1	45	N 6.0 E 6.0 S 6.0 W 6.0	4.0	4.0	Early Mature	Good		91.6	5.4	40+	B	1
T247	1	*Acer pseudoplatanus* Sycamore	13.0	1	24	N 4.5 E 4.5 S 4.5 W 4.5	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured.	26.1	2.9	40+	B	1
T248	1	*Acer pseudoplatanus* Sycamore	14.0	1	29	N 5.0 E 5.0 S 5.0 W 5.0	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured.	38.0	3.5	40+	B	1
T249	1	*Acer pseudoplatanus* Sycamore	13.0	1	23	N 3.0 E 3.0 S 3.0 W 3.0	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured.	23.9	2.8	40+	B	1
T250	1	*Acer pseudoplatanus* Sycamore	13.0	1	25	N 4.0 E 4.0 S 4.0 W 4.0	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured.	28.3	3.0	40+	B	1
T251	1	*Acer pseudoplatanus* Sycamore	13.5	1	28	N 4.5 E 5.0 S 4.5 W 4.5	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured.	35.5	3.4	40+	B	1
T252	1	*Acer pseudoplatanus* Sycamore	13.0	1	46	N 4.5 E 4.5 S 4.5 W 4.5	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured.	95.7	5.5	40+	B	1
T253	1	*Acer pseudoplatanus* Sycamore	13.0	1	24	N 4.5 E 4.5 S 4.5 W 4.5	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured.	26.1	2.9	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T254	1	*Acer pseudoplatanus* Sycamore	13.0	1	23	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Good	Access to inspect base - Restricted / obscured.	23.9	2.8	40+	B	1
T255	1	*Acer pseudoplatanus* Sycamore	13.5	1	25	N 5.0 E 5.0 S 5.0 W 5.0	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured.	28.3	3.0	40+	B	1
T256	1	*Acer pseudoplatanus* Sycamore	12.0	1	20	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Fair	Access to inspect base - Restricted / obscured.	18.1	2.4	40+	C	1
H257	150 30 30 5	*Crataegus monogyna* Common Hawthorn/Quick/May *other* Other *Acer pseudoplatanus* Sycamore *Fraxinus excelsior* Ash	3.0	1	10	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge, with areas of self set sycamore, the same size of the hedge.	4.5	1.2	40+	B	2
T258	1	*Quercus robur* English Oak	9.0	1	22	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Good	Access to inspect base - Restricted / obscured.	21.9	2.6	40+	B	1
T259	1	*Quercus robur* English Oak	15.0	1	50	N 6.0 E 6.0 S 6.0 W 6.0	4.0	4.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Deadwood - Minor. Ash dieback suspected.	113.1	6.0	0-10	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H260	500 100 20 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *other* Other *Corylus avellana* Common Hazel	3.0	1	10	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Staked tree / trees. **Fell - Ground level.** Remove a 3-m span. To facilitate development.	4.5	1.2	40+	B	2
T261	1	*Quercus robur* English Oak	3.5	1	8	N 1.0 E 1.0 S 1.0 W 1.0	1.0	1.0	Semi Mature	Good	Access to inspect base - Restricted / obscured. Staked tree / trees.	2.9	1.0	40+	C	1
T262	1	*Quercus robur* English Oak	6.0	1	15	N 3.0 E 3.0 S 3.0 W 3.0	3.0	3.0	Semi Mature	Good	Access to inspect base - Restricted / obscured. Staked tree / trees.	10.2	1.8	40+	C	1
T263	1	*Quercus robur* English Oak	9.0	1	20	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Semi Mature	Good	Access to inspect base - Restricted / obscured.	18.1	2.4	40+	B	1
T264	1	*Quercus robur* English Oak	9.0	1	22	N 4.0 E 4.0 S 4.0 W 4.0	2.5	2.5	Semi Mature	Good	Access to inspect base - Restricted / obscured.	21.9	2.6	40+	B	1
T265	1	*Quercus robur* English Oak	7.0	1	11	N 2.0 E 2.0 S 2.0 W 2.0	1.5	1.5	Semi Mature	Good	Access to inspect base - Restricted / obscured.	5.5	1.3	40+	B	1
T266	1	*Quercus robur* English Oak	11.0	1	21	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Semi Mature	Good	Access to inspect base - Restricted / obscured.	20.0	2.5	40+	B	1
T267	1	*Quercus robur* English Oak	11.0	1	20	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Semi Mature	Good	Access to inspect base - Restricted / obscured.	18.1	2.4	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T268	1	*Quercus robur* English Oak	9.0	1	16	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Semi Mature	Good	Access to inspect base - Restricted / obscured.	11.6	1.9	40+	C	1
T269	1	*Fraxinus excelsior* Ash	19.0	1	84	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Semi Mature	Poor	Access to inspect base - Restricted / obscured. Die-back - Upper crown. Decline - Evident / observed. Fungal fruiting body - structural decay suspected.			0-10	U	
T270	1	*Pyrus sp.* Pear sp.	5.0	1	60	N 1.0 E 1.0 S 1.0 W 1.0	2.0	2.0	Late Mature	Fair	Access to inspect base - Restricted / obscured. Habitat - High value. Partly collapsed.	162.9	7.2	40+	C	1
T271	1	*Quercus robur* English Oak	9.0	1	20	N 2.0 E 2.0 S 2.0 W 2.0	2.0	2.0	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed.	18.1	2.4	40+	B	1
T272	1	*Quercus robur* English Oak	11.0	1	26	N 5.0 E 5.0 S 5.0 W 5.0	2.5	2.5	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed.	30.6	3.1	40+	B	1
T273	1	*Quercus robur* English Oak	11.0	1	22	N 5.0 E 5.0 S 5.0 W 5.0	2.5	2.5	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed.	21.9	2.6	40+	B	1
T274	1	*Quercus robur* English Oak	9.0	1	24	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed.	26.1	2.9	40+	B	1
T275	1	*Quercus robur* English Oak	9.0	1	19	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed.	16.3	2.3	40+	B	1
T276	1	*Quercus robur* English Oak	9.0	1	35	N 5.0 E 5.0 S 5.0 W 5.0	1.5	1.5	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed.	55.4	4.2	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H277	15 10 5	*Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel *other* Other	3.0	1	8	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Staked tree / trees.	2.9	1.0	40+	B	2
T278	1	*Quercus robur* English Oak	9.0	1	13	N E S W 3.0 3.0 3.0 3.0	1.5	1.5	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed.	7.6	1.6	40+	B	1
T279	1	*Quercus robur* English Oak	9.0	1	14	N E S W 4.5 4.5 4.5 4.5	1.5	1.5	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed.	8.9	1.7	40+	B	1
T280	1	*Quercus robur* English Oak	9.0	1	22	N E S W 5.0 5.0 5.0 5.0	2.5	2.5	Early Mature	Good	Access to inspect base - Restricted / obscured. No significant faults observed.	21.9	2.6	40+	B	1
T281	1	*Quercus robur* English Oak	9.0	1	20	N E S W 4.0 4.0 4.0 4.0	2.5	2.5	Early Mature	Good	No significant faults observed.	18.1	2.4	40+	B	1
T282	1	*Quercus robur* English Oak	9.0	1	16	N E S W 3.0 3.0 3.0 3.0	2.0	2.0	Early Mature	Good	No significant faults observed.	11.6	1.9	40+	B	1
T283	1	*Quercus robur* English Oak	9.0	1	13	N E S W 3.0 3.0 3.0 3.0	2.0	2.0	Early Mature	Good	Branch - Broken.	7.6	1.6	40+	B	1
T284	1	*Quercus robur* English Oak	8.0	1	9	N E S W 3.0 3.0 3.0 3.0	2.0	2.0	Early Mature	Good	No significant faults observed.	3.7	1.1	40+	B	1
T285	1	*Quercus robur* English Oak	8.0	1	10	N E S W 2.0 2.0 2.0 2.0	2.0	2.0	Early Mature	Good	No significant faults observed.	4.5	1.2	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T286	1	*Quercus robur* English Oak	9.0	1	26	N E S W 3.0 3.0 3.0 3.0	1.5	1.5	Early Mature	Good	No significant faults observed.	30.6	3.1	40+	B	1
H287	50 40 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *other* Other	3.0	1	8	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Staked tree / trees.	2.9	1.0	40+	B	2
T288	1	*Quercus robur* English Oak	15.0	1	87	N E S W 6.0 6.0 6.0 6.0	3.0	3.0	Mature	Good	Deadwood - Major. Deadwood - Minor. Epicormic growth - Crown. Pruning wounds - Historic.	342.4	10.4	40+	A	1
T289	1	*Quercus robur* English Oak	17.0	1	110	N E S W 8.0 8.0 8.0 8.0	3.0	3.0	Mature	Good	Deadwood - Major. Deadwood - Minor. Epicormic growth - Crown. Pruning wounds - Historic.	547.4	13.2	40+	A	1
T290	1	*Fraxinus excelsior* Ash	17.0	1	98	N E S W 7.0 6.0 7.0 10.0	3.0	3.0	Mature	Poor	Die-back - Throughout crown. Decay entry points. Deadwood - Major. Deadwood - Minor. Decay / structural defect - Extensive. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Principal stems. Epicormic growth - Crown. Habitat - High value. Pruning wounds - Historic. Ash dieback observed.	434.5	11.8	0-10	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H291	60 60 30	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *other* Other	4.0	1	8	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown. Field boundary hedge/group.	2.9	1.0	20-40	C	2
T292	1	*Quercus robur* English Oak	9.0	1	38	N E S W 5.0 5.0 5.0 5.0	3.0	3.0	Early Mature	Good		65.3	4.6	40+	B	1
T293	1	*Quercus robur* English Oak	18.0	1	70	N E S W 7.0 7.0 7.0 7.0	2.5	2.5	Early Mature	Good	Deadwood - Minor.	221.7	8.4	40+	A	1
T294	1	*Quercus robur* English Oak	17.0	1	50	N E S W 5.0 5.0 5.0 5.0	4.0	4.0	Early Mature	Good	Deadwood - Minor.	113.1	6.0	40+	B	1
T295	1	*Quercus robur* English Oak	16.0	1	55	N E S W 7.0 7.0 7.0 7.0	3.0	3.0	Early Mature	Good	Epicormic growth - Crown.	136.8	6.6	40+	B	1
T296	1	*Quercus robur* English Oak	17.0	1	40	N E S W 6.5 6.5 6.5 6.5	4.0	4.0	Early Mature	Good	Epicormic growth - Crown.	72.4	4.8	40+	B	1
T297	1	*Quercus robur* English Oak	12.0	1	45	N E S W 7.0 7.0 7.0 7.0	3.0	3.0	Early Mature	Good	Epicormic growth - Crown.	91.6	5.4	40+	B	1
T298	1	*Quercus robur* English Oak	16.0	1	55	N E S W 7.0 7.0 7.0 7.0	4.0	4.0	Early Mature	Good	Epicormic growth - Crown.	136.8	6.6	40+	B	1
T299	1	*Quercus robur* English Oak	6.0	1	15	N E S W 2.5 2.5 2.5 2.5	1.0	1.0	Early Mature	Good		10.2	1.8	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T300	1	*Quercus robur* English Oak	20.0	1	45	N E S W 4.0 9.0 9.0 9.0	2.5	2.5	Early Mature	Good	Epicormic growth - Crown.	91.6	5.4	40+	B	1
H301	150 40 20 15	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *other* Other *Sambucus sp.* Elder sp.	2.5	1	10	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field/plantation boundary hedge.	4.5	1.2	40+	B	2
H302	5 5 3	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus sp.* Elder sp. *Prunus spinosa* Blackthorn/Sloe	2.5	1	10	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown. Field/plantation boundary hedge. Gappy in places.	4.5	1.2	40+	B	2
H303	2	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge. Gappy in places.	4.5	1.2	40+	C	2
H304	4	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge. Gappy in places.	4.5	1.2	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H305	9	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge. Gappy in places.	4.5	1.2	40+	C	2
H306	30	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge. Gappy in places.	4.5	1.2	40+	C	2
H307	120 25 20	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Sambucus sp.* Elder sp.	3.0	1	10	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge.	4.5	1.2	40+	B	2
T308	1	*Quercus robur* English Oak	18.5	1	105	N E S W 7.0 7.0 7.0 7.0	2.5	2.5	Mature	Good	Branch - Broken. Deadwood - Major. Decay / structural defect - Extensive. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Principal stems. Habitat - High value.	498.8	12.6	40+	A	1
H309	80 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus sp.* Elder sp.	3.0	1	10	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge.	4.5	1.2	40+	C	2
T310	1	*Quercus robur* English Oak	20.0	1	131	N E S W 11.0 11.0 11.0 11.0	2.5	2.5	Mature	Good	Branch - Broken. Deadwood - Major. Deadwood - Minor. Epicormic growth - Crown.	706.9	15.0	40+	A	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T311	1	*Fraxinus excelsior* Ash	17.5	1	120	N E S W 8.0 8.0 8.0 8.0	5.0	5.0	Mature	Fair	Deadwood - Major. Decay / structural defect - Extensive. Decay / structural defect - Localised. Decay / structural defect - Open cavity / cavities. Habitat - High value.	651.4	14.4	10-20	B	1
H312	80 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus sp.* Elder sp.	3.0	1	10	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge.	4.5	1.2	40+	C	2
T313	1	*Fraxinus excelsior* Ash	12.0	1	82	N E S W 5.0 5.0 2.0 5.0	2.0	2.0	Mature	Fair	Competition - Adjacent trees. Deadwood - Major. Decay / structural defect - Extensive. Decay / structural defect - Localised. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Principal stems. Habitat - High value.	304.2	9.8	10-20	C	1
T314	1	*Quercus robur* English Oak	20.0	1	149	N E S W 11.0 11.0 11.0 11.0	3.0	3.0	Mature	Good	Branch - Broken. Deadwood - Minor. Epicormic growth - Crown. Habitat - High value. Pruning wounds - Recent.	706.9	15.0	40+	A	1
T315	1	*Quercus robur* English Oak	14.0	1	80	N E S W 9.0 9.0 9.0 9.0	3.0	3.0	Mature	Good	Deadwood - Minor. Epicormic growth - Crown. Pruning wounds - Recent.	289.5	9.6	40+	A	1
H316	40	*Prunus spinosa* Blackthorn/Sloe	3.0	1	5	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge.	1.1	0.6	40+	C	2
H317	40	*Prunus spinosa* Blackthorn/Sloe	3.0	1	5	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge.	1.1	0.6	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T318	1	*Quercus robur* English Oak	15.0	1	110	N E S W 6.5 6.5 6.5 6.5	2.0	2.0	Mature	Good	Branch - Broken. Decay / structural defect - Major. Epicormic growth - Crown. Off site. Diameter has been estimated.	547.4	13.2	40+	A	1
T319	1	*Quercus robur* English Oak	18.0	1	125	NW NE SE SW 8.0 8.0 4.5 8.0	2.0	2.0	Mature	Good	Branch - Broken. Deadwood - Minor. Epicormic growth - Crown. Recent large broken branch in site field.	706.9	15.0	40+	A	1
H320	40	*Prunus spinosa* Blackthorn/Sloe	3.0	1	5	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge.	1.1	0.6	40+	C	2
T321	1	*Quercus robur* English Oak	8.0	1	35	N E S W 4.0 4.0 4.0 4.0	2.0	2.0	Early Mature	Good	Topped under HV line.	55.4	4.2	20-40	C	1
T322	1	*Quercus robur* English Oak	21.0	1	156	N E S W 9.0 9.0 9.0 9.0	3.0	3.0	Mature	Good	Branch - Broken. Deadwood - Major. Deadwood - Minor. Epicormic growth - Crown.	706.9	15.0	40+	A	1
T323	1	*Quercus robur* English Oak	17.0	1	85	N E S W 7.0 7.0 7.0 7.0	3.0	3.0	Mature	Good	Deadwood - Minor. Epicormic growth - Crown.	326.9	10.2	40+	B	1
H324	120	*Prunus spinosa* Blackthorn/Sloe	5.0	1	5	N E S W 1.3 1.3 1.3 1.3	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge.	1.1	0.6	20-40	C	2
T325	1	*Quercus robur* English Oak	19.0	1	95	N E S W 9.0 9.0 9.0 9.0	3.0	3.0	Mature	Good	Deadwood - Minor. Epicormic growth - Crown.	408.3	11.4	40+	A	1
T326	1	*Quercus robur* English Oak	10.0	1	49	N E S W 5.0 5.0 5.0 5.0	2.0	2.0	Mature	Good	Deadwood - Minor. Epicormic growth - Crown.	108.6	5.9	40+	B	1
T327	1	*Quercus robur* English Oak	15.0	1	58	N E S W 7.0 7.0 7.0 7.0	3.0	3.0	Mature	Good	Access to inspect base - Not possible.	152.2	7.0	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H328	30 5 5 2	*Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May *Salix caprea* Goat Willow/Great Sallow	5.0	1	10	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown. Group, forming hedgerow.	4.5	1.2	20-40	C	2
T329	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	2	21	N 2.0 E 2.0 S 2.0 W 2.0	1.0	1.0	Mature	Good		20.4	2.5	20-40	C	1
H330	5 5 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel	3.5	1	15	N 2.0 E 2.0 S 2.0 W 2.0	0.5	0.5	Early Mature	Good	Hedgerow - Neglected / overgrown. Gappy in places.	10.2	1.8	10-20	C	2
T331	1	*Quercus robur* English Oak	15.0	1	73	N 5.0 E 5.0 S 5.0 W 5.0	3.5	3.5	Mature	Good	Deadwood - Minor. Edge of woodland.	241.1	8.8	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G332	30 15 10 10 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Quercus robur* English Oak *Acer pseudoplatanus* Sycamore *Cerasus avium* Wild Cherry *Castanea sativa* Sweet Chestnut	16.0	1	55	N E S W 6.0 6.0 6.0 6.0	2.0	2.0	Early Mature	Good	Off site woodland group. Native broadleaves. Species count and composition have been estimated.	136.8	6.6	40+	B	2
H333	240 6	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus sp.* Elder sp.	2.5	1	15	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge. Planted linear row.	10.2	1.8	40+	B	2
H334	2	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	15	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Mature	Good	Hedgerow - Maintained. Section of field boundary hedge.	10.2	1.8	40+	C	2
H335	9	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	15	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Mature	Good	Hedgerow - Maintained. Section of field boundary hedge.	10.2	1.8	40+	C	2
T336	1	*Quercus robur* English Oak	9.0	1	38	NW NE SE SW 5.5 2.0 0.5 3.0	3.5	3.5	Semi Mature	Good		65.3	4.6	20-40	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T337	1	*Crataegus monogyna* Common Hawthorn/Quick/May	9.0	1	27	N 2.5 E 2.5 S 2.5 W 2.5	3.0	3.0	Mature	Good		33.0	3.2	20-40	C	1
H338	20 20	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	4.5	1	10	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown. Linear hedge bounding recently harvested plantation.	4.5	1.2	10-20	C	2
T339	1	*Fraxinus excelsior* Ash	17.0	1	120	N 10.0 E 10.0 S 10.0 W 10.0	3.5	3.5	Late Mature	Fair	Access to inspect base - Not possible. Branch - Broken. Deadwood - Minor. Decay / structural defect - Base. Decay / structural defect - Extensive. Decay / structural defect - Principal stems. Fungal fruiting body - structural decay suspected. Habitat - High value. Diameter estimated due to access restrictions. Compacted track from recent harvesting work on NW side.	651.4	14.4	10-20	B	1
H340	5 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	4.5	1	10	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown. Linear hedge bounding recently harvested plantation.	4.5	1.2	10-20	C	2
H341	6	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Section of Hawthorn hedge.	4.5	1.2	40+	C	2
H342	50	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Section of Hawthorn hedge.	4.5	1.2	40+	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T343	1	*Salix fragilis* Crack Willow	12.0	1	50	N E S W 6.0 6.0 6.0 6.0	3.0	3.0	Mature	Fair	Access to inspect base - Not possible. Deadwood - Minor. Located on edge of pond.	113.1	6.0	10-20	B	1
T344	1	*Alnus glutinosa* Common Alder	12.0	4	37	N E S W 6.0 6.0 6.0 6.0	3.0	3.0	Early Mature	Good	Access to inspect base - Not possible. Located on edge of group.	64.5	4.5	20-40	B	1
T345	1	*Alnus glutinosa* Common Alder	12.0	1	45	N E S W 6.0 6.0 6.0 6.0	3.0	3.0	Early Mature	Good	Access to inspect base - Not possible. Located on edge of group.	91.6	5.4	20-40	B	1
G346	30 20 15 10	*Crataegus monogyna* Common Hawthorn/Quick/May *other* Other *Alnus glutinosa* Common Alder *Salix sp.* Willow sp.	5.0	1	25	N E S W 2.0 2.0 2.0 2.0	0.5	0.5	Early Mature	Good	Habitat - High value. Group around pond.	28.3	3.0	20-40	B	2
T347	1	*Salix fragilis* Crack Willow	9.0	1	35	N E S W 6.0 6.0 6.0 6.0	3.0	3.0	Early Mature	Good	Access to inspect base - Not possible. Located on edge of group.	55.4	4.2	20-40	B	1
H348	100	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	10	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Count estimated. Gappy in places. **Fell - Ground level.** Remove a 5-m span. To facilitate development.	4.5	1.2	40+	B	2
T349	1	*Populus alba* White Poplar/Abele	12.0	5	44	N E S W 5.0 5.0 5.0 5.0	2.0	2.0	Early Mature	Good	Edge of plantation.	90.5	5.4	20-40	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T350	1	*Populus alba* White Poplar/Abele	13.0	5	55	N 8.0 E 8.0 S 8.0 W 8.0	2.0	2.0	Early Mature	Good	Edge of plantation.	141.4	6.7	20-40	B	1
H351	100	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown. Count estimated. Gappy in places.	4.5	1.2	40+	B	2
T352	1	*Quercus robur* English Oak	20.0	1	96	N 10.0 E 10.0 S 10.0 W 10.0	5.0	5.0	Mature	Good	Deadwood - Minor. Pruning wounds - Historic. In hedgerow. Tree has been crown lifted.	416.9	11.5	40+	B	1
T353	1	*Fraxinus excelsior* Ash	9.0	1	17	N 3.0 E 3.0 S 3.0 W 3.0	4.0	4.0	Early Mature	Fair	Hedgerow tree. **Fell - Ground level.** To facilitate development.	13.1	2.0	10-20	C	1
T354	1	*Fraxinus excelsior* Ash	9.0	1	16	N 3.0 E 3.0 S 3.0 W 3.0	4.0	4.0	Early Mature	Fair	Hedgerow tree. **Fell - Ground level.** To facilitate development.	11.6	1.9	10-20	C	1
T355	1	*Fraxinus excelsior* Ash	8.0	1	20	N 3.0 E 3.0 S 3.0 W 3.0	2.0	2.0	Semi Mature	Fair	Hedgerow tree.	18.1	2.4	10-20	C	1
T356	1	*Fraxinus excelsior* Ash	10.0	1	20	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Semi Mature	Fair	Hedgerow tree.	18.1	2.4	10-20	C	1
T357	1	*Fraxinus excelsior* Ash	9.0	1	20	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Semi Mature	Fair	Hedgerow tree.	18.1	2.4	10-20	C	1
T358	1	*Quercus robur* English Oak	17.0	1	92	N 9.0 E 9.0 S 9.0 W 9.0	5.0	5.0	Mature	Good	Deadwood - Major. Pruning wounds - Historic. Crown lifted. Some areas of die back within the crown.	382.9	11.0	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T359	1	*Aesculus hippocastanum* Horse Chestnut	15.0	1	96	N 9.0 E 9.0 S 8.0 W 9.0	3.0	3.0	Mature	Good	Pruning wounds - Historic.	416.9	11.5	40+	B	1
T360	1	*Fraxinus excelsior* Ash	9.5	1	16	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Fair	Hedgerow tree.	11.6	1.9	10-20	C	1
T361	1	*Fraxinus excelsior* Ash	9.0	1	14	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Fair	Hedgerow tree.	8.9	1.7	10-20	C	1
T362	1	*Quercus robur* English Oak	9.0	1	22	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Good	Hedgerow tree.	21.9	2.6	40+	B	1
T363	1	*Fraxinus excelsior* Ash	11.0	1	27	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Fair	Ivy or climbing plant. Hedgerow tree.	33.0	3.2	10-20	C	1
T364	1	*Fraxinus excelsior* Ash	12.0	1	26	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Fair	Hedgerow tree.	30.6	3.1	10-20	C	1
T365	1	*Corylus avellana* Common Hazel	7.0	1	16	N 3.0 E 3.0 S 3.0 W 3.0	3.0	3.0	Early Mature	Fair	Hedgerow tree.	11.6	1.9	10-20	C	1
T366	1	*Fraxinus excelsior* Ash	12.0	1	17	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Fair	Hedgerow tree.	13.1	2.0	10-20	C	1
T367	1	*Fraxinus excelsior* Ash	9.0	1	18	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Fair	Hedgerow tree.	14.7	2.2	10-20	C	1
H368	300	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	10	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Count estimated.	4.5	1.2	40+	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T369	1	*Acer pseudoplatanus* Sycamore	10.0	1	19	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Good	Hedgerow tree.	16.3	2.3	40+	B	1
T370	1	*Quercus robur* English Oak	8.0	1	13	N 3.0 E 3.0 S 3.0 W 3.0	4.0	4.0	Early Mature	Good	Hedgerow tree.	7.6	1.6	40+	C	1
T371	1	*Acer pseudoplatanus* Sycamore	17.0	1	93	N 8.0 E 8.0 S 8.0 W 8.0	3.0	3.0	Early Mature	Fair	Branch - Broken. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Principal stems. Epicormic growth - Base. Hedgerow tree.	391.3	11.2	20-40	C	1
T372	1	*Quercus robur* English Oak	12.0	1	76	N 8.0 E 8.0 S 8.0 W 8.0	3.0	3.0	Early Mature	Fair	Deadwood - Minor. Ivy or climbing plant. Hedgerow tree.	261.3	9.1	20-40	C	1
H373	150	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	10	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Count estimated.	4.5	1.2	40+	B	2
G375	3	*Betula pendula* Silver Birch	9.0	1	15	N 1.5 E 1.5 S 1.5 W 1.5	1.0	1.0	Early Mature	Good	Third party group of trees.	10.2	1.8	20-40	B	2
T376	1	*Tilia x vulgaris* Common Lime	10.0	1	35	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Early Mature	Good		55.4	4.2	40+	B	1
T377	1	*Tilia x vulgaris* Common Lime	10.0	1	32	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Early Mature	Good	Competition - Adjacent trees.	46.3	3.8	40+	B	1
T378	1	*Quercus robur* English Oak	18.0	1	136	N 6.0 E 9.0 S 9.0 W 10.0	4.0	4.0	Mature	Good	Deadwood - Minor. Epicormic growth - Crown. Ivy or climbing plant.	706.9	15.0	40+	A	1
T379	1	*Tilia x vulgaris* Common Lime	10.0	1	21	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Early Mature	Good	Competition - Adjacent trees.	20.0	2.5	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T380	1	*Tilia x vulgaris* Common Lime	13.0	1	31	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Good		43.5	3.7	40+	B	1
T381	1	*Tilia x vulgaris* Common Lime	12.0	1	31	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Early Mature	Good	Competition - Adjacent trees.	43.5	3.7	40+	B	1
T382	1	*Tilia x vulgaris* Common Lime	15.0	1	46	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Mature	Good	Competition - Adjacent trees.	95.7	5.5	40+	B	1
T383	1	*Tilia x vulgaris* Common Lime	10.0	1	20	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Good	Competition - Adjacent trees.	18.1	2.4	40+	B	1
T384	1	*Tilia x vulgaris* Common Lime	10.0	1	24	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Good	Competition - Adjacent trees.	26.1	2.9	40+	B	1
T385	1	*Quercus robur* English Oak	14.0	1	53	N 8.0 E 8.0 S 8.0 W 8.0	3.0	3.0	Early Mature	Good		127.1	6.4	40+	B	1
T386	1	*Tilia x vulgaris* Common Lime	12.0	1	26	N 3.0 E 3.0 S 3.0 W 3.0	3.0	3.0	Early Mature	Good		30.6	3.1	40+	B	1
T387	1	*Tilia x vulgaris* Common Lime	11.0	1	26	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Good		30.6	3.1	40+	B	1
T388	1	*Tilia x vulgaris* Common Lime	16.0	1	88	N 9.0 E 9.0 S 9.0 W 9.0	3.0	3.0	Mature	Good		350.3	10.6	40+	A	1
T400	1	*Crataegus monogyna* Common Hawthorn/Quick/May	8.0	1	37	N 3.0 E 3.0 S 3.0 W 3.0	3.0	3.0	Early Mature	Good	Edge of plantation.	61.9	4.4	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T401	1	*Quercus robur* English Oak	13.0	1	69	N 7.0 E 7.0 S 7.0 W 7.0	3.0	3.0	Early Mature	Fair	Deadwood - Minor. Some areas of tip dieback on crown periphery.	215.4	8.3	40+	B	1
G402	60 30	*Quercus robur* English Oak *Acer pseudoplatanus* Sycamore	15.0	1	45	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Good	Off site plantation of mostly natives broadleaves. Hedge edging of Hawthorn around South and West.	91.6	5.4	40+	B	2
T404	1	*Acer pseudoplatanus* Sycamore	11.0	1	20	N 5.0 E 5.0 S 5.0 W 5.0	4.0	4.0	Early Mature	Good		18.1	2.4	20-40	B	2
T405	1	*Acer pseudoplatanus* Sycamore	12.0	1	35	N 5.0 E 5.0 S 5.0 W 5.0	4.0	4.0	Early Mature	Good		55.4	4.2	20-40	B	2
G406	10	*Acer pseudoplatanus* Sycamore	12.0	1	20	N 1.0 E 1.0 S 1.0 W 1.0	3.0	3.0	Early Mature	Good	Linear hedgerow group.	18.1	2.4	20-40	B	2
T407	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	1	15	N 2.0 E 2.0 S 2.0 W 2.0	2.0	2.0	Early Mature	Good		10.2	1.8	20-40	B	2
T408	1	*Acer pseudoplatanus* Sycamore	9.0	2	20	N 4.0 E 4.0 S 4.0 W 4.0	3.5	3.5	Early Mature	Good		19.0	2.5	20-40	B	2
G409	4	*Acer pseudoplatanus* Sycamore	12.0	1	20	N 2.5 E 2.5 S 2.5 W 2.5	2.0	2.0	Early Mature	Good	Linear hedgerow group.	18.1	2.4	20-40	B	2
G410	100 5	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May	12.0	1	5	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Early Mature	Good	Understory hedge group.	1.1	0.6	20-40	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H411	4 1	*Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May	4.5	1	5	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Early Mature	Good	Hedge remnant.	1.1	0.6	20-40	C	2
H412	25 9 5	*Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May	12.0	1	5	N E S W 1.5 1.5 1.5 1.5	0.0	0.0	Early Mature	Good	Hedge remnant.	1.1	0.6	20-40	C	2
H413	40	*Prunus spinosa* Blackthorn/Sloe	3.0	1	5	N E S W 2.5 2.5 2.5 2.5	0.0	0.0	Early Mature	Good	Hedge remnant.	1.1	0.6	20-40	C	2
H414	15 5 5	*Acer pseudoplatanus* Sycamore *other* Other *Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	10	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Field boundary hedge, with areas of self set sycamore, the same size of the hedge.	4.5	1.2	40+	B	2
T415	1	*Acer pseudoplatanus* Sycamore	10.0	1	20	N E S W 4.5 4.5 4.5 4.5	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured.	18.1	2.4	20-40	C	1
T416	1	*Acer pseudoplatanus* Sycamore	11.0	1	20	N E S W 4.5 4.5 4.5 4.5	4.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured.	18.1	2.4	20-40	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T417	1	*Corylus avellana* Common Hazel	3.5	6	17	N 5.0 E 5.0 S 5.0 W 5.0	0.5	0.5	Early Mature	Good	No significant faults observed. Part of hedge.	13.3	2.1	20-40	C	1 2
G418	2	*Corylus avellana* Common Hazel	4.0	5	11	N 2.5 E 2.5 S 2.5 W 2.5	0.0	0.0	Semi Mature	Good	Hedge group.	5.7	1.3	20-40	C	2
T419	1	*Corylus avellana* Common Hazel	2.5	4	14	N 1.5 E 1.5 S 1.5 W 1.5	0.5	0.5	Semi Mature	Good	No significant faults observed. Part of hedge.	8.9	1.7	20-40	C	1 2
T420	1	*Fraxinus excelsior* Ash	12.0	2	59	N 4.5 E 4.5 S 4.5 W 4.5	2.0	2.0	Early Mature	Fair		157.7	7.1	10-20	B	1
H421	30 2	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	5	N 2.5 E 2.5 S 2.5 W 2.5	0.0	0.0	Early Mature	Good	Hedge remnant.	1.1	0.6	20-40	C	2
H422	5 2	*Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May	4.0	5	11	N 2.5 E 2.5 S 2.5 W 2.5	0.0	0.0	Semi Mature	Good	Hedge remnant.	5.7	1.3	20-40	C	2
T423	1	*Fraxinus excelsior* Ash	17.0	1	85	N 6.0 E 8.0 S 6.0 W 6.0	2.0	2.0	Mature	Poor	Access to inspect base - Not possible. Deadwood - Minor. Ivy or climbing plant. Ash die back suspected.	326.9	10.2	0-10	C	1
T424	1	*Fraxinus excelsior* Ash	12.0	1	80	N 5.0 E 5.0 S 5.0 W 5.0	1.5	1.5	Mature	Fair	Access to inspect base - Not possible. Die-back - Upper crown. Deadwood - Minor.	289.5	9.6	0-10	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T425	1	*Fraxinus excelsior* Ash	16.5	1	83	N 8.5 E 8.5 S 8.5 W 8.5	2.0	2.0	Mature	Fair	Access to inspect base - Not possible. Ivy or climbing plant.	311.7	10.0	40+	B	1
T426	1	*Fraxinus excelsior* Ash	6.5	1	13	N 3.0 E 3.0 S 3.0 W 3.0	1.5	1.5	Semi Mature	Fair	Leaning trunk - Minor.	7.6	1.6	20-40	C	1
T427	1	*Quercus robur* English Oak	15.0	1	74	N 8.5 E 8.5 S 8.5 W 8.5	2.0	2.0	Mature	Good	Deadwood - Minor.	247.7	8.9	40+	B	1
H428	20	*Prunus spinosa* Blackthorn/Sloe	2.0	1	3	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedge remnant.	0.4	0.4	20-40	C	2
T429	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	5	22	N 2.0 E 2.0 S 2.0 W 2.0	1.5	1.5	Early Mature	Good		22.6	2.7	20-40	C	1
T430	1	*Fraxinus excelsior* Ash	11.0	2	46	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Mature	Fair	Access to inspect base - Not possible. Die-back - Upper crown. Deadwood - Minor.	96.1	5.5	0-10	B	1
H431	20	*Prunus spinosa* Blackthorn/Sloe	3.0	1	3	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedge remnant.	0.4	0.4	20-40	C	2
G432	5	*Salix caprea* Goat Willow/Great Sallow	7.0	1	8	N 5.0 E 5.0 S 5.0 W 5.0	0.0	0.0	Early Mature	Good		2.9	1.0	20-40	C	2
T433	1	*Fraxinus excelsior* Ash	13.0	1	60	N 6.0 E 6.0 S 6.0 W 6.0	4.0	4.0	Mature	Poor	Access to inspect base - Not possible. Die-back - Throughout crown. Deadwood - Minor.	162.9	7.2	20-40	B	1
T434	1	*Quercus robur* English Oak	12.0	1	60	N 6.0 E 6.0 S 6.0 W 6.0	2.0	2.0	Early Mature	Poor	Access to inspect base - Restricted / obscured.	162.9	7.2	20-40	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T435	1	*Fraxinus excelsior* Ash	9.0	1	20	N 3.0 E 3.0 S 3.0 W 3.0	2.0	2.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Ash die back suspected.	18.1	2.4	20-40	C	1
T436	1	*Fraxinus excelsior* Ash	12.0	5	44	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Ash die back suspected.	90.5	5.4	20-40	C	1
T437	1	*Fraxinus excelsior* Ash	12.5	2	25	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Ash die back suspected.	28.3	3.0	20-40	C	1
T438	1	*Corylus avellana* Common Hazel	7.0	10	12	N 3.0 E 3.0 S 3.0 W 3.0	2.0	2.0	Early Mature	Fair	Access to inspect base - Restricted / obscured.	7.2	1.5	20-40	C	1
H439	60	*Prunus spinosa* Blackthorn/Sloe	3.0	1	3	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedge remnant.	0.4	0.4	20-40	C	2
H440	2	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	5	11	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Semi Mature	Good	Hedge remnant.	5.7	1.3	20-40	C	2
T441	1	*Quercus robur* English Oak	15.0	1	78	N 8.5 E 2.0 S 8.5 W 8.5	2.0	2.0	Mature	Good	Deadwood - Minor. Epicormic growth - Crown.	275.2	9.4	40+	B	1
T442	1	*Fraxinus excelsior* Ash	15.0	2	88	N 7.5 E 7.5 S 7.5 W 7.5	2.0	2.0	Mature	Poor	Die-back - Throughout crown. Deadwood - Minor. Ash die back observed.			0-10	U	
G443	4	*Corylus avellana* Common Hazel	4.0	5	11	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good		5.7	1.3	20-40	C	2
G444	4	*Corylus avellana* Common Hazel	4.0	5	11	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good		5.7	1.3	20-40	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T445	1	*Quercus robur* English Oak	15.0	1	90	N E S W 9.0 9.0 9.0 9.0	3.5	3.5	Mature	Poor	Access to inspect base - Restricted / obscured. Deadwood - Minor.	366.4	10.8	20-40	A	1
G446	4	*Corylus avellana* Common Hazel	4.0	5	11	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good		5.7	1.3	20-40	C	2
T447	1	*Quercus robur* English Oak	6.0	1	70	N E S W 0.5 0.5 0.5 0.5	2.0	2.0	Mature	Fair	Decay / structural defect - Open cavity / cavities. Habitat - High value. High stump, with some new shoots.	221.7	8.4	20-40	C	1
T448	1	*Quercus robur* English Oak	3.0	1	50	N E S W 1.0 1.0 1.0 1.0	3.0	3.0	Mature	Fair	Decay / structural defect - Open cavity / cavities. Habitat - High value. High stump, with some new shoots.	113.1	6.0	20-40	C	1
T449	1	*Corylus avellana* Common Hazel	6.0	10	12	N E S W 3.0 3.0 3.0 3.0	2.0	2.0	Early Mature	Fair	Access to inspect base - Restricted / obscured.	7.2	1.5	20-40	C	1
T450	1	*Quercus robur* English Oak	16.0	1	98	N E S W 10.0 10.0 10.0 10.0	2.5	2.5	Mature	Poor	Deadwood - Major. Deadwood - Minor.	434.5	11.8	20-40	A	1
T451	1	*Fraxinus excelsior* Ash	15.0	1	79	N E S W 7.0 7.0 7.0 10.0	2.5	2.5	Mature	Fair	Deadwood - Minor. Ivy or climbing plant.	282.3	9.5	10-20	B	1
H452	2 1	*Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May	7.0	5	11	N E S W 3.0 3.0 3.0 3.0	1.5	1.5	Early Mature	Good	On bank of ditch. Hedge remnant.	5.7	1.3	20-40	C	2
H453	2	*Corylus avellana* Common Hazel	7.0	15	19	N E S W 3.5 3.5 3.5 3.5	1.5	1.5	Early Mature	Good	On bank of ditch. Hedge remnant.	17.0	2.3	20-40	C	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T454	1	*Fraxinus excelsior* Ash	13.0	3	35	N 4.5 E 4.5 S 4.5 W 4.5	2.5	2.5	Mature	Fair	Access to inspect base - Not possible. Competition - Adjacent trees. Ivy or climbing plant. Edge of water.	56.5	4.2	10-20	C	1
T455	1	*Quercus robur* English Oak	14.0	1	80	N 8.0 E 8.0 S 8.0 W 8.0	3.0	3.0	Mature	Poor	Deadwood - Major. Deadwood - Minor.	289.5	9.6	20-40	A	1
T456	1	*Fraxinus excelsior* Ash	12.0	1	25	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Mature	Fair	Access to inspect base - Restricted / obscured. Decline - Evident / observed. Ivy or climbing plant. Edge of water. Ash die back observed.			0-10	U	
T457	1	*Fraxinus excelsior* Ash	16.0	2	88	N 8.0 E 8.0 S 8.0 W 8.0	2.0	2.0	Mature	Fair	Access to inspect base - Restricted / obscured. Decline - Evident / observed. Ivy or climbing plant. Edge of water. Ash die back observed.			0-10	U	
H458	8	*Corylus avellana* Common Hazel	7.0	15	19	N 1.0 E 1.0 S 1.0 W 1.0	1.5	1.5	Early Mature	Good	On bank of ditch. Hedge remnant.	17.0	2.3	20-40	C	2
T459	1	*Fraxinus excelsior* Ash	20.0	1	88	N 9.0 E 9.0 S 9.0 W 9.0	2.0	2.0	Mature	Poor	Decline - Evident / observed. Decay / structural defect - Base. Decay / structural defect - Extensive. Decay / structural defect - Principal stems. Edge of water. Ash die back observed.			0-10	U	
T460	1	*Fraxinus excelsior* Ash	21.0	1	105	N 10.0 E 10.0 S 10.0 W 10.0	5.0	5.0	Mature	Fair	Deadwood - Major. Deadwood - Minor. Pruning wounds - Historic. Edge of ditch.	498.8	12.6	0-10	B	1
T461	1	*Quercus robur* English Oak	22.0	1	77	N 11.0 E 11.0 S 11.0 W 11.0	3.0	3.0	Mature	Good	Deadwood - Major. Deadwood - Minor. Edge of ditch.	268.2	9.2	0-10	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T462	1	*Quercus robur* English Oak	18.5	1	96	N 9.0 E 9.0 S 9.0 W 9.0	5.0	5.0	Mature	Good	Deadwood - Major. Deadwood - Minor. Edge of ditch.	416.9	11.5	40+	A	1
T463	1	*Quercus robur* English Oak	14.0	1	87	N 9.0 E 9.0 S 9.0 W 9.0	5.0	5.0	Mature	Good	Die-back - Upper crown. Deadwood - Major. Ivy or climbing plant. Edge of ditch.	342.4	10.4	40+	B	1
T464	1	*Fraxinus excelsior* Ash	14.0	1	90	N 8.0 E 8.0 S 8.0 W 8.0	5.0	5.0	Mature	Fair	Die-back - Upper crown. Deadwood - Major. Ivy or climbing plant. Edge of ditch. Ash die back suspected.	366.4	10.8	10-20	C	1
H465	400	*Crataegus monogyna* Common Hawthorn/Quick/May	3.5	1	5	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** To facilitate development.	1.1	0.6	40+	B	2
H466	20 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel	3.5	1	5	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Ends at Edge of plantation. **Fell - Ground level.** To facilitate development.	1.1	0.6	40+	C	2
H467	500	*Crataegus monogyna* Common Hawthorn/Quick/May	3.5	1	5	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Maintained, with gaps in places. **Fell - Ground level.** Remove a 3-m span. To facilitate development.	1.1	0.6	40+	B	2
T468	1	*Quercus robur* English Oak	13.0	1	68	N 7.0 E 7.0 S 7.0 W 7.0	4.0	4.0	Mature	Good	Deadwood - Minor. Ivy or climbing plant.	209.2	8.2	40+	B	1
T469	1	*Acer pseudoplatanus* Sycamore	11.0	1	35	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Good	Ivy or climbing plant.	55.4	4.2	20-40	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H470	400 100 50	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *other* Other	2.5	1	8	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Species count and composition are indicative only.	2.9	1.0	20-40	B	2
T471	1	*Salix fragilis* Crack Willow	7.0	15	19	N E S W 5.0 5.0 5.0 5.0	3.0	3.0	Semi Mature	Fair	Multi-stemmed.	17.0	2.3	10-20	C	1
T472	1	*Quercus robur* English Oak	13.0	1	78	N E S W 8.0 8.0 8.0 8.0	4.0	4.0	Mature	Good	Deadwood - Minor.	275.2	9.4	40+	A	1
T473	1	*Quercus robur* English Oak	12.0	1	68	N E S W 7.0 7.0 7.0 7.0	4.0	4.0	Mature	Good	Deadwood - Minor.	209.2	8.2	40+	B	1
T474	1	*Quercus robur* English Oak	5.0	1	95	N E S W 0.5 0.5 0.5 0.5	1.0	1.0	Mature	Poor	Decay / structural defect - Extensive. Decay / structural defect - Principal stems. Habitat - High value. High stump with regeneration/epicormic growth.	408.3	11.4	10-20	C	1
T475	1	*Quercus robur* English Oak	18.5	1	108	N E S W 10.0 10.0 10.0 10.0	5.0	5.0	Ancient or Veteran	Fair	Branch - Broken. Deadwood - Major. Deadwood - Minor. Decay / structural defect - Extensive. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Principal stems. Habitat - High value.	527.7	13.0	40+	A	1 3

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H476	200 20 5	*Crataegus monogyna* Common Hawthorn/Quick/May *other* Other *Corylus avellana* Common Hazel	2.5	1	8	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Species count and composition are indicative only.	2.9	1.0	20-40	B	2
T477	1	*Quercus robur* English Oak	15.0	1	84	N 8.0 E 8.0 S 8.0 W 8.0	3.0	3.0	Mature	Fair	Die-back - Throughout crown. Deadwood - Minor. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	319.2	10.1	20-40	B	1
T478	1	*Acer pseudoplatanus* Sycamore	14.0	1	51	N 7.0 E 7.0 S 7.0 W 7.0	3.0	3.0	Mature	Fair	Fork - Weak with included bark. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	117.7	6.1	20-40	C	1
H479	16 10 4	*Corylus avellana* Common Hazel *Sambucus sp.* Elder sp. *Crataegus monogyna* Common Hawthorn/Quick/May	3.5	1	8	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Fair	**Fell - Ground level.** Remove a 8-m span. To facilitate development.	2.9	1.0	20-40	B	2
H480	350	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	5	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Maintained, with gaps in places. Count is indicative only.	1.1	0.6	40+	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T481	1	*Tilia x vulgaris* Common Lime	4.0	1	12	N E S W 1.8 1.8 1.8 1.8	1.0	1.0	Semi Mature	Good	Staked tree / trees.	6.5	1.4	40+	C	1
H482	50 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus sp.* Elder sp.	3.5	1	5	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Maintained, with gaps in places. Count is indicative only. **Fell - Ground level.** Remove a 7-m span. To facilitate development.	1.1	0.6	40+	B	2
T483	1	*Quercus robur* English Oak	16.0	1	120	N E S W 9.0 9.0 9.0 9.0	3.0	3.0	Mature	Good	Tree is off site, in adjacent paddock.	651.4	14.4	40+	A	1
H484	50 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus sp.* Elder sp.	3.5	1	5	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Maintained, with gaps in places. Count is indicative only.	1.1	0.6	40+	B	2
H485	50	*Crataegus monogyna* Common Hawthorn/Quick/May	3.5	1	5	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Maintained, with gaps in places. Count is indicative only.	1.1	0.6	40+	B	2
T486	1	*Quercus robur* English Oak	14.0	1	94	N E S W 9.0 9.0 9.0 9.0	3.0	3.0	Mature	Good	Deadwood - Minor. Ivy or climbing plant.	399.7	11.3	40+	A	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H487	70 20 5	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple	3.5	1	5	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Staked tree / trees. Maintained, with gaps in places. Count is indicative only.	1.1	0.6	40+	B	2
G488	10 8 5 5 1	*other* Other *Alnus glutinosa* Common Alder *Sorbus sp.* Sorbus sp. *Sorbus aucuparia* Rowan/Mountain Ash *Aesculus hippocastanum* Horse Chestnut	7.0	1	10	N E S W 3.0 3.0 3.0 3.0	0.5	0.5	Semi Mature	Good	Tree count and composition has been estimated.	4.5	1.2	10-20	B	2
T489	1	*Tilia x vulgaris* Common Lime	8.0	1	35	N E S W 4.5 4.5 4.5 4.5	2.0	2.0	Early Mature	Good	No significant faults observed.	55.4	4.2	40+	B	1
T490	1	*Tilia x vulgaris* Common Lime	8.0	1	29	N E S W 3.0 3.0 3.0 3.0	1.5	1.5	Early Mature	Good	No significant faults observed.	38.0	3.5	40+	B	1
T491	1	*Tilia x vulgaris* Common Lime	7.5	1	20	N E S W 3.0 3.0 3.0 3.0	2.0	2.0	Early Mature	Good	No significant faults observed.	18.1	2.4	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T492	1	*Tilia x vulgaris* Common Lime	8.5	1	25	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	No significant faults observed.	28.3	3.0	40+	B	1
T493	1	*Tilia x vulgaris* Common Lime	7.0	1	29	N 3.0 E 3.0 S 3.0 W 3.0	2.0	2.0	Early Mature	Good	No significant faults observed.	38.0	3.5	40+	B	1
T494	1	*Quercus robur* English Oak	19.0	1	125	N 10.0 E 10.0 S 10.0 W 10.0	2.5	2.5	Mature	Good	Deadwood - Minor. Pruning wounds - Historic. Tree is off site, in adjacent paddock.	706.9	15.0	40+	A	1
H495	400	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	10	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	B	2
T496	1	*Quercus robur* English Oak	19.0	1	115	N 10.0 E 10.0 S 10.0 W 10.0	2.5	2.5	Mature	Good	Deadwood - Minor. Tree is off site.	598.3	13.8	40+	A	1
H497	400	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	10	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	B	2
T498	1	*Quercus robur* English Oak	3.0	1	5	N 1.0 E 1.0 S 1.0 W 1.0	1.0	1.0	Semi Mature	Good	Staked tree / trees.	1.1	0.6	40+	C	1
T499	1	*Quercus robur* English Oak	3.0	1	8	N 1.5 E 1.5 S 1.5 W 1.5	1.0	1.0	Semi Mature	Good	Staked tree / trees.	2.9	1.0	40+	C	1
T500	1	*Quercus robur* English Oak	3.0	1	8	N 1.5 E 1.5 S 1.5 W 1.5	1.0	1.0	Semi Mature	Good	Staked tree / trees.	2.9	1.0	40+	C	1
T501	1	*Quercus robur* English Oak	3.5	1	8	N 1.8 E 1.8 S 1.8 W 1.8	1.0	1.0	Semi Mature	Good	Staked tree / trees.	2.9	1.0	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T502	1	*Quercus robur* English Oak	17.0	1	94	N E S W 8.0 8.0 8.0 8.0	5.0	5.0	Mature	Good	Deadwood - Major. Deadwood - Minor. Epicormic growth - Crown.	399.7	11.3	40+	A	1
T503	1	*Quercus robur* English Oak	16.0	1	106	N E S W 7.0 7.0 7.0 9.0	5.0	5.0	Mature	Good	Deadwood - Major. Deadwood - Minor. Epicormic growth - Crown. Ivy or climbing plant.	508.3	12.7	40+	A	1
T504	1	*Quercus robur* English Oak	5.0	1	85	N E S W 0.0 0.0 0.0 0.0	0.0	0.0	Mature	Dead	Decay / structural defect - Extensive. Decay / structural defect - Open cavity / cavities. Ivy or climbing plant. High stump with habitat value.			0-10	U	
T505	1	*Quercus robur* English Oak	8.0	1	70	N E S W 4.0 4.0 4.0 4.0	5.0	5.0	Early Mature	Good	Deadwood - Minor. Decay / structural defect - Major. Decay / structural defect - Open cavity / cavities. Epicormic growth - Crown. Ivy or climbing plant. Past storm damage. **Fell - Ground level.** Possible removal to facilitate cable installation.	221.7	8.4	40+	B	1
T506	1	*Quercus robur* English Oak	19.5	1	126	N E S W 7.5 7.5 7.5 7.5	3.0	3.0	Mature	Good	Deadwood - Minor. Epicormic growth - Crown. Ivy or climbing plant. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	706.9	15.0	40+	A	1
H507	400 50	*Crataegus monogyna* Common Hawthorn/Quick/May *other* Other	2.0	1	10	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Staked tree / trees. Species count and composition are indicative only. **Fell - Ground level.** Remove a 25-m span. To facilitate development.	4.5	1.2	40+	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T508	1	*Quercus robur* English Oak	18.0	1	118	N 8.0 E 8.0 S 8.0 W 8.0	4.0	4.0	Mature	Poor	Die-back - Throughout crown. Decline - Suspected. Epicormic growth - Crown.	629.9	14.2	10-20	C	1
T509	1	*Quercus robur* English Oak	15.0	1	96	N 9.0 E 9.0 S 9.0 W 9.0	3.0	3.0	Mature	Good	Deadwood - Minor. Epicormic growth - Crown. Ivy or climbing plant.	416.9	11.5	40+	A	1
T510	1	*Ilex aquifolium* Holly	9.0	5	33	N 3.0 E 3.0 S 3.0 W 3.0	1.0	1.0	Mature	Poor		50.9	4.0	10-20	C	1
H511	6	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	5	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Section of hedge.	1.1	0.6	40+	C	2
T512	1	*Quercus robur* English Oak	5.0	1	10	N 2.0 E 2.0 S 2.0 W 2.0	1.0	1.0	Semi Mature	Good	Staked tree / trees.	4.5	1.2	40+	C	1
H513	20	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	8	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Gappy hedge.	2.9	1.0	20-40	C	2
G514	10	*Alnus glutinosa* Common Alder	10.0	1	25	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	Linear group extends out past the off site Scots Pine, plantation.	28.3	3.0	20-40	B	2
T515	1	*Quercus robur* English Oak	19.5	1	86	N 7.5 E 7.5 S 7.5 W 7.5	3.0	3.0	Mature	Good	Branch - Broken. Deadwood - Minor. Epicormic growth - Crown. Ivy or climbing plant. Edge of plantation.	334.6	10.3	40+	B	1
T516	1	*Quercus robur* English Oak	18.0	1	76	N 6.0 E 9.0 S 6.0 W 6.0	3.0	3.0	Mature	Good	Branch - Broken. Deadwood - Minor. Epicormic growth - Crown. Ivy or climbing plant. Edge of plantation. Leaning East.	261.3	9.1	40+	B	1
T517	1	*Quercus robur* English Oak	18.0	1	75	N 9.0 E 9.0 S 9.0 W 9.0	3.0	3.0	Mature	Good	Deadwood - Minor. Edge of plantation.	254.5	9.0	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T518	1	*Quercus robur* English Oak	18.0	1	75	N 9.0 E 9.0 S 9.0 W 9.0	3.0	3.0	Mature	Good	Deadwood - Minor. Edge of plantation.	254.5	9.0	40+	B	1
T519	1	*Quercus robur* English Oak	18.0	1	75	N 9.0 E 9.0 S 9.0 W 9.0	3.0	3.0	Mature	Good	Deadwood - Minor. Edge of plantation.	254.5	9.0	40+	B	1
G520	10	*Quercus robur* English Oak	19.0	1	95	N 7.0 E 7.0 S 7.0 W 7.0	5.0	5.0	Mature	Good	Deadwood - Minor. Plotted to indicate crown spread extending out of plantation.	408.3	11.4	40+	B	2
T521	1	*Fraxinus excelsior* Ash	17.0	1	75	N 10.0 E 10.0 S 10.0 W 10.0	2.0	2.0	Mature	Poor	Die-back - Throughout crown. Decline - Evident / observed. Ivy or climbing plant. Ash die back evident.	254.5	9.0	0-10	C	1
H522	400 50	*Crataegus monogyna* Common Hawthorn/Quick/May *other* Other	3.0	1	10	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Staked tree / trees. Species count and composition are indicative only.	4.5	1.2	40+	B	2
T523	1	*Fraxinus excelsior* Ash	17.0	1	81	N 10.0 E 10.0 S 10.0 W 10.0	2.0	2.0	Mature	Poor	Die-back - Throughout crown. Decline - Evident / observed. Ivy or climbing plant. Ash die back evident.			0-10	U	
T524	1	*Acer pseudoplatanus* Sycamore	13.0	1	45	N 7.0 E 7.0 S 7.0 W 7.0	2.0	2.0	Mature	Good	Deadwood - Minor. Epicormic growth - Base.	91.6	5.4	20-40	B	1
T525	1	*Fraxinus excelsior* Ash	17.0	1	55	N 9.0 E 9.0 S 9.0 W 9.0	2.0	2.0	Mature	Fair	Access to inspect base - Restricted / obscured. Decline - Suspected. Ash die back suspected.			0-10	U	
T526	1	*Fraxinus excelsior* Ash	15.5	2	53	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Mature	Fair	Access to inspect base - Restricted / obscured. Decline - Suspected. Ash die back suspected.	127.8	6.4	0-10	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T527	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.5	3	40	N 4.0 E 4.0 S 4.0 W 4.0	0.5	0.5	Mature	Good	Competition - Adjacent trees.	74.6	4.9	20-40	B	1
T528	1	*Acer campestre* Field Maple	8.5	4	49	N 5.0 E 5.0 S 5.0 W 5.0	0.5	0.5	Mature	Good	Competition - Adjacent trees. Ivy or climbing plant.	110.1	5.9	20-40	B	1
T529	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.5	6	24	N 4.0 E 4.0 S 4.0 W 4.0	0.5	0.5	Mature	Fair	Multi-stemmed.	27.1	2.9	20-40	C	1
T530	1	*Quercus robur* English Oak	13.0	1	78	NW 8.0 NE 10.0 SE 8.0 SW 8.0	2.0	2.0	Mature	Good	No significant faults observed. On South side of ditch.	275.2	9.4	40+	B	1
T531	1	*Fraxinus excelsior* Ash	16.0	1	78	N 8.0 E 9.0 S 8.0 W 8.0	2.0	2.0	Mature	Poor	Decay / structural defect - Base. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Principal stems. Habitat - High value. Ivy or climbing plant. On South side of ditch.	275.2	9.4	0-10	B	1
T532	1	*Fraxinus excelsior* Ash	17.0	3	91	N 11.0 E 11.0 S 9.5 W 11.0	3.5	3.5	Mature	Fair	Decline - Suspected. Deadwood - Minor. Ivy or climbing plant. On adjacent bank of ditch.	380.2	11.0	10-20	C	1
T533	1	*Fraxinus excelsior* Ash	17.0	2	71	N 9.0 E 9.0 S 9.0 W 9.0	3.5	3.5	Mature	Fair	Decline - Suspected. Deadwood - Minor. Ivy or climbing plant. On adjacent bank of ditch.	228.5	8.5	10-20	C	1
T534	1	*Fraxinus excelsior* Ash	15.0	3	38	N 6.0 E 6.0 S 6.0 W 6.0	5.5	5.5	Early Mature	Fair	Die-back - Upper crown. Decline - Suspected. Deadwood - Minor. Ivy or climbing plant. On adjacent bank of ditch.	66.5	4.6	10-20	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T535	1	*Fraxinus excelsior* Ash	14.0	1	90	N 7.0 E 7.0 S 7.0 W 7.0	5.5	5.5	Ancient or Veteran	Fair	Branch - Broken. Die-back - Throughout crown. Decline - Suspected. Deadwood - Major. Deadwood - Minor. Decay / structural defect - Extensive. Decay / structural defect - Open cavity / cavities. Epicormic growth - Crown. Habitat - High value. On South bank of ditch.	366.4	10.8	20-40	B	1 3
T536	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.5	6	24	N 4.0 E 4.0 S 4.0 W 4.0	0.5	0.5	Mature	Fair	On North side of ditch.	27.1	2.9	20-40	C	1
G537	3	*Acer campestre* Field Maple	7.5	4	30	N 3.5 E 3.5 S 3.5 W 3.5	0.5	0.5	Early Mature	Good		40.7	3.6	40+	B	2
T538	1	*Crataegus monogyna* Common Hawthorn/Quick/May	3.5	12	17	N 4.0 E 4.0 S 4.0 W 4.0	0.5	0.5	Mature	Fair	On North side of ditch.	13.6	2.1	20-40	C	1
T539	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.5	1	10	N 1.5 E 1.5 S 1.5 W 1.5	0.5	0.5	Mature	Good	On north side of ditch.	4.5	1.2	20-40	C	1
T540	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.5	3	17	N 1.5 E 1.5 S 1.5 W 1.5	0.5	0.5	Mature	Good		13.6	2.1	20-40	C	1
T541	1	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	4	26	N 1.5 E 1.5 S 1.5 W 1.5	0.5	0.5	Mature	Good		31.7	3.2	20-40	C	1
T542	1	*Fraxinus excelsior* Ash	11.0	1	55	N 7.0 E 7.0 S 7.0 W 7.0	3.5	3.5	Early Mature	Poor	Access to inspect base - Not possible. Decline - Suspected. On edge of East Side of ditch.	136.8	6.6	0-10	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T543	1	*Quercus robur* English Oak	18.0	1	75	N E S W 9.0 9.0 9.0 9.0	3.5	3.5	Early Mature	Good	Access to inspect base - Not possible. Deadwood - Minor. On edge of East Side of ditch.	254.5	9.0	40+	B	1
T544	1	*Fraxinus excelsior* Ash	17.0	1	65	N E S W 8.0 8.0 7.0 8.0	3.5	3.5	Early Mature	Poor	Branch - Broken. Die-back - Throughout crown. Decline - Suspected. On edge of East Side of ditch.	191.1	7.8	0-10	C	1
T545	1	*Fraxinus excelsior* Ash	7.0	2	25	N E S W 4.0 4.0 4.0 4.0	2.0	2.0	Semi Mature	Fair	Decline - Suspected. On edge of East Side of ditch.	28.3	3.0	0-10	C	1
H546	50 30 10 5	*other* Other *Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel	4.0	1	10	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown. Species count and composition are indicative only.	4.5	1.2	10-20	C	2
T547	1	*Corylus avellana* Common Hazel	5.5	8	14	N E S W 4.0 4.0 4.0 4.0	2.0	2.0	Semi Mature	Fair	On edge of East Side of ditch.	9.0	1.7	0-10	C	1
G548	4	*Corylus avellana* Common Hazel	7.0	8	14	N E S W 2.5 2.5 2.5 2.5	0.5	0.5	Early Mature	Fair		9.0	1.7	20-40	C	2
H549	6	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	8	14	N E S W 1.0 1.0 1.0 1.0	0.5	0.5	Early Mature	Fair	Hedge remnant.	9.0	1.7	20-40	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H550	6 3	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel	7.0	8	14	N E S W 1.5 1.5 1.5 1.5	0.5	0.5	Early Mature	Fair	Hedge remnant.	9.0	1.7	20-40	C	2
T551	1	*Quercus robur* English Oak	17.0	1	89	N E S W 9.0 9.0 9.0 9.0	3.0	3.0	Mature	Good	Deadwood - Minor. On edge of East Side of ditch.	358.3	10.7	40+	B	1
H552	30 30 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel	4.0	1	10	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown. Species count and composition are indicative only.	4.5	1.2	10-20	C	2
H553	40 10 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel	4.0	1	10	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown. Species count and composition are indicative only.	4.5	1.2	10-20	C	2
T554	1	*Quercus robur* English Oak	16.0	1	90	N E S W 8.0 8.0 8.0 8.0	3.0	3.0	Mature	Fair	Die-back - Throughout crown. Deadwood - Minor. Decay / structural defect - Localised. Decay / structural defect - Principal stems. On edge of north side of ditch.	366.4	10.8	20-40	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H555	8 5	*Corylus avellana* Common Hazel *Prunus spinosa* Blackthorn/Sloe	4.5	8	14	N E S W 1.0 1.0 1.0 1.0	0.5	0.5	Early Mature	Fair	Linear form. Hedge remnant.	9.0	1.7	20-40	C	2
T556	1	*Quercus robur* English Oak	17.0	1	86	N E S W 8.0 8.0 9.0 8.0	2.0	2.0	Mature	Good	Deadwood - Minor. Epicormic growth - Crown. Ivy or climbing plant.	334.6	10.3	40+	B	1
T557	1	*Fraxinus excelsior* Ash	18.0	1	122	N E S W 8.0 8.0 8.0 8.0	5.0	5.0	Mature	Poor	Decline - Suspected. Deadwood - Minor. Decay / structural defect - Open cavity / cavities. Ash die back observed.	673.3	14.6	0-10	C	1
T558	1	*Fraxinus excelsior* Ash	17.5	2	87	N E S W 8.5 8.5 8.5 8.5	5.0	5.0	Mature	Poor	Decline - Suspected. Deadwood - Major. Deadwood - Minor. Decay / structural defect - Open cavity / cavities. Ash die back observed.	349.2	10.5	0-10	C	1
G559	5	*Salix fragilis* Crack Willow	16.0	5	106	N E S W 5.0 5.0 5.0 5.0	1.0	1.0	Mature	Fair	Partially collapsed.	511.2	12.8	20-40	C	2
H560	100 20 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *other* Other	4.0	1	15	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown. Species count and composition are indicative only.	10.2	1.8	10-20	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H561	100 20 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *other* Other	4.0	1	15	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown. Species count and composition are indicative only.	10.2	1.8	10-20	B	2
G562	6 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Pinus sylvestris* Scots Pine	12.0	1	50	N E S W 4.0 4.0 4.0 4.0	3.0	3.0	Early Mature	Good	Stand of trees in corner of field.	113.1	6.0	20-40	B	2
H563	7 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus sp.* Elder sp.	4.0	1	15	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown. Species count and composition are indicative only.	10.2	1.8	20-40	C	2
H564	50	*Crataegus monogyna* Common Hawthorn/Quick/May	4.5	1	15	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Species count and composition are indicative only. Recently flail cut on North side.	10.2	1.8	20-40	C	2
T565	1	*Fraxinus excelsior* Ash	16.0	1	60	N E S W 8.0 8.0 8.0 8.0	4.0	4.0	Mature	Poor	Die-back - Throughout crown. Decline - Evident / observed. Deadwood - Minor. Ivy or climbing plant. Ash die back observed.	162.9	7.2	0-10	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H566	15 15 5	*Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple	5.0	1	15	N E S W 1.8 1.8 1.8 1.8	0.0	0.0	Mature	Fair	Hedgerow - Neglected / overgrown. Species count and composition are indicative only. Gappy unmanaged hedge.	10.2	1.8	20-40	C	2
T567	1	*Fraxinus excelsior* Ash	11.0	1	40	N E S W 4.5 4.5 4.5 4.5	4.0	4.0	Mature	Poor	Access to inspect base - Not possible. Decline - Evident / observed. Dead tree / trees. Ash die back observed.			0-10	U	
T568	1	*Quercus robur* English Oak	17.0	1	130	N E S W 13.0 13.0 13.0 13.0	3.0	3.0	Mature	Good	Access to inspect base - Restricted / obscured. Deadwood - Minor.	706.9	15.0	40+	A	1
T569	1	*Fraxinus excelsior* Ash	14.0	1	57	N E S W 7.0 7.0 7.0 7.0	4.0	4.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Decline - Evident / observed. Ivy or climbing plant. Ash die back observed.	147.0	6.8	0-10	C	1
H570	15 5 5	*Corylus avellana* Common Hazel *Acer campestre* Field Maple *Crataegus monogyna* Common Hawthorn/Quick/May	5.0	1	15	N E S W 1.8 1.8 1.8 1.8	0.0	0.0	Mature	Fair	Hedgerow - Neglected / overgrown. Species count and composition are indicative only. Gappy unmanaged hedge.	10.2	1.8	20-40	C	2
T571	1	*Fraxinus excelsior* Ash	14.0	1	53	N E S W 7.0 7.0 8.5 7.0	4.0	4.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Decline - Evident / observed. Ivy or climbing plant. Leaning trunk - Minor. Ash die back observed.	127.1	6.4	0-10	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T572	1	*Fraxinus excelsior* Ash	14.0	2	70	N 6.5 E 6.5 S 6.5 W 6.5	4.0	4.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Decline - Evident / observed. Ivy or climbing plant. Leaning trunk - Minor. Ash die back observed.	222.8	8.4	0-10	C	1
T573	1	*Quercus robur* English Oak	11.0	1	57	N 6.5 E 6.5 S 6.5 W 6.5	5.0	5.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Deadwood - Minor. Ivy or climbing plant.	147.0	6.8	40+	B	1
T574	1	*Fraxinus excelsior* Ash	15.5	1	60	N 6.5 E 6.5 S 6.5 W 6.5	4.0	4.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Decline - Evident / observed. Ivy or climbing plant. Leaning trunk - Minor. Ash die back observed.			0-10	U	
T575	1	*Fraxinus excelsior* Ash	12.0	1	54	N 5.5 E 5.5 S 5.5 W 8.5	4.0	4.0	Early Mature	Fair	Access to inspect base - Restricted / obscured. Decline - Evident / observed. Ivy or climbing plant. Leaning trunk - Minor. Ash die back observed.	131.9	6.5	0-10	C	1
T576	1	*Crataegus monogyna* Common Hawthorn/Quick/May	7.0	1	25	N 2.5 E 2.5 S 2.5 W 2.5	1.5	1.5	Early Mature	Fair	Access to inspect base - Not possible. Ivy or climbing plant.	28.3	3.0	0-10	C	1
T577	1	*Fraxinus excelsior* Ash	14.0	1	75	N 8.0 E 8.0 S 8.0 W 8.0	1.5	1.5	Early Mature	Fair	Access to inspect base - Not possible. Die-back - Upper crown. Ivy or climbing plant. Ash die back observed.	254.5	9.0	0-10	C	1
T578	1	*Crataegus monogyna* Common Hawthorn/Quick/May	7.0	1	20	N 1.0 E 1.0 S 1.0 W 1.0	1.5	1.5	Early Mature	Fair	Access to inspect base - Not possible. Ivy or climbing plant.	18.1	2.4	0-10	C	1
T579	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	7	26	N 1.8 E 1.8 S 1.8 W 1.8	1.5	1.5	Early Mature	Fair	Access to inspect base - Not possible. Ivy or climbing plant.	31.7	3.2	0-10	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T580	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	7	52	N 1.5 E 1.5 S 1.5 W 1.5	1.5	1.5	Early Mature	Fair	Access to inspect base - Not possible. Die-back - Throughout crown. Leaning trunk - Major.			0-10	U	
T581	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	3	20	N 3.0 E 3.0 S 3.0 W 3.0	1.5	1.5	Early Mature	Fair	Access to inspect base - Not possible.	19.2	2.5	0-10	C	1
T582	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	2	14	N 3.0 E 3.0 S 3.0 W 3.0	1.5	1.5	Early Mature	Fair	Access to inspect base - Not possible.	9.0	1.7	0-10	C	1
T583	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	2	14	N 4.0 E 4.0 S 4.0 W 4.0	1.5	1.5	Early Mature	Fair	Access to inspect base - Not possible.	9.0	1.7	0-10	C	1
T584	1	*Fraxinus excelsior* Ash	12.0	1	35	N 4.0 E 4.0 S 4.0 W 4.0	4.0	4.0	Mature	Poor	Die-back - Throughout crown. Decline - Evident / observed. Ivy or climbing plant. Ash die back observed.	55.4	4.2	0-10	C	1
H585	15 11 2	*Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash *Quercus robur* English Oak	8.0	1	15	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown. Species count and composition are indicative only. Gappy unmanaged hedge. Interspersed dead Ash every 5m or so. Flail cut on West Side.	10.2	1.8	10-20	C	2
T586	1	*Fraxinus excelsior* Ash	9.5	1	30	N 5.0 E 5.0 S 5.0 W 5.0	4.5	4.5	Early Mature	Good	Access to inspect base - Not possible. Ash die back observed.	40.7	3.6	40+	B	1
T587	1	*Quercus robur* English Oak	16.0	1	120	N 10.0 E 10.0 S 10.0 W 10.0	4.0	4.0	Mature	Good	Branch - Broken. Deadwood - Minor. Ivy or climbing plant.	651.4	14.4	40+	A	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T588	1	*Quercus robur* English Oak	19.0	1	123	N 10.0 E 10.0 S 10.0 W 10.0	4.0	4.0	Mature	Good	Deadwood - Minor. Ivy or climbing plant.	684.4	14.8	40+	A	1
T589	1	*Quercus robur* English Oak	19.0	1	43	N 9.0 E 9.0 S 9.0 W 9.0	3.0	3.0	Mature	Fair	Branch - Broken. Die-back - Throughout crown. Deadwood - Minor.	83.6	5.2	20-40	B	1
T590	1	*Quercus robur* English Oak	16.0	1	35	N 7.0 E 7.0 S 7.0 W 7.0	3.0	3.0	Mature	Fair	Die-back - Throughout crown. Decline - Suspected. Ivy or climbing plant.	55.4	4.2	0-10	C	1
T591	1	*Acer campestre* Field Maple	13.0	1	35	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Good	Access to inspect base - Not possible. Ivy or climbing plant. Ash dieback observed.	55.4	4.2	40+	B	1
T592	1	*Fraxinus excelsior* Ash	15.0	1	45	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Poor	Die-back - Throughout crown. Decline - Suspected. Ivy or climbing plant. Ash dieback observed.			0-10	U	
T593	1	*Fraxinus excelsior* Ash	13.0	1	40	N 5.0 E 5.0 S 5.0 W 5.0	4.0	4.0	Early Mature	Poor	Die-back - Throughout crown. Decline - Suspected. Ivy or climbing plant. Ash dieback observed.			0-10	U	
T594	1	*Quercus robur* English Oak	10.0	1	42	N 6.0 E 6.0 S 6.0 W 6.0	3.0	3.0	Early Mature	Good		79.8	5.0	40+	B	1
T595	1	*Acer campestre* Field Maple	9.5	1	35	N 6.0 E 6.0 S 6.0 W 6.0	1.0	1.0	Early Mature	Good	Access to inspect base - Restricted / obscured.	55.4	4.2	40+	B	1
T596	1	*Quercus robur* English Oak	17.0	1	85	N 9.0 E 9.0 S 9.0 W 9.0	2.0	2.0	Early Mature	Fair	Access to inspect base - Restricted / obscured. Deadwood - Minor.	326.9	10.2	20-40	B	1
T597	1	*Salix caprea* Goat Willow/Great Sallow	8.5	4	20	N 4.0 E 4.0 S 4.0 W 4.0	0.0	0.0	Early Mature	Good	Access to inspect base - Restricted / obscured.	18.1	2.4	20-40	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T598	1	*Fraxinus excelsior* Ash	15.0	1	60	N 7.0 E 7.0 S 7.0 W 7.0	2.0	2.0	Early Mature	Poor	Die-back - Throughout crown. Decline - Suspected. Ivy or climbing plant. Ash dieback observed.	162.9	7.2	0-10	C	1
T599	1	*Salix fragilis* Crack Willow	16.0	1	60	N 5.0 E 5.0 S 5.0 W 5.0	1.5	1.5	Mature	Poor	Branch - Broken. Die-back - Throughout crown. Decline - Suspected. Ivy or climbing plant.	162.9	7.2	0-10	C	1
T600	1	*Salix caprea* Goat Willow/Great Sallow	8.5	5	22	N 4.0 E 4.0 S 4.0 W 4.0	0.0	0.0	Early Mature	Good	Access to inspect base - Restricted / obscured.	22.6	2.7	20-40	C	1
T601	1	*Quercus robur* English Oak	17.0	1	95	N 8.0 E 8.0 S 8.0 W 8.0	2.0	2.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Deadwood - Minor. Ivy or climbing plant.	408.3	11.4	40+	B	1
T602	1	*Fraxinus excelsior* Ash	9.5	1	70	N 2.5 E 2.5 S 2.5 W 2.5	2.0	2.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Decline - Suspected. Deadwood - Minor. Ivy or climbing plant. Ash die back observed.	221.7	8.4	0-10	C	1
T603	1	*Acer campestre* Field Maple	10.0	1	30	N 2.5 E 2.5 S 2.5 W 2.5	2.0	2.0	Early Mature	Good		40.7	3.6	40+	B	1
T604	1	*Acer campestre* Field Maple	10.0	1	30	N 2.5 E 2.5 S 2.5 W 2.5	2.0	2.0	Early Mature	Good		40.7	3.6	40+	B	1
T605	1	*Acer campestre* Field Maple	11.0	1	35	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good		55.4	4.2	40+	B	1
T606	1	*Salix caprea* Goat Willow/Great Sallow	7.0	6	19	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Early Mature	Good	Access to inspect base - Restricted / obscured.	17.4	2.4	20-40	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T607	1	*Fraxinus excelsior* Ash	11.0	1	30	N E S W 4.0 4.0 4.0 4.0	3.0	3.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Decline - Suspected. Deadwood - Minor. Ivy or climbing plant. Ash die back observed.	40.7	3.6	0-10	C	1
T608	1	*Quercus robur* English Oak	17.5	1	91	N E S W 9.0 9.0 9.0 9.0	3.0	3.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Branch - Broken. Deadwood - Minor.	374.6	10.9	40+	B	1
T609	1	*Fraxinus excelsior* Ash	11.0	2	42	N E S W 4.0 4.0 4.0 4.0	3.0	3.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Decline - Suspected. Deadwood - Minor. Ivy or climbing plant. Ash die back observed.	81.4	5.1	0-10	C	1
T610	1	*Quercus robur* English Oak	18.5	1	100	N E S W 10.0 10.0 10.0 10.0	3.0	3.0	Early Mature	Good	Access to inspect base - Not possible. Deadwood - Minor.	452.4	12.0	40+	A	1
T611	1	*Quercus robur* English Oak	16.5	1	68	N E S W 7.0 7.0 7.0 7.0	2.5	2.5	Early Mature	Good	Deadwood - Minor.	209.2	8.2	40+	B	1
T612	1	*Quercus robur* English Oak	16.5	1	75	N E S W 7.0 7.0 7.0 7.0	2.5	2.5	Early Mature	Good	Deadwood - Minor.	254.5	9.0	40+	B	1
H613	50 10 5	*Crataegus monogyna* Common Hawthorn/Quick/May *other* Other *Fraxinus excelsior* Ash	5.0	1	15	N E S W 1.5 1.5 1.5 1.5	0.0	0.0	Mature	Fair	Hedgerow - Neglected / overgrown. Ivy or climbing plant. Species count and composition are indicative only.	10.2	1.8	20-40	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H614	500	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	10	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Gaps in places. **Fell - Ground level.** To facilitate development.	4.5	1.2	40+	B	2
T615	1	*Acer pseudoplatanus* Sycamore	19.0	1	65	N E S W 7.0 7.0 7.0 7.0	4.0	4.0	Mature	Good	Edge of plantation.	191.1	7.8	40+	B	1
G616	60 50 20 20 20 10	*Acer pseudoplatanus* Sycamore *Crataegus monogyna* Common Hawthorn/Quick/May *other* Other *Fraxinus excelsior* Ash *Quercus robur* English Oak *Picea sp.* Spruce sp.	20.0	1	50	N E S W 4.0 4.0 4.0 4.0	3.0	3.0	Early Mature	Good	Species count and composition are indicative only.	113.1	6.0	40+	B	2
T617	1	*Quercus robur* English Oak	9.0	1	25	N E S W 4.0 4.0 4.0 4.0	2.0	2.0	Early Mature	Good		28.3	3.0	40+	B	1
T618	1	*Quercus robur* English Oak	16.0	1	82	N E S W 7.0 7.0 7.0 7.0	2.0	2.0	Mature	Good	Deadwood - Minor.	304.2	9.8	40+	A	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H619	5 3	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel	6.0	1	10	N E S W 1.5 1.5 1.5 1.5	0.5	0.5	Mature	Good	Section of unmanaged hedge.	4.5	1.2	20-40	C	1
T620	1	*Quercus robur* English Oak	6.0	1	15	N E S W 3.0 3.0 3.0 3.0	0.5	0.5	Semi Mature	Good		10.2	1.8	40+	C	1
T621	1	*Corylus avellana* Common Hazel	6.0	5	11	N E S W 2.0 2.0 2.0 2.0	0.5	0.5	Early Mature	Good		5.7	1.3	20-40	C	1
T622	1	*Corylus avellana* Common Hazel	6.0	5	11	N E S W 2.0 2.0 2.0 2.0	0.5	0.5	Early Mature	Good		5.7	1.3	20-40	C	1
T623	1	*Quercus robur* English Oak	10.0	1	35	N E S W 5.0 5.0 5.0 5.0	1.0	1.0	Early Mature	Good	Ivy or climbing plant.	55.4	4.2	40+	B	1
T624	1	*Acer pseudoplatanus* Sycamore	7.5	1	25	N E S W 3.0 3.0 3.0 3.0	3.0	3.0	Early Mature	Good		28.3	3.0	20-40	C	1
T625	1	*Quercus robur* English Oak	8.5	2	40	N E S W 5.0 5.0 5.0 5.0	2.0	2.0	Early Mature	Good	Stems - Sub-dominant.	73.5	4.8	40+	B	1
H626	200 20	*Crataegus monogyna* Common Hawthorn/Quick/May *other* Other	2.5	1	8	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Species count and composition are indicative only. **Fell - Ground level.** Remove a 5-m span. To facilitate development.	2.9	1.0	20-40	B	2
T627	1	*Salix fragilis* Crack Willow	9.5	1	60	N E S W 4.0 4.0 4.0 4.0	2.0	2.0	Early Mature	Good	Decay / structural defect - Extensive. Previously storm damaged and regrowing.	162.9	7.2	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T628	1	*Quercus robur* English Oak	17.0	1	107	N E S W 8.0 8.0 9.0 8.0	2.0	2.0	Mature	Good	Deadwood - Minor.	517.9	12.8	40+	A	1
H629	100 30	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel	2.5	1	8	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Species count and composition are indicative only.	2.9	1.0	20-40	B	2
H630	10 5	*Populus sp.* Poplar sp. *Salix sp.* Willow sp.	3.0	1	8	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Species count and composition are indicative only.	2.9	1.0	20-40	C	2
T631	1	*Quercus robur* English Oak	10.0	1	62	N E S W 6.0 6.0 6.0 6.0	1.0	1.0	Early Mature	Good	Deadwood - Minor.	173.9	7.4	40+	B	1
T632	1	*Corylus avellana* Common Hazel	3.0	6	12	N E S W 2.0 2.0 2.0 0.5	0.5	0.5	Early Mature	Good	Deadwood - Minor.	6.8	1.5	10-20	C	1
T633	1	*Quercus robur* English Oak	10.0	1	85	N E S W 6.0 6.0 6.0 6.0	1.0	1.0	Early Mature	Good	Access to inspect base - Not possible. Deadwood - Minor.	326.9	10.2	40+	B	1
T634	1	*Quercus robur* English Oak	16.5	1	130	N E S W 10.0 10.0 10.0 10.0	2.0	2.0	Mature	Good	Branch - Broken. Deadwood - Minor. Off site tree.	706.9	15.0	40+	A	1
T635	1	*Quercus robur* English Oak	17.0	1	110	N E S W 12.0 12.0 12.0 12.0	1.0	1.0	Mature	Good	Access to inspect base - Restricted / obscured. Deadwood - Minor. Ivy or climbing plant.	547.4	13.2	40+	A	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T636	1	*Fraxinus excelsior* Ash	15.5	2	52	N 7.0 E 7.0 S 7.0 W 7.0	1.0	1.0	Mature	Poor	Access to inspect base - Restricted / obscured. Die-back - Throughout crown. Decline - Evident / observed. Ivy or climbing plant.			0-10	U	
T637	1	*Quercus robur* English Oak	11.5	1	92	N 7.0 E 7.0 S 7.0 W 7.0	1.0	1.0	Mature	Good	Access to inspect base - Restricted / obscured. Deadwood - Minor. Epicormic growth - Crown. Ivy or climbing plant.	382.9	11.0	40+	B	1
T638	1	*Fraxinus excelsior* Ash	15.0	1	57	N 5.0 E 5.0 S 5.0 W 5.0	1.0	1.0	Mature	Poor	Access to inspect base - Restricted / obscured. Decline - Evident / observed. Ivy or climbing plant.			0-10	U	
T639	1	*Quercus robur* English Oak	17.0	1	98	N 11.0 E 11.0 S 11.0 W 11.0	1.0	1.0	Mature	Good	Access to inspect base - Restricted / obscured. Deadwood - Minor. Ivy or climbing plant.	434.5	11.8	40+	A	1
H640	4 4	*Corylus avellana* Common Hazel *Prunus spinosa* Blackthorn/Sloe	5.0	7	18	N 1.5 E 1.5 S 1.5 W 1.5	0.5	0.5	Early Mature	Good	Hedge remnant.	15.5	2.2	10-20	C	2
T641	1	*Quercus robur* English Oak	17.0	1	95	N 9.0 E 9.0 S 9.0 W 9.0	1.0	1.0	Mature	Good	Access to inspect base - Restricted / obscured. Deadwood - Minor. Ivy or climbing plant.	408.3	11.4	40+	A	1
H642	15 4	*Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel	5.0	7	18	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Early Mature	Good	Hedge remnant.	15.5	2.2	10-20	C	2
T643	1	*Corylus avellana* Common Hazel	5.0	10	25	N 3.0 E 3.0 S 3.0 W 3.0	0.5	0.5	Early Mature	Good		29.0	3.0	10-20	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T644	1	*Quercus robur* English Oak	18.0	1	115	N E S W 10.0 10.0 10.0 10.0	2.0	2.0	Mature	Good	Access to inspect base - Restricted / obscured. Deadwood - Minor. Ivy or climbing plant.	598.3	13.8	40+	A	1
T645	1	*Quercus robur* English Oak	6.0	1	9	N E S W 1.5 1.5 1.5 1.5	2.0	2.0	Semi Mature	Good	No significant faults observed.	3.7	1.1	40+	C	1
T646	1	*Quercus robur* English Oak	15.5	1	86	N E S W 4.0 4.0 4.0 4.0	2.0	2.0	Mature	Good	Access to inspect base - Restricted / obscured. Deadwood - Minor. Ivy or climbing plant.	334.6	10.3	40+	B	1
H647	2 1 1	*Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May *Quercus robur* English Oak	6.5	7	18	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Early Mature	Good	Hedge remnant.	15.5	2.2	40+	C	2
T648	1	*Salix fragilis* Crack Willow	11.0	1	160	N E S W 9.0 9.0 9.0 9.0	1.0	1.0	Late Mature	Good	Ivy or climbing plant. Pollard - Regrown.	706.9	15.0	40+	B	1
T649	1	*Fraxinus excelsior* Ash	16.0	1	107	N E S W 9.0 9.0 9.0 9.0	5.0	5.0	Mature	Fair	Decline - Suspected.	517.9	12.8	0-10	C	1
T650	1	*Quercus robur* English Oak	15.5	1	76	N E S W 9.0 9.0 9.0 9.0	2.0	2.0	Mature	Good	Access to inspect base - Restricted / obscured. Deadwood - Minor. Ivy or climbing plant.	261.3	9.1	40+	B	1
T651	1	*Quercus robur* English Oak	16.0	2	107	N E S W 9.0 9.0 9.0 9.0	2.0	2.0	Mature	Good	Access to inspect base - Restricted / obscured. Deadwood - Minor. Ivy or climbing plant.	525.9	12.9	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T652	1	*Quercus robur* English Oak	15.5	1	120	N E S W 8.0 8.0 8.0 8.0	2.0	2.0	Mature	Good	Access to inspect base - Restricted / obscured. Branch - Broken. Deadwood - Minor. Epicormic growth - Crown. Epicormic growth - Bole / principal stems. Old storm damage in upper crown.	651.4	14.4	40+	B	1
T653	1	*Salix fragilis* Crack Willow	10.0	2	55	N E S W 7.0 7.0 7.0 7.0	3.5	3.5	Mature	Fair	Deadwood - Minor.	137.7	6.6	20-40	B	1
T654	1	*Salix fragilis* Crack Willow	10.0	1	45	N E S W 5.5 5.5 5.5 5.5	3.5	3.5	Early Mature	Fair	Access to inspect base - Not possible. Surrounded by long nettles.	91.6	5.4	20-40	B	1
T655	1	*Salix fragilis* Crack Willow	11.0	1	45	N E S W 5.5 5.5 5.5 5.5	3.5	3.5	Early Mature	Fair	Access to inspect base - Not possible. Surrounded by long nettles.	91.6	5.4	20-40	B	1
T656	1	*Sambucus sp.* Elder sp.	4.0	4	16	N E S W 2.0 2.0 2.0 2.0	1.0	1.0	Mature	Fair	Access to inspect base - Not possible. Surrounded by long nettles.	11.6	1.9	10-20	C	1
T657	1	*Acer pseudoplatanus* Sycamore	11.0	1	40	N E S W 5.0 5.0 5.0 5.0	3.5	3.5	Mature	Good	Access to inspect base - Not possible. Surrounded by long nettles.	72.4	4.8	20-40	B	1
T658	1	*Salix fragilis* Crack Willow	11.0	1	45	N E S W 5.5 5.5 5.5 5.5	3.5	3.5	Mature	Fair	Access to inspect base - Not possible. Surrounded by long nettles.	91.6	5.4	20-40	B	1
H659	2 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel	5.5	5	22	N E S W 2.5 2.5 2.5 2.5	0.5	0.5	Early Mature	Good		22.6	2.7	20-40	C	2
T660	1	*Alnus glutinosa* Common Alder	13.0	3	52	N E S W 6.0 6.0 6.0 6.0	2.0	2.0	Mature	Good	Access to inspect base - Not possible. Multi-stemmed.	124.4	6.3	20-40	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H661	6	*Sambucus sp.* Elder sp.	5.5	2	11	N 1.0 E 1.0 S 1.0 W 1.0	0.5	0.5	Early Mature	Fair	Hedge remnant.	5.8	1.4	10-20	C	2
T662	1	*Quercus robur* English Oak	16.0	1	88	N 8.0 E 8.0 S 8.0 W 7.0	2.0	2.0	Mature	Good	Access to inspect base - Restricted / obscured. Deadwood - Minor.	350.3	10.6	40+	A	1
T663	1	*Fraxinus excelsior* Ash	12.5	1	55	N 5.0 E 5.0 S 5.0 W 7.0	2.5	2.5	Early Mature	Poor	Access to inspect base - Restricted / obscured. Die-back - Throughout crown. Decline - Evident / observed. Ivy or climbing plant.			0-10	U	
H664	5	*Crataegus monogyna* Common Hawthorn/Quick/May	5.5	5	22	N 2.0 E 2.0 S 2.0 W 2.0	1.0	1.0	Early Mature	Fair		22.6	2.7	20-40	C	2
G665	13	*Alnus glutinosa* Common Alder	14.0	1	38	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	Group around pond.	65.3	4.6	20-40	B	2
T666	1	*Acer pseudoplatanus* Sycamore	6.0	8	22	N 3.0 E 3.0 S 3.0 W 3.0	1.0	1.0	Semi Mature	Good		23.2	2.7	20-40	C	1
H667	400	*Crataegus monogyna* Common Hawthorn/Quick/May	3.5	1	10	N 0.8 E 0.8 S 0.8 W 0.8	0.0	0.0	Early Mature	Good	Species count and composition are indicative only. Recently flail cut on East side.	4.5	1.2	40+	B	2
T668	1	*Fraxinus excelsior* Ash	9.0	2	18	N 3.0 E 3.0 S 3.0 W 3.0	1.0	1.0	Semi Mature	Fair	Ivy or climbing plant.	14.7	2.2	20-40	C	1
T669	1	*Acer pseudoplatanus* Sycamore	10.0	5	22	N 3.0 E 3.0 S 3.0 W 3.0	1.0	1.0	Early Mature	Fair	Ivy or climbing plant.	22.6	2.7	20-40	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H670	300 25	*Crataegus monogyna* Common Hawthorn/Quick/May *other* Other	3.5	1	10	N E S W 0.8 0.8 0.8 0.8	0.0	0.0	Early Mature	Good	Species count and composition are indicative only. Recently flail cut on East side.	4.5	1.2	40+	B	2
T671	1	*Acer pseudoplatanus* Sycamore	8.0	1	40	N E S W 3.0 3.0 4.5 3.0	1.5	1.5	Early Mature	Fair	Access to inspect base - Not possible. Ivy or climbing plant.	72.4	4.8	20-40	C	1
T672	1	*Acer pseudoplatanus* Sycamore	9.5	1	35	N E S W 3.5 3.5 3.5 3.5	2.0	2.0	Early Mature	Fair	Access to inspect base - Not possible. Ivy or climbing plant.	55.4	4.2	20-40	C	1
T673	1	*Fraxinus excelsior* Ash	10.0	3	41	N E S W 3.5 3.5 3.5 3.5	2.0	2.0	Early Mature	Poor	Access to inspect base - Not possible. Decline - Evident / observed. Ivy or climbing plant. Ash dieback observed.			20-40	U	
T674	1	*Fraxinus excelsior* Ash	10.0	2	29	N E S W 3.5 3.5 3.5 3.5	2.0	2.0	Early Mature	Poor	Access to inspect base - Not possible. Decline - Suspected. Ivy or climbing plant.	38.5	3.5	20-40	C	1
T675	1	*Quercus robur* English Oak	11.0	1	30	N E S W 3.5 3.5 3.5 3.5	3.0	3.0	Early Mature	Good	Access to inspect base - Not possible. Ivy or climbing plant.	40.7	3.6	40+	B	1
T676	1	*Acer campestre* Field Maple	8.5	1	30	N E S W 2.5 2.5 2.5 2.5	2.0	2.0	Early Mature	Good	Access to inspect base - Not possible. Competition - Adjacent trees. Ivy or climbing plant.	40.7	3.6	40+	B	1
T677	1	*Fraxinus excelsior* Ash	11.5	3	37	N E S W 4.0 4.0 4.0 4.0	2.0	2.0	Early Mature	Poor	Access to inspect base - Not possible. Decline - Suspected. Ivy or climbing plant.	63.7	4.5	20-40	C	1
T678	1	*Fraxinus excelsior* Ash	12.0	1	35	N E S W 4.0 4.0 4.0 4.0	2.0	2.0	Early Mature	Poor	Access to inspect base - Not possible. Decline - Evident / observed. Ivy or climbing plant. Ash dieback.			0-10	U	

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T679	1	*Fraxinus excelsior* Ash	11.5	2	35	N 4.0 E 4.0 S 5.0 W 4.0	2.0	2.0	Early Mature	Poor	Access to inspect base - Not possible. Decline - Evident / observed. Ivy or climbing plant.			20-40	U	
T680	1	*Quercus robur* English Oak	11.5	1	53	N 5.5 E 5.5 S 5.5 W 5.5	2.0	2.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Ivy or climbing plant.	127.1	6.4	40+	B	1
G681	3	*Quercus robur* English Oak	12.0	1	35	N 5.0 E 5.0 S 5.0 W 5.0	0.0	0.0	Early Mature	Good		55.4	4.2	40+	B	2
T682	1	*Acer pseudoplatanus* Sycamore	11.5	1	35	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Ivy or climbing plant.	55.4	4.2	40+	B	1
T683	1	*Fraxinus excelsior* Ash	9.5	1	35	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Poor	Access to inspect base - Not possible. Decline - Evident / observed. Ivy or climbing plant. Ash dieback.			0-10	U	
T684	1	*Fraxinus excelsior* Ash	9.5	1	25	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Poor	Access to inspect base - Not possible. Decline - Evident / observed. Ivy or climbing plant. Ash dieback.			0-10	U	
T685	1	*Acer pseudoplatanus* Sycamore	10.0	1	22	N 2.5 E 2.5 S 2.5 W 2.5	2.0	2.0	Early Mature	Fair	Access to inspect base - Not possible. Ivy or climbing plant.	21.9	2.6	10-20	C	1
T686	1	*Fraxinus excelsior* Ash	8.0	1	25	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Poor	Access to inspect base - Not possible. Decline - Evident / observed. Ivy or climbing plant. Ash dieback.			0-10	U	
T687	1	*Quercus robur* English Oak	9.0	1	17	N 4.0 E 4.0 S 5.0 W 4.0	2.0	2.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Ivy or climbing plant.	13.1	2.0	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T688	1	*Quercus robur* English Oak	9.5	1	67	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Deadwood - Minor. Ivy or climbing plant.	203.1	8.0	40+	B	1
T689	1	*Acer campestre* Field Maple	9.0	1	24	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Deadwood - Minor. Ivy or climbing plant.	26.1	2.9	40+	B	1
T690	1	*Fraxinus excelsior* Ash	9.5	1	25	N 4.5 E 4.5 S 4.5 W 4.5	4.0	4.0	Early Mature	Poor	Access to inspect base - Not possible. Decline - Evident / observed. Ivy or climbing plant. Ash dieback.			0-10	U	
T691	1	*Fraxinus excelsior* Ash	9.5	1	40	N 5.0 E 5.0 S 5.0 W 5.0	4.0	4.0	Early Mature	Poor	Access to inspect base - Not possible. Decline - Evident / observed. Ivy or climbing plant. Ash dieback.			0-10	U	
T692	1	*Crataegus monogyna* Common Hawthorn/Quick/May	9.5	1	30	N 3.0 E 3.0 S 3.0 W 3.0	4.0	4.0	Mature	Fair	Access to inspect base - Not possible. Competition - Adjacent trees. Ivy or climbing plant.	40.7	3.6	0-10	B	1
T693	1	*Acer campestre* Field Maple	10.5	1	40	N 4.5 E 4.5 S 4.5 W 4.5	4.0	4.0	Mature	Good	Access to inspect base - Not possible. Competition - Adjacent trees. Ivy or climbing plant. In group, at edge.	72.4	4.8	40+	B	1
T694	1	*Crataegus monogyna* Common Hawthorn/Quick/May	9.5	3	32	N 3.0 E 3.0 S 3.0 W 3.0	4.0	4.0	Mature	Fair	Access to inspect base - Not possible. Competition - Adjacent trees. Ivy or climbing plant.	46.4	3.8	40+	B	1
T695	1	*Acer campestre* Field Maple	10.5	1	55	N 5.5 E 5.5 S 5.5 W 5.5	4.0	4.0	Mature	Good	Access to inspect base - Not possible. Competition - Adjacent trees. In group, at edge.	136.8	6.6	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G696	15 10 10 5 5 5	*Crataegus monogyna* Common Hawthorn/Quick/May *other* Other *Quercus robur* English Oak *Acer campestre* Field Maple *Acer pseudoplatanus* Sycamore *Fraxinus excelsior* Ash	13.0	1	50	N 4.5 E 4.5 S 4.5 W 4.5	2.5	2.5	Early Mature	Good	Access to inspect base - Restricted / obscured. Ivy or climbing plant. Species count and composition are indicative only.	113.1	6.0	40+	B	2
H697	100 50 40 30 15	*Crataegus monogyna* Common Hawthorn/Quick/May *other* Other *Corylus avellana* Common Hazel *Prunus spinosa* Blackthorn/Sloe *Acer campestre* Field Maple	5.0	1	15	N 1.3 E 1.3 S 1.3 W 1.3	1.0	1.0	Mature	Fair	Hedgerow - Neglected / overgrown. Recently flail cut on west side. Species count and composition are indicative only.	10.2	1.8	20-40	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T698	1	*Acer pseudoplatanus* Sycamore	14.0	3	52	N 6.0 E 6.0 S 6.0 W 6.0	4.5	4.5	Early Mature	Good	Multi-stemmed.	124.4	6.3	20-40	C	1
T699	1	*Acer pseudoplatanus* Sycamore	14.0	6	73	N 8.0 E 8.0 S 8.0 W 8.0	4.5	4.5	Early Mature	Fair	Branch - Broken. Deadwood - Minor. Multi-stemmed.	244.3	8.8	10-20	C	1
T700	1	*Acer pseudoplatanus* Sycamore	12.0	1	53	N 7.0 E 7.0 S 7.0 W 7.0	4.5	4.5	Early Mature	Fair	Branch - Broken. Deadwood - Minor.	127.1	6.4	10-20	C	1
T701	1	*Acer pseudoplatanus* Sycamore	12.0	1	41	N 7.0 E 7.0 S 7.0 W 7.0	4.5	4.5	Early Mature	Good		76.0	4.9	20-40	B	1
T702	1	*Fraxinus excelsior* Ash	10.0	2	49	N 7.0 E 7.0 S 7.0 W 7.0	4.5	4.5	Early Mature	Fair	Ivy or climbing plant.	110.8	5.9	10-20	C	1
T703	1	*Acer pseudoplatanus* Sycamore	13.0	1	54	N 9.0 E 9.0 S 9.0 W 9.0	4.5	4.5	Early Mature	Good		131.9	6.5	20-40	B	1
T704	1	*Fraxinus excelsior* Ash	12.0	5	33	N 7.0 E 7.0 S 7.0 W 7.0	4.5	4.5	Early Mature	Poor	Decline - Suspected. Ash dieback.	50.9	4.0	0-10	C	1
T705	1	*Fraxinus excelsior* Ash	14.0	1	53	N 7.0 E 7.0 S 7.0 W 7.0	4.5	4.5	Early Mature	Fair	Decline - Suspected. Deadwood - Minor. Epicormic growth - Crown. Ash dieback.	127.1	6.4	0-10	C	1
T706	1	*Quercus robur* English Oak	14.0	1	72	N 7.0 E 5.0 S 2.0 W 5.0	4.0	4.0	Early Mature	Fair	Die-back - Upper crown. Deadwood - Major. Deadwood - Minor.	234.5	8.6	20-40	B	1
T707	1	*Quercus robur* English Oak	15.0	1	72	N 4.0 E 9.0 S 7.0 W 11.0	5.0	5.0	Early Mature	Fair	Branch - Broken. Competition - Adjacent trees. Deadwood - Minor.	234.5	8.6	20-40	B	1
T708	1	*Fraxinus excelsior* Ash	15.0	1	72	N 5.0 E 9.0 S 9.0 W 9.0	5.0	5.0	Early Mature	Fair	Competition - Adjacent trees. Decline - Suspected. Deadwood - Minor.	234.5	8.6	10-20	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T709	1	*Fraxinus excelsior* Ash	17.0	1	72	N E S W 5.0 8.0 8.0 8.0	5.0	5.0	Mature	Poor	Competition - Adjacent trees. Die-back - Throughout crown. Decline - Evident / observed.			0-10	U	
T710	1	*Fraxinus excelsior* Ash	15.0	1	65	N E S W 7.0 7.0 7.0 7.0	5.0	5.0	Early Mature	Fair	Access to inspect base - Not possible. Decline - Suspected. Deadwood - Minor.	191.1	7.8	10-20	C	1
H711	50 20 15 10	*Crataegus monogyna* Common Hawthorn/Quick/May *other* Other *Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel	5.0	1	15	N E S W 1.3 1.3 1.3 1.3	1.0	1.0	Mature	Fair	Hedgerow - Neglected / overgrown. Species count and composition are indicative only.	10.2	1.8	20-40	C	2
T712	1	*Fraxinus excelsior* Ash	18.0	1	85	N E S W 10.0 10.0 10.0 10.0	7.0	7.0	Mature	Poor	Access to inspect base - Restricted / obscured. Decline - Evident / observed. Ivy or climbing plant. Ash die back.			0-10	U	
T713	1	*Quercus robur* English Oak	18.0	1	88	N E S W 8.0 8.0 8.0 8.0	6.0	6.0	Mature	Good	Access to inspect base - Restricted / obscured. Deadwood - Major. Decay / structural defect - Extensive. Decay / structural defect - Open cavity / cavities. Habitat - High value. Ivy or climbing plant. Leaning trunk - Minor.	350.3	10.6	40+	B	1
T714	1	*Fraxinus excelsior* Ash	12.0	1	50	N E S W 6.0 6.0 6.0 6.0	4.0	4.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Decline - Evident / observed. Ivy or climbing plant. Ash die back.	113.1	6.0	0-10	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T715	1	*Fraxinus excelsior* Ash	10.0	2	46	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Decline - Evident / observed. Ivy or climbing plant. Ash die back.	96.1	5.5	0-10	C	1
T716	1	*Fraxinus excelsior* Ash	7.0	1	40	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Decline - Evident / observed. Ivy or climbing plant. Ash die back.			0-10	U	
T717	1	*Quercus robur* English Oak	9.0	1	60	N 6.0 E 6.0 S 6.0 W 6.0	2.5	2.5	Early Mature	Good	Deadwood - Minor. Ivy or climbing plant. Leaning trunk - Minor.	162.9	7.2	40+	B	1
T718	1	*Fraxinus excelsior* Ash	10.0	1	45	N 6.0 E 6.0 S 6.0 W 6.0	3.0	3.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Decline - Evident / observed. Ivy or climbing plant. Ash die back.			0-10	U	
T719	1	*Fraxinus excelsior* Ash	10.0	3	52	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Decline - Evident / observed. Ivy or climbing plant. Ash die back.			0-10	U	
T720	1	*Quercus robur* English Oak	10.0	2	113	N 7.0 E 7.0 S 7.0 W 7.0	3.0	3.0	Early Mature	Fair	Die-back - Throughout crown. Deadwood - Major. Deadwood - Minor. Habitat - High value. Leaning trunk - Minor.	582.3	13.6	40+	B	1
T721	1	*Quercus robur* English Oak	10.0	1	54	N 6.0 E 6.0 S 6.0 W 6.0	6.0	6.0	Early Mature	Good	Deadwood - Minor.	131.9	6.5	40+	B	1
T722	1	*Quercus robur* English Oak	10.0	1	54	N 7.5 E 7.5 S 7.5 W 7.5	3.0	3.0	Early Mature	Good	Deadwood - Minor. Ivy or climbing plant.	131.9	6.5	40+	B	1
T723	1	*Quercus robur* English Oak	12.0	4	88	N 9.0 E 9.0 S 9.0 W 9.0	3.0	3.0	Early Mature	Good	Deadwood - Minor. Multi-stemmed.	354.6	10.6	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T724	1	*Fraxinus excelsior* Ash	10.0	2	36	N E S W 5.0 5.0 5.0 5.0	3.0	3.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Decline - Evident / observed. Ivy or climbing plant. Ash die back.			0-10	U	
H725	150 50 50 40	*Crataegus monogyna* Common Hawthorn/Quick/May *other* Other *Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel	5.0	1	15	N E S W 1.3 1.3 1.3 1.3	1.0	1.0	Mature	Fair	Hedgerow - Neglected / overgrown. Species count and composition are indicative only.	10.2	1.8	20-40	C	2
T726	1	*Quercus robur* English Oak	13.0	1	60	N E S W 8.0 8.0 9.0 8.0	4.0	4.0	Early Mature	Good	Deadwood - Minor.	162.9	7.2	40+	B	1
T727	1	*Fraxinus excelsior* Ash	11.5	2	36	N E S W 5.0 5.0 6.5 5.0	3.0	3.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Decline - Evident / observed. Ivy or climbing plant. Ash die back.			0-10	U	
T728	1	*Quercus robur* English Oak	15.0	2	55	N E S W 8.0 8.0 9.0 8.0	4.0	4.0	Early Mature	Good	Deadwood - Minor. Stems - Sub-dominant.	141.6	6.7	40+	B	1
T729	1	*Quercus robur* English Oak	15.0	3	75	N E S W 8.0 8.0 8.0 8.0	3.0	3.0	Early Mature	Good	Deadwood - Minor. Multi-stemmed.	255.6	9.0	40+	B	1
T730	1	*Quercus robur* English Oak	13.0	1	37	N E S W 5.0 5.0 5.0 5.0	3.0	3.0	Early Mature	Good	Competition - Adjacent trees. Deadwood - Minor.	61.9	4.4	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T731	1	*Quercus robur* English Oak	17.5	1	98	N E S W 9.0 9.0 9.0 9.0	7.0	7.0	Early Mature	Good	Deadwood - Minor. Pruning wounds - Historic.	434.5	11.8	40+	A	1
T732	1	*Fraxinus excelsior* Ash	10.5	1	48	N E S W 8.0 8.0 8.0 8.0	6.5	6.5	Early Mature	Poor	Die-back - Throughout crown. Decline - Evident / observed. Ash die back.			0-10	U	
T733	1	*Quercus robur* English Oak	15.0	1	64	N E S W 9.0 9.0 9.0 9.0	4.0	4.0	Early Mature	Good	Deadwood - Minor.	185.3	7.7	40+	B	1
T734	1	*Quercus robur* English Oak	12.0	1	64	N E S W 6.0 7.0 7.0 7.0	1.0	1.0	Early Mature	Good	Deadwood - Major. Deadwood - Minor.	185.3	7.7	40+	B	1
T735	1	*Populus x canescens* Grey Poplar	21.0	1	180	N E S W 12.0 7.0 7.0 7.0	3.0	3.0	Early Mature	Fair	Deadwood - Major. Deadwood - Minor. Decay / structural defect - Extensive. Decay / structural defect - Major. Decay / structural defect - Open cavity / cavities. Old storm damage on secondary stem at 4m with major decay cavity and new 10m shoots.	706.9	15.0	20-40	B	1
H736	80 40 20 20	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *other* Other *Prunus spinosa* Blackthorn/Sloe	5.0	1	15	N E S W 1.3 1.3 1.3 1.3	1.0	1.0	Mature	Fair	Hedgerow - Neglected / overgrown. Species count and composition are indicative only.	10.2	1.8	20-40	C	2
G737	6	*Acer pseudoplatanus* Sycamore	9.5	1	25	N E S W 3.0 3.0 3.0 3.0	1.0	1.0	Early Mature	Good	Linear row spaced apart.	28.3	3.0	20-40	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T738	1	*Acer pseudoplatanus* Sycamore	13.0	1	45	N 6.0 E 6.0 S 6.0 W 6.0	3.0	3.0	Early Mature	Good	Typical tree within group.	91.6	5.4	40+	B	1
T739	1	*Quercus robur* English Oak	19.0	1	50	N 8.0 E 8.0 S 8.0 W 8.0	3.0	3.0	Early Mature	Good	Larger tree within group.	113.1	6.0	40+	B	1
T740	1	*Quercus robur* English Oak	17.0	1	50	N 8.5 E 8.5 S 8.5 W 8.5	3.0	3.0	Early Mature	Good	Larger tree within group.	113.1	6.0	40+	B	1
T741	1	*Quercus robur* English Oak	15.5	1	50	N 8.5 E 8.5 S 8.5 W 8.5	3.0	3.0	Early Mature	Good	Larger tree within group.	113.1	6.0	40+	B	1
T742	1	*Quercus robur* English Oak	17.0	1	50	N 7.0 E 7.0 S 7.0 W 7.0	3.0	3.0	Early Mature	Good	Larger tree within group.	113.1	6.0	40+	B	1
T743	1	*Picea sp.* Spruce sp.	13.0	1	35	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	First spruce of adjacent plantation.	55.4	4.2	10-20	B	1 2
T744	1	*Picea sp.* Spruce sp.	14.0	1	35	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good		55.4	4.2	10-20	B	2
T745	1	*Picea sp.* Spruce sp.	14.0	1	30	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	Last spruce of group.	40.7	3.6	10-20	B	2
T746	1	*Acer pseudoplatanus* Sycamore	14.0	6	48	N 5.0 E 5.0 S 5.0 W 5.0	3.5	3.5	Early Mature	Good		108.6	5.9	10-20	B	2
T747	1	*Quercus robur* English Oak	18.5	1	102	N 10.0 E 10.0 S 10.0 W 10.0	3.5	3.5	Early Mature	Good	Largest tree on edge of plantation.	470.7	12.2	40+	A	1
T748	1	*Quercus robur* English Oak	19.0	1	80	N 10.0 E 10.0 S 10.0 W 10.0	5.0	5.0	Mature	Good	Branch - Broken. Deadwood - Major. Deadwood - Minor.	289.5	9.6	40+	A	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T749	1	*Quercus robur* English Oak	18.5	1	102	N 10.0 E 10.0 S 10.0 W 10.0	3.5	3.5	Early Mature	Good	Largest tree on edge of plantation.	470.7	12.2	40+	B	1
H750	15 10 10 8	*Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel *Salix sp.* Willow sp. *Acer pseudoplatanus* Sycamore	5.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Fair	Species count and composition are indicative only.	4.5	1.2	20-40	C	2
T751	1	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	2	15	N 1.3 E 1.3 S 1.3 W 1.3	0.5	0.5	Early Mature	Good		11.0	1.9	20-40	C	1
H752	2	*Crataegus monogyna* Common Hawthorn/Quick/May	4.5	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Fair	Hedge remnant.	4.5	1.2	20-40	C	2
T753	1	*Alnus glutinosa* Common Alder	8.5	2	35	N 4.0 E 4.0 S 4.0 W 4.0	0.5	0.5	Early Mature	Good	Stems - Co-dominant.	56.5	4.2	20-40	B	1
T754	1	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	2	14	N 1.5 E 1.5 S 1.5 W 1.5	0.5	0.5	Early Mature	Good		9.0	1.7	20-40	C	1
H755	2	*Crataegus monogyna* Common Hawthorn/Quick/May	4.5	1	15	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Fair	Hedge remnant.	10.2	1.8	20-40	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T756	1	*Fraxinus excelsior* Ash	10.0	1	82	N E S W 0.5 0.5 0.5 5.0	5.0	5.0	Early Mature	Poor	Decline - Evident / observed. Decay / structural defect - Extensive. Decay / structural defect - Major. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Principal stems. Habitat - High value.	304.2	9.8	20-40	C	1
T757	1	*Quercus robur* English Oak	17.0	1	75	N E S W 5.5 5.5 5.5 5.5	3.0	3.0	Mature	Good	Access to inspect base - Restricted / obscured. Deadwood - Minor. Ivy or climbing plant. Located on East Bank of ditch.	254.5	9.0	40+	B	1
G758	20 20 10 10 5	*other* Other *Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash *Quercus robur* English Oak *Acer pseudoplatanus* Sycamore	15.0	1	50	N E S W 7.0 7.0 7.0 7.0	4.0	4.0	Early Mature	Good	Triangular copse of broadleaved trees. Species count and composition are indicative only.	113.1	6.0	40+	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T759	1	*Populus x canadensis* Hybrid Black Poplars	25.0	1	130	N 4.0 E 9.0 S 10.0 W 11.0	4.0	4.5	Mature	Fair	Branch - Broken. Branch - Suspended. Deadwood - Minor. Epicormic growth - Crown. Epicormic growth - Base / bole / principal stems. Form - Poor crown structure. Root damage - Mechanical. Shedding limb / limbs - Major. Storm damage. Large and spreading poplar which comprises a poor crown form owing to recent limb failures. Several large diameter subs remain with fractured ends. Crown heavily biased to the south. **Remove faulted limb / limbs.**	706.9	15.0	20-40	C	1
T760	1	*Populus x canadensis* Hybrid Black Poplars	25.0	1	110	N 12.0 E 13.0 S 5.0 W 12.0	4.0	1.5	Mature	Fair	Deadwood - Minor. Epicormic growth - Crown. Epicormic growth - Base / bole / principal stems. Root damage - Mechanical. Storm damage. Unbalanced crown - Major. Crown heavily biased to the north.	547.4	13.2	20-40	C	1
G761	7	*Populus x canadensis* Hybrid Black Poplars	20.0	1	115	N 8.0 E 8.0 S 8.0 W 8.0	4.0	5.0	Mature	Good	Base / stems obscured - Vegetation. Deadwood - Major. Deadwood - Minor. Ivy or climbing plant. No significant faults observed. Root environment - Compacted. Access track runs adjacent to the trees, beneath the eastern crown.	598.3	13.8	40+	B	2
T762	1	*Quercus robur* English Oak	13.0	1	80	N 7.0 E 6.5 S 6.0 W 7.0	2.0	2.5	Early Mature	Fair	Deadwood - Minor. Epicormic growth - Crown. Suppressed crown - Minor. Small and squat crown form. The tree is positioned along the boundary, set back from the access track by circa. 3m. Fungal fruiting body of assumed Laetiporous sulphureus at base, detached from tree.	289.5	9.6	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G763	60 50 25 10	*Acer pseudoplatanus* Sycamore *Betula pendula* Silver Birch *Fagus sylvatica* Common Beech *Quercus robur* English Oak	15.0	1	32	N E S W 4.0 4.0 4.0 4.0	1.0	2.0	Semi Mature	Good	Deadwood - Minor. No significant faults observed. Several dead trees noted amongst the group. Sycamore and ash are the principal upper canopy trees with an understory of small holly, elder and hawthorn. Measurements approximate only.	46.3	3.8	40+	B	2
T764	1	*Populus x canadensis* Hybrid Black Poplars	25.0	1	70	N E S W 10.0 10.0 9.0 11.0	6.0	6.0	Mature	Good	Access to inspect base - Restricted / obscured. Deadwood - Minor. Ivy or climbing plant. Storm damage. Access track at base, within 1m. Stem measured over dense ivy.	221.7	8.4	20-40	B	1
T765	1	*Quercus robur* English Oak	15.0	1	81	N E S W 11.0 10.0 8.0 7.0	2.0	2.5	Early Mature	Good	Deadwood - Minor. No obvious major defects observed. Small diameter deadwood throughout the crown. Access track runs south of the trees stem, within 2m.	296.8	9.7	40+	B	1
T766	1	*Quercus robur* English Oak	14.0	1	96	N E S W 9.0 9.0 9.0 8.0	1.0	4.0	Mature	Fair	Decay / structural defect in crown limb / limbs - Localised. Deadwood - Major. Deadwood - Minor. Epicormic growth - Crown. Form - Low canopy. Ivy or climbing plant. Root damage - Mechanical. Sparse crown on the south east aspect owing to previous branch failures with one large diameter dead branch partially failed and suspended in the crown, south at circa. 10m. Cultivated field to the north.	416.9	11.5	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T767	1	*Quercus robur* English Oak	10.0	1	78	N E S W 5.0 6.0 4.5 6.0	1.0	2.0	Mature	Fair	Die-back - Mid crown. Deadwood - Major. Deadwood - Minor. Epicormic growth - Crown. Fungal fruiting body - structural decay suspected. Root damage - Mechanical. Two fruiting bodies of Fistulina hepatica noted at base, south side of the tree. Large wound on the main stem at circa. 5m, extending to 6.5m, previous limb or stem failure.	275.2	9.4	20-40	B	1
T768	1	*Populus x canadensis* Hybrid Black Poplars	5.5	2	18	N E S W 2.5 2.5 2.5 2.5	0.0	1.0	Semi Mature	Fair	Multi-stemmed from base.	15.2	2.2	20-40	C	1
G769	50 25 25 20 5	*Fagus sylvatica* Common Beech *Acer pseudoplatanus* Sycamore *Fraxinus excelsior* Ash *Salix caprea* Goat Willow/Great Sallow *Betula pendula* Silver Birch	15.0	1	41	N E S W 4.0 4.0 4.0 4.0	2.0	1.5	Early Mature	Good	Landscape buffer group, situated along the boundary. Trees with tall and drawn forms and interlocking crowns.	76.0	4.9	40+	B	2
T770	1	*Quercus robur* English Oak	15.0	1	71	N E S W 8.0 8.0 8.0 8.0	4.0	6.5	Mature	Fair	Unable to gain access to measure, all measurements approximate only. No obvious defects from northern vantage point.	228.0	8.5	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G771	90 4 1	*Acer pseudoplatanus* Sycamore *Betula pendula* Silver Birch *Cerasus avium* Wild Cherry	16.0	1	41	N E S W 5.0 4.0 5.0 4.0	3.5	3.0	Early Mature	Good	Dead tree / trees. Dead trees noted in the group, with gaps of circa. 3-6m on average between trees. Group appears to have been recently thinned.	76.0	4.9	40+	B	2
H772	6 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	5.0	3	16	N E S W 1.5 0.5 1.5 0.5	0.0	0.5	Early Mature	Good		12.9	2.0	40+	C	2
T773	1	*Quercus robur* English Oak	6.0	1	44	N E S W 4.5 4.5 4.5 4.5	1.0	1.5	Semi Mature	Good	Access to inspect base - Not possible. Access to inspect base - Restricted / obscured. No significant faults observed.	87.6	5.3	40+	B	1
G774	10	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	3	13	N E S W 1.5 1.5 1.5 1.5	0.0	0.5	Early Mature	Good	Hedgerow - Neglected / overgrown. Gaps present along length.	7.9	1.6	40+	C	2
H775	15	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	3	15	N E S W 1.5 1.5 1.5 1.5	0.0	0.5	Early Mature	Good	Hedgerow - Maintained. Hedgerow - Neglected / overgrown. Outgrown hedge, gaps present.	11.0	1.9	40+	C	2
T776	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	4	17	N E S W 2.0 2.0 2.0 2.0	0.5	1.0	Early Mature	Good	Characteristic of the species.	13.6	2.1	20-40	C	1
T777	1	*Quercus robur* English Oak	7.0	1	31	N E S W 4.5 4.5 4.5 4.5	1.0	1.0	Semi Mature	Good		43.5	3.7	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T778	1	*Quercus robur* English Oak	6.0	1	28	N 3.0 E 4.0 S 4.0 W 3.0	1.0	1.0	Semi Mature	Good		35.5	3.4	40+	B	1
T779	1	*Quercus robur* English Oak	6.0	10	31	N 3.0 E 3.0 S 3.0 W 3.0	1.0	1.0	Semi Mature	Good		45.2	3.8	40+	B	1
G780	4	*Malus sp.* Apple sp.	4.0	3	19	N 3.0 E 3.0 S 3.0 W 3.0	0.5	0.5	Early Mature	Good	Characteristic of the species, small and squat crown forms.	17.6	2.4	20-40	B	2
G781	2 1	*Castanea sp.* Sweet Chestnut sp. *Quercus robur* English Oak	13.0	4	60	N 6.5 E 6.0 S 4.0 W 6.5	0.5	1.0	Mature	Good	Access to inspect base - Not possible. Access to inspect base - Restricted / obscured. Decay / structural defect - Bole. Epicormic growth - Base / bole / principal stems. Ivy or climbing plant. Multi-stemmed. Root damage - Mechanical. Coppiced form. Deep drainage ditch runs north of trees. **Reduce lateral limb / limbs.** Prune back c. 2 m from northern end. To facilitate development.	163.2	7.2	20-40	B	2
T782	1	*Fraxinus excelsior* Ash	11.0	8	84	N 6.0 E 6.0 S 6.0 W 6.0	2.0	1.0	Early Mature	Poor	Sparse and thinning crown, suspected ash dieback. Situated offsite. Separated from the site by deep drainage ditch.	325.7	10.2	10-20	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
W783	3 2 2 2 1 1 1	*Acer pseudoplatanus* Sycamore *Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash *Quercus robur* English Oak *Pinus sylvestris* Scots Pine *Sambucus sp.* Elder sp. *Betula pendula* Silver Birch	16.0	1	46	N 6.0 E 6.0 S 6.0 W 6.0	6.0	2.0	Early Mature	Good	Species count representative of a 25x25m area. Situated offsite, dense boundary woodland of mixed deciduous species. English elm and hawthorn formed understory tree cover. PROW bisects edge of woodland. Deep drainage ditch runs along southern edge of woodland.	95.7	5.5	40+	A	2 3
T784	1	*Crataegus monogyna* Common Hawthorn/Quick/May	8.0	6	56	N 4.0 E 4.0 S 4.0 W 4.0	0.0	0.5	Mature	Good	Situated offsite. Measurements approximate only.	143.6	6.8	20-40	B	1
T785	1	*Crataegus monogyna* Common Hawthorn/Quick/May	8.0	5	51	N 4.0 E 4.0 S 4.0 W 4.0	0.0	0.5	Mature	Good	Situated offsite. Measurements approximate only. Flail damaged crown.	119.7	6.2	20-40	B	1
T786	1	*Crataegus monogyna* Common Hawthorn/Quick/May	8.0	3	48	N 4.0 E 4.0 S 4.0 W 4.0	0.0	0.5	Mature	Good	Situated offsite. Measurements approximate only. Flail damaged crown. Possibly 2 trees.	105.4	5.8	20-40	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T787	1	*Fraxinus excelsior* Ash	12.0	1	70	N E S W 7.0 7.0 7.0 7.0	1.5	2.0	Mature	Fair	Access to inspect base - Not possible. Access to inspect base - Restricted / obscured. Deadwood - Minor. Epicormic growth - Crown. Root damage - Mechanical. Deep drainage ditch to the south, tree positioned on the edge of the bank.	221.7	8.4	20-40	B	1
W788	100 100 50 20 20 20 5 5	*Acer pseudoplatanus* Sycamore *Quercus robur* English Oak *Fraxinus excelsior* Ash *Corylus avellana* Common Hazel *Sambucus sp.* Elder sp. *Alnus glutinosa* Common Alder *Sorbus aria* Whitebeam *Salix caprea* Goat Willow/Great Sallow	12.0	1	28	N E S W 4.0 4.0 4.0 4.0	2.0	1.5	Early Mature	Good	Deadwood - Minor. Measurements averaged. Dense woodland buffer, trees planted at close spacing of circa. 3-4m. Etiolated forms, no obvious major defects. Numbers approximate.	35.5	3.4	40+	A	2
G789	15	*Alnus glutinosa* Common Alder	6.5	1	10	N E S W 2.5 2.5 2.5 2.5	1.0	1.0	Young	Good	Group of young alder along a ditch. Limited long-term value. Multi-stemmed from base.	4.5	1.2	20-40	C	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G790	50 20 20 20 10 10 5 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Acer pseudoplatanus* Sycamore *Corylus avellana* Common Hazel *Quercus robur* English Oak *Fraxinus excelsior* Ash *Cerasus avium* Wild Cherry *Alnus glutinosa* Common Alder *Salix caprea* Goat Willow/Great Sallow	14.0	1	21	N 3.5 E 3.5 S 3.0 W 3.0	0.5	1.0	Semi Mature	Good	Access to inspect base - Not possible. Access to inspect base - Restricted / obscured. Bark wound - Squirrel. Dead tree / trees. Epicormic growth - Crown. Ivy or climbing plant. Numbers approximate.	20.0	2.5	40+	B	2
T791	1	*Quercus petraea* Sessile Oak	6.0	1	34	N 3.0 E 4.5 S 5.0 W 3.0	2.0	1.7	Semi Mature	Good	Situated on the edge of a ditch.	52.3	4.1	40+	B	1
T792	1	*Quercus robur* English Oak	10.0	1	48	N 4.5 E 2.5 S 6.5 W 7.0	4.0	1.7	Early Mature	Good	Situated on the edge of a ditch. Asymmetrical crown form.	104.2	5.8	40+	B	1
T793	1	*Quercus robur* English Oak	8.0	1	30	N 5.5 E 2.0 S 5.5 W 2.0	4.0	2.0	Semi Mature	Good	Situated on the edge of a ditch.	40.7	3.6	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T794	1	*Quercus robur* English Oak	8.0	1	40	N E S W 5.0 5.0 5.0 2.0	4.0	1.5	Early Mature	Good		72.4	4.8	40+	B	1
T795	1	*Quercus robur* English Oak	9.5	1	60	N E S W 6.5 6.5 6.5 6.5	3.5	1.5	Early Mature	Good	Situated on the edge of a ditch. No obvious major defects.	162.9	7.2	40+	B	1
T796	1	*Quercus robur* English Oak	5.0	1	30	N E S W 3.0 3.0 3.0 1.5	2.0	1.0	Semi Mature	Fair	Suppressed crown - Major. Stem measurement approximated due to step bank.	40.7	3.6	20-40	C	1
G797	2 1	*Quercus robur* English Oak *Acer campestre* Field Maple	9.5	1	34	N E S W 5.0 5.0 5.0 5.0	3.0	1.5	Semi Mature	Good	3 trees positioned along the edge of a ditch. Trees formed with a cohesive crown.	52.3	4.1	40+	B	2
G798	11 4 2	*Quercus robur* English Oak *Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May	10.5	1	30	N E S W 3.5 3.5 3.5 3.5	4.0	2.0	Semi Mature	Good	Average crown and stem recorded. Smaller trees form a dense understory which has been managed by a flail to form a more formal hedge.	40.7	3.6	40+	B	2
G799	4 2 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Alnus glutinosa* Common Alder *Quercus robur* English Oak	10.0	3	48	N E S W 4.0 4.0 4.0 4.0	2.0	1.5	Early Mature	Good	Situated offsite. Measurements approximate only.	105.1	5.8	20-40	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T800	1	*Crataegus monogyna* Common Hawthorn/Quick/May	7.0	5	29	N E S W 3.0 1.5 4.0 1.0	0.5	0.5	Mature	Good	Situated off site, measurements approximated. Flail damage evident on western crown.	38.6	3.5	40+	C	1
G801	3 1 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple *Sambucus sp.* Elder sp.	8.0	3	25	N E S W 4.5 2.0 4.0 1.0	0.5	0.5	Early Mature	Good	Unmanaged hedge, situated off site, measurements approximated.	29.1	3.0	20-40	C	2
T802	1	*Alnus glutinosa* Common Alder	9.0	9	84	N E S W 4.0 4.0 4.0 4.0	5.0	2.0	Mature	Good	Coppiced form. The tree is situated on the bank of a field boundary ditch. Measurements approximated. Flail damage noted on western crown.	319.2	10.1	20-40	B	1
G803	4	*Crataegus monogyna* Common Hawthorn/Quick/May	9.5	7	74	N E S W 3.5 3.5 3.5 3.5	0.0	1.0	Mature	Good	Situated off site, not a constraint to development.	248.3	8.9	20-40	B	2
G804	4 2 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Quercus robur* English Oak *Acer campestre* Field Maple	10.0	1	45	N E S W 4.0 5.5 3.0 5.5	5.0	2.0	Early Mature	Good	Understory of hazel. Situated off site. Unable to measure accurately due to deep field boundary ditch.	91.6	5.4	20-40	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G805	1 1	*Alnus glutinosa* Common Alder *Crataegus monogyna* Common Hawthorn/Quick/May	8.5	3	45	N E S W 3.0 2.0 2.0 1.0	5.0	1.0	Mature	Good	Situated off site. Outgrown hedge. Separated from the site by a deep boundary ditch.	92.0	5.4	20-40	B	2
T806	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	3	49	N E S W 4.0 4.0 4.0 4.0	3.0	1.0	Mature	Good		112.4	6.0	20-40	B	1
G807	1 1 1 1 1	*Acer campestre* Field Maple *Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash *Quercus robur* English Oak	10.5	6	24	N E S W 3.0 3.0 3.0 3.0	5.0	0.5	Early Mature	Good	Off site tree group/partially managed hedge.	27.1	2.9	40+	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G808	1 1 1 1 1	*Acer campestre* Field Maple *Crataegus monogyna* Common Hawthorn/Quick/May *Ilex aquifolium* Holly *Quercus robur* English Oak *Sambucus sp.* Elder sp.	10.5	1	30	N 4.5 E 4.5 S 4.5 W 4.5	4.0	1.5	Early Mature	Good	Average measurements given. Gaps present along length.	40.7	3.6	40+	B	2
T809	1	*Fraxinus excelsior* Ash	12.0	7	79	N 6.0 E 6.0 S 6.0 W 6.0	5.0	2.0	Early Mature	Fair	Situated off site, unable to gain access. Sparse and thinning crown, due back at branch extremities. Ditch adjacent to the tree.	285.0	9.5	20-40	C	1
T810	1	*Alnus glutinosa* Common Alder	10.0	11	96	N 6.0 E 6.0 S 6.0 W 6.0	4.5	0.5	Mature	Good	Situated off site. Measurements approximate only.	418.5	11.5	40+	B	1
G811	10 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus sp.* Elder sp.	7.0	1	15	N 3.0 E 3.0 S 3.0 W 3.0	4.0	0.5	Mature	Good	Unmaintained hedge.	10.2	1.8	40+	C	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G812	5 5 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash *Quercus robur* English Oak	13.5	2	57	N E S W 5.5 5.5 5.5 5.5	5.0	1.0	Early Mature	Good	Situated off site, measurements given as an average. Deep boundary ditch runs west of trees. Ash and oak form upper canopy. The trees are multi-stemmed from base.	147.0	6.8	20-40	B	2
G813	15 5 5 2 1 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash *Quercus robur* English Oak *Acer campestre* Field Maple *Salix sp.* Willow sp. *Sambucus sp.* Elder sp.	12.0	1	30	N E S W 4.0 4.0 4.0 4.0	4.0	1.5	Early Mature	Good	The tree group is not a continuous line of trees and has gaps present along is length. The trees are separated from the site by a deep boundary ditch. No real constraint to development. Numbers approximate.	40.7	3.6	40+	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G814	80 30 30 20 20 10 10 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Fagus sylvatica* Common Beech *Acer pseudoplatanus* Sycamore *Fraxinus excelsior* Ash *Betula pendula* Silver Birch *Laurocerasus officinalis* Cherry Laurel *Sambucus sp.* Elder sp. *Larix decidua* European Larch/Common Larch	17.0	1	44	N E S W 5.0 5.0 5.0 5.0	4.0	3.0	Early Mature	Good	Access to inspect base - Not possible. Access to inspect base - Restricted / obscured. Deadwood - Minor. Epicormic growth - Crown. Ivy or climbing plant. Average stem of the larger trees given. Dense trees group situated off site. Tree crowns overhang the access road. Numbers approximate.	87.6	5.3	40+	A	2
G815	25 10 5	*Fraxinus excelsior* Ash *Corylus avellana* Common Hazel *Quercus robur* English Oak	11.0	1	32	N E S W 3.5 3.5 3.5 3.5	4.0	1.0	Semi Mature	Good	Roadside trees. Etiolated forms. Numbers approximate.	46.3	3.8	20-40	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G816	60	*Populus nigra 'Italica'* Lomardy Poplar	20.0	1	40	N 2.5 E 2.5 S 2.5 W 2.5	1.0	1.5	Early Mature	Good	Double planned row of Lombardy poplar, positioned along the road and field edge. Trees uniformly spaced. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	72.4	4.8	20-40	B	2
T817	1	*Fraxinus excelsior* Ash	13.0	1	75	N 6.5 E 4.0 S 7.0 W 7.0	5.0	3.0	Mature	Fair	Access to inspect base - Restricted / obscured. Branch - Suspended. Bark wound - Minor. Die-back - Throughout crown. Decay / structural defect in crown limb / limbs - Localised. Decay / structural defect - Open cavity / cavities. Epicormic growth - Bole / principal stems. Root damage - Mechanical. Storm damage. Several fruiting bodies of Inonotus hispidus on the main stem, North, at circa. 3-4m.	254.5	9.0	20-40	C	1
T818	1	*Quercus robur* English Oak	9.5	1	51	N 4.5 E 4.5 S 4.5 W 4.5	1.0	3.0	Early Mature	Good	Decay / structural defect in crown limb / limbs - Minor. Deadwood - Minor. Root damage - Mechanical.	117.7	6.1	40+	B	1
T819	1	*Prunus spinosa* Blackthorn/Sloe	5.0	9	27	N 2.5 E 2.0 S 2.0 W 2.0	0.0	0.5	Early Mature	Good	Multi-stemmed tree.	33.0	3.2	20-40	C	1
T820	1	*Fraxinus excelsior* Ash	10.0	1	45	N 4.5 E 4.5 S 4.5 W 4.5	1.0	2.0	Early Mature	Fair	Access to inspect base - Not possible. Access to inspect base - Restricted / obscured. Die-back - Upper crown. Decay / structural defect in crown limb / limbs - Minor. Deadwood - Major. Epicormic growth - Crown. Root damage - Mechanical.	91.6	5.4	20-40	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T821	1	*Fraxinus excelsior* Ash	10.0	3	38	N E S W 4.5 4.5 4.5 4.5	1.5	1.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Root damage - Mechanical.	66.3	4.6	20-40	C	1
T822	1	*Quercus robur* English Oak	9.0	2	36	N E S W 4.0 4.0 4.0 4.0	1.0	1.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Root damage - Mechanical. Downgraded to a category C as unable to assess the lower stem and base.	59.0	4.3	20-40	C	1
T823	1	*Fraxinus excelsior* Ash	10.0	6	36	N E S W 4.0 4.0 4.0 4.0	1.5	1.5	Semi Mature	Good	Base / stems obscured - Vegetation. Root damage - Mechanical. Multi-stemmed from base.	61.1	4.4	20-40	C	1
T824	1	*Fraxinus excelsior* Ash	14.0	5	55	N E S W 6.0 6.0 6.0 6.0	2.0	2.5	Early Mature	Good	Base / stems obscured - Vegetation. Root damage - Mechanical. Measurements approximated.	139.8	6.7	20-40	C	1
G825	20 10 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Quercus robur* English Oak *Salix caprea* Goat Willow/Great Sallow	9.0	1	26	N E S W 4.0 4.0 4.0 4.0	1.0	1.5	Semi Mature	Good	Base / stems obscured - Vegetation. Hedgerow - Neglected / overgrown. Root damage - Mechanical. Stem measurements given as an average. Numbers approximate.	30.6	3.1	20-40	C	2
G826	30 7	*Prunus spinosa* Blackthorn/Sloe *Fraxinus excelsior* Ash	10.0	1	22	N E S W 3.0 3.0 3.0 3.0	0.5	0.5	Semi Mature	Good	Good landscape buffer value. Predominantly blackthorn.	21.9	2.6	40+	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T827	1	*Fraxinus excelsior* Ash	12.0	1	50	N E S W 6.0 6.0 6.0 6.0	2.0	2.0	Early Mature	Good	Access to inspect base - Not possible. Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Deadwood - Minor. Root damage - Mechanical. Stem completely obscured, possibly multiple stems.	113.1	6.0	40+	B	1
T828	1	*Acer campestre* Field Maple	10.0	10	72	N E S W 5.0 5.0 5.0 5.0	0.0	0.5	Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Root damage - Mechanical. Coppiced form. Possible bundle planting.	239.3	8.7	40+	B	1
T829	1	*Acer pseudoplatanus* Sycamore	9.0	8	39	N E S W 3.0 3.0 3.0 3.0	0.0	0.5	Semi Mature	Good		70.9	4.8	20-40	C	1
T830	1	*Acer pseudoplatanus* Sycamore	9.0	8	39	N E S W 3.0 3.0 3.0 3.0	0.0	0.5	Semi Mature	Good		70.9	4.8	20-40	C	1
T831	1	*Acer pseudoplatanus* Sycamore	8.0	4	37	N E S W 3.0 3.0 3.0 3.0	0.0	0.5	Semi Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Root damage - Mechanical.	64.8	4.5	20-40	C	1
H832	20 20	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	3.0	1	80	N E S W 2.0 1.0 2.0 1.0	0.0	0.5	Early Mature	Good	Hedgerow - Neglected / overgrown. Gaps present along the boundary.	289.5	9.6	40+	C	2
T833	1	*Corylus avellana* Common Hazel	4.0	10	15	N E S W 2.5 2.5 2.5 2.5	0.0	0.5	Early Mature	Good		11.3	1.9	40+	C	1
T834	1	*Corylus avellana* Common Hazel	4.0	10	15	N E S W 2.5 2.5 2.5 2.5	0.0	0.5	Early Mature	Good		11.3	1.9	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T835	1	*Corylus avellana* Common Hazel	4.0	10	15	N E S W 2.5 2.5 2.5 2.5	0.0	0.5	Early Mature	Good		11.3	1.9	40+	C	1
T836	1	*Corylus avellana* Common Hazel	4.0	10	15	N E S W 2.5 2.5 2.5 2.5	0.0	0.5	Early Mature	Good		11.3	1.9	40+	C	1
T837	1	*Acer pseudoplatanus* Sycamore	8.5	3	19	N E S W 3.5 3.5 3.5 3.5	1.0	0.5	Semi Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Root damage - Mechanical. **Fell - Ground level.** To facilitate development.	16.5	2.3	20-40	C	1
T838	1	*Quercus robur* English Oak	11.0	5	54	N E S W 5.5 5.5 5.5 5.5	1.0	1.5	Semi Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Epicormic growth - Crown. Root damage - Mechanical. Multi-stemmed from base.	132.6	6.5	40+	B	1
G839	1 1 1	*Corylus avellana* Common Hazel *Quercus robur* English Oak *Salix x blanda* Willow sp.	7.0	11	19	N E S W 2.0 2.0 2.0 2.0	0.0	0.5	Semi Mature	Good	Multi-stemmed. Root damage - Mechanical.	17.9	2.4	20-40	C	2
T840	1	*Quercus robur* English Oak	7.0	1	31	N E S W 4.5 4.5 4.5 4.5	1.0	2.0	Semi Mature	Good		43.5	3.7	40+	B	1
T841	1	*Prunus spinosa* Blackthorn/Sloe	3.5	9	15	N E S W 1.5 1.5 1.5 1.5	0.0	0.5	Early Mature	Good		10.2	1.8	20-40	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T842	1	*Quercus robur* English Oak	14.0	3	73	N E S W 6.0 6.0 6.0 6.0	2.5	1.5	Early Mature	Good	Access to inspect base - Restricted / obscured. Multi-stemmed. No significant faults observed. Root damage - Mechanical.	243.8	8.8	40+	B	1
H938	30 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus sp.* Elder sp.	3.5	8	25	N E S W 2.0 2.0 2.0 2.0	0.5	0.5	Mature	Good	Hedgerow - Maintained. Multi-stemmed. Characteristic of the species. Gaps present along the length of the boundary. Numbers approximate.	29.3	3.1	40+	C	2
G939	30 15 7 1 1	*Quercus robur* English Oak *Acer pseudoplatanus* Sycamore *Fraxinus excelsior* Ash *Pinus sylvestris* Scots Pine *Quercus cerris* Turkey Oak	16.0	1	45	N E S W 4.0 4.0 4.0 4.0	2.0	2.5	Early Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Branch - Broken. Die-back - Upper crown. Decay entry points. Dead tree / trees. Deadwood - Major. Deadwood - Minor. Oak and ash form the upper canopy tree cover with a hawthorn and blackthorn hedge positioned along the woodland edge. Larger trees set back circa. 4-5m from the field margin. Several dead/during an noted towards the southern end of the group.	91.6	5.4	40+	B	2
T940	1	*Quercus robur* English Oak	14.0	1	83	N E S W 8.5 5.5 8.5 8.5	5.0	6.0	Mature	Good	Positioned on the southern edge of a field boundary ditch.	311.7	10.0	40+	A	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T941	1	*Quercus robur* English Oak	9.0	1	80	N 5.0 E 5.0 S 5.5 W 6.0	3.5	3.0	Early Mature	Fair	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Die-back - Upper crown. Deadwood - Minor. Epicormic growth - Crown. Epicormic growth - Bole / principal stems. Form - Small sail area / crown extent. Ivy or climbing plant. No significant faults observed.	289.5	9.6	40+	B	1
T942	1	*Quercus robur* English Oak	11.0	1	71	N 8.0 E 8.0 S 8.0 W 8.0	3.5	2.5	Mature	Good	Deadwood - Minor. Epicormic growth - Crown. No significant faults observed. Root environment - Compacted. Farm access track to the south, within 2m.	228.0	8.5	40+	A	1
T943	1	*Quercus robur* English Oak	14.0	1	90	N 8.0 E 8.5 S 6.0 W 7.5	2.0	4.5	Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Die-back - Upper crown. Deadwood - Minor. Epicormic growth - Crown. No significant faults observed. Root environment - Compacted. Access track to the south, within 3m.	366.4	10.8	40+	A	1
T944	1	*Quercus robur* English Oak	16.0	1	101	N 8.5 E 8.5 S 8.5 W 8.5	3.0	4.0	Mature	Good	Deadwood - Minor. No significant faults observed. Situated on the western bank of the ditch.	461.5	12.1	40+	A	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T945	1	*Quercus robur* English Oak	13.0	1	90	N E S W 5.0 5.0 7.0 7.5	1.0	3.0	Mature	Fair	Bark wound - Major. Die-back - Upper crown. Deadwood - Major. Decay / structural defect - Major. Fungal fruiting body - structural decay suspected. Hollow trunk - Open cavity. Lightning damage. Root damage - Mechanical. Ditch at base to the east. Seam of exposed heartwood runs down the entire length of the main stem, east side. Laetiporous sulphureus fruiting bodies at base. Hollowing stem evident from loose bark and open and exposed cavity. Veteran features, possible future candidate.	366.4	10.8	20-40	B	1 3
T946	1	*Quercus robur* English Oak	15.0	1	100	N E S W 9.0 9.0 9.0 9.0	2.5	4.0	Mature	Good	Bark wound - Minor. Deadwood - Major. Deadwood - Minor. Decay / structural defect - Minor. Decay / structural defect - Bole. Epicormic growth - Crown. Pruning wounds - Historic. Root damage - Mechanical. Bird box on main stem at circa. 4m, south east facing	452.4	12.0	40+	A	1
T947	1	*Quercus robur* English Oak	17.0	1	134	N E S W 9.0 10.0 8.5 6.5	5.5	5.0	Ancient or Veteran	Fair	Bark wound - Major. Decay / structural defect in crown limb / limbs - Major. Deadwood - Major. Deadwood - Minor. Decay / structural defect - Localised. Epicormic growth - Crown. Epicormic growth - Bole / principal stems. Lightning damage. Root damage - Mechanical. Large isolated oak part of a row of field boundary oak trees. Western crown almost entirely devoid of live crown growth, worth the principal stems and crown framework dead. Assumed lightning damage. Small Fistulina hepatica fungus at base, west side. Lower crown epicormic growth forming.	706.9	15.0	40+	A	1 3

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T948	1	*Quercus robur* English Oak	16.0	1	114	N E S W 8.0 9.0 9.0 7.0	4.5	3.0	Late Mature	Good	Decay / structural defect in crown limb / limbs - Localised. Deadwood - Major. Deadwood - Minor. Decay / structural defect - Principal stems. No significant faults observed. Access track runs south of the tree within 3m of the base.	587.9	13.7	40+	A	1
T949	1	*Quercus robur* English Oak	16.0	1	119	N E S W 6.0 8.0 8.0 8.0	3.0	3.0	Late Mature	Fair	Bark wound - Major. Decay / structural defect in crown limb / limbs - Open cavity / cavities. Deadwood - Major. Deadwood - Minor. Decay / structural defect - Base. Decay / structural defect - Major. Decay / structural defect - Principal stems. Decay / structural defect - Bole. Lightning damage. Root environment - Compacted. Assumed lightning strike damage with am area of decayed and exposed heartwood spanning the length of the main stem from circa. 11m to ground level. Dense epicormic growth has formed in the lower crown. Fruiting body at base, west, assumed Chicken of the Woods. Potential veteran tree.	640.6	14.3	40+	A	1 3
T950	1	*Quercus robur* English Oak	15.0	1	101	N E S W 8.0 10.0 10.0 10.0	5.0	4.0	Mature	Good	Deadwood - Major. Deadwood - Minor. Decay / structural defect - Localised. Decay / structural defect - Bole. Epicormic growth - Crown. No significant faults observed. Root environment - Compacted.	461.5	12.1	40+	A	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T951	1	*Quercus robur* English Oak	10.0	1	85	N E S W 6.0 6.0 6.0 3.0	3.0	2.0	Mature	Fair	Base / stems obscured - Vegetation. Bark wound - Minor. Decay / structural defect - Base. Decay / structural defect - Localised. Form - Small sail area / crown extent. Elder at base. Branch socket cavity on the south east side of the main stem, circa. 3m above ground level.	326.9	10.2	40+	B	1
T952	1	*Quercus robur* English Oak	10.0	1	110	N E S W 3.0 3.0 5.0 5.0	4.0	1.5	Late Mature	Fair	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Deadwood - Major. Deadwood - Minor. Epicormic growth - Crown. Epicormic growth - Base / bole / principal stems. Form - Small sail area / crown extent. Root damage - Mechanical. Stem heavily burred.	547.4	13.2	40+	A	1 3
T953	1	*Quercus robur* English Oak	16.0	1	102	N E S W 10.0 10.0 10.0 10.0	5.0	3.5	Late Mature	Good	Access to inspect base - Not possible. Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Decay / structural defect in crown limb / limbs - Localised. Deadwood - Major. Deadwood - Minor. Epicormic growth - Crown. No significant faults observed. Root damage - Mechanical. Close cultivation of the soil. Situated 2m from field edge.	470.7	12.2	40+	A	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T954	1	*Quercus robur* English Oak	15.0	1	110	N 10.0 E 10.0 S 10.0 W 10.0	5.0	3.0	Late Mature	Good	Access to inspect base - Not possible. Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Decay / structural defect in crown limb / limbs - Localised. Deadwood - Major. Deadwood - Minor. Epicormic growth - Crown. No significant faults observed. Root damage - Mechanical. Close cultivation of the soil. Situated 2m from field edge.	547.4	13.2	40+	A	1
T955	1	*Quercus robur* English Oak	16.0	1	130	N 8.0 E 9.0 S 8.0 W 10.0	5.0	5.0	Late Mature	Good	Access to inspect base - Not possible. Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Decay / structural defect in crown limb / limbs - Localised. Deadwood - Major. Deadwood - Minor. Epicormic growth - Crown. No significant faults observed. Pruning wounds - Historic. Root damage - Mechanical. Close cultivation of the soil. Situated 2m from field edge.	706.9	15.0	40+	A	1
T956	1	*Quercus robur* English Oak	15.0	1	95	N 8.0 E 8.0 S 9.0 W 6.0	5.0	5.0	Mature	Good	Access to inspect base - Not possible. Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Decay / structural defect in crown limb / limbs - Localised. Deadwood - Minor. Epicormic growth - Crown. No significant faults observed. Root damage - Mechanical. Close cultivation of the soil. Situated 2m from field edge.	408.3	11.4	40+	A	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G957	50 40 35 25	*Acer pseudoplatanus* Sycamore *Cerasus avium* Wild Cherry *Fagus sylvatica* Common Beech *Castanea sp.* Sweet Chestnut sp.	13.5	1	30	N E S W 3.5 3.5 3.5 3.5	2.0	1.5	Semi Mature	Good	Average stem and crown spread given. Situated offsite, all measurements approximated. Trees spaced at 3-4m intervals.	40.7	3.6	40+	B	2
H958	5	*Prunus spinosa* Blackthorn/Sloe	3.0	3	8	N E S W 1.0 1.0 1.0 1.0	0.0	0.5	Early Mature	Good	Hedgerow - Maintained.	3.0	1.0	20-40	C	2
H959	10 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	4.0	1	6	N E S W 1.5 1.5 1.5 1.5	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Numbers approximate.	1.6	0.7	40+	C	2
H960	50 10 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple *Sambucus sp.* Elder sp.	3.5	1	8	N E S W 1.5 1.5 1.5 1.5	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Average stem given. Ditch at base. Gaps present along the length of the boundary. **Fell - Ground level.** Remove a 4-m span. To facilitate development.	2.9	1.0	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T961	1	*Quercus robur* English Oak	20.0	1	140	N E S W 8.5 8.5 8.5 8.5	4.0	1.5	Late Mature	Good	Deadwood - Minor. Epicormic growth - Crown. Epicormic growth - Bole / principal stems. Fungal fruiting body - structural decay suspected. Two small Fistulina hepatica fungus fruiting bodies at base, east side. Close cultivation of the soil.	706.9	15.0	40+	A	1 3
T1012	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	5	55	N E S W 4.0 2.0 4.0 2.0	0.0	1.0	Mature	Fair	Die-back - Upper crown.	141.4	6.7	40+	C	1
T1013	1	*Quercus robur* English Oak	13.0	1	78	N E S W 8.0 6.0 9.0 7.0	0.0	2.5	Mature	Good	Epicormic growth - Base / bole / principal stems.	275.2	9.4	40+	B	1
H1014	15 1	*Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel	4.0	2	16	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Early Mature	Good	Hedge remnant.	13.0	2.0	40+	C	2
T1015	1	*Fraxinus excelsior* Ash	12.0	3	63	N E S W 6.0 3.0 6.0 6.0	0.5	2.0	Early Mature	Fair	Growing on west bank of ditch. Chalara (ash dieback) present. Minor symptoms.	183.3	7.6	20-40	C	1
T1016	1	*Fraxinus excelsior* Ash	13.0	6	73	NW NE SE SW 6.0 6.0 5.0 6.0	0.0	0.5	Early Mature	Fair	Coppice stool - Coppice origin / Mature stems. Ownership uncertain. Chalara (ash dieback) present. Minor symptoms.	244.3	8.8	20-40	C	1
T1017	1	*Quercus robur* English Oak	14.0	1	84	N E S W 6.0 9.0 5.0 9.0	1.0	1.5	Early Mature	Good	Branch - Broken. Pruned back on site side.	319.2	10.1	40+	B	1
T1018	1	*Alnus glutinosa* Common Alder	5.0	1	15	N E S W 1.0 4.0 1.0 1.0	0.0	1.0	Semi Mature	Fair	Fire damage - Base / bole / principal stems. Suppressed crown - Major.	10.2	1.8	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1019	1	*Quercus robur* English Oak	9.0	1	57	NW 4.0 NE 4.0 SE 5.0 SW 6.0	0.5	2.0	Early Mature	Fair	Deadwood - Minor. Decay / structural defect - Bole. Epicormic growth - Base / bole / principal stems. Hollow trunk - Open cavity. Leader lost historically. Squat form. Formerly twin-stemmed; smaller stem long dead. Sparse upper crown. Veteran features.	147.0	6.8	20-40	B	1 3
T1020	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	35	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.5	Mature	Good	Ownership uncertain.	55.4	4.2	40+	C	1
T1021	1	*Corylus avellana* Common Hazel	4.0	20	22	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Semi Mature	Good	Coppice stool - Coppice origin / Mature stems. Ownership uncertain.	22.6	2.7	40+	C	1
G1022	2 1 1	*Acer campestre* Field Maple *Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May	13.0	2	49	N 4.0 E 4.0 S 4.0 W 4.0	0.0	1.0	Early Mature	Good	Measurements represent average for larger trees in group. Blackthorn understorey.	110.8	5.9	40+	B	2
T1023	1	*Quercus robur* English Oak	13.0	1	56	N 6.0 E 6.0 S 6.0 W 6.0	1.0	2.0	Early Mature	Good	Growing on east bank of dry ditch. Ownership uncertain.	141.9	6.7	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1024	5 4 2 2 2 1 1	*Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder *Prunus spinosa* Blackthorn/Sloe *Salix caprea* Goat Willow/Great Sallow *Quercus robur* English Oak *Ulmus glabra* Wych Elm	7.0	1	30	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Mature	Fair	Old neglected hedge. Stems on east bank or within dry ditch. Numbers approximate.	40.7	3.6	40+	B	2
T1025	1	*Quercus robur* English Oak	13.0	3	68	NW 6.0 NE 7.0 SE 4.0 SW 6.0	1.0	2.5	Early Mature	Good	Access to inspect base - Not possible. Growing on east bank of dry ditch. Ownership uncertain.	212.4	8.2	40+	B	1
T1026	1	*Quercus robur* English Oak	13.0	2	67	NW 4.0 NE 9.0 SE 7.0 SW 6.0	1.0	2.2	Early Mature	Good	Access to inspect base - Not possible. Ivy or climbing plant. Growing on east bank of dry ditch. Ownership uncertain.	204.7	8.1	40+	B	1
T1027	1	*Fraxinus excelsior* Ash	15.0	1	54	NW 6.0 NE 5.0 SE 8.0 SW 5.0	3.0	2.5	Early Mature	Poor	Die-back - Throughout crown. Chalara (ash dieback) present. Severe symptoms. Mature epicormic stem from base.	131.9	6.5	10-20	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1028	1	*Quercus robur* English Oak	9.0	1	30	NW 5.0 NE 2.0 SE 5.0 SW 6.0	0.0	1.0	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Squat form. Part of probably remnant hedge on small mound.	40.7	3.6	40+	B	1
T1029	1	*Quercus robur* English Oak	9.0	2	50	NW 5.0 NE 2.0 SE 5.0 SW 2.0	0.0	1.0	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Squat form. Part of probably remnant hedge on small mound.	113.1	6.0	40+	B	1
T1030	1	*Quercus robur* English Oak	9.0	1	42	NW 5.0 NE 5.0 SE 5.0 SW 2.0	0.0	1.0	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Squat form. Part of probably remnant hedge on small mound.	79.8	5.0	40+	B	1
T1031	1	*Corylus avellana* Common Hazel	4.0	20	13	NW 3.0 NE 4.0 SE 3.0 SW 2.0	0.0	0.0	Early Mature	Good	Coppice stool - Regrown. Part of probably remnant hedge on small mound.	8.1	1.6	40+	C	1 2
H1032	2 1 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Sambucus nigra* Elder	4.0	2	25	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Early Mature	Fair	Hedge remnant.	28.3	3.0	20-40	C	1
T1033	1	*Quercus robur* English Oak	10.0	1	52	N 4.0 E 6.0 S 5.0 W 5.0	0.5	2.5	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Growing on north bank of ditch. Slightly sparse crown.	122.3	6.2	40+	B	1
T1034	1	*Quercus robur* English Oak	5.0	1	55	N 3.0 E 6.0 S 3.0 W 6.0	0.5	0.5	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Growing on north bank of ditch. Two large boughs have failed. Squat form.	136.8	6.6	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1035	1	*Quercus robur* English Oak	9.0	1	65	N E S W 4.0 5.0 6.0 5.0	0.0	1.5	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Growing on north bank of ditch. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	191.1	7.8	40+	B	1
T1036	1	*Fraxinus excelsior* Ash	12.0	1	45	N E S W 5.0 5.0 6.0 5.0	0.0	2.0	Early Mature	Fair	Die-back - Upper crown. Epicormic growth - Base / bole / principal stems. Chalara (ash dieback) present. Moderate symptoms. Mature epicormic stems from base. Growing on north bank of ditch.	91.6	5.4	10-20	C	1
G1037	2	*Corylus avellana* Common Hazel	4.0	1	15	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Semi Mature	Good	Coppice stool - Regrown.	10.2	1.8	40+	C	1
T1038	1	*Fraxinus excelsior* Ash	12.0	5	55	N E S W 6.0 5.0 5.0 5.0	2.0	3.0	Early Mature	Fair	Coppice stool - Coppice origin / Mature stems. Die-back - Upper crown. Chalara (ash dieback) present. Moderate symptoms. Sparse crown.	141.4	6.7	10-20	C	1
T1039	1	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	2	35	N E S W 3.0 3.0 3.0 3.0	0.0	0.5	Early Mature	Good	Hedge remnant.	56.5	4.2	40+	C	1
T1040	1	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	5	33	N E S W 3.0 3.0 3.0 3.0	0.0	0.5	Early Mature	Good	Hedge remnant.	50.9	4.0	40+	C	1
T1041	1	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	2	35	N E S W 3.0 3.0 3.0 3.0	0.0	0.5	Early Mature	Good	Hedge remnant.	56.5	4.2	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1042	1	*Quercus robur* English Oak	11.0	1	53	N E S W 5.0 5.0 6.0 5.0	0.0	1.5	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Ivy or climbing plant. Growing on north bank of ditch.	127.1	6.4	40+	B	1
T1043	1	*Alnus glutinosa* Common Alder	9.0	1	50	N E S W 4.0 6.0 5.0 7.0	0.0	1.0	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Ivy or climbing plant. Growing on north bank of ditch. Mature epicormic stems from base.	113.1	6.0	40+	B	1
T1044	1	*Quercus robur* English Oak	9.0	1	60	N E S W 6.0 6.0 5.0 5.0	0.0	0.5	Early Mature	Good	Epicormic growth - Crown. Growing on north bank of ditch.	162.9	7.2	40+	B	1
T1045	1	*Quercus robur* English Oak	8.0	2	46	NW NE SE SW 3.0 4.0 3.0 4.0	0.5	1.5	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Growing on north bank of ditch. Squat form	96.1	5.5	40+	C	1
T1046	1	*Fraxinus excelsior* Ash	10.0	5	67	N E S W 5.0 7.0 6.0 7.0	0.5	1.0	Early Mature	Fair	Die-back - Upper crown. Chalara (ash dieback) present. Minor symptoms.	203.6	8.0	10-20	C	1
H1047	8 1	*Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel	4.0	1	10	N E S W 2.5 2.5 2.5 2.5	0.0	0.0	Early Mature	Good	Hedge remnant.	4.5	1.2	40+	C	1
T1048	1	*Quercus robur* English Oak	10.0	3	69	N E S W 4.0 7.0 5.0 6.0	4.0	1.5	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Growing on North bank of ditch.	217.1	8.3	40+	B	1
T1049	1	*Fraxinus excelsior* Ash	12.0	5	60	N E S W 4.0 4.0 6.0 4.0	4.0	4.0	Early Mature	Poor	Die-back - Throughout crown. Chalara (ash dieback) present. Severe symptoms. Growing on north bank of ditch.	163.8	7.2	10-20	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1050	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	8	28	N 2.5 E 2.5 S 2.5 W 2.5	0.5	0.5	Early Mature	Good	Growing on south bank of ditch.	36.2	3.4	40+	C	1
T1051	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	8	28	N 2.5 E 2.5 S 2.5 W 2.5	0.5	0.5	Early Mature	Good	Growing on south bank of ditch.	36.2	3.4	40+	C	1
T1052	1	*Fraxinus excelsior* Ash	13.0	1	55	N 4.0 E 6.0 S 6.0 W 6.0	3.0	2.5	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Chalara (ash dieback) present. Minor symptoms. Growing on south bank of ditch. Mature epicormic stems from base.	136.8	6.6	20-40	B	1
T1053	1	*Corylus avellana* Common Hazel	4.0	25	25	N 3.0 E 3.0 S 3.0 W 3.0	0.5	0.0	Early Mature	Good	Coppice stool - Regrown.	28.3	3.0	40+	C	1
T1054	1	*Quercus robur* English Oak	16.0	1	70	N 4.0 E 8.0 S 8.0 W 7.0	2.5	2.0	Early Mature	Good	Base / stems obscured - Vegetation. Growing on south bank of ditch.	221.7	8.4	40+	B	1
H1055	3 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel	5.0	10	15	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Early Mature	Good	Hedge remnant. Growing on south bank of ditch.	11.3	1.9	40+	C	1
H1056	2 1	*Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May	5.0	15	19	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Early Mature	Good	Coppice stool - Regrown. Hedge remnant. Growing around ditch/culvert.	17.0	2.3	40+	C	1
T1057	1	*Quercus robur* English Oak	4.0	1	12	N 1.0 E 1.0 S 1.0 W 2.0	0.5	1.0	Young	Good	Base / stems obscured - Vegetation.	6.5	1.4	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1058	2	*Corylus avellana* Common Hazel	3.0	12	17	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Semi Mature	Good	Coppice stool - Regrown. Growing on east bank of ditch. Hedge remnant. **Fell - Ground level.** To facilitate development.	13.6	2.1	40+	C	1
G1059	3 3 3	*Quercus robur* English Oak *Populus tremula* Aspen *Corylus avellana* Common Hazel	13.0	2	49	N E S W 4.0 4.0 4.0 4.0	0.0	1.0	Early Mature	Good	Growing on east bank of ditch. Blackthorn understorey.	110.8	5.9	40+	C	2
H1060	5	*Corylus avellana* Common Hazel	3.0	12	17	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Semi Mature	Good	Coppice stool - Regrown. Growing on east bank of ditch. Hedge remnant. **Fell - Ground level.** To facilitate development.	13.6	2.1	40+	C	1
T1061	1	*Fraxinus excelsior* Ash	9.0	2	42	N E S W 4.0 4.0 4.0 3.0	0.0	0.5	Early Mature	Fair	Die-back - Mid crown. Die-back - Upper crown. Chalara (ash dieback) present. Moderate symptoms. Growing on south bank of ditch. Hawthorn and hazel beneath.	81.4	5.1	10-20	C	1
T1062	1	*Quercus robur* English Oak	9.0	1	55	N E S W 6.0 6.0 6.0 6.0	0.0	0.5	Early Mature	Fair	Base / stems obscured - Vegetation. Epicormic growth - Base. Growing on north bank of ditch. Sparse crown	136.8	6.6	40+	C	1
T1063	1	*Corylus avellana* Common Hazel	4.0	15	19	NW NE SE SW 3.0 1.0 3.0 3.0	0.0	0.0	Early Mature	Good	Coppice stool - Regrown.	17.0	2.3	40+	C	1
T1064	1	*Corylus avellana* Common Hazel	4.0	15	19	NW NE SE SW 3.0 1.0 2.0 3.0	0.0	0.0	Early Mature	Good	Coppice stool - Regrown.	17.0	2.3	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1065	1	*Corylus avellana* Common Hazel	4.0	25	25	NW 3.0 NE 1.0 SE 3.0 SW 1.5	0.0	0.0	Early Mature	Good	Coppice stool - Regrown.	28.3	3.0	40+	C	1
T1066	1	*Corylus avellana* Common Hazel	3.0	10	9	NW 1.0 NE 0.5 SE 1.0 SW 1.0	0.0	0.0	Early Mature	Good	Coppice stool - Regrown.	4.1	1.1	40+	C	1
T1067	1	*Corylus avellana* Common Hazel	3.0	10	9	NW 1.0 NE 0.5 SE 1.0 SW 1.0	0.0	0.0	Early Mature	Good	Coppice stool - Regrown.	4.1	1.1	40+	C	1
T1068	1	*Corylus avellana* Common Hazel	3.0	10	9	NW 1.0 NE 0.5 SE 1.0 SW 1.0	0.0	0.0	Early Mature	Good	Coppice stool - Regrown.	4.1	1.1	40+	C	1
T1069	1	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	10	15	NW 2.0 NE 2.0 SE 2.0 SW 2.0	0.0	0.0	Early Mature	Good	Coppice stool - Regrown.	11.3	1.9	40+	C	1
T1070	1	*Corylus avellana* Common Hazel	3.0	8	14	NW 2.0 NE 2.0 SE 2.0 SW 2.0	0.0	0.0	Early Mature	Good	Coppice stool - Regrown.	9.0	1.7	40+	C	1
H1071	3	*Corylus avellana* Common Hazel	3.0	8	8	N 1.0 E 0.5 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedge remnant.	3.3	1.0	40+	C	1
T1072	1	*Corylus avellana* Common Hazel	3.0	12	17	N 2.0 E 1.0 S 2.0 W 2.0	0.0	0.0	Early Mature	Good	Coppice stool - Regrown.	13.6	2.1	40+	C	1
T1073	1	*Alnus glutinosa* Common Alder	6.0	2	41	N 4.0 E 2.5 S 4.0 W 2.5	2.5	2.0	Semi Mature	Good	Epicormic growth - Base. Pruned back on site side.	76.9	4.9	40+	C	1
T1074	1	*Quercus robur* English Oak	3.0	2	12	N 1.5 E 1.5 S 1.5 W 1.5	0.5	0.5	Young	Good		6.7	1.5	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1075	1	*Quercus robur* English Oak	5.0	1	15	N E S W 2.0 2.0 2.0 2.0	0.5	0.5	Young	Good		10.2	1.8	40+	C	1
T1076	1	*Corylus avellana* Common Hazel	3.0	6	7	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Fair		2.4	0.9	20-40	C	1
H1077	5 1	*Salix cinerea* Grey Sallow *Crataegus monogyna* Common Hawthorn/Quick/May	6.0	3	25	N E S W 4.0 4.0 4.0 2.0	0.0	0.0	Early Mature	Good	Fallen tree / trees - Partial collapse. Hedge remnant. Pruned back on site side.	30.5	3.1	40+	C	1
H1078	13 10 2	*Corylus avellana* Common Hazel *Prunus spinosa* Blackthorn/Sloe *Salix cinerea* Grey Sallow	5.0	3	25	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Early Mature	Good	Coppice stool - Regrown. Measurements represent average for larger trees in group.	30.5	3.1	40+	C	2
T1079	1	*Quercus robur* English Oak	13.0	2	50	N E S W 6.0 6.0 5.0 3.0	2.0	1.5	Early Mature	Good	Branch - Broken.	117.3	6.1	40+	B	1
G1080	50	*Cupressocyparis leylandii* Leyland Cypress	14.0	1	25	N E S W 3.0 3.0 3.0 3.0	0.5	0.5	Early Mature	Good	Screen for farmhouse.	28.3	3.0	20-40	C	2
G1081	15	*Cupressocyparis leylandii* Leyland Cypress	14.0	1	25	N E S W 3.0 3.0 3.0 3.0	0.5	0.5	Early Mature	Good	Screen for farmhouse.	28.3	3.0	20-40	C	2
T1082	1	*Quercus cerris* Turkey Oak	3.0	1	10	N E S W 1.5 1.5 1.5 1.5	1.0	0.5	Young	Good	On neighbouring land.	4.5	1.2	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1083	1	*Quercus robur* English Oak	4.0	1	12	N 1.5 E 1.5 S 1.5 W 1.5	1.0	0.5	Young	Good	On neighbouring land.	6.5	1.4	40+	C	1
T1084	1	*Quercus robur* English Oak	12.0	1	45	N 5.0 E 5.0 S 5.0 W 5.0	1.0	1.0	Semi Mature	Good	On neighbouring land.	91.6	5.4	40+	B	1
T1085	1	*Quercus robur* English Oak	18.0	1	108	N 10.0 E 10.0 S 8.0 W 10.0	1.0	2.5	Mature	Good	Ivy or climbing plant. On neighbouring land. Growing on south bank of ditch.	527.7	13.0	40+	A	1
T1086	1	*Quercus robur* English Oak	5.0	1	12	N 1.5 E 1.5 S 1.5 W 1.5	1.0	0.5	Young	Good	On neighbouring land.	6.5	1.4	40+	C	1
T1087	1	*Quercus robur* English Oak	16.0	1	60	N 4.0 E 6.0 S 5.0 W 7.0	2.0	4.0	Early Mature	Fair	Access to inspect base - Not possible. Epicormic growth - Bole / principal stems. Ivy or climbing plant. Leaning trunk - Minor. Shedding limb / limbs - Historic. Shedding limb / limbs - Minor. Slightly sparse crown. Growing on south bank of ditch.	162.9	7.2	20-40	B	1
H1088	5 1 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Betula pendula* Silver Birch	5.0	1	15	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Mature	Fair	Hedgerow - Neglected / overgrown. Gappy.	10.2	1.8	20-40	C	1
T1089	1	*Fraxinus excelsior* Ash	16.0	1	82	N 4.0 E 6.0 S 6.0 W 2.0	3.0	2.0	Mature	Poor	Die-back - Throughout crown. Chalara (ash dieback) present. Severe symptoms. Growing on South bank of ditch.	304.2	9.8	10-20	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1090	1	*Quercus robur* English Oak	15.0	2	96	N 6.0 E 6.0 S 6.0 W 6.0	3.0	2.5	Early Mature	Good	Growing on south bank of ditch.	418.5	11.5	40+	B	1
T1091	1	*Quercus robur* English Oak	15.0	1	52	N 7.0 E 7.0 S 5.0 W 7.0	3.0	0.0	Early Mature	Good	Epicormic growth - Bole / principal stems. Growing on south bank of ditch.	122.3	6.2	40+	B	1
G1092	52	*Populus x canadensis* Hybrid Black Poplars	28.0	1	100	N 5.0 E 10.0 S 10.0 W 10.0	3.0	2.5	Mature	Good	Ivy or climbing plant. Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Shedding limb / limbs - Recent. Edge of mature poplar plantation. Numbers approximate. Canopies extend 10 m into field on north-South edge. No access into group. Some broken tops. Measurements represent average for larger trees in group. Predominantly hawthorn low gappy hedge beneath.	452.4	12.0	20-40	B	2
W1093	8 6 4	*Populus balsamifera* Balsam Poplar *Fraxinus excelsior* Ash *Quercus robur* English Oak	17.0	1	50	N 5.0 E 6.0 S 8.0 W 6.0	3.0	2.5	Early Mature	Good	Woodland edge. On neighbouring land. Growing on north side of deep ditch. Sided up to 3 m on site side due to ditch dredging. Canopies extend c. 10 m into site from southern ditch bank. 4 m high hedge of hawthorn and hazel beneath. Numbers approximate. Inaccessible. Measurements estimated.	113.1	6.0	40+	B	2
H1094	14 9	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel	5.0	5	33	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown. Hedge remnant. Gappy. Growing on bank of ditch.	50.9	4.0	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1095	1	*Fraxinus excelsior* Ash	11.0	6	61	NW 6.0 E 4.0 S 6.0 W 4.0	1.0	1.5	Early Mature	Fair	Coppice stool - Coppice origin / Mature stems. Chalara (ash dieback) present. Moderate symptoms. Growing on south west bank of ditch.	169.6	7.3	10-20	C	1
T1096	1	*Fraxinus excelsior* Ash	11.0	2	35	N 3.0 E 3.0 S 3.0 W 3.0	4.0	4.0	Semi Mature	Poor	Die-back - Throughout crown. Epicormic growth - Base. Chalara (ash dieback) present. Severe symptoms. Growing on north East bank of ditch. On neighbouring land.			0-10	U	
T1097	1	*Salix fragilis* Crack Willow	6.0	6	73	N 4.0 E 4.0 S 4.0 W 4.0	0.5	1.0	Mature	Fair	Coppice stool - Coppice origin / Mature stems. Topped. **Fell - Ground level.** To facilitate development.	244.3	8.8	10-20	C	1
T1098	1	*Fraxinus excelsior* Ash	13.0	3	46	N 4.0 E 4.0 S 4.0 W 4.0	1.0	4.0	Semi Mature	Fair	Chalara (ash dieback) present. Minor symptoms. Growing at foot of highway embankment. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	99.8	5.6	10-20	C	1
T1099	1	*Fraxinus excelsior* Ash	8.0	1	30	N 3.0 E 2.0 S 4.0 W 3.0	2.5	3.0	Semi Mature	Fair	Die-back - Upper crown. Chalara (ash dieback) present. Minor symptoms. Growing at foot of highway embankment. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	40.7	3.6	10-20	C	1
T1100	1	*Fraxinus excelsior* Ash	8.0	1	23	N 2.0 E 1.0 S 2.0 W 2.0	2.5	3.0	Semi Mature	Fair	Die-back - Upper crown. Chalara (ash dieback) present. Minor symptoms. Growing at foot of highway embankment.	23.9	2.8	10-20	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1101	1	*Fraxinus excelsior* Ash	13.0	2	30	N 2.0 E 4.0 S 4.0 W 2.0	2.5	3.0	Semi Mature	Fair	Die-back - Upper crown. Chalara (ash dieback) present. Moderate symptoms. Growing at foot of highway embankment.	42.2	3.7	10-20	C	1
T1102	1	*Fraxinus excelsior* Ash	10.0	1	30	N 5.0 E 2.0 S 3.0 W 4.0	3.0	2.5	Semi Mature	Fair	Die-back - Upper crown. Leaning trunk - Minor. Chalara (ash dieback) present. Moderate symptoms. Growing at foot of highway embankment.	40.7	3.6	10-20	C	1
T1103	1	*Crataegus monogyna* Common Hawthorn/Quick/May	7.0	1	15	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Early Mature	Good	Growing at foot of highway embankment.	10.2	1.8	40+	C	1
T1104	1	*Fraxinus excelsior* Ash	13.0	2	46	N 5.0 E 4.0 S 4.0 W 4.0	0.5	2.5	Semi Mature	Fair	Chalara (ash dieback) present. Minor symptoms. Growing at top of highway embankment.	96.1	5.5	10-20	C	1
T1105	1	*Fraxinus excelsior* Ash	9.0	1	30	N 4.0 E 3.0 S 3.0 W 3.0	1.0	2.5	Semi Mature	Fair	Die-back - Upper crown. Leaning trunk - Major. Chalara (ash dieback) present. Moderate symptoms. Growing at foot of highway embankment.	40.7	3.6	10-20	C	1
T1106	1	*Fraxinus excelsior* Ash	10.0	1	25	N 4.0 E 2.0 S 4.0 W 2.0	3.0	3.0	Semi Mature	Fair	Die-back - Upper crown. Chalara (ash dieback) present. Minor symptoms. Growing at foot of highway embankment.	28.3	3.0	10-20	C	1
T1107	1	*Fraxinus excelsior* Ash	10.0	3	38	N 4.0 E 2.0 S 5.0 W 4.0	1.0	2.5	Semi Mature	Fair	Die-back - Upper crown. Chalara (ash dieback) present. Minor symptoms. Growing at foot of highway embankment.	65.4	4.6	10-20	C	1
T1108	1	*Fraxinus excelsior* Ash	10.0	2	28	N 2.0 E 2.0 S 3.0 W 2.0	3.0	2.5	Semi Mature	Fair	Die-back - Upper crown. Chalara (ash dieback) present. Minor symptoms. Growing at foot of highway embankment.	36.2	3.4	10-20	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1109	1	*Fraxinus excelsior* Ash	11.0	1	43	N 5.0 E 5.0 S 5.0 W 5.0	1.5	2.5	Early Mature	Fair	Die-back - Upper crown. Chalara (ash dieback) present. Minor symptoms. Growing at foot of highway embankment.	83.6	5.2	10-20	C	1
G1110	18	*Fraxinus excelsior* Ash	11.0	4	60	N 5.0 E 4.0 S 5.0 W 4.0	2.0	2.5	Semi Mature	Fair	Die-back - Upper crown. Growing at foot of highway embankment. Chalara (ash dieback) present. Minor symptoms. Measurements represent average for larger trees in group.	162.9	7.2	10-20	C	1
T1111	1	*Fraxinus excelsior* Ash	11.0	2	33	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Semi Mature	Fair	Die-back - Upper crown. Fungal fruiting body - structural decay suspected. Chalara (ash dieback) present. Minor symptoms. Growing at foot of highway embankment. Inonotus hispidus bracket on smaller stem.	50.9	4.0	10-20	C	1
T1112	1	*Fraxinus excelsior* Ash	11.0	3	48	N 4.0 E 6.0 S 6.0 W 4.0	3.0	3.0	Early Mature	Fair	Die-back - Upper crown. Epicormic growth - Base / bole / principal stems. Chalara (ash dieback) present. Minor symptoms. Growing at foot of highway embankment.	108.6	5.9	10-20	C	1
T1113	1	*Fraxinus excelsior* Ash	11.0	2	46	N 5.0 E 3.0 S 5.0 W 5.0	2.5	2.0	Semi Mature	Fair	Die-back - Upper crown. Leaning trunk - Minor. Chalara (ash dieback) present. Minor symptoms. Growing at foot of highway embankment.	95.9	5.5	10-20	C	1
T1114	1	*Fraxinus excelsior* Ash	11.0	5	55	N 4.0 E 4.0 S 4.0 W 4.0	2.5	4.0	Semi Mature	Fair	Die-back - Upper crown. Chalara (ash dieback) present. Minor symptoms. Growing at foot of highway embankment.	141.4	6.7	10-20	C	1
T1115	1	*Fraxinus excelsior* Ash	11.0	3	43	N 3.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Semi Mature	Fair	Die-back - Upper crown. Chalara (ash dieback) present. Minor symptoms. Growing at foot of highway embankment.	86.4	5.2	10-20	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1116	1	*Quercus robur* English Oak	9.0	1	33	N 3.0 E 3.0 S 3.0 W 3.0	3.0	2.0	Semi Mature	Good	Growing at foot of highway embankment.	49.3	4.0	40+	C	1
T1117	1	*Fraxinus excelsior* Ash	9.0	2	36	N 4.0 E 3.0 S 3.0 W 3.0	3.0	1.5	Semi Mature	Fair	Die-back - Upper crown. Chalara (ash dieback) present. Minor symptoms. Growing at foot of highway embankment.	58.8	4.3	10-20	C	1
T1118	1	*Acer campestre* Field Maple	4.0	1	15	N 2.0 E 2.0 S 2.0 W 2.0	0.0	1.0	Semi Mature	Good		10.2	1.8	40+	C	1
T1119	1	*Fraxinus excelsior* Ash	8.0	2	28	N 3.0 E 3.0 S 3.0 W 3.0	3.0	3.0	Semi Mature	Fair	Die-back - Upper crown. Chalara (ash dieback) present. Minor symptoms. Growing at foot of highway embankment.	36.2	3.4	10-20	C	1
T1120	1	*Fraxinus excelsior* Ash	10.0	5	55	N 4.0 E 4.0 S 4.0 W 4.0	3.0	2.5	Semi Mature	Fair	Die-back - Upper crown. Multi-stemmed. Chalara (ash dieback) present. Minor symptoms. Growing at foot of highway embankment.	141.4	6.7	10-20	C	1
G1121	2	*Acer campestre* Field Maple	6.0	1	20	N 2.5 E 2.5 S 2.5 W 2.5	3.0	2.0	Early Mature	Fair	Hedge remnant.	18.1	2.4	40+	C	1
T1122	1	*Fraxinus excelsior* Ash	11.0	1	35	N 5.0 E 5.0 S 5.0 W 5.0	1.0	2.5	Semi Mature	Good	Growing at top of highway embankment.	55.4	4.2	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1123	50 35 25 10 5 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Quercus robur* English Oak *Prunus spinosa* Blackthorn/Sloe *Sambucus nigra* Elder *Acer campestre* Field Maple *Corylus avellana* Common Hazel	14.0	1	65	N 6.0 E 6.0 S 6.0 W 6.0	0.0	0.0	Mature	Good	On neighbouring land. Mature trees on bank to west of group, understorey of Hazel coppice and field maple to East on site side. Measurements represent average for larger trees in group.	191.1	7.8	40+	A	2
G1124	10 10	*Salix fragilis* Crack Willow *Quercus robur* English Oak	13.0	1	30	N 4.0 E 4.0 S 4.0 W 4.0	1.0	1.0	Semi Mature	Good	On neighbouring land. Good screen. Numbers approximate.	40.7	3.6	40+	C	2
G1125	5	*Fraxinus excelsior* Ash	8.0	1	20	N 3.0 E 3.0 S 3.0 W 3.0	3.0	2.5	Semi Mature	Poor	Die-back - Throughout crown. On neighbouring land. Chalara (ash dieback) present. Moderate symptoms.	18.1	2.4	10-20	C	1
T1126	1	*Fraxinus excelsior* Ash	9.0	3	34	N 3.0 E 3.0 S 3.0 W 3.0	2.5	2.5	Semi Mature	Fair	Die-back - Upper crown. On neighbouring land. Chalara (ash dieback) present. Minor symptoms. Inaccessible. Measurements estimated.	54.3	4.2	10-20	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1127	1	*Fraxinus excelsior* Ash	9.0	1	25	N 2.0 E 2.0 S 2.0 W 2.0	2.5	3.0	Semi Mature	Fair	Die-back - Throughout crown. On neighbouring land. Chalara (ash dieback) present. Moderate symptoms. Inaccessible. Measurements estimated.	28.3	3.0	10-20	C	1
T1128	1	*Fraxinus excelsior* Ash	7.0	1	20	N 2.0 E 2.0 S 2.0 W 2.0	3.0	3.0	Semi Mature	Fair	Die-back - Upper crown. On neighbouring land. Chalara (ash dieback) present. Minor symptoms. Inaccessible. Measurements estimated.	18.1	2.4	10-20	C	1
T1129	1	*Fraxinus excelsior* Ash	7.0	1	20	N 2.0 E 2.0 S 2.0 W 2.0	3.0	3.0	Semi Mature	Fair	Die-back - Upper crown. On neighbouring land. Chalara (ash dieback) present. Minor symptoms. Inaccessible. Measurements estimated.	18.1	2.4	10-20	C	1
T1130	1	*Fraxinus excelsior* Ash	9.0	1	30	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Semi Mature	Fair	Die-back - Upper crown. On neighbouring land. Chalara (ash dieback) present. Minor symptoms. Inaccessible. Measurements estimated.	40.7	3.6	10-20	C	1
T1131	1	*Acer campestre* Field Maple	10.0	1	25	N 2.0 E 2.0 S 2.0 W 2.0	3.0	3.0	Semi Mature	Good	Inaccessible. Measurements estimated. On neighbouring land.	28.3	3.0	40+	C	1
T1132	1	*Acer campestre* Field Maple	10.0	1	30	N 2.5 E 2.5 S 2.5 W 2.5	3.0	3.0	Semi Mature	Good	Inaccessible. Measurements estimated. On neighbouring land.	40.7	3.6	40+	C	1
T1133	1	*Fraxinus excelsior* Ash	11.0	1	25	N 2.5 E 2.5 S 2.5 W 2.5	5.0	3.0	Semi Mature	Fair	Die-back - Upper crown. On neighbouring land. Chalara (ash dieback) present. Minor symptoms. Inaccessible. Measurements estimated.	28.3	3.0	10-20	C	1
T1134	1	*Acer campestre* Field Maple	10.0	1	30	N 4.0 E 4.0 S 4.0 W 4.0	3.0	2.0	Semi Mature	Good	Inaccessible. Measurements estimated. On neighbouring land.	40.7	3.6	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1135	1	*Fraxinus excelsior* Ash	11.0	1	25	N 3.0 E 3.0 S 3.0 W 3.0	3.0	3.0	Semi Mature	Fair	Die-back - Upper crown. On neighbouring land. Chalara (ash dieback) present. Minor symptoms. Inaccessible. Measurements estimated.	28.3	3.0	10-20	C	1
T1136	1	*Acer campestre* Field Maple	10.0	2	50	N 5.0 E 5.0 S 5.0 W 5.0	4.0	2.5	Semi Mature	Good	Inaccessible. Measurements estimated. On neighbouring land.	113.1	6.0	40+	C	1
T1137	1	*Acer campestre* Field Maple	10.0	1	45	N 4.0 E 4.0 S 4.0 W 4.0	4.0	2.5	Semi Mature	Good	Inaccessible. Measurements estimated. On neighbouring land.	91.6	5.4	40+	C	1
T1138	1	*Fraxinus excelsior* Ash	7.0	1	25	N 2.0 E 2.0 S 2.0 W 2.0	3.0	3.0	Semi Mature	Fair	Die-back - Upper crown. On neighbouring land. Chalara (ash dieback) present. Minor symptoms. Inaccessible. Measurements estimated.	28.3	3.0	10-20	C	1
T1139	1	*Fraxinus excelsior* Ash	8.0	1	30	N 2.0 E 3.0 S 2.0 W 2.0	3.0	3.0	Semi Mature	Fair	Die-back - Upper crown. On neighbouring land. Chalara (ash dieback) present. Minor symptoms. Inaccessible. Measurements estimated.	40.7	3.6	10-20	C	1
T1140	1	*Acer campestre* Field Maple	7.0	1	25	N 2.5 E 2.5 S 2.5 W 2.5	3.0	2.5	Semi Mature	Good	Inaccessible. Measurements estimated. On neighbouring land.	28.3	3.0	40+	C	1
T1141	1	*Fraxinus excelsior* Ash	9.0	1	30	N 4.0 E 3.0 S 2.0 W 3.0	4.0	3.0	Semi Mature	Fair	Die-back - Upper crown. On neighbouring land. Chalara (ash dieback) present. Minor symptoms. Inaccessible. Measurements estimated.	40.7	3.6	10-20	C	1
T1142	1	*Acer campestre* Field Maple	9.0	1	25	N 2.5 E 2.5 S 2.5 W 2.5	3.0	2.5	Semi Mature	Good	Inaccessible. Measurements estimated. On neighbouring land.	28.3	3.0	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1143	1	*Acer campestre* Field Maple	10.0	1	30	N 2.5 E 2.5 S 2.5 W 2.5	3.0	3.0	Semi Mature	Good	Inaccessible. Measurements estimated. On neighbouring land.	40.7	3.6	40+	C	1
T1144	1	*Acer campestre* Field Maple	10.0	1	30	N 2.5 E 3.0 S 2.5 W 2.5	3.0	3.0	Semi Mature	Good	Inaccessible. Measurements estimated. On neighbouring land.	40.7	3.6	40+	C	1
H1145	30 30 30 10 10	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Swida sanguinea* Common Dogwood *Sambucus nigra* Elder	3.5	1	8	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown. Good screen. Numbers approximate. On neighbouring land.	2.9	1.0	40+	B	2
T1146	1	*Salix caprea* Goat Willow/Great Sallow	10.0	11	116	N 8.0 E 4.0 S 6.0 W 6.0	3.0	2.5	Early Mature	Good	Multi-stemmed.	609.6	13.9	40+	B	1
H1147	5	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	20	N 3.0 E 2.0 S 3.0 W 3.0	0.0	0.0	Mature	Good	Hedge remnant.	18.1	2.4	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1148	15 5 3 2	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Viburnum lantana* Wayfaring Tree *Rosa canina* Dog-rose	4.0	1	20	N 3.0 E 2.0 S 3.0 W 3.0	0.0	0.0	Mature	Good	Hedge remnant.	18.1	2.4	40+	C	2
T1149	1	*Fraxinus excelsior* Ash	16.0	1	60	N 8.0 E 7.0 S 7.0 W 5.0	5.0	4.0	Mature	Fair	Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems. Chalara (ash dieback) present. Minor symptoms.	162.9	7.2	20-40	B	1
T1150	1	*Fraxinus excelsior* Ash	10.0	5	49	N 4.0 E 5.0 S 4.0 W 4.0	3.0	3.0	Early Mature	Fair	Coppice stool - Coppice origin / Mature stems. Chalara (ash dieback) present. Minor symptoms.	109.5	5.9	20-40	C	1
T1151	1	*Malus sp.* Apple sp.	5.0	5	44	NW 4.0 NE 6.0 SE 3.0 SW 5.0	0.5	0.5	Early Mature	Good	Hedge remnant.	90.5	5.4	40+	C	1
T1152	1	*Salix caprea* Goat Willow/Great Sallow	7.0	3	46	N 4.0 E 5.0 S 4.0 W 4.0	0.0	0.5	Early Mature	Good	On neighbouring land in wet depression.	97.3	5.6	40+	C	1
T1153	1	*Quercus robur* English Oak	9.0	1	38	N 4.0 E 5.0 S 4.0 W 3.0	0.0	1.0	Early Mature	Good		65.3	4.6	40+	C	1
T1154	1	*Quercus robur* English Oak	8.0	1	35	N 4.0 E 4.0 S 4.0 W 3.0	1.0	1.5	Early Mature	Good	Arboricultural work - Historic. On neighbouring land.	55.4	4.2	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1155	1	*Quercus robur* English Oak	10.0	2	64	N E S W 8.0 4.0 7.0 3.0	0.0	0.5	Early Mature	Good	Arboricultural work - Historic. Epicormic growth - Base / bole / principal stems.	187.3	7.7	40+	B	1
T1156	1	*Quercus robur* English Oak	10.0	1	40	N E S W 7.0 3.0 4.0 4.0	0.0	0.5	Early Mature	Fair	Arboricultural work - Historic. Epicormic growth - Base / bole / principal stems.	72.4	4.8	40+	C	1
H1157	10 7	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May	6.0	1	20	N E S W 2.5 2.5 2.5 2.5	0.0	0.0	Mature	Good	Hedgerow - Neglected / overgrown. Hedge remnant.	18.1	2.4	40+	C	2
T1158	1	*Quercus robur* English Oak	14.0	3	78	NW NE SE SW 4.0 7.5 5.0 8.0	0.0	2.5	Early Mature	Good		276.0	9.4	40+	B	1
T1159	1	*Fraxinus excelsior* Ash	14.0	7	66	NW NE SE SW 5.0 8.0 6.0 5.0	0.5	2.5	Early Mature	Fair	Coppice stool - Coppice origin / Mature stems. Die-back - Upper crown. Chalara (ash dieback) present. Minor symptoms.	197.9	7.9	20-40	C	1
T1160	1	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	10	31	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Early Mature	Good	Hedge remnant.	45.2	3.8	40+	C	1
T1161	1	*Acer pseudoplatanus* Sycamore	11.0	1	46	N E S W 4.0 4.0 4.0 4.0	3.0	2.5	Early Mature	Good	Ivy or climbing plant. Growing on highway verge. Ownership uncertain.	95.7	5.5	40+	C	1
T1162	1	*Acer pseudoplatanus* Sycamore	10.0	1	40	N E S W 3.0 3.0 3.0 3.0	3.0	2.5	Early Mature	Fair	Base / stems obscured - Vegetation. Ivy or climbing plant. Growing on highway verge. Ownership uncertain.	72.4	4.8	40+	C	1
T1163	1	*Acer pseudoplatanus* Sycamore	11.0	2	41	N E S W 3.0 3.0 3.0 3.0	3.0	2.0	Early Mature	Fair	Base / stems obscured - Vegetation. Ivy or climbing plant. Growing on highway verge. Ownership uncertain.	78.8	5.0	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1164	1	*Aesculus hippocastanum* Horse Chestnut	16.0	1	85	NW NE SE SW 7.0 7.0 6.0 7.0	4.0	2.5	Mature	Good	Shedding limb / limbs - Historic. Shedding limb / limbs - Minor. Growing on highway verge. Ownership uncertain.	326.9	10.2	40+	B	1
T1165	1	*Quercus robur* English Oak	18.0	1	82	NW NE SE SW 8.0 7.0 8.0 8.0	3.0	5.0	Mature	Good	Growing on highway verge. Ownership uncertain.	304.2	9.8	40+	A	1
H1166	100	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	5	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. Numbers approximate.	1.1	0.6	40+	C	2
T1174	1	*Quercus robur* English Oak	16.0	1	92	N E S W 5.0 7.0 7.0 5.0	2.0	3.0	Ancient or Veteran	Good	Bark wound - Major. Deadwood - Major. Hollow trunk - Open cavity. Leaning trunk - Minor. Stag-headed crown. Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Shedding limb / limbs - Recent. Large old tearout wound with brown rot. Top has blown out, hollowing below.	382.9	11.0	40+	A	3
H1175	60 30 1 1	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Rosa canina* Dog-rose *Acer campestre* Field Maple	2.0	1	10	N E S W 1.5 1.5 1.5 1.5	0.0	0.0	Early Mature	Good	Double row.	4.5	1.2	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1176	1	*Quercus robur* English Oak	17.0	1	102	N E S W 7.0 7.5 6.0 8.0	1.0	3.0	Mature	Good	Decay / structural defect in crown limb / limbs - Open cavity / cavities. Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Woodpecker holes. Veteran features.	470.7	12.2	40+	A	1
T1177	1	*Quercus robur* English Oak	11.0	1	90	NW NE SE SW 5.0 5.0 5.0 7.0	1.0	1.0	Mature	Good	Base / stems obscured - Vegetation. Decay / structural defect in crown limb / limbs - Open cavity / cavities. Deadwood - Major. Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Shedding limb / limbs - Recent. Veteran features.	366.4	10.8	40+	B	1
T1178	1	*Quercus robur* English Oak	14.0	1	94	NW NE SE SW 5.0 6.0 5.0 8.0	2.0	4.0	Mature	Fair	Deadwood - Major. Fungal fruiting body - structural decay suspected. Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Sparse crown. Fistulina hepatica bracket at base. Veteran features.	399.7	11.3	40+	B	1
H1179	40 30 1	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder	2.0	1	10	N E S W 1.5 1.5 1.5 1.5	0.0	0.0	Early Mature	Good	Double row.	4.5	1.2	40+	C	2
H1185	200 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash	3.0	1	15	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Mature	Good	Hedgerow - Maintained. Numbers approximate.	10.2	1.8	40+	C	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1186	1	*Fraxinus excelsior* Ash	8.0	1	25	N E S W 2.0 2.0 2.0 2.0	3.0	1.5	Semi Mature	Good	Growing on highway verge. **Fell - Ground level.** To facilitate development.	28.3	3.0	40+	C	1
T1187	1	*Fraxinus excelsior* Ash	8.0	2	28	NW NE SE SW 2.0 3.0 2.0 3.0	3.0	2.0	Semi Mature	Good	Growing on highway verge. **Fell - Ground level.** To facilitate development.	36.2	3.4	40+	C	1
T1188	1	*Fraxinus excelsior* Ash	8.0	1	27	NW NE SE SW 3.0 3.0 3.0 3.0	2.0	1.5	Semi Mature	Good	Growing on highway verge. **Fell - Ground level.** To facilitate development.	33.0	3.2	40+	C	1
T1189	1	*Fraxinus excelsior* Ash	8.0	1	29	NW NE SE SW 3.0 3.0 3.0 2.0	2.0	1.5	Semi Mature	Good	Growing on highway verge.	38.0	3.5	40+	C	1
H1190	200 50 2	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Acer pseudoplatanus* Sycamore	3.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Numbers approximate.	4.5	1.2	40+	C	2
T1191	1	*Quercus robur* English Oak	9.0	2	50	NW NE SE SW 4.0 4.0 4.0 3.0	3.0	2.0	Early Mature	Good	Ivy or climbing plant.	117.3	6.1	40+	B	1
H1192	40	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	15	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Mature	Good	Hedgerow - Neglected / overgrown. Numbers approximate.	10.2	1.8	40+	C	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1194	1	*Quercus robur* English Oak	10.0	2	54	NW 5.0 NE 5.0 SE 5.0 SW 5.0	3.0	2.0	Early Mature	Good	Growing on east bank of deep ditch.	135.2	6.6	40+	B	1
T1197	1	*Quercus robur* English Oak	7.8	1	30	NW 3.0 NE 4.0 SE 3.0 SW 4.0	1.8	1.5	Semi Mature	Good	Good long-term potential.	40.7	3.6	40+	C	1
H1198	20 15	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Numbers approximate.	4.5	1.2	40+	C	2
H1199	100 80	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Numbers approximate.	4.5	1.2	40+	C	2
H1200	20 15	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Numbers approximate.	4.5	1.2	40+	C	2
H1201	20 15	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Numbers approximate.	4.5	1.2	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1202	1	*Quercus robur* English Oak	16.0	1	83	N 6.0 E 6.0 S 6.0 W 6.0	3.0	3.0	Mature	Good	Shedding limb / limbs - Historic. Shedding limb / limbs - Major.	311.7	10.0	40+	A	1
H1203	200 100 10 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Fraxinus excelsior* Ash *Acer pseudoplatanus* Sycamore	3.0	1	12	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Numbers approximate.	6.5	1.4	40+	C	2
T1204	1	*Quercus robur* English Oak	18.0	1	105	N 10.0 E 11.0 S 9.0 W 9.0	1.0	2.0	Mature	Good	Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Shedding limb / limbs - Recent.	498.8	12.6	40+	A	1
H1205	20 3	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Numbers approximate.	4.5	1.2	40+	C	2
T1207	1	*Quercus robur* English Oak	7.0	1	26	N 2.5 E 2.5 S 2.5 W 2.5	1.5	1.0	Semi Mature	Good	Good long-term potential.	30.6	3.1	40+	C	1
T1208	1	*Quercus robur* English Oak	8.0	1	26	NW 4.0 NE 3.0 SE 3.0 SW 3.0	1.5	1.0	Semi Mature	Good	Base / stems obscured - Vegetation. Good long-term potential.	30.6	3.1	40+	C	1
T1209	1	*Quercus robur* English Oak	7.0	1	23	N 3.0 E 3.0 S 3.0 W 3.0	2.0	1.5	Semi Mature	Good	Good long-term potential.	23.9	2.8	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1210	1	*Quercus robur* English Oak	7.0	1	25	N E S W 3.0 3.0 3.0 3.0	2.0	2.0	Semi Mature	Good	Good long-term potential.	28.3	3.0	40+	C	1
T1211	1	*Quercus robur* English Oak	5.0	1	17	N E S W 2.5 2.5 2.5 2.5	1.5	1.5	Semi Mature	Fair	Good long-term potential.	13.1	2.0	40+	C	1
H1212	200 100	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	1.5	1	10	N E S W 0.5 0.5 0.5 0.5	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Numbers approximate.	4.5	1.2	40+	C	2
H1213	50 20	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	1.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Numbers approximate. Gappy and uneven height.	4.5	1.2	20-40	C	2
H1214	10	*Crataegus monogyna* Common Hawthorn/Quick/May	1.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Numbers approximate. Hedge remnant.	4.5	1.2	20-40	C	2
H1215	5	*Crataegus monogyna* Common Hawthorn/Quick/May	1.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Numbers approximate. Hedge remnant.	4.5	1.2	20-40	C	2
H1216	3	*Crataegus monogyna* Common Hawthorn/Quick/May	1.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Numbers approximate. Hedge remnant.	4.5	1.2	20-40	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1217	200 200	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May	1.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Gappy and uneven height. Numbers approximate. **Fell - Ground level.** Remove a 5-m span. To facilitate development.	4.5	1.2	20-40	C	2
T1218	1	*Acer pseudoplatanus* Sycamore	11.0	1	45	N E S W 5.0 5.0 5.0 5.0	2.5	2.0	Early Mature	Good	Epicormic growth - Base / bole / principal stems.	91.6	5.4	40+	B	1
T1219	1	*Acer pseudoplatanus* Sycamore	12.0	1	45	N E S W 5.0 6.0 5.0 6.0	2.5	2.5	Early Mature	Good	Epicormic growth - Base / bole / principal stems.	91.6	5.4	40+	B	1
H1220	40 25 3 1	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Acer pseudoplatanus* Sycamore *Quercus robur* English Oak	1.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Numbers approximate.	4.5	1.2	40+	C	2
H1221	25 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder	2.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Numbers approximate.	4.5	1.2	40+	C	2
T1233	1	*Quercus robur* English Oak	16.0	1	108	NW NE SE SW 7.0 10.0 9.0 9.0	0.5	3.0	Mature	Good	Deadwood - Major. Form - Low canopy. Shedding limb / limbs - Historic. Shedding limb / limbs - Major.	527.7	13.0	40+	A	1 3

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1234	1	*Quercus robur* English Oak	12.0	1	100	NW 6.0 NE 7.0 SE 6.0 SW 6.0	0.5	2.0	Mature	Good	Deadwood - Minor. Decay / structural defect - Bole. Epicormic growth - Base / bole / principal stems. Form - Low canopy. Hollow trunk - Open cavity. Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Top blown out historically. Large lighting scar from top of bole to base. Veteran features.	452.4	12.0	40+	A	1 3
T1235	1	*Quercus robur* English Oak	9.0	1	26	N 4.0 E 4.0 S 4.0 W 4.0	0.5	1.0	Semi Mature	Good	Form - Low canopy. Good long-term potential.	30.6	3.1	40+	C	1
H1236	25 25	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Numbers approximate.	4.5	1.2	20-40	C	2
H1237	25 25	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Numbers approximate.	4.5	1.2	20-40	C	2
T1238	1	*Acer pseudoplatanus* Sycamore	9.0	1	35	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Semi Mature	Good	Epicormic growth - Base / bole / principal stems.	55.4	4.2	40+	C	1
T1239	1	*Acer pseudoplatanus* Sycamore	12.0	1	40	N 4.0 E 4.0 S 4.0 W 4.0	3.0	1.5	Early Mature	Fair	Epicormic growth - Base / bole / principal stems. Slightly sparse crown.	72.4	4.8	40+	C	1
T1240	1	*Acer pseudoplatanus* Sycamore	6.0	1	25	N 2.0 E 2.0 S 2.0 W 2.0	2.0	2.0	Semi Mature	Dead	Dead tree / trees.			0-10	U	

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1241	1	*Acer pseudoplatanus* Sycamore	11.0	1	32	N E S W 4.0 4.0 3.0 4.0	2.5	1.5	Early Mature	Fair	Epicormic growth - Base / bole / principal stems. Slightly sparse crown.	46.3	3.8	40+	C	1
T1242	1	*Aesculus hippocastanum* Horse Chestnut	16.0	1	110	N E S W 8.0 9.0 9.0 9.0	3.0	2.0	Mature	Fair	Arboricultural work - Historic. Branch - Suspended. Shedding limb / limbs - Major. Shedding limb / limbs - Recent.	547.4	13.2	20-40	B	1
H1243	100 50	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	2.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Numbers approximate.	4.5	1.2	40+	C	2
T1244	1	*Acer pseudoplatanus* Sycamore	12.0	1	47	N E S W 6.0 5.0 4.0 6.0	4.0	3.0	Early Mature	Good	Base / stems obscured - Vegetation. Ivy or climbing plant.	99.9	5.6	40+	B	1
T1252	1	*Quercus robur* English Oak	19.0	1	52	NW NE SE SW 6.0 2.0 4.0 6.0	3.0	2.5	Early Mature	Good	Shedding limb / limbs - Major. Shedding limb / limbs - Recent. Unbalanced crown - Major. Woodland edge specimen. Half of crown recently torn out.	122.3	6.2	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
W1253	50 30 10 10 1	*Acer pseudoplatanus* Sycamore *Quercus robur* English Oak *Salix caprea* Goat Willow/Great Sallow *Fraxinus excelsior* Ash *Malus sp.* Apple sp.	14.0	1	35	NW 4.0 NE 2.0 SE 4.0 SW 4.0	1.0	2.0	Early Mature	Fair	Die-back - Upper crown. Decline - Evident / observed. Dead tree / trees. Edge of plantation woodland, predominantly sycamore and oak. Some deaths from sooty bark disease. Stems c. 4.5 m from eastern edge of track; canopies overhang track by c 2 m. Numbers approximate. Chalara (ash dieback) present. Moderate symptoms. Blackthorn understorey at edge.	55.4	4.2	40+	B	2
T1254	1	*Quercus robur* English Oak	14.0	1	101	NW 6.0 NE 7.0 SE 8.0 SW 7.0	3.0	5.0	Mature	Good	Arboricultural work - Historic. Deadwood - Minor. Root damage - Mammal. Reaction wood / Adaptive growth - Base. Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Sheep tree.	461.5	12.1	40+	A	1
T1255	1	*Quercus robur* English Oak	14.0	1	102	NW 9.0 NE 5.0 SE 9.0 SW 7.0	1.0	4.0	Mature	Good	Arboricultural work - Historic. Deadwood - Minor. Form - Low canopy. Root damage - Mammal. Reaction wood / Adaptive growth - Base. Shedding limb / limbs - Minor. Shedding limb / limbs - Recent. Sheep tree.	470.7	12.2	40+	A	1
W1256	25	*Quercus robur* English Oak	13.0	1	50	N 5.0 E 5.0 S 5.0 W 5.0	2.0	1.5	Early Mature	Good	Woodland edge. Predominantly early mature oak standards with hazel coppice. Closest stems c. 4 m from path edge, canopies overhang track by 2 m. Mixed hedge of hawthorn, field maple, blackthorn e at western edge.	113.1	6.0	40+	A	1 3

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
W1257	15 10 5 1	*Quercus robur* English Oak *Acer pseudoplatanus* Sycamore *Fraxinus excelsior* Ash *Betula pendula* Silver Birch	14.0	1	35	NW 4.0 NE 4.0 SE 4.0 SW 5.0	1.0	2.0	Early Mature	Good	Edge of plantation woodland, predominantly sycamore and oak. Stems c. 7 m from eastern edge of track; canopies do not overhang track. Numbers approximate. Chalara (ash dieback) present. Moderate symptoms. Blackthorn and hawthorn understorey at edge.	55.4	4.2	40+	B	2
G1258	5 5 2	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Acer pseudoplatanus* Sycamore	5.0	10	18	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Semi Mature	Good	Coppice stool - Regrown. Planted shelterbelt.	16.3	2.3	40+	C	2
T1259	1	*Quercus robur* English Oak	14.0	1	90	NW 5.0 NE 8.0 SE 8.0 SW 8.0	1.0	4.0	Mature	Good	Arboricultural work - Historic. Epicormic growth - Base / bole / principal stems. Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Growing on north bank of ditch.	366.4	10.8	40+	B	2
T1260	1	*Acer pseudoplatanus* Sycamore	15.0	3	43	NW 3.0 NE 4.0 SE 4.0 SW 4.0	1.0	1.5	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Growing on north bank of ditch.	84.8	5.2	40+	C	1
T1261	1	*Quercus robur* English Oak	14.0	1	63	NW 5.0 NE 7.0 SE 7.0 SW 7.0	1.0	2.5	Early Mature	Good	Arboricultural work - Historic. Epicormic growth - Base / bole / principal stems. Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Growing on north bank of ditch.	179.6	7.6	40+	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1262	1	*Quercus robur* English Oak	14.0	1	80	NW 6.0 NE 8.0 SE 7.0 SW 9.0	3.0	2.5	Mature	Good	Epicormic growth - Base / bole / principal stems. Ivy or climbing plant. Growing on north bank of ditch.	289.5	9.6	40+	B	2
T1263	1	*Fraxinus excelsior* Ash	12.0	1	50	NW 3.0 NE 3.0 SE 1.0 SW 7.0	4.0	2.0	Early Mature	Poor	Die-back - Throughout crown. Decline - Evident / observed. Deadwood - Major. Chalara (ash dieback) present. Severe symptoms.			0-10	U	
G1264	3 2 1	*Fraxinus excelsior* Ash *Acer pseudoplatanus* Sycamore *Quercus robur* English Oak	8.0	1	35	N 3.0 E 3.0 S 3.0 W 3.0	0.0	1.0	Early Mature	Fair	Growing on north bank of ditch. Chalara (ash dieback) present. Moderate symptoms. Hawthorn understorey.	55.4	4.2	40+	C	2
T1265	1	*Quercus robur* English Oak	15.0	1	92	N 4.0 E 4.0 S 4.0 W 4.0	1.5	4.0	Early Mature	Good	Arboricultural work - Historic. Deadwood - Minor. Decay / structural defect - Base. Decay / structural defect - Open cavity / cavities. Reaction wood / Adaptive growth - Base. Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Starting to stag-head. Sheep tree. Veteran features.	382.9	11.0	40+	B	1
T1266	1	*Quercus robur* English Oak	14.0	1	130	NW 5.0 NE 9.0 SE 11.0 SW 7.0	3.0	3.0	Mature	Good	Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Growing on North bank of ditch. Twin-stemmed at 2 m.	706.9	15.0	40+	A	1 2
T1267	1	*Quercus robur* English Oak	10.0	1	40	N 4.0 E 4.0 S 4.0 W 4.0	1.0	2.5	Early Mature	Good	Growing on north bank of ditch.	72.4	4.8	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1268	1	*Quercus robur* English Oak	14.0	1	102	NW 7.0 NE 10.0 SE 6.0 SW 9.0	3.0	2.0	Mature	Good	Arboricultural work - Historic. Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Growing on north bank of ditch. Twin-stemmed at 2 m.	470.7	12.2	40+	A	1 2
T1269	1	*Quercus robur* English Oak	9.0	1	40	NW 6.0 NE 3.0 SE 8.0 SW 2.0	1.0	1.5	Early Mature	Fair	Arboricultural work - Historic. Growing on north bank of ditch.	72.4	4.8	40+	C	1
T1270	1	*Quercus robur* English Oak	9.0	1	30	NW 5.0 NE 2.0 SE 4.0 SW 2.0	2.0	4.0	Early Mature	Fair	Growing on north bank of ditch.	40.7	3.6	40+	C	1
T1271	1	*Quercus robur* English Oak	9.0	1	27	NW 4.0 NE 2.0 SE 5.0 SW 3.0	2.0	3.0	Early Mature	Fair	Epicormic growth - Base / bole / principal stems. Growing on north bank of ditch.	33.0	3.2	40+	C	1
T1272	1	*Quercus robur* English Oak	16.0	1	75	NW 6.0 NE 4.0 SE 6.0 SW 8.0	4.0	4.0	Early Mature	Good	Growing on north bank of ditch.	254.5	9.0	40+	B	1
T1273	1	*Quercus robur* English Oak	10.0	1	45	NW 5.0 NE 4.0 SE 6.0 SW 4.0	3.0	2.0	Early Mature	Good	Growing on north bank of ditch.	91.6	5.4	40+	B	1
T1274	1	*Quercus robur* English Oak	10.0	1	35	NW 5.0 NE 6.0 SE 5.0 SW 6.0	3.0	2.5	Early Mature	Good	Growing on north bank of ditch.	55.4	4.2	40+	B	1
T1275	1	*Quercus robur* English Oak	11.0	1	55	NW 5.0 NE 9.0 SE 7.0 SW 6.0	2.0	2.0	Early Mature	Good	Base / stems obscured - Vegetation. Growing on north bank of ditch.	136.8	6.6	40+	B	1
T1276	1	*Quercus robur* English Oak	11.0	1	30	NW 3.0 NE 2.0 SE 4.0 SW 5.0	2.0	3.0	Early Mature	Good	Epicormic growth - Bole / principal stems. Growing on north bank of ditch.	40.7	3.6	40+	C	1
T1277	1	*Quercus robur* English Oak	11.0	1	90	NW 6.0 NE 6.0 SE 6.0 SW 6.0	3.5	3.0	Mature	Fair	Die-back - Upper crown. Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Growing on north bank of ditch.	366.4	10.8	40+	A	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1278	1	*Quercus robur* English Oak	14.0	1	105	NW 5.0 NE 9.0 SE 7.0 SW 7.0	1.0	2.0	Mature	Fair	Arboricultural work - Historic. Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Reaction wood / Adaptive growth - Base. Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Growing on north bank of ditch.	498.8	12.6	40+	A	1
T1279	1	*Acer campestre* Field Maple	10.0	1	75	NW 4.0 NE 5.0 SE 5.0 SW 5.0	3.0	1.5	Mature	Good	Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems. Growing on north bank of ditch. Slightly sparse crown.	254.5	9.0	40+	B	1
T1280	1	*Fraxinus excelsior* Ash	12.0	1	40	NW 4.0 NE 4.0 SE 4.0 SW 1.0	5.0	4.0	Early Mature	Dead	Dead tree / trees.			0-10	U	
T1281	1	*Quercus robur* English Oak	10.0	2	120	NW 4.0 NE 3.0 SE 3.0 SW 6.0	3.0	3.0	Mature	Good	Epicormic growth - Base / bole / principal stems. Growing on north bank of ditch. Twin stemmed at 2 m	653.7	14.4	40+	B	1
T1282	1	*Fraxinus excelsior* Ash	11.0	3	66	NW 5.0 NE 3.0 SE 5.0 SW 7.0	2.0	3.0	Early Mature	Fair	Die-back - Throughout crown. Shedding limb / limbs - Major. Shedding limb / limbs - Recent. Chalara (ash dieback) present. Moderate symptoms.	202.4	8.0	10-20	C	1
G1283	2	*Quercus robur* English Oak	9.0	1	30	N 4.0 E 4.0 S 4.0 W 4.0	3.0	2.0	Semi Mature	Good		40.7	3.6	40+	C	1
G1284	2	*Quercus robur* English Oak	9.0	1	30	N 4.0 E 4.0 S 4.0 W 4.0	3.0	2.0	Semi Mature	Good		40.7	3.6	40+	C	1
T1285	1	*Fraxinus excelsior* Ash	8.0	1	40	N 3.0 E 3.0 S 4.0 W 3.0	2.0	2.0	Early Mature	Poor	Die-back - Throughout crown. Chalara (ash dieback) present. Moderate symptoms.	72.4	4.8	10-20	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1286	50 50 10 5 5	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple *Fraxinus excelsior* Ash *Acer pseudoplatanus* Sycamore	2.0	1	15	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown. Gappy. Growing on north bank of ditch. Numbers approximate.	10.2	1.8	40+	C	2
T1287	1	*Cerasus serrulata* Japanese Cherry	8.0	1	35	N 4.0 E 5.0 S 4.0 W 4.0	1.0	1.5	Early Mature	Good	On neighbouring land (garden).	55.4	4.2	40+	C	1
T1288	1	*Castanea sativa* Sweet Chestnut	9.0	1	35	N 3.0 E 3.0 S 4.0 W 4.0	1.0	2.0	Early Mature	Good	On neighbouring land (garden).	55.4	4.2	40+	C	1
T1289	1	*Pinus sylvestris* Scots Pine	9.0	1	20	NW 3.0 NE 3.0 SE 3.0 SW 1.0	2.5	2.0	Semi Mature	Good	On neighbouring land (garden).	18.1	2.4	40+	C	1
T1290	1	*Castanea sativa* Sweet Chestnut	9.0	1	30	N 3.0 E 3.0 S 4.0 W 2.0	1.0	2.0	Early Mature	Good	On neighbouring land (garden).	40.7	3.6	40+	C	1
T1291	1	*Betula pendula* Silver Birch	9.0	1	15	N 3.0 E 3.0 S 3.0 W 3.0	2.0	2.0	Semi Mature	Good	On neighbouring land (garden).	10.2	1.8	40+	C	1
T1292	1	*Betula pendula* Silver Birch	12.0	1	30	N 3.0 E 3.0 S 3.0 W 3.0	1.0	2.5	Early Mature	Good	On neighbouring land (garden).	40.7	3.6	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1293	1	*Juglans regia* Walnut	7.0	1	15	N 2.0 E 2.0 S 2.0 W 2.0	1.0	2.0	Semi Mature	Good	On neighbouring land (garden).	10.2	1.8	40+	C	1
T1294	1	*Pinus sylvestris* Scots Pine	9.0	1	28	N 3.0 E 3.0 S 4.0 W 3.0	2.0	2.0	Early Mature	Good	On neighbouring land (garden).	35.5	3.4	40+	C	1
T1295	1	*Juglans regia* Walnut	7.0	1	15	N 2.0 E 2.0 S 2.0 W 1.0	1.0	2.0	Semi Mature	Good	On neighbouring land (garden).	10.2	1.8	40+	C	1
T1296	1	*Betula pendula* Silver Birch	10.0	1	25	N 3.0 E 3.0 S 3.0 W 2.0	1.0	1.5	Early Mature	Good	On neighbouring land (garden).	28.3	3.0	40+	C	1
T1297	1	*Fagus sylvatica* Common Beech	6.0	1	12	N 2.0 E 2.0 S 2.0 W 1.0	1.0	1.0	Semi Mature	Good	On neighbouring land (garden).	6.5	1.4	40+	C	1
G1298	4	*Pinus sylvestris* Scots Pine	9.0	1	15	N 2.0 E 2.0 S 2.0 W 2.0	1.0	1.0	Semi Mature	Good	On neighbouring land (garden).	10.2	1.8	40+	C	1
H1299	20 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Numbers approximate.	4.5	1.2	40+	C	1
H1300	70 30	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	2.5	1	15	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Mature	Good	Hedgerow - Maintained. Numbers approximate.	10.2	1.8	40+	C	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1301	60 10 6	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Sambucus nigra* Elder	2.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Numbers approximate.	4.5	1.2	40+	C	2
T1302	1	*Salix fragilis* Crack Willow	14.0	6	73	N E S W 6.0 6.0 4.0 6.0	1.5	2.5	Mature	Fair	Decay / structural defect - Open cavity / cavities. Decay / structural defect - Bole. Multi-stemmed. Pollard - Lapsed / Mature stems. Low pollard; mature regrowth from shattered bole. Growing on north bank of ditch.	244.3	8.8	20-40	C	1
H1303	60 10 6	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Sambucus nigra* Elder	2.0	1	15	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Numbers approximate. Gappy.	10.2	1.8	40+	C	2
T1304	1	*Quercus robur* English Oak	16.0	1	40	N E S W 7.0 2.0 2.0 5.0	1.0	2.5	Semi Mature	Good		72.4	4.8	40+	C	1
T1305	1	*Quercus robur* English Oak	16.0	1	40	N E S W 7.0 5.0 2.0 2.0	1.0	2.5	Semi Mature	Good		72.4	4.8	40+	C	1
T1306	1	*Quercus robur* English Oak	4.0	1	20	N E S W 2.5 2.5 2.5 2.5	1.0	1.0	Semi Mature	Good	Good long-term potential. Squat form.	18.1	2.4	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1307	1	*Quercus robur* English Oak	6.0	1	25	N E S W 2.0 2.0 3.0 2.0	1.0	1.0	Semi Mature	Good	Good long-term potential.	28.3	3.0	40+	C	1
H1308	80 20 3 1	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder *Acer pseudoplatanus* Sycamore	2.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Numbers approximate.	4.5	1.2	40+	C	2
T1309	1	*Betula pendula* Silver Birch	18.0	2	39	NW NE SE SW 7.0 6.0 3.0 7.0	1.5	3.0	Early Mature	Good	Growing on north bank of ditch.	71.2	4.8	40+	C	1
T1310	1	*Betula pendula* Silver Birch	18.0	4	52	NW NE SE SW 7.0 3.0 3.0 5.0	3.0	3.0	Early Mature	Good	Growing on north bank of ditch.	126.2	6.3	40+	C	1
T1311	1	*Betula pendula* Silver Birch	18.0	3	43	NW NE SE SW 6.0 6.0 3.0 5.0	2.0	2.5	Early Mature	Good	Growing on north bank of ditch.	87.1	5.3	40+	C	1
G1312	6	*Betula pendula* Silver Birch	18.0	1	25	N E S W 4.0 2.0 2.0 2.0	1.0	3.0	Early Mature	Good	Growing on north bank of ditch.	28.3	3.0	40+	C	1 2
T1313	1	*Salix caprea* Goat Willow/Great Sallow	10.0	5	33	N E S W 3.0 3.0 3.0 6.0	1.0	2.0	Early Mature	Fair	Coppice stool - Regrown. Epicormic growth - Base / bole / principal stems. Growing on north bank of ditch.	50.9	4.0	20-40	C	1
T1314	1	*Quercus robur* English Oak	17.0	1	35	N E S W 5.0 6.0 2.0 6.0	2.0	1.5	Semi Mature	Good	Growing on south bank of ditch.	55.4	4.2	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1315	1	*Quercus robur* English Oak	17.0	1	40	NW 6.0 NE 6.0 SE 6.0 SW 2.0	2.0	0.5	Semi Mature	Good	Growing on south bank of ditch.	72.4	4.8	40+	C	1
G1316	2	*Betula pendula* Silver Birch	18.0	1	30	N 4.0 E 4.0 S 4.0 W 4.0	1.0	3.0	Early Mature	Good	Growing on East bank of ditch.	40.7	3.6	40+	C	1 2
W1317	100 20	*Acer pseudoplatanus* Sycamore *Quercus robur* English Oak	13.0	1	20	N 2.0 E 2.0 S 2.0 W 2.0	1.0	1.0	Early Mature	Fair	Sycamore and oak plantation. Hawthorn understorey at edges. Separated from site fields by deep ditches. Numbers approximate.	18.1	2.4	40+	B	2
G1318	3 1	*Acer pseudoplatanus* Sycamore *Quercus robur* English Oak	11.0	1	20	N 3.0 E 3.0 S 3.0 W 3.0	2.0	2.0	Semi Mature	Good	Growing on south bank of ditch.	18.1	2.4	40+	C	1
T1319	1	*Acer pseudoplatanus* Sycamore	9.0	1	30	N 3.0 E 3.0 S 3.0 W 3.0	1.5	0.5	Early Mature	Poor	Die-back - Throughout crown.	40.7	3.6	10-20	C	1
T1320	1	*Quercus robur* English Oak	9.0	1	40	NW 5.0 NE 3.0 SE 4.0 SW 5.0	2.0	2.5	Early Mature	Good	Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems. Growing on south bank of ditch.	72.4	4.8	40+	B	1
T1321	1	*Quercus robur* English Oak	11.0	1	65	NW 6.0 NE 7.0 SE 6.0 SW 6.0	2.0	2.0	Early Mature	Good	Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems. Growing on south bank of ditch.	191.1	7.8	40+	B	1
T1322	1	*Fraxinus excelsior* Ash	8.0	4	40	NW 4.0 NE 6.0 SE 1.0 SW 2.0	3.0	4.0	Semi Mature	Poor	Die-back - Throughout crown. Decline - Evident / observed. Chalara (ash dieback) present. Severe symptoms.			0-10	U	

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1323	1	*Quercus robur* English Oak	11.0	1	30	NW 2.0 NE 3.0 SE 5.0 SW 6.0	2.0	1.0	Early Mature	Good	Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems. Growing on south bank of ditch. Good long-term potential.	40.7	3.6	40+	C	1
T1324	1	*Quercus robur* English Oak	11.0	1	70	NW 6.0 NE 6.0 SE 6.0 SW 7.0	1.0	2.5	Early Mature	Good	Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Fungal fruiting body - structural decay suspected. Growing on south bank of ditch. Pseudoinonotus dryadeus brackets at base.	221.7	8.4	40+	B	1
T1325	1	*Quercus robur* English Oak	11.0	1	30	NW 5.0 NE 5.0 SE 5.0 SW 5.0	2.0	2.5	Early Mature	Good	Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems. Growing on south bank of ditch. Good long-term potential.	40.7	3.6	40+	C	1
H1326	50 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder	2.5	4	20	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Gappy. Numbers approximate.	18.1	2.4	20-40	C	2
T1327	1	*Acer campestre* Field Maple	4.0	6	24	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Early Mature	Good	Coppice stool - Coppice origin / Mature stems.	27.1	2.9	40+	C	1
T1328	1	*Quercus robur* English Oak	18.0	1	106	NW 8.0 NE 8.0 SE 9.0 SW 9.0	1.5	2.5	Mature	Good	Arboricultural work - Historic. Deadwood - Minor. Epicormic growth - Bole / principal stems. Root damage - Stock. Reaction wood / Adaptive growth - Base. Sheep tree.	508.3	12.7	40+	A	1
H1329	3	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown. Hedge remnant.	4.5	1.2	20-40	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1330	1	*Quercus robur* English Oak	10.0	1	35	N E S W 4.0 4.0 4.0 4.0	2.0	1.5	Early Mature	Good	Good long-term potential. Growing on south bank of ditch.	55.4	4.2	40+	B	1
T1331	1	*Quercus robur* English Oak	9.0	1	83	NW NE SE SW 1.0 2.0 6.0 4.0	0.5	3.0	Mature	Poor	Epicormic growth - Bole / principal stems. North side of crown and tree dead, stem devoid of bark and cambium on this side.	311.7	10.0	10-20	C	1
T1332	1	*Fraxinus excelsior* Ash	14.0	1	52	N E S W 3.0 1.0 4.0 4.0	2.5	3.0	Mature	Fair	Coalesced decay seam - Suspected. Die-back - Upper crown. Fungal fruiting body - structural decay suspected. Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Chalara (ash dieback) present. Moderate symptoms. Growing on north bank of ditch. Mature epicormic stems from base. Inonotus hispidus on stem.	122.3	6.2	10-20	C	1
T1333	1	*Quercus robur* English Oak	14.0	1	94	N E S W 9.0 6.0 6.0 3.0	2.5	2.5	Mature	Good	Growing on north bank of ditch.	399.7	11.3	40+	B	1
T1334	1	*Quercus robur* English Oak	16.0	1	116	N E S W 7.0 10.0 9.0 10.0	2.0	3.0	Mature	Good	Epicormic growth - Bole / principal stems. Shedding limb / limbs - Major. Shedding limb / limbs - Recent. Growing on north bank of ditch.	608.7	13.9	40+	A	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1335	30 20 1 1	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Salix caprea* Goat Willow/Great Sallow *Acer campestre* Field Maple	2.5	1	12	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown. Gappy. Numbers approximate.	6.5	1.4	40+	C	2
T1336	1	*Quercus robur* English Oak	14.0	1	86	NW 9.0 NE 7.0 SE 9.0 SW 7.0	3.0	2.0	Mature	Good	Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Shedding limb / limbs - Historic. Shedding limb / limbs - Minor.	334.6	10.3	40+	A	1
G1337	2	*Fraxinus excelsior* Ash	10.0	1	30	N 3.0 E 3.0 S 3.0 W 3.0	3.0	3.0	Semi Mature	Poor	Die-back - Throughout crown. Decline - Evident / observed. Chalara (ash dieback) present. Severe symptoms. Growing on west bank of ditch.			0-10	U	
T1338	1	*Fraxinus excelsior* Ash	10.0	2	67	NW 5.0 NE 4.0 SE 6.0 SW 2.0	4.0	3.0	Early Mature	Poor	Die-back - Throughout crown. Decline - Evident / observed. Deadwood - Major. Chalara (ash dieback) present. Severe symptoms. Growing on east bank of ditch.			0-10	U	
T1339	1	*Quercus robur* English Oak	13.0	1	72	NW 8.0 NE 8.0 SE 9.0 SW 8.0	3.0	2.0	Mature	Good	Growing on east bank of ditch.	234.5	8.6	40+	A	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1340	1	*Salix fragilis* Crack Willow	16.0	1	216	NW 10.0 NE 10.0 SE 20.0 SW 12.0	0.5	2.0	Ancient or Veteran	Good	Decay / structural defect - Extensive. Decay / structural defect - Bole. Hollow trunk - Open cavity. Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Massive old lapsed pollard. Low branch to south east has layered, branch to north appears to have sent down roots to create 2 new stems.	706.9	15.0	40+	A	3
T1341	1	*Quercus robur* English Oak	8.0	1	20	N 2.0 E 2.0 S 2.0 W 2.0	1.0	2.0	Semi Mature	Good	Base / stems obscured - Vegetation.	18.1	2.4	40+	C	1
T1342	1	*Quercus robur* English Oak	8.0	1	20	N 2.0 E 2.0 S 2.0 W 2.0	2.5	1.5	Semi Mature	Good	Base / stems obscured - Vegetation.	18.1	2.4	40+	C	1
H1343	80 20 3	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Acer campestre* Field Maple	2.5	1	12	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Gappy. Numbers approximate.	6.5	1.4	40+	C	2
T1344	1	*Quercus robur* English Oak	9.0	1	25	N 3.0 E 3.0 S 3.0 W 3.0	2.0	1.5	Semi Mature	Good	Base / stems obscured - Vegetation.	28.3	3.0	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
W1345	30 5 2	*Quercus robur* English Oak *Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash	15.0	1	40	N E S W 4.0 4.0 4.0 4.0	3.0	2.5	Early Mature	Good	Edge trees in oak plantation. Blackthorn hedge understorey. Closest stems c. 3 m from Eastern edge if track. Canopies overhang track by 3 m max. **Reduce lateral limb / limbs.** Prune back c. 3 m from northern end. To facilitate development. **Lift low canopy - Highways clearance.** Lift northern side of crown to 5 m above ground level.	72.4	4.8	40+	B	2
T1346	1	*Quercus robur* English Oak	16.0	1	80	NW NE SE SW 9.0 6.0 8.0 9.0	3.0	2.5	Early Mature	Good		289.5	9.6	40+	B	1
W1347	10	*Pseudotsuga menziesii* Douglas Fir	15.0	1	30	NW NE SE SW 4.0 3.0 3.0 3.0	2.0	3.0	Early Mature	Good	Edge trees in mixed plantation. Crowns overhang path by c. 3 m. Stems c. 1 m from path edge at closest point.	40.7	3.6	40+	B	2
T1348	1	*Acer pseudoplatanus* Sycamore	16.0	1	50	N E S W 5.0 5.0 5.0 5.0	5.0	3.0	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Growing on north bank of ditch.	113.1	6.0	40+	B	1
H1349	30 25 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Acer pseudoplatanus* Sycamore *Fraxinus excelsior* Ash	12.0	1	20	NW NE SE SW 3.0 3.0 1.0 3.0	1.0	1.0	Semi Mature	Good	Growing on north bank of ditch. Multistemmed sycamore and hawthorn outgrown hedge t edge of plantation. Measurements represent average for larger trees (sycamore) in group. Chalara (ash dieback) present. Moderate symptoms.	18.1	2.4	40+	C	2
T1350	1	*Quercus robur* English Oak	16.0	1	50	N E S W 6.0 6.0 6.0 6.0	5.0	3.0	Early Mature	Good	Growing on edge of plantation.	113.1	6.0	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
W1351	10 3 3 1	*Pseudotsuga menziesii* Douglas Fir *Picea sitchensis* Sitka Spruce *Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash	17.0	1	25	NW 4.0 NE 4.0 SE 4.0 SW 4.0	4.0	3.0	Early Mature	Good	Edge trees in plantation. Crowns overhang path by c. 2 m. Stems c. 1 m from path edge at closest point.	28.3	3.0	20-40	C	2
T1352	1	*Quercus robur* English Oak	14.0	1	75	N 5.0 E 5.0 S 5.0 W 5.0	1.0	2.5	Early Mature	Good	Form - Low canopy. Reaction wood / Adaptive growth - Base. Open grown field specimen. Good long-term potential.	254.5	9.0	40+	B	1
T1353	1	*Quercus robur* English Oak	13.0	1	60	N 5.0 E 5.0 S 5.0 W 5.0	1.0	2.5	Early Mature	Good	Form - Low canopy. Reaction wood / Adaptive growth - Base. Open grown field specimen. Good long-term potential.	162.9	7.2	40+	B	1
T1354	1	*Quercus robur* English Oak	13.0	1	60	NW 4.0 NE 4.0 SE 4.0 SW 5.0	1.0	2.5	Early Mature	Good	Form - Low canopy. Reaction wood / Adaptive growth - Base. Open grown field specimen. Good long-term potential.	162.9	7.2	40+	B	1
T1355	1	*Quercus robur* English Oak	13.0	1	60	N 6.0 E 8.0 S 8.0 W 6.0	2.0	2.5	Early Mature	Good	Arboricultural work - Historic. Form - Low canopy. Open grown field specimen. Good long-term potential.	162.9	7.2	40+	B	1
T1356	1	*Quercus robur* English Oak	13.0	1	74	N 7.0 E 6.0 S 5.0 W 7.0	2.0	2.5	Early Mature	Good	Arboricultural work - Historic. Form - Low canopy. Open grown field specimen. Good long-term potential.	247.7	8.9	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1357	1	*Quercus robur* English Oak	13.0	1	74	NW 8.0 NE 8.0 SE 8.0 SW 8.0	1.0	2.5	Early Mature	Good	Form - Low canopy. Reaction wood / Adaptive growth - Base. Open grown field specimen. Good long-term potential.	247.7	8.9	40+	B	1
T1358	1	*Quercus robur* English Oak	13.0	1	91	NW 6.0 NE 8.0 SE 7.0 SW 8.0	1.5	3.0	Early Mature	Good	Form - Low canopy. Reaction wood / Adaptive growth - Base. Open grown field specimen. Good long-term potential.	374.6	10.9	40+	B	1
T1359	1	*Quercus robur* English Oak	13.0	1	72	NW 7.0 NE 5.0 SE 4.0 SW 8.0	2.5	3.0	Early Mature	Fair	Die-back - Upper crown. Deadwood - Minor. Open grown field specimen. Good long-term potential.	234.5	8.6	40+	B	1
T1360	1	*Quercus robur* English Oak	13.0	1	66	NW 6.0 NE 6.0 SE 6.0 SW 6.0	2.5	3.0	Early Mature	Fair	Die-back - Upper crown. Deadwood - Minor. Open grown field specimen. Good long-term potential.	197.1	7.9	40+	B	1
T1361	1	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	30	NW 3.0 NE 1.5 SE 3.0 SW 1.5	0.5	0.5	Mature	Fair	Hedge remnant.	40.7	3.6	20-40	C	1
T1362	1	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	30	N 1.5 E 3.0 S 1.5 W 3.0	0.5	0.5	Mature	Fair	Hedge remnant.	40.7	3.6	20-40	C	1
T1363	1	*Quercus robur* English Oak	13.0	1	58	NW 3.0 NE 6.0 SE 3.0 SW 7.0	2.5	3.0	Early Mature	Good	Deadwood - Minor. Decay / structural defect - Bole. Epicormic growth - Base. Shedding limb / limbs - Historic. Shedding limb / limbs - Major.	152.2	7.0	40+	B	1
T1364	1	*Quercus robur* English Oak	13.0	1	69	NW 3.0 NE 7.0 SE 5.0 SW 8.0	3.0	3.0	Early Mature	Good	Deadwood - Minor.	215.4	8.3	40+	B	1
T1365	1	*Quercus robur* English Oak	13.0	1	78	NW 7.0 NE 7.0 SE 5.0 SW 9.0	2.0	2.5	Early Mature	Good	Deadwood - Minor.	275.2	9.4	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1366	6	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	15	N 2.0 E 2.0 S 2.0 W 2.0	0.5	0.5	Early Mature	Good	Hedgerow - Neglected / overgrown. Hedge remnant.	10.2	1.8	40+	C	2
T1367	1	*Quercus robur* English Oak	18.0	2	60	N 3.0 E 7.0 S 6.0 W 7.0	1.0	2.5	Early Mature	Good		164.0	7.2	40+	B	1
T1368	1	*Quercus robur* English Oak	18.0	1	45	N 3.0 E 7.0 S 6.0 W 7.0	1.0	3.0	Early Mature	Good		91.6	5.4	40+	B	1
G1369	10	*Fraxinus excelsior* Ash	16.0	1	25	NW 3.0 NE 3.0 SE 4.0 SW 3.0	2.0	2.5	Early Mature	Fair	Woodland edge group. Chalara (ash dieback) present. Moderate symptoms.	28.3	3.0	10-20	C	1
G1370	3	*Fraxinus excelsior* Ash	16.0	4	50	NW 3.0 NE 3.0 SE 5.0 SW 3.0	1.5	3.0	Early Mature	Fair	Woodland edge group. Chalara (ash dieback) present. Moderate symptoms.	113.1	6.0	10-20	C	1
W1371	50 20 20	*Quercus robur* English Oak *Fraxinus excelsior* Ash *Acer pseudoplatanus* Sycamore	14.0	1	25	NW 3.0 NE 3.0 SE 4.0 SW 3.0	2.0	2.0	Early Mature	Good	Mixed broadleaf woodland strip. Numbers approximate. Hawthorn hedge along southern boundary.	28.3	3.0	40+	B	2
T1372	1	*Quercus robur* English Oak	12.0	1	40	NW 7.0 NE 6.0 SE 6.0 SW 5.0	1.0	2.5	Early Mature	Good	Base / stems obscured - Vegetation.	72.4	4.8	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1373	45 2 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Quercus robur* English Oak *Acer pseudoplatanus* Sycamore	2.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.5	Early Mature	Fair	Hedgerow - Neglected / overgrown. Growing on south bank of ditch.	4.5	1.2	40+	C	2
T1374	1	*Quercus robur* English Oak	16.0	1	45	NW NE SE SW 7.0 8.0 6.0 8.0	1.5	4.0	Early Mature	Good	Growing on north bank of ditch.	91.6	5.4	40+	B	1
T1375	1	*Quercus robur* English Oak	18.0	1	40	NW NE SE SW 6.0 4.0 5.0 7.0	2.0	3.0	Early Mature	Good	Growing on north bank of ditch.	72.4	4.8	40+	B	1
T1376	1	*Quercus robur* English Oak	9.0	1	15	NW NE SE SW 2.5 2.5 2.5 1.0	3.0	3.0	Semi Mature	Good	Growing on south bank of ditch.	10.2	1.8	40+	C	1
T1377	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	2	28	N E S W 2.0 0.5 3.0 3.0	0.0	0.5	Mature	Fair	Hedge remnant.	36.2	3.4	40+	C	1
T1378	1	*Fraxinus excelsior* Ash	10.0	8	70	N E S W 7.0 7.0 6.0 6.0	1.5	2.0	Early Mature	Good	Coppice stool - Coppice origin / Mature stems. Hedge remnant.	226.2	8.5	40+	C	1
T1379	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	40	N E S W 3.0 4.0 3.0 3.0	0.0	0.5	Mature	Fair	Hedge remnant.	72.4	4.8	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1380	6 3	*Fraxinus excelsior* Ash *Crataegus monogyna* Common Hawthorn/Quick/May	15.0	3	49	N E S W 4.0 3.0 3.0 3.0	4.0	0.5	Early Mature	Poor	Coppice stool - Coppice origin / Mature stems. Die-back - Upper crown. Old hedge specimens. Chalara (ash dieback) present. Moderate symptoms.	109.7	5.9	10-20	C	2
T1381	1	*Fraxinus excelsior* Ash	14.0	7	52	N E S W 4.0 4.0 4.0 4.0	6.0	4.0	Early Mature	Poor	Coppice stool - Coppice origin / Mature stems. Die-back - Throughout crown. Decline - Evident / observed. Chalara (ash dieback) present. Severe symptoms.			0-10	U	
T1382	1	*Fraxinus excelsior* Ash	12.0	3	55	N E S W 8.0 3.0 7.0 2.0	3.0	3.0	Early Mature	Fair	Coppice stool - Coppice origin / Mature stems. Die-back - Upper crown. Chalara (ash dieback) present. Moderate symptoms.	136.8	6.6	10-20	C	1
H1383	8	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	20	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Mature	Fair	Hedge remnant.	18.1	2.4	20-40	C	2
T1384	1	*Fraxinus excelsior* Ash	15.0	5	55	N E S W 5.0 5.0 5.0 6.0	0.0	0.5	Early Mature	Fair	Coppice stool - Coppice origin / Mature stems. Die-back - Throughout crown. Chalara (ash dieback) present. Moderate symptoms.	141.4	6.7	10-20	C	1
H1385	2 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash	3.0	1	20	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Mature	Fair	Hedge remnant.	18.1	2.4	20-40	C	2
T1386	1	*Quercus robur* English Oak	14.0	1	100	NW NE SE SW 8.0 8.0 9.0 10.0	1.5	7.0	Mature	Good	Arboricultural work - Historic. Epicormic growth - Base / bole / principal stems. Shedding limb / limbs - Historic. Shedding limb / limbs - Major.	452.4	12.0	40+	A	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1387	25 1	*Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel	4.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Numbers approximate.	4.5	1.2	40+	C	2
T1388	1	*Quercus robur* English Oak	14.0	1	102	NW NE SE SW 8.0 9.0 11.0 11.0	3.0	4.0	Mature	Good	Arboricultural work - Historic. Epicormic growth - Base / bole / principal stems.	470.7	12.2	40+	A	1
H1389	60 25 10 5	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Fraxinus excelsior* Ash	4.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Numbers approximate. Gappy at Southern end. **Fell - Ground level.** Remove a 5-m span. To facilitate development.	4.5	1.2	40+	C	2
G1390	20	*other* Other	13.0	1	60	N E S W 4.0 4.0 4.0 4.0	2.0	2.0	Early Mature	Good		162.9	7.2	40+	B	2
T1393	1	*Quercus robur* English Oak	13.0	1	71	N E S W 7.0 7.0 7.0 7.0	1.5	1.5	Early Mature	Good	Arboricultural work - Historic. Growing on bank of ditch.	228.0	8.5	40+	B	1
G1394	50	*Ulmus sp.* Elm sp.	9.0	1	10	N E S W 2.0 2.0 2.0 2.0	2.0	1.5	Semi Mature	Fair	Growing on southern bank of ditch. On neighbouring land. Numbers approximate.	4.5	1.2	10-20	C	1
T1395	1	*Quercus robur* English Oak	13.0	3	81	N E S W 7.0 8.0 7.0 10.0	3.0	1.5	Early Mature	Good	Arboricultural work - Historic. Epicormic growth - Base. Leaning trunk - Minor. Growing on northern bank of ditch.	300.8	9.8	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1396	1	*Quercus robur* English Oak	13.0	2	57	N E S W 6.0 6.0 6.0 6.0	1.5	1.0	Early Mature	Good	Epicormic growth - Base. Growing on northern bank of ditch.	148.4	6.9	40+	B	1
T1397	1	*Quercus robur* English Oak	13.0	2	81	NW NE SE SW 8.0 8.0 6.0 7.0	3.0	3.0	Early Mature	Good	Arboricultural work - Historic. Epicormic growth - Base / bole / principal stems. Growing on northern bank of ditch.	299.7	9.8	40+	B	1
T1398	1	*Quercus robur* English Oak	13.0	1	41	NW NE SE SW 5.0 5.0 5.0 5.0	3.0	3.0	Semi Mature	Good	Growing on northern bank of ditch.	76.0	4.9	40+	C	1
T1399	1	*Quercus robur* English Oak	13.0	1	57	N E S W 6.0 7.0 7.0 7.0	2.0	3.0	Early Mature	Good	Branch - Broken. Branch - Suspended. Epicormic growth - Bole / principal stems. Ivy or climbing plant. Growing on northern bank of ditch.	147.0	6.8	40+	B	1
T1400	1	*Quercus robur* English Oak	13.0	1	80	N E S W 7.0 8.0 7.0 8.0	3.0	2.5	Early Mature	Good	Arboricultural work - Historic. Epicormic growth - Base / bole / principal stems. Growing on northern bank of ditch.	289.5	9.6	40+	B	1
T1401	1	*Fraxinus excelsior* Ash	14.0	2	43	NW NE SE SW 2.0 4.0 4.0 4.0	6.0	4.0	Semi Mature	Fair	Epicormic growth - Base / bole / principal stems. Growing on northern bank of ditch. Chalara (ash dieback) present. Minor symptoms.	84.7	5.2	10-20	C	1
G1402	6	*Fraxinus excelsior* Ash	9.0	1	12	N E S W 3.0 3.0 3.0 3.0	1.0	1.0	Semi Mature	Fair	Growing on southern bank of ditch. On neighbouring land.	6.5	1.4	10-20	C	1
T1403	1	*Fraxinus excelsior* Ash	14.0	2	44	NW NE SE SW 4.0 4.0 4.0 4.0	6.0	4.0	Semi Mature	Fair	Epicormic growth - Base / bole / principal stems. Ivy or climbing plant. Growing on northern bank of ditch. Chalara (ash dieback) present. Minor symptoms.	90.9	5.4	10-20	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1404	1	*Quercus robur* English Oak	15.0	1	52	N E S W 7.0 5.0 8.0 5.0	3.0	4.0	Early Mature	Good	Ivy or climbing plant. Growing on northern bank of ditch.	122.3	6.2	40+	B	1
H1405	30	*Ulmus sp.* Elm sp.	5.0	1	5	N E S W 1.5 1.5 1.5 1.5	0.0	0.0	Semi Mature	Fair	Growing on southern bank of ditch. On neighbouring land.	1.1	0.6	10-20	C	1
T1406	1	*Fraxinus excelsior* Ash	14.0	3	43	N E S W 4.0 4.0 4.0 4.0	3.0	2.5	Semi Mature	Fair	Epicormic growth - Base. Growing on southern bank of ditch. On neighbouring land. Chalara (ash dieback) present. Moderate symptoms.	84.8	5.2	20-40	C	1
T1407	1	*Fraxinus excelsior* Ash	11.0	4	27	NW NE SE SW 4.0 4.0 4.0 3.0	3.0	2.0	Semi Mature	Fair	Epicormic growth - Base. Growing on southern bank of ditch. On neighbouring land. Chalara (ash dieback) present. Moderate symptoms.	33.4	3.3	20-40	C	1
T1408	1	*Quercus robur* English Oak	14.0	1	80	NW NE SE SW 6.0 7.0 8.0 6.0	4.0	5.0	Early Mature	Good	Arboricultural work - Recent. Decay / structural defect in crown limb / limbs - Open cavity / cavities. Epicormic growth - Base / bole / principal stems. Ivy or climbing plant. Growing on northern bank of ditch. Large lower limb has recently torn out.	289.5	9.6	40+	B	1
T1409	1	*Alnus glutinosa* Common Alder	16.0	3	69	NW NE SE SW 6.0 7.0 6.0 7.0	3.0	2.5	Early Mature	Good	Epicormic growth - Base. Growing on northern bank of ditch.	217.1	8.3	40+	B	1
T1410	1	*Quercus robur* English Oak	11.0	1	65	NW NE SE SW 3.0 6.0 6.0 5.0	4.0	4.0	Early Mature	Good	Arboricultural work - Recent. Branch - Broken. Decay / structural defect in crown limb / limbs - Open cavity / cavities. Deadwood - Minor. Epicormic growth - Bole / principal stems. Growing on northern bank of ditch. Large lower limb has recently torn out.	191.1	7.8	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1411	1	*Salix fragilis* Crack Willow	4.0	1	130	N E S W 2.0 2.0 2.0 2.0	3.0	2.0	Early Mature	Poor	Fallen tree / trees - Partial collapse. Growing on northern bank of ditch. Tree has collapsed in recent storms.			0-10	U	
T1412	1	*Salix fragilis* Crack Willow	17.0	1	110	NW NE SE SW 6.0 7.0 8.0 8.0	6.0	1.5	Mature	Fair	Arboricultural work - Recent. Growing on southern bank of ditch. On neighbouring land. Recent large limb failure and large tearout wound on stem.	547.4	13.2	40+	B	1
H1413	50 30 5 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Acer campestre* Field Maple *Sambucus nigra* Elder	4.0	1	25	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Early Mature	Good	Growing on southern bank of ditch. On neighbouring land.	28.3	3.0	40+	C	2
T1414	1	*Fraxinus excelsior* Ash	16.0	1	80	N E S W 6.0 8.0 6.0 11.0	5.0	3.0	Mature	Fair	Arboricultural work - Historic. Epicormic growth - Base / bole / principal stems. Ivy or climbing plant. Growing on southern bank of ditch. On neighbouring land. Inaccessible. Measurements estimated. Chalara (ash dieback) present. Minor symptoms.	289.5	9.6	20-40	B	1
T1415	1	*Crataegus monogyna* Common Hawthorn/Quick/May	9.0	1	20	N E S W 2.0 2.0 2.0 2.0	1.0	2.0	Early Mature	Fair	Suppressed crown - Major. Growing on southern bank of ditch. On neighbouring land.	18.1	2.4	20-40	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1416	1	*Crataegus monogyna* Common Hawthorn/Quick/May	8.0	1	55	NW 1.0 NE 1.0 SE 1.0 SW 3.0	2.0	1.5	Early Mature	Fair	Arboricultural work - Recent. Branch - Broken. Ivy or climbing plant. Growing on northern bank of ditch. Recently topped.	136.8	6.6	20-40	C	1
T1417	1	*Salix caprea* Goat Willow/Great Sallow	9.0	1	45	N 4.0 E 5.0 S 4.0 W 5.0	2.5	1.5	Early Mature	Good	Epicormic growth - Base. Growing on northern bank of ditch.	91.6	5.4	40+	C	1
H1418	5 1	*Prunus spinosa* Blackthorn/Sloe *Salix caprea* Goat Willow/Great Sallow	4.0	1	10	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Semi Mature	Good	Growing on southern bank of ditch. On neighbouring land. Hedge remnant.	4.5	1.2	40+	C	1
G1419	2	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	1	6	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Semi Mature	Fair	Growing on southern bank of ditch. Hedge remnant. On neighbouring land.	1.6	0.7	20-40	C	1
T1420	1	*Crataegus monogyna* Common Hawthorn/Quick/May	8.0	5	26	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.5	Early Mature	Fair	Arboricultural work - Recent. Growing on southern bank of ditch. On neighbouring land.	32.6	3.2	20-40	C	1
T1421	1	*Fraxinus excelsior* Ash	9.0	1	20	N 1.0 E 1.0 S 1.0 W 2.0	6.0	4.0	Semi Mature	Fair	Arboricultural work - Recent. Growing on southern bank of ditch. On neighbouring land.	18.1	2.4	20-40	C	1
T1422	1	*Quercus robur* English Oak	13.0	1	80	NW 6.0 NE 7.0 SE 6.0 SW 7.0	2.0	2.2	Early Mature	Fair	Base / stems obscured - Vegetation. Die-back - Upper crown. Epicormic growth - Base / bole / principal stems. Growing on southern bank of ditch.	289.5	9.6	40+	B	1
G1423	20	*Salix fragilis* Crack Willow	18.0	1	45	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Fair	Inaccessible. Measurements estimated. On neighbouring land around perimeter of raised area. Some leaning/partially collapsed specimens.	91.6	5.4	20-40	C	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1424	1	*Tilia x vulgaris* Common Lime	20.0	2	63	N E S W 6.0 6.0 6.0 6.0	0.0	2.0	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Form - Low canopy. Twin-stemmed.	179.7	7.6	40+	B	1
H1425	30 10 3	*Corylus avellana* Common Hazel *Ulmus sp.* Elm sp. *Acer campestre* Field Maple	2.0	15	19	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Dutch elm disease. Dead tree / trees. Hedgerow - Maintained. Multi-stemmed. Growing on southern bank of ditch. Height increases to 6 m on uncut eastern third. **Fell - Ground level.** Remove a 15-m span. To facilitate development.	17.0	2.3	40+	C	2
T1426	1	*Acer campestre* Field Maple	10.0	1	60	N E S W 5.0 7.0 5.0 7.0	3.0	2.5	Early Mature	Good	Epicormic growth - Base. Growing on southern bank of ditch in hedge.	162.9	7.2	40+	B	1
T1427	1	*Crataegus monogyna* Common Hawthorn/Quick/May	8.0	2	42	N E S W 3.0 4.0 3.0 5.0	3.0	0.5	Mature	Good	Epicormic growth - Base. Growing on southern bank of ditch in hedge.	81.4	5.1	40+	C	1
H1428	2	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	3	25	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Early Mature	Fair		30.5	3.1	20-40	C	1
T1429	1	*Acer campestre* Field Maple	13.0	3	51	N E S W 4.0 5.0 4.0 5.0	4.0	4.0	Early Mature	Good	Multi-stemmed. Growing on southern bank of ditch in hedge.	122.1	6.2	40+	B	1
T1430	1	*Acer campestre* Field Maple	15.0	1	65	N E S W 5.0 5.0 5.0 5.0	4.0	2.0	Mature	Good	Base / stems obscured - Vegetation. Ivy or climbing plant. Growing on southern bank of ditch in hedge.	191.1	7.8	40+	B	1
T1431	1	*Fraxinus excelsior* Ash	9.0	1	61	N E S W 3.0 5.0 4.0 3.0	5.0	5.0	Early Mature	Fair	Decay / structural defect - Base. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Bole. Epicormic growth - Crown. Most of crown has failed.	168.3	7.3	20-40	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1432	1	*Fraxinus excelsior* Ash	7.0	2	19	N 2.0 E 2.0 S 2.0 W 2.0	1.0	1.5	Semi Mature	Good		16.7	2.3	40+	C	1
G1433	4	*Populus x canadensis* Hybrid Black Poplars	5.0	3	8	N 2.0 E 2.0 S 2.0 W 2.0	1.0	0.5	Young	Fair		3.4	1.0	20-40	C	1 2
T1434	1	*Fraxinus excelsior* Ash	9.0	1	30	N 3.0 E 3.0 S 3.0 W 3.0	1.0	0.5	Semi Mature	Fair	Growing on eastern bank of ditch. Chalara (ash dieback) present. Minor symptoms. On neighbouring land.	40.7	3.6	10-20	C	1
G1435	15	*Acer pseudoplatanus* Sycamore	18.0	1	50	N 4.0 E 4.0 S 4.0 W 4.0	1.5	1.5	Early Mature	Good	Ivy or climbing plant. Understorey of elder.	113.1	6.0	40+	B	2
T1436	1	*Acer pseudoplatanus* Sycamore	17.0	4	85	N 5.0 E 5.0 S 5.0 W 5.0	3.0	4.0	Early Mature	Good	Base / stems obscured - Vegetation. Epicormic growth - Base. Ivy or climbing plant. Growing on east bank of ditch.	328.0	10.2	40+	B	1
T1437	1	*Acer pseudoplatanus* Sycamore	10.0	1	20	N 2.0 E 2.0 S 2.0 W 2.0	0.5	0.5	Semi Mature	Good	Growing on east bank of ditch.	18.1	2.4	40+	C	1
T1438	1	*Acer pseudoplatanus* Sycamore	17.0	6	61	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Good	Epicormic growth - Base. Ivy or climbing plant. Growing on west bank of ditch. On neighbouring land.	169.6	7.3	40+	B	1
T1439	1	*Acer pseudoplatanus* Sycamore	17.0	1	40	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Good	Epicormic growth - Base. Ivy or climbing plant. Growing on west bank of ditch. On neighbouring land.	72.4	4.8	40+	B	1
T1440	1	*Crataegus monogyna* Common Hawthorn/Quick/May	8.0	6	24	N 3.0 E 3.0 S 3.0 W 3.0	1.0	0.5	Early Mature	Good	Epicormic growth - Base. Growing on east bank of ditch.	27.1	2.9	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1441	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	3	32	N 2.0 E 4.0 S 4.0 W 4.0	1.0	0.5	Early Mature	Good	Branch - Broken. Epicormic growth - Base. Growing on east bank of ditch.	46.4	3.8	40+	C	1
T1442	1	*Salix caprea* Goat Willow/Great Sallow	7.0	6	61	N 5.0 E 3.0 S 6.0 W 3.0	0.0	0.0	Early Mature	Fair	Multi-stemmed. Growing on west bank of ditch. On neighbouring land. Some failed stems.	169.6	7.3	20-40	C	1
H1443	15	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	5	22	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown.	22.6	2.7	40+	C	2
T1444	1	*Acer pseudoplatanus* Sycamore	17.0	6	48	N 3.0 E 3.0 S 3.0 W 1.0	1.0	2.0	Early Mature	Good	Ivy or climbing plant. Multi-stemmed.	108.6	5.9	40+	C	1
T1445	1	*Acer pseudoplatanus* Sycamore	17.0	4	40	N 3.0 E 1.0 S 3.0 W 3.0	1.0	2.0	Early Mature	Good	Ivy or climbing plant. Multi-stemmed.	72.4	4.8	40+	C	1
T1446	1	*Populus nigra 'Italica'* Lomardy Poplar	30.0	1	50	N 2.5 E 2.5 S 2.5 W 2.5	4.0	3.0	Early Mature	Fair	Inaccessible. Measurements estimated. On neighbouring land.	113.1	6.0	40+	C	1 2
T1447	1	*Salix caprea* Goat Willow/Great Sallow	7.0	2	53	N 4.0 E 4.0 S 4.0 W 4.0	0.5	0.5	Early Mature	Good	Inaccessible. Measurements estimated. On neighbouring land.	127.8	6.4	40+	C	1
G1448	25 5 1	*Fraxinus excelsior* Ash *Salix caprea* Goat Willow/Great Sallow *Betula pendula* Silver Birch	14.0	1	30	N 3.0 E 3.0 S 3.0 W 3.0	3.0	2.0	Early Mature	Good	Inaccessible. Measurements estimated. On neighbouring land. Numbers approximate.	40.7	3.6	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1449	15	*Fraxinus excelsior* Ash	10.0	5	17	N 2.0 E 2.0 S 2.0 W 2.0	0.5	0.5	Semi Mature	Fair	Inaccessible. Measurements estimated. On neighbouring land.	14.5	2.1	40+	C	1
T1450	1	*Fraxinus excelsior* Ash	19.0	1	100	N 8.0 E 8.0 S 7.0 W 6.0	5.0	5.0	Early Mature	Fair	Base / stems obscured - Vegetation. Epicormic growth - Base. Ivy or climbing plant. Shedding limb / limbs - Major. Shedding limb / limbs - Recent. Growing on south bank of ditch. Chalara (ash dieback) present. Moderate symptoms. Large recent bough failure and tearout wound on stem.	452.4	12.0	10-20	C	1
T1451	1	*Fraxinus excelsior* Ash	6.0	5	17	N 1.5 E 1.5 S 1.5 W 1.5	1.0	1.0	Young	Fair	Base / stems obscured - Vegetation. Ivy or climbing plant. Growing on south bank of ditch.	14.5	2.1	20-40	C	1
T1452	1	*Quercus robur* English Oak	12.0	1	85	N 7.0 E 7.0 S 7.0 W 7.0	3.0	2.5	Mature	Good	Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems. Ivy or climbing plant. Leaning trunk - Minor. Growing on south bank of ditch.	326.9	10.2	40+	B	1
T1453	1	*Fraxinus excelsior* Ash	14.0	1	52	N 9.0 E 8.0 S 7.0 W 4.0	3.0	1.5	Early Mature	Fair		122.3	6.2	20-40	C	1
T1454	1	*Fraxinus excelsior* Ash	14.0	1	50	N 7.0 E 6.0 S 7.0 W 4.0	3.0	2.0	Early Mature	Fair		113.1	6.0	20-40	C	1
T1455	1	*Fraxinus excelsior* Ash	19.0	4	69	N 4.0 E 9.0 S 7.0 W 4.0	6.0	4.0	Early Mature	Fair	Branch - Broken. Multi-stemmed. Shedding limb / limbs - Major. Shedding limb / limbs - Recent. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	217.6	8.3	20-40	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1456	40	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.5	0.5	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
T1457	1	*Fraxinus excelsior* Ash	18.0	1	70	N 7.0 E 7.0 S 7.0 W 7.0	4.0	4.0	Early Mature	Good	Base / stems obscured - Vegetation. Ivy or climbing plant.	221.7	8.4	40+	B	1
T1458	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	3	43	N 4.0 E 4.0 S 4.0 W 4.0	0.5	0.5	Early Mature	Fair	Ivy or climbing plant. Multi-stemmed.	87.1	5.3	20-40	C	1
H1459	10	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	1	25	N 2.0 E 2.0 S 2.0 W 2.0	0.5	0.5	Early Mature	Fair	Gappy.	28.3	3.0	20-40	C	1 2
T1460	1	*Quercus robur* English Oak	15.0	1	84	N 9.0 E 9.0 S 8.0 W 7.0	4.0	3.0	Mature	Good	Arboricultural work - Historic. Deadwood - Major. Decay / structural defect - Base. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Bole.	319.2	10.1	40+	B	1 2
H1461	25	*Crataegus monogyna* Common Hawthorn/Quick/May	1.0	1	10	N 0.5 E 0.5 S 0.5 W 0.5	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
H1462	100	*Crataegus monogyna* Common Hawthorn/Quick/May	1.0	1	10	N 0.5 E 0.5 S 0.5 W 0.5	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Closely clipped. **Fell - Ground level.** Remove a 7-m span. To facilitate development.	4.5	1.2	40+	C	2
T1463	1	*Quercus robur* English Oak	7.0	1	22	N 2.5 E 2.5 S 2.5 W 2.5	0.5	1.0	Semi Mature	Good	Growing on east bank of ditch. On neighbouring land.	21.9	2.6	40+	C	1
T1464	1	*Quercus robur* English Oak	8.0	4	37	N 3.0 E 3.0 S 3.0 W 1.0	0.5	0.5	Semi Mature	Good	Multi-stemmed. Growing on east bank of ditch. On neighbouring land.	64.5	4.5	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1465	1	*Quercus robur* English Oak	8.0	1	30	N E S W 3.0 4.0 3.0 2.0	2.0	2.5	Early Mature	Good	Arboricultural work - Historic. Multi-stemmed. Growing on east bank of ditch. On neighbouring land.	40.7	3.6	40+	C	1
T1466	1	*Fraxinus excelsior* Ash	15.0	5	55	N E S W 3.0 4.0 3.0 1.5	5.0	4.0	Early Mature	Poor	Arboricultural work - Historic. Arboricultural work - Recent. Multi-stemmed. Poor past pruning. Growing on east bank of ditch. On neighbouring land.	141.4	6.7	10-20	C	1
T1467	1	*Quercus robur* English Oak	8.0	1	40	N E S W 5.0 5.0 5.0 2.0	2.0	3.0	Early Mature	Good	Arboricultural work - Historic. Multi-stemmed. Growing on east bank of ditch. On neighbouring land.	72.4	4.8	40+	C	1
H1468	50	*Prunus spinosa* Blackthorn/Sloe	1.5	1	5	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Growing on west bank of ditch.	1.1	0.6	40+	C	2
H1469	150	*Prunus spinosa* Blackthorn/Sloe	1.5	1	5	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. Growing on east bank of ditch.	1.1	0.6	40+	C	2
T1470	1	*Fraxinus excelsior* Ash	15.0	1	56	N E S W 6.0 4.0 6.0 7.0	4.0	5.0	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Growing on southern bank of ditch. Mature epicormic stems from base. On neighbouring land. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	141.9	6.7	40+	B	1
T1471	1	*Fraxinus excelsior* Ash	6.0	3	32	N E S W 2.0 2.0 2.0 2.0	2.0	2.0	Semi Mature	Fair	On neighbouring land.	46.4	3.8	20-40	C	1
G1472	8	*Betula pendula* Silver Birch	9.0	1	20	N E S W 2.0 2.0 2.0 2.0	2.0	2.5	Semi Mature	Good	On neighbouring land (garden).	18.1	2.4	40+	C	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1473	1	*Betula pendula* Silver Birch	10.0	1	20	N 2.0 E 2.0 S 2.0 W 2.0	2.0	2.0	Semi Mature	Good	On neighbouring land (garden). Inaccessible. Measurements estimated.	18.1	2.4	40+	C	1
T1474	1	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	1	20	N 1.0 E 1.0 S 1.0 W 1.0	1.0	1.0	Semi Mature	Good	On neighbouring land (garden). Inaccessible. Measurements estimated.	18.1	2.4	40+	C	1
G1475	4	*Fraxinus excelsior* Ash	14.0	2	28	N 3.0 E 3.0 S 3.0 W 3.0	3.0	3.0	Semi Mature	Fair	Chalara (ash dieback) present. Minor symptoms. Growing on southern bank of ditch. On neighbouring land.	36.2	3.4	20-40	C	1
T1476	1	*Salix fragilis* Crack Willow	3.0	1	125	N 0.5 E 0.5 S 0.5 W 0.5	3.0	3.0	Mature	Poor	Base / stems obscured - Vegetation. Decay / structural defect - Base. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Bole. Fallen tree / trees - Partial collapse. Ivy or climbing plant. Tree has failed at c. 3 m in recent storm. On neighbouring land.			0-10	U	
T1477	1	*Salix fragilis* Crack Willow	10.0	3	72	N 3.0 E 4.0 S 3.0 W 3.0	3.0	4.0	Early Mature	Fair	Pollard - Regrown. On neighbouring land.	236.4	8.7	40+	C	1
H1478	40 5	*Fraxinus excelsior* Ash *Sambucus nigra* Elder	2.5	1	10	N 0.5 E 0.5 S 0.5 W 0.5	0.5	0.5	Semi Mature	Fair		4.5	1.2	40+	C	2
G1479	10 5	*Salix fragilis* Crack Willow *Quercus robur* English Oak	14.0	1	40	N 3.0 E 3.0 S 3.0 W 3.0	3.0	3.0	Early Mature	Good	On neighbouring land. Inaccessible. Measurements estimated. Numbers approximate. Some willows to the east have been pollarded/coppiced.	72.4	4.8	40+	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1480	15 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Salix fragilis* Crack Willow	8.0	3	34	N E S W 2.0 2.0 2.0 2.0	0.5	0.5	Early Mature	Good	Inaccessible. Measurements estimated. On neighbouring land.	54.3	4.2	40+	C	2
G1481	5 2 1	*Pinus sylvestris* Scots Pine *Betula pendula* Silver Birch *Alnus glutinosa* Common Alder	7.0	1	10	N E S W 1.5 1.5 1.5 1.5	0.0	1.0	Young	Good	On neighbouring land. Random planting.	4.5	1.2	40+	C	2
H1482	10	*Salix sp.* Willow sp.	5.0	1	6	N E S W 1.0 1.0 1.0 1.0	1.0	0.0	Semi Mature	Good	Hedge remnant. Growing on eastern bank of ditch.	1.6	0.7	40+	C	2
T1483	1	*Fraxinus excelsior* Ash	13.0	3	40	N E S W 4.0 4.0 4.0 4.0	3.0	3.0	Early Mature	Fair	Epicormic growth - Base / bole / principal stems. Growing on eastern bank of ditch.	74.6	4.9	20-40	C	1
H1484	5	*Salix sp.* Willow sp.	5.0	3	10	N E S W 1.0 1.0 1.0 1.0	1.0	0.0	Semi Mature	Good	Hedge remnant. Growing on eastern bank of ditch.	4.9	1.2	40+	C	2
T1485	1	*Salix caprea* Goat Willow/Great Sallow	5.0	12	20	N E S W 3.0 1.0 3.0 2.0	0.5	0.5	Semi Mature	Good	Growing on eastern bank of ditch. On neighbouring land.	19.5	2.5	40+	C	1
T1486	1	*Salix caprea* Goat Willow/Great Sallow	5.0	12	20	N E S W 3.0 1.0 3.0 2.0	0.5	0.5	Semi Mature	Good	Growing on eastern bank of ditch. On neighbouring land.	19.5	2.5	40+	C	1
T1487	1	*Alnus glutinosa* Common Alder	8.0	1	10	N E S W 1.5 1.5 1.5 1.5	1.0	1.0	Young	Good	Growing on western bank of ditch.	4.5	1.2	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1488	1	*Alnus glutinosa* Common Alder	7.0	1	10	N E S W 1.5 1.5 1.5 1.5	1.0	1.0	Young	Good	Growing on western bank of ditch.	4.5	1.2	40+	C	1
T1489	1	*Alnus glutinosa* Common Alder	7.0	1	10	N E S W 1.0 1.0 1.0 1.0	1.0	1.0	Young	Good	Growing on western bank of ditch.	4.5	1.2	40+	C	1
G1490	5 1 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple *Populus x canadensis* Hybrid Black Poplars	4.0	3	16	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Young	Good	Growing on eastern bank of ditch.	11.9	1.9	40+	C	2
T1491	1	*Alnus glutinosa* Common Alder	5.0	1	5	N E S W 1.0 1.0 1.0 1.0	1.0	1.0	Young	Good	Growing on western bank of ditch.	1.1	0.6	40+	C	1
T1492	1	*Alnus glutinosa* Common Alder	7.0	1	10	N E S W 1.0 1.0 1.0 1.0	1.0	1.0	Young	Good	Growing on western bank of ditch.	4.5	1.2	40+	C	1
T1493	1	*Alnus glutinosa* Common Alder	7.0	1	10	N E S W 1.0 1.0 1.0 1.0	1.0	1.0	Young	Good	Growing on western bank of ditch.	4.5	1.2	40+	C	1
T1494	1	*Alnus glutinosa* Common Alder	7.0	1	10	N E S W 1.0 1.0 1.0 1.0	1.0	1.0	Young	Good	Growing on western bank of ditch.	4.5	1.2	40+	C	1
T1495	1	*Alnus glutinosa* Common Alder	7.0	1	10	N E S W 1.0 1.0 1.0 1.0	1.0	1.0	Young	Good	Growing on western bank of ditch.	4.5	1.2	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1496	1	*Acer campestre* Field Maple	16.0	8	70	N E S W 5.0 5.0 5.0 5.0	2.5	2.0	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Multi-stemmed. Growing on northern bank of ditch in front of railway fencing. On neighbouring land.	226.2	8.5	40+	B	1 2
T1497	1	*Acer campestre* Field Maple	16.0	2	67	N E S W 5.0 6.0 5.0 6.0	2.5	2.0	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Multi-stemmed. Growing on northern bank of ditch in front of railway fencing. On neighbouring land. Mature epicormic stems from base.	204.7	8.1	40+	B	1 2
T1498	1	*Salix caprea* Goat Willow/Great Sallow	8.0	3	14	N E S W 2.0 2.0 1.0 2.0	1.0	0.5	Young	Good		9.6	1.8	40+	C	1
H1499	15 5 2 2	*Prunus cerasifera* Cherry Plum (Myrobalan) *Fraxinus excelsior* Ash *Acer campestre* Field Maple *Sambucus nigra* Elder	2.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Young	Good	Growing on southern bank of ditch.	4.5	1.2	40+	C	2
T1500	1	*Fraxinus excelsior* Ash	14.0	4	41	N E S W 4.0 4.0 5.0 3.0	3.0	3.0	Semi Mature	Fair	Growing on northern bank of ditch.	79.2	5.0	20-40	C	1
T1501	1	*Fraxinus excelsior* Ash	16.0	3	63	N E S W 5.0 7.0 7.0 6.0	5.0	3.0	Early Mature	Fair	Growing on railway embankment.	183.2	7.6	20-40	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1502	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	1	20	N 2.0 E 2.0 S 2.0 W 2.0	1.5	1.0	Early Mature	Good	Growing on northern bank of ditch.	18.1	2.4	40+	C	1
T1503	1	*Salix fragilis* Crack Willow	24.0	1	135	N 8.0 E 12.0 S 9.0 W 12.0	5.0	2.0	Mature	Good	Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Shedding limb / limbs - Recent. On neighbouring land. On western bank of ditch. Large branch has recently failed over dyke into field edge.	706.9	15.0	40+	B	1
T1504	1	*Crataegus monogyna* Common Hawthorn/Quick/May	8.0	1	12	N 1.0 E 1.0 S 1.0 W 1.0	1.0	1.0	Semi Mature	Good	Growing on eastern bank of ditch.	6.5	1.4	40+	C	1
T1505	1	*Populus alba* White Poplar/Abele	16.0	3	49	N 4.0 E 4.0 S 4.0 W 2.0	3.0	1.5	Early Mature	Good	Growing on eastern bank of ditch.	109.7	5.9	40+	C	1
T1506	1	*Populus alba* White Poplar/Abele	13.0	2	25	N 2.0 E 1.0 S 3.0 W 4.0	0.5	1.0	Semi Mature	Good	Growing on eastern bank of ditch.	28.3	3.0	40+	C	1
G1507	6	*Populus alba* White Poplar/Abele	17.0	1	25	N 3.0 E 3.0 S 3.0 W 3.0	1.0	0.5	Semi Mature	Good	Growing on eastern bank of ditch.	28.3	3.0	40+	C	2
G1508	10	*Populus alba* White Poplar/Abele	20.0	2	63	N 9.0 E 9.0 S 9.0 W 9.0	5.0	3.0	Early Mature	Good	Growing on eastern bank of ditch. Hawthorn understorey.	183.2	7.6	40+	B	2
T1509	1	*Populus alba* White Poplar/Abele	20.0	2	84	N 9.0 E 9.0 S 9.0 W 9.0	5.0	4.0	Early Mature	Good	Inaccessible due to crops. Measurements estimated. Around 0.5 m between stems, but probably one specimen.	325.7	10.2	40+	B	1
T1510	1	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	10	18	N 2.5 E 2.5 S 2.5 W 1.0	0.0	0.0	Semi Mature	Good	Growing on Eastern bank of ditch around electricity pole.	16.3	2.3	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1511	1	*Fraxinus excelsior* Ash	11.0	1	61	N E S W 8.0 8.0 8.0 8.0	0.5	1.5	Early Mature	Good		168.3	7.3	40+	B	1
H1512	2 2 1	*Sambucus nigra* Elder *Prunus cerasifera* Cherry Plum (Myrobalan) *Crataegus monogyna* Common Hawthorn/Quick/May	6.0	1	20	N E S W 2.0 2.0 2.0 2.0	0.5	0.5	Early Mature	Good	Hedgerow - Neglected / overgrown. Hedge remnant.	18.1	2.4	40+	C	2
T1513	1	*Quercus robur* English Oak	8.0	2	49	N E S W 6.0 6.0 6.0 6.0	1.0	1.5	Semi Mature	Good	Good long-term potential.	110.8	5.9	40+	C	1
H1514	10 10	*Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel	1.0	10	15	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Hedge remnant.	11.3	1.9	40+	C	2
T1515	1	*Corylus avellana* Common Hazel	1.5	15	23	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Coppice stool - Regrown. Hedge remnant.	24.4	2.8	40+	C	1
T1516	1	*Salix caprea* Goat Willow/Great Sallow	1.5	2	46	N E S W 0.5 0.5 0.5 0.5	1.5	1.5	Early Mature	Fair	Topped at 1.5 m. Growing in ditch.	96.1	5.5	20-40	C	1
H1517	10 2	*Prunus spinosa* Blackthorn/Sloe *Fraxinus excelsior* Ash	1.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Hedge remnant.	4.5	1.2	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1518	100 2	*Prunus spinosa* Blackthorn/Sloe *Fraxinus excelsior* Ash	1.5	1	10	N E S W 1.5 1.5 1.5 1.5	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Growing on both banks, and in centre of, ditch. Cut on site side.	4.5	1.2	40+	C	2
G1519	5 1	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May	2.0	3	22	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Early Mature	Fair	Inaccessible. Measurements estimated. Scrubby hawthorn group. Topped at 1-2 m	23.2	2.7	20-40	C	2
G1520	4	*Salix sp.* Willow sp.	9.0	2	54	N E S W 2.0 2.0 2.0 2.0	3.0	3.0	Early Mature	Fair	Topped and flailed.	132.3	6.5	20-40	C	1
T1521	1	*Salix caprea* Goat Willow/Great Sallow	8.0	1	50	N E S W 1.0 2.0 2.0 2.0	2.0	2.0	Early Mature	Fair	Topped and flailed. On neighbouring land.	113.1	6.0	20-40	C	1
T1522	1	*Salix caprea* Goat Willow/Great Sallow	9.0	6	61	N E S W 3.0 3.0 3.0 3.0	2.0	1.5	Early Mature	Fair	Topped and flailed. On neighbouring land.	169.6	7.3	20-40	C	1
T1523	1	*Quercus robur* English Oak	10.0	1	70	N E S W 5.0 7.0 6.0 7.0	1.5	2.5	Early Mature	Fair	Inaccessible due to crops. Measurements estimated. Top has fairly recently blown out.	221.7	8.4	40+	B	1 3
T1524	1	*Fraxinus excelsior* Ash	11.0	1	70	N E S W 6.0 6.0 6.0 6.0	1.0	1.0	Early Mature	Good	Inaccessible due to crops. Measurements estimated. Appears to have regrown after being cut at around 1 m.	221.7	8.4	40+	B	1 3

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1525	15 5 5	*Acer campestre* Field Maple *Corylus avellana* Common Hazel *Fraxinus excelsior* Ash	10.0	1	25	N E S W 3.0 3.0 3.0 3.0	0.5	0.5	Semi Mature	Good	Small plantation. Ownership uncertain. Ash in centre suppressed.	28.3	3.0	40+	C	1
T1526	1	*Aesculus hippocastanum* Horse Chestnut	15.0	1	65	N E S W 5.0 5.0 5.0 5.0	2.5	2.0	Early Mature	Good	On neighbouring land. Inaccessible. Measurements estimated.	191.1	7.8	40+	B	1
T1527	1	*Crataegus monogyna* Common Hawthorn/Quick/May	9.0	2	35	N E S W 3.0 3.0 3.0 3.0	1.0	1.0	Early Mature	Fair	On neighbouring land. Inaccessible. Measurements estimated.	56.5	4.2	20-40	C	1
T1528	1	*Acer pseudoplatanus* Sycamore	13.0	2	39	N E S W 4.0 4.0 4.0 4.0	2.0	2.0	Early Mature	Good	On neighbouring land. Inaccessible. Measurements estimated.	69.0	4.7	40+	C	1
T1529	1	*Quercus robur* English Oak	6.0	1	30	N E S W 3.0 4.0 3.0 3.0	0.5	0.5	Semi Mature	Good	Access to inspect base - Not possible. Natural regeneration.	40.7	3.6	10-20	C	1
G1530	3	*Salix caprea* Goat Willow/Great Sallow	10.0	1	25	N E S W 4.0 4.0 4.0 4.0	0.0	0.5	Semi Mature	Good	Access to inspect base - Not possible. Multi-stemmed. Natural regeneration. DBH estimated due to dense undergrowth	28.3	3.0	20-40	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1531	4 1 1	*Salix caprea* Goat Willow/Great Sallow *Crataegus monogyna* Common Hawthorn/Quick/May *Quercus robur* English Oak	10.0	1	35	N 5.0 E 5.0 S 5.0 W 5.0	0.0	0.5	Semi Mature	Good	Access to inspect base - Not possible. Multi-stemmed. Natural regeneration. DBH estimated due to dense undergrowth	55.4	4.2	20-40	B	2
G1532	5	*Salix caprea* Goat Willow/Great Sallow	10.0	1	55	N 6.0 E 6.0 S 6.0 W 6.0	0.5	0.5	Early Mature	Good	Access to inspect base - Not possible. Multi-stemmed. Natural regeneration. Pollard - Lapsed / Mature stems. DBH estimated due to dense undergrowth	136.8	6.6	20-40	B	2
H1533	10 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash	4.0	1	15	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Semi Mature	Good	Hedgerow - Neglected / overgrown. DBH estimated due to dense undergrowth	10.2	1.8	10-20	C	2
T1534	1	*Quercus robur* English Oak	14.0	1	68	N 7.0 E 8.0 S 8.0 W 6.0	2.0	2.5	Early Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Epicormic growth - Bole / principal stems. No significant faults observed. DBH estimated due to dense vegetation.	209.2	8.2	20-40	B	1
T1535	1	*Fraxinus excelsior* Ash	12.0	3	98	N 7.0 E 6.0 S 7.0 W 6.0	1.5	1.5	Mature	Fair	Die-back - Upper crown. Decline - Suspected. Multi-stemmed. No significant faults observed. DBH estimated due to dense vegetation. Die back lesions on tertiary branches consistent with Ash dieback infection.	437.6	11.8	20-40	B	1 2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1536	1	*Crataegus monogyna* Common Hawthorn/Quick/May	7.0	2	47	N E S W 5.0 5.0 2.0 3.0	1.5	1.5	Mature	Fair	Die-back - Upper crown. Decline - Suspected. No significant faults observed. Twin-stemmed. DBH estimated due to dense vegetation.	100.8	5.7	20-40	B	1 2
T1537	1	*Fraxinus excelsior* Ash	13.0	1	63	N E S W 8.0 6.0 7.0 7.0	1.5	2.5	Early Mature	Fair	Die-back - Upper crown. Decline - Suspected. Epicormic growth - Crown. No significant faults observed.	179.6	7.6	20-40	B	1 2
T1538	1	*Fraxinus excelsior* Ash	14.0	1	75	N E S W 9.0 6.0 7.0 7.0	0.5	3.0	Mature	Fair	Die-back - Upper crown. Decline - Suspected. Deadwood - Minor. Epicormic growth - Crown. No significant faults observed.	254.5	9.0	20-40	B	1 2
T1539	1	*Alnus glutinosa* Common Alder	10.0	1	42	N E S W 5.0 4.0 4.0 3.0	0.5	2.5	Early Mature	Fair	Die-back - Throughout crown. Die-back - Upper crown. Decline - Evident / observed. Deadwood - Minor. No significant faults observed.	79.8	5.0	10-20	C	1
H1540	100 80 40 30 15	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Sambucus nigra* Elder *Fraxinus excelsior* Ash *Quercus robur* English Oak	3.5	1	18	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Hedgerow - Neglected / overgrown. **Fell - Ground level.** Remove a 25-m span. To facilitate development.	14.7	2.2	10-20	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1541	50 50	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	2.0	1	18	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Hedgerow - Maintained. Hedgerow assessed with binoculars from river bank.	14.7	2.2	10-20	C	2
H1542	50	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	18	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Hedgerow - Maintained. Hedgerow assessed with binoculars from river bank. **Fell - Ground level.** Remove a 25-m span. To facilitate development.	14.7	2.2	10-20	C	2
H1543	30	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	18	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Hedgerow - Maintained. Hedgerow assessed with binoculars from river bank.	14.7	2.2	10-20	C	2
H1544	20	*Crataegus monogyna* Common Hawthorn/Quick/May	1.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Hedgerow - Maintained. Hedgerow assessed with binoculars from river bank. **Fell - Ground level.** Remove a 16-m span. To facilitate development.	4.5	1.2	10-20	C	2
H1545	30	*Crataegus monogyna* Common Hawthorn/Quick/May	1.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Hedgerow - Maintained. Hedgerow assessed with binoculars from river bank.	4.5	1.2	10-20	C	2
T1546	1	*Quercus robur* English Oak	6.0	1	14	N E S W 2.0 2.5 2.0 2.5	2.5	2.5	Young	Good	Access to inspect base - Not possible. Base / stems obscured - Structure. Young planted tree / trees. DBH estimated due to dense vegetation. **Fell - Ground level.** To facilitate development.	8.9	1.7	20-40	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1547	1	*Quercus robur* English Oak	3.0	1	8	N 1.5 E 1.5 S 1.5 W 1.5	1.5	1.5	Young	Good	Access to inspect base - Not possible. Base / stems obscured - Structure. Young planted tree / trees. DBH estimated due to dense vegetation. **Fell - Ground level.** To facilitate development.	2.9	1.0	20-40	C	1
T1548	1	*Quercus robur* English Oak	3.0	1	8	N 1.5 E 1.5 S 1.5 W 1.5	1.5	1.5	Young	Good	Access to inspect base - Not possible. Base / stems obscured - Structure. Young planted tree / trees. DBH estimated due to dense vegetation. **Fell - Ground level.** To facilitate development.	2.9	1.0	20-40	C	1
T1549	1	*Quercus robur* English Oak	4.0	1	8	N 2.0 E 2.0 S 2.0 W 2.0	1.5	1.5	Young	Good	Access to inspect base - Not possible. Base / stems obscured - Structure. Young planted tree / trees. DBH estimated due to dense vegetation. **Fell - Ground level.** To facilitate development.	2.9	1.0	20-40	C	1
T1550	1	*Quercus robur* English Oak	4.0	1	16	N 2.0 E 2.0 S 2.0 W 2.0	1.5	2.0	Young	Good	Access to inspect base - Not possible. Base / stems obscured - Structure. Young planted tree / trees. DBH estimated due to dense vegetation. **Fell - Ground level.** To facilitate development.	11.6	1.9	20-40	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1551	60 20 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Euonymus sp.* Spindle *Salix caprea* Goat Willow/Great Sallow	1.5	1	10	N E S W 0.5 0.5 0.5 0.5	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** Remove a 176-m span. To facilitate development.	4.5	1.2	20-40	C	2
T1552	1	*Tilia platyphyllos* Large Leaved Lime	12.0	1	58	N E S W 4.0 5.0 5.0 5.0	1.5	2.5	Early Mature	Good	Access to inspect base - Restricted / obscured. Epicormic growth - Base / bole / principal stems. Fork - Suspected structurally sound. Rubbing limbs. DBH estimated due to dense vegetation. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	152.2	7.0	20-40	B	1 2
T1553	1	*Tilia platyphyllos* Large Leaved Lime	8.0	3	37	N E S W 2.0 3.0 3.0 3.0	1.5	2.5	Semi Mature	Good	Access to inspect base - Restricted / obscured. Epicormic growth - Base / bole / principal stems. Fork - Suspected structurally sound. Multi-stemmed. DBH estimated due to dense vegetation. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	64.3	4.5	20-40	B	1 2
T1554	1	*Quercus robur* English Oak	10.0	1	48	N E S W 3.0 5.0 5.0 5.0	1.5	2.5	Semi Mature	Good	Epicormic growth - Bole / principal stems. Fork - Suspected structurally sound. No significant faults observed. **Fell - Ground level.** To facilitate development.	104.2	5.8	20-40	B	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1555	1	*Quercus rubra* Red Oak	8.0	1	40	N E S W 4.0 6.0 5.0 6.0	0.2	2.5	Semi Mature	Good	Form - Low canopy. No significant faults observed. **Fell - Ground level.** To facilitate development.	72.4	4.8	20-40	B	1 2
T1556	1	*Tilia platyphyllos* Large Leaved Lime	8.0	1	38	N E S W 4.0 4.0 4.0 2.5	0.5	3.0	Semi Mature	Good	Access to inspect base - Restricted / obscured. Epicormic growth - Base / bole / principal stems. Ivy or climbing plant. DBH estimated due to dense vegetation. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	65.3	4.6	20-40	B	1 2
T1557	1	*Fagus sylvatica* Common Beech	10.0	1	63	N E S W 5.0 5.0 6.0 3.0	4.0	1.5	Early Mature	Good	Epicormic growth - Bole / principal stems. No significant faults observed. Pruning wounds - Suspected compartmentalised.	179.6	7.6	20-40	B	1 2
T1558	1	*Alnus glutinosa* Common Alder	12.0	1	65	N E S W 5.0 4.0 6.0 6.0	2.0	2.5	Early Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Epicormic growth - Bole / principal stems. No significant faults observed. DBH estimated due to dense vegetation. **Fell - Ground level.**	191.1	7.8	20-40	B	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1559	1	*Salix fragilis* Crack Willow	10.0	2	93	N E S W 2.0 8.0 3.0 2.0	1.5	3.0	Mature	Fair	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Die-back - Upper crown. Deadwood - Minor. Decay / structural defect - Extensive. Decay / structural defect - Major. Decay / structural defect - Bole. Epicormic growth - Bole / principal stems. Leaning trunk - Minor. Reaction wood / Adaptive growth - Stem / stems. Suppressed crown - Minor. Twin-stemmed. DBH estimated due to dense vegetation. **Fell - Ground level.**	391.3	11.2	10-20	C	1
G1560	7	*Salix caprea* Goat Willow/Great Sallow	7.0	1	38	N E S W 5.0 5.0 5.0 5.0	0.5	0.5	Early Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Fallen tree / trees - Partial collapse. Multi-stemmed. DBH estimated due to dense undergrowth	65.3	4.6	20-40	B	2
G1561	150 100 80 60	*Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Quercus robur* English Oak	5.0	1	18	N E S W 2.0 2.0 2.0 2.0	0.5	0.5	Young	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Form - Low canopy. Multi-stemmed. No significant faults observed. Twin-stemmed. Young planted tree / trees. DBH estimated due to dense undergrowth	14.7	2.2	20-40	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1562	200 80 40 30	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Acer campestre* Field Maple *Rosa canina* Dog-rose	1.5	1	15	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Hedgerow - Maintained. DBH estimated due to dense undergrowth. **Fell - Ground level.** Remove a 45-m span. To facilitate development.	10.2	1.8	20-40	C	2
T1563	1	*Alnus glutinosa* Common Alder	4.0	1	10	N 2.0 E 2.0 S 2.0 W 2.0	1.5	1.5	Young	Good	Access to inspect base - Not possible. Young planted tree / trees. DBH estimated due to dense vegetation.	4.5	1.2	20-40	C	1
T1564	1	*Fraxinus excelsior* Ash	14.0	1	55	N 4.0 E 5.0 S 7.0 W 6.0	3.0	1.5	Early Mature	Fair	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Die-back - Lower crown. Die-back - Mid crown. Decay / structural defect in crown limb / limbs - Localised. Decay / structural defect in crown limb / limbs - Open cavity / cavities. Epicormic growth - Bole / principal stems. Pruning wounds - Suspected compartmentalised. Root environment - Restricted. Shedding limb / limbs - Historic. DBH estimated due to ditch.	136.8	6.6	20-40	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1565	150 60 50 20	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Acer campestre* Field Maple *Rosa canina* Dog-rose	1.5	1	15	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Hedgerow - Maintained. DBH estimated due to dense undergrowth. **Fell - Ground level.** Remove a 42-m span. To facilitate development.	10.2	1.8	20-40	C	2
H1566	30 15 10 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Acer campestre* Field Maple *Rosa canina* Dog-rose	1.5	1	15	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Hedgerow - Maintained. DBH estimated due to dense undergrowth.	10.2	1.8	20-40	C	2
T1567	1	*Crataegus monogyna* Common Hawthorn/Quick/May	7.0	5	49	N 2.0 E 2.0 S 5.0 W 3.0	0.0	0.5	Early Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Dense crown. Form - Low canopy. Multi-stemmed. No significant faults observed. Poor past pruning. DBH estimated due to low canopy.	109.5	5.9	20-40	B	1
T1568	1	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	8	22	N 0.5 E 0.5 S 0.5 W 0.5	0.0	0.0	Young	Good	Access to inspect base - Not possible. Multi-stemmed. Young planted tree / trees. DBH estimated due to ditch line	23.2	2.7	20-40	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1569	40 20 10	*Acer campestre* Field Maple *Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel	2.5	1	16	N E S W 1.5 1.5 1.5 1.5	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Hedgerow - Maintained. DBH estimated due to dense undergrowth. Fragmented hedgeline along field parcel boundary.	11.6	1.9	20-40	C	2
H1570	70 60 50 40	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel *Acer campestre* Field Maple	2.5	1	16	N E S W 1.5 1.5 1.5 1.5	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Hedgerow - Maintained. DBH estimated due to dense undergrowth. **Fell - Ground level.** Remove a 10-m span. To facilitate development.	11.6	1.9	20-40	C	2
T1571	1	*Fraxinus excelsior* Ash	14.0	2	60	N E S W 4.0 5.0 5.0 5.0	4.0	5.0	Early Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Deadwood - Minor. Ivy or climbing plant. Twin-stemmed. DBH estimated due to dense vegetation.	167.4	7.3	20-40	B	1
H1572	60 60	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	2.0	1	12	N E S W 0.5 0.5 0.5 0.5	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Hedgerow - Maintained. DBH estimated due to dense undergrowth	6.5	1.4	20-40	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1573	1	*Acer campestre* Field Maple	10.0	1	58	N E S W 4.0 5.0 5.0 3.0	1.5	1.5	Early Mature	Good	Access to inspect base - Restricted / obscured. Epicormic growth - Bole / principal stems. No significant faults observed. Pruning wounds - Suspected compartmentalised. Unbalanced crown - Minor.	152.2	7.0	40+	B	1
G1574	50 50 30	*Salix caprea* Goat Willow/Great Sallow *Salix fragilis* Crack Willow *Salix viminalis* Osier	15.0	1	55	N E S W 7.0 7.0 7.0 7.0	0.5	0.5	Early Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Multi-stemmed. Natural regeneration. Twin-stemmed. DBH estimated due to no access to trees. Tree group assessed from northern embankment of Great Ouse.	136.8	6.6	20-40	B	2
G1575	10 2 1	*Salix viminalis* Osier *Alnus glutinosa* Common Alder *Crataegus monogyna* Common Hawthorn/Quick/May	8.0	1	25	N E S W 4.0 4.0 4.0 4.0	0.5	0.5	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Multi-stemmed. Natural regeneration. Root environment - Restricted. Twin-stemmed. DBH estimated due to no access to trees.	28.3	3.0	20-40	B	2
G1576	4	*Salix fragilis* Crack Willow	19.0	1	85	N E S W 10.0 10.0 10.0 10.0	1.5	1.5	Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Die-back - Upper crown. Deadwood - Minor. Decay / structural defect - Bole. Multi-stemmed. Natural regeneration. Root environment - Restricted. Shedding limb / limbs - Historic. Twin-stemmed. DBH estimated due to no access to trees.	326.9	10.2	20-40	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1577	80 25	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	8.0	1	35	N E S W 5.0 5.0 5.0 5.0	1.5	1.5	Early Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Hedgerow - Neglected / overgrown. Multi-stemmed. Twin-stemmed. DBH estimated due to no access to trees.	55.4	4.2	20-40	B	2
T1578	1	*Fraxinus excelsior* Ash	14.0	1	50	N E S W 7.0 6.0 7.0 5.0	2.5	2.5	Early Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Deadwood - Minor. DBH estimated due to dense vegetation.	113.1	6.0	20-40	B	1 2
H1579	60 25 15 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Sambucus nigra* Elder *Corylus avellana* Common Hazel	2.0	1	12	N E S W 0.5 0.5 0.5 0.5	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Hedgerow - Maintained. DBH estimated due to dense undergrowth	6.5	1.4	20-40	C	2
H1580	50 15 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Rosa canina* Dog-rose *Quercus robur* English Oak	1.5	1	10	N E S W 0.5 0.5 0.5 0.5	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Hedgerow - Maintained. DBH estimated due to dense undergrowth. Fragmented hedgeline along field parcel boundary.	4.5	1.2	20-40	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1581	1	*Quercus robur* English Oak	9.0	1	48	N E S W 7.0 7.0 6.0 6.0	2.5	2.5	Semi Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Deadwood - Minor. No significant faults observed. Reaction wood / Adaptive growth - Limb / limbs.	104.2	5.8	40+	B	1
H1582	10	*Fraxinus excelsior* Ash	1.5	1	10	N E S W 0.5 0.5 0.5 0.5	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Hedgerow - Maintained. DBH estimated due to dense undergrowth. Fragmented hedgeline along field parcel boundary.	4.5	1.2	20-40	C	2
T1583	1	*Fraxinus excelsior* Ash	8.0	6	46	N E S W 4.5 3.5 3.0 3.0	2.5	2.0	Semi Mature	Fair	Access to inspect base - Restricted / obscured. Coppice stool - Coppice origin / Mature stems. Decline - Suspected. Multi-stemmed. DBH estimated due to dense vegetation.	98.0	5.6	10-20	C	1
H1584	70 45 20	*Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple *Rosa canina* Dog-rose	6.0	1	15	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Restricted / obscured. Hedgerow - Neglected / overgrown. DBH estimated due to dense undergrowth. Fragmented hedgeline along field parcel boundary. **Fell - Ground level.** Remove 20-m span. To facilitate development.	10.2	1.8	20-40	B	2
T1585	1	*Acer campestre* Field Maple	8.0	5	33	N E S W 3.0 3.5 3.0 1.5	0.5	0.5	Semi Mature	Good	Access to inspect base - Restricted / obscured. Hedgerow - Historic. Multi-stemmed. DBH estimated due to dense vegetation.	50.9	4.0	10-20	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1586	20	*Crataegus monogyna* Common Hawthorn/Quick/May	1.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Restricted / obscured. Hedgerow - Maintained. DBH estimated due to dense undergrowth. Fragmented hedgeline along field parcel boundary.	4.5	1.2	20-40	C	2
H1587	40	*Crataegus monogyna* Common Hawthorn/Quick/May	1.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Restricted / obscured. Hedgerow - Maintained. DBH estimated due to dense undergrowth. Fragmented hedgeline along field parcel boundary.	4.5	1.2	20-40	C	2
T1588	1	*Fraxinus excelsior* Ash	17.0	5	71	N 7.0 E 7.0 S 9.0 W 6.0	1.0	2.5	Early Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Form - Low canopy. Multi-stemmed. DBH estimated due to dense vegetation.	231.6	8.6	20-40	B	1
H1589	80	*Crataegus monogyna* Common Hawthorn/Quick/May	1.5	1	8	N 0.5 E 0.5 S 0.5 W 0.5	0.0	0.0	Young	Good	Access to inspect base - Not possible. Hedgerow - Maintained. DBH estimated due to dense undergrowth. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	2.9	1.0	20-40	C	2
T1590	1	*Fraxinus excelsior* Ash	16.0	1	68	N 8.0 E 8.0 S 6.0 W 7.0	2.0	2.5	Early Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Epicormic growth - Bole / principal stems. Form - Good crown structure. Form - Low canopy. Ivy or climbing plant. DBH estimated due to dense vegetation.	209.2	8.2	40+	A	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1591	50 40 15 10 10	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Ilex aquifolium* Holly *Quercus robur* English Oak	5.0	1	12	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Hedgerow - Maintained. DBH estimated due to dense undergrowth	6.5	1.4	20-40	B	2
T1592	1	*Quercus robur* English Oak	15.0	1	46	N 5.0 E 5.0 S 5.0 W 4.0	6.0	2.5	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Ivy or climbing plant. DBH estimated due to dense vegetation.	95.7	5.5	40+	B	1 2
T1593	1	*Quercus robur* English Oak	14.0	1	68	N 3.0 E 6.0 S 6.0 W 6.0	6.0	1.5	Early Mature	Fair	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Deadwood - Minor. Ivy or climbing plant. DBH estimated due to dense vegetation.	209.2	8.2	40+	B	1 2
T1594	1	*Quercus robur* English Oak	12.0	1	42	N 1.0 E 3.0 S 2.0 W 4.0	6.0	3.0	Semi Mature	Fair	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Deadwood - Minor. Ivy or climbing plant. DBH estimated due to dense vegetation.	79.8	5.0	40+	B	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1595	1	*Quercus robur* English Oak	12.0	1	60	N E S W 7.0 5.0 3.0 4.0	6.0	2.0	Early Mature	Fair	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Deadwood - Minor. Epicormic growth - Bole / principal stems. Ivy or climbing plant. DBH estimated due to dense vegetation.	162.9	7.2	40+	B	1 2
T1596	1	*Fraxinus excelsior* Ash	7.0	1	36	N E S W 3.0 2.0 3.0 3.5	1.0	1.0	Semi Mature	Fair	Decline - Suspected. Epicormic growth - Bole / principal stems. No significant faults observed.	58.6	4.3	10-20	C	1
T1597	1	*Malus robusta* Orchard Apple	4.0	1	22	N E S W 3.0 2.0 2.0 2.0	0.2	0.5	Semi Mature	Good	Dense crown. Form - Low canopy. No significant faults observed.	21.9	2.6	10-20	C	1
T1598	1	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	4	18	N E S W 2.0 2.0 3.0 1.5	0.2	0.5	Semi Mature	Good	Dense crown. Form - Low canopy. Multi-stemmed. No significant faults observed. DBH estimated no access to land.	16.2	2.3	10-20	C	1
W1599	80 30 30 25 20	*Betula pendula* Silver Birch *Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash *Corylus avellana* Common Hazel *Pinus sylvestris* Scots Pine	18.0	1	25	N E S W 3.0 3.0 3.0 3.0	3.0	3.0	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Suppressed crown - Minor. Shelterbelt planting on mound. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	28.3	3.0	40+	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1600	25	*Ulmus procera* English Elm	6.0	1	18	N E S W 1.5 1.5 1.5 1.5	0.0	0.0	Semi Mature	Fair	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Decline - Evident / observed. Dutch elm disease. Hedgerow - Neglected / overgrown. DBH estimated due to dense undergrowth	14.7	2.2	10-20	C	2
H1601	100 50 25	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Sambucus nigra* Elder	2.5	1	10	N E S W 0.5 0.5 0.5 0.5	0.0	0.0	Young	Good	Access to inspect base - Not possible. Hedgerow - Maintained. DBH estimated due to dense undergrowth	4.5	1.2	20-40	C	2
T1602	1	*Quercus robur* English Oak	8.0	1	36	N E S W 5.0 5.0 5.0 4.0	3.0	2.5	Semi Mature	Good	Form - Good crown structure. No significant faults observed.	58.6	4.3	40+	B	1
H1603	15	*Crataegus monogyna* Common Hawthorn/Quick/May	3.5	1	16	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Young	Good	Access to inspect base - Not possible. Hedgerow - Neglected / overgrown. DBH estimated due to dense undergrowth. Fragmented lapsed hedgeline along field parcel boundary.	11.6	1.9	20-40	C	2
H1604	55	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	14	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Young	Good	Access to inspect base - Not possible. Hedgerow - Neglected / overgrown. DBH estimated due to dense undergrowth. Fragmented lapsed hedgeline along field parcel boundary.	8.9	1.7	20-40	C	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1605	30	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	14	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Young	Good	Access to inspect base - Not possible. Hedgerow - Neglected / overgrown. DBH estimated due to dense undergrowth. Fragmented lapsed hedgeline along field parcel boundary.	8.9	1.7	20-40	C	2
T1606	1	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	6	14	N 1.0 E 1.0 S 1.0 W 1.0	0.5	0.5	Young	Good	Multi-stemmed. No significant faults observed. Natural regeneration. DBH estimated due to dense vegetation.	9.8	1.8	20-40	C	1
T1607	1	*Fraxinus excelsior* Ash	5.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.5	0.5	Young	Fair	No significant faults observed. Natural regeneration. DBH estimated due to dense vegetation.	4.5	1.2	20-40	C	1
T1608	1	*Crataegus monogyna* Common Hawthorn/Quick/May	7.0	5	35	N 2.5 E 3.0 S 3.0 W 3.0	0.5	0.5	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Dense crown. Multi-stemmed. No significant faults observed. DBH estimated due to dense vegetation.	57.9	4.3	20-40	C	1
T1609	1	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	6	N 0.5 E 0.5 S 0.5 W 0.5	0.5	0.5	Young	Good	No significant faults observed. Natural regeneration. DBH estimated due to dense vegetation.	1.6	0.7	20-40	C	1
G1610	40 35 30	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel	8.0	1	35	N 4.0 E 4.0 S 4.0 W 4.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Coppice stool - Coppice origin / Mature stems. Hedgerow - Neglected / overgrown. Ivy or climbing plant. Multi-stemmed. Twin-stemmed. DBH estimated due to dense undergrowth. Lapsed hedgerow trees along field parcel boundary.	55.4	4.2	20-40	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1611	100 80 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Salix caprea* Goat Willow/Great Sallow	2.5	1	16	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Young	Good	Access to inspect base - Not possible. Hedgerow - Maintained. DBH estimated due to dense undergrowth. Fragmented lapsed hedgeline along field parcel boundary. Hedgerow assessed from adjacent field parcel using binoculars.	11.6	1.9	20-40	C	2
H1612	300 300	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	3.0	1	10	N 0.5 E 0.5 S 0.5 W 0.5	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Hedgerow - Neglected / overgrown. DBH estimated due to dense undergrowth. **Fell - Ground level.** Remove a 190-m span. To facilitate development.	4.5	1.2	20-40	C	2
H1613	60 60	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	3.0	1	10	N 0.5 E 0.5 S 0.5 W 0.5	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Hedgerow - Neglected / overgrown. DBH estimated due to dense undergrowth.	4.5	1.2	20-40	C	2
T1614	1	*Acer pseudoplatanus* Sycamore	17.0	8	98	N 5.0 E 6.0 S 7.0 W 5.0	5.5	2.5	Early Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Epicormic growth - Base. Multi-stemmed. No significant faults observed. Natural regeneration. DBH estimated due to dense vegetation.	443.3	11.9	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1615	1	*Quercus robur* English Oak	18.0	1	195	N E S W 8.0 10.0 9.0 10.0	3.0	2.5	Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Form - Good crown structure. Form - Low canopy. Pruning wounds - Historic. DBH estimated due to dense vegetation. Tree assessed from edge of field boundary using binoculars.	706.9	15.0	40+	A	1
G1616	2 2 1 1	*Alnus glutinosa* Common Alder *Fraxinus excelsior* Ash *Crataegus monogyna* Common Hawthorn/Quick/May *Quercus robur* English Oak	9.0	1	40	N E S W 6.0 6.0 6.0 6.0	1.0	2.0	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. No significant faults observed. Suppressed crown - Minor. DBH estimated due to dense undergrowth	72.4	4.8	20-40	B	2
G1617	20 6 2	*Prunus cerasifera* Cherry Plum (Myrobalan) *Quercus cerris* Turkey Oak *Acer campestre* Field Maple	12.0	1	40	N E S W 6.0 6.0 6.0 6.0	1.0	1.0	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Multi-stemmed. Suppressed crown - Minor. Twin-stemmed. DBH estimated due to dense undergrowth	72.4	4.8	20-40	B	2
G1618	14 10	*Ulmus procera* English Elm *Crataegus monogyna* Common Hawthorn/Quick/May	6.0	1	14	N E S W 2.0 2.0 2.0 2.0	1.0	1.5	Young	Fair	Access to inspect base - Restricted / obscured. Base / stems obscured - Structure. Die-back - Throughout crown. Decline - Evident / observed. Dutch elm disease. Dead tree / trees. Hedgerow - Neglected / overgrown. Natural regeneration. DBH estimated due to dense undergrowth	8.9	1.7	10-20	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1619	3	*Sambucus nigra* Elder	2.0	1	15	N 0.5 E 0.5 S 0.5 W 0.5	0.0	0.0	Semi Mature	Good	Access to inspect base - Restricted / obscured. Hedgerow - Neglected / overgrown. DBH estimated due to dense undergrowth. Fragmented hedgeline along field parcel boundary.	10.2	1.8	20-40	C	2
T1620	1	*Sambucus nigra* Elder	2.5	6	24	N 1.5 E 2.0 S 2.0 W 2.0	0.0	0.0	Semi Mature	Good	Multi-stemmed. No significant faults observed. Natural regeneration. DBH estimated due to dense vegetation.	27.1	2.9	20-40	C	2
G1621	3	*Sambucus nigra* Elder	4.0	6	24	NW 1.0 NE 2.0 SE 1.0 SW 2.0	0.5	0.0	Early Mature	Poor		27.1	2.9	10-20	C	1
T1622	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	6	36	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.5	Mature	Good	Form - Low canopy. Natural regeneration. Twin-stemmed. Growing on railway embankment.	61.1	4.4	40+	C	1
G1623	3 1	*Acer campestre* Field Maple *Fraxinus excelsior* Ash	8.0	1	12	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.5	Semi Mature	Good	Hedgerow - Neglected / overgrown. Multi-stemmed. No significant faults observed. DBH estimated due to dense undergrowth. Lapsed hedgerow trees. **Fell - Ground level.** To facilitate development.	6.5	1.4	20-40	B	2
T1624	1	*Fraxinus excelsior* Ash	7.0	10	69	N 2.0 E 6.0 S 5.0 W 5.0	0.5	0.5	Early Mature	Fair	Die-back - Throughout crown. Decline - Evident / observed. Deadwood - Minor. Epicormic growth - Crown. Multi-stemmed. Symptoms of Ash dieback infection. Growing under power lines.	219.0	8.3	10-20	C	1
T1625	1	*Carpinus betulus* Hornbeam	8.0	1	36	N 4.0 E 4.0 S 3.0 W 4.0	0.5	1.5	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. DBH estimated due to dense vegetation.	58.6	4.3	20-40	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1626	200 150 80 50	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel *Acer pseudoplatanus* Sycamore	2.5	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Hedgerow - Maintained. DBH estimated due to dense undergrowth	4.5	1.2	20-40	C	2
H1627	80 40 30 20	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Acer pseudoplatanus* Sycamore *Corylus avellana* Common Hazel	2.5	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Hedgerow - Maintained. DBH estimated due to dense undergrowth	4.5	1.2	20-40	C	2
T1628	1	*Quercus robur* English Oak	7.0	1	16	N 2.5 E 2.5 S 2.5 W 2.5	2.5	2.5	Young	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Natural regeneration. Young planted tree / trees. DBH estimated due to dense vegetation.	11.6	1.9	20-40	C	1
T1629	1	*Acer pseudoplatanus* Sycamore	7.0	9	51	N 4.0 E 3.0 S 2.0 W 4.0	3.0	2.5	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Multi-stemmed. Suppressed crown - Minor. DBH estimated due to dense vegetation. Lapsed hedgerow tree.	117.7	6.1	20-40	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1630	1	*Salix caprea* Goat Willow/Great Sallow	7.0	9	54	N 1.0 E 4.0 S 8.0 W 5.0	3.0	3.5	Early Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Multi-stemmed. Suppressed crown - Minor. DBH estimated due to dense vegetation. Lapsed hedgerow tree.	131.9	6.5	20-40	B	2
T1631	1	*Fraxinus excelsior* Ash	7.0	9	30	N 2.0 E 2.5 S 1.5 W 2.0	3.5	3.5	Semi Mature	Fair	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Die-back - Throughout crown. Decline - Evident / observed. Deadwood - Minor. Multi-stemmed. Suppressed crown - Minor. DBH estimated due to dense vegetation. Lapsed hedgerow tree. Ash die back infection evident.	40.7	3.6	10-20	C	1 2
T1632	1	*Fraxinus excelsior* Ash	10.0	1	52	N 3.0 E 4.0 S 4.0 W 4.0	2.5	3.5	Early Mature	Fair	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Die-back - Upper crown. Decline - Evident / observed. Deadwood - Minor. Epicormic growth - Crown. Suppressed crown - Minor. DBH estimated due to dense vegetation. Lapsed hedgerow tree. Ash die back infection evident.	122.3	6.2	10-20	C	1 2
T1633	1	*Fraxinus excelsior* Ash	5.0	1	8	N 1.5 E 1.0 S 1.0 W 1.0	2.0	2.0	Young	Fair	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Die-back - Upper crown. Decline - Evident / observed. Deadwood - Minor. Epicormic growth - Crown. Natural regeneration. Suppressed crown - Minor. Young planted tree / trees. DBH estimated due to dense vegetation. Lapsed hedgerow tree. Ash die back infection evident.	2.9	1.0	10-20	C	1 2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1634	1	*Quercus robur* English Oak	6.0	1	31	N E S W 3.0 3.0 3.0 3.0	2.0	3.5	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. DBH estimated due to dense vegetation.	43.5	3.7	40+	B	1 2
T1635	1	*Quercus robur* English Oak	6.0	1	31	N E S W 2.5 3.0 3.0 3.0	2.0	2.5	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. DBH estimated due to dense vegetation.	43.5	3.7	40+	B	1 2
G1636	5 2	*Acer pseudoplatanus* Sycamore *Acer campestre* Field Maple	7.0	1	35	N E S W 4.0 4.0 4.0 4.0	1.0	1.5	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. DBH estimated due to dense undergrowth	55.4	4.2	20-40	B	2
T1637	1	*Corylus avellana* Common Hazel	6.0	12	41	N E S W 4.0 4.0 3.0 4.0	1.0	1.0	Semi Mature	Good	Access to inspect base - Not possible. Coppice stool - Coppice origin / Mature stems. Multi-stemmed. DBH estimated due to dense vegetation.	78.2	5.0	20-40	C	1 2
T1638	1	*Corylus avellana* Common Hazel	6.0	12	34	N E S W 2.0 1.5 3.0 3.0	1.0	1.0	Semi Mature	Good	Access to inspect base - Not possible. Competition - Adjacent trees. Coppice stool - Coppice origin / Mature stems. Multi-stemmed. DBH estimated due to dense vegetation. **Fell - Ground level.** To facilitate development.	54.3	4.2	20-40	C	1 2
T1639	1	*Fraxinus excelsior* Ash	12.0	6	48	N E S W 5.0 6.5 7.0 4.0	1.5	2.5	Early Mature	Fair	Access to inspect base - Not possible. Coppice stool - Coppice origin / Mature stems. Multi-stemmed. DBH estimated due to dense vegetation. Ash dieback symptoms evident. **Fell - Ground level.** To facilitate development.	108.6	5.9	20-40	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1640	1	*Corylus avellana* Common Hazel	4.0	8	28	N E S W 2.0 4.0 2.0 4.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Coppice stool - Coppice origin / Mature stems. Multi-stemmed. DBH estimated due to dense vegetation.	36.2	3.4	20-40	C	1
T1641	1	*Corylus avellana* Common Hazel	4.0	7	26	N E S W 2.0 4.0 2.0 4.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Coppice stool - Coppice origin / Mature stems. Multi-stemmed. DBH estimated due to dense vegetation.	31.7	3.2	20-40	C	1
T1642	1	*Acer pseudoplatanus* Sycamore	15.0	6	53	N E S W 4.0 6.5 6.0 4.0	1.5	2.5	Early Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Die-back - Lower crown. Die-back - Mid crown. Deadwood - Minor. Multi-stemmed. DBH estimated due to dense vegetation. Dieback in eastern lower canopy.	131.4	6.5	20-40	B	1
H1643	1200 200 30 30	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple *Euonymus sp.* Spindle	1.5	1	8	N E S W 0.5 0.5 0.5 0.5	0.0	0.0	Young	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Hedgerow - Maintained. DBH estimated due to dense undergrowth **Fell - Ground level.** Remove a 25-m span. To facilitate development.	2.9	1.0	20-40	C	2
T1644	1	*Corylus avellana* Common Hazel	7.0	8	22	N E S W 4.0 3.0 3.0 1.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Coppice stool - Regrown. Multi-stemmed. DBH estimated due to dense vegetation.	23.2	2.7	20-40	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1645	3 1	*Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May	6.0	1	12	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Multi-stemmed. DBH estimated due to dense undergrowth	6.5	1.4	20-40	C	2
T1646	1	*Corylus avellana* Common Hazel	5.0	9	24	N E S W 1.0 3.0 1.0 3.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Coppice stool - Regrown. Multi-stemmed. DBH estimated due to dense vegetation.	26.1	2.9	20-40	C	1
G1647	3	*Corylus avellana* Common Hazel	5.0	1	10	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Multi-stemmed.	4.5	1.2	20-40	C	2
H1648	150 25 20	*Crataegus monogyna* Common Hawthorn/Quick/May *Salix fragilis* Crack Willow *Fraxinus excelsior* Ash	4.0	1	15	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Hedgerow - Neglected / overgrown. DBH estimated due to dense undergrowth. Lapsed overgrown hedgerow. Flailed on ditch side.	10.2	1.8	20-40	C	2
H1649	80 10 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Salix fragilis* Crack Willow *Fraxinus excelsior* Ash	3.0	1	15	N E S W 0.5 0.5 0.5 0.5	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Hedgerow - Neglected / overgrown. DBH estimated due to dense undergrowth. Lapsed overgrown hedgerow.	10.2	1.8	20-40	C	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1650	1	*Salix fragilis* Crack Willow	15.0	1	125	N E S W 8.0 7.0 10.0 10.0	1.5	1.5	Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Decay / structural defect - Suspected. Form - Low canopy vehicle damage. Ivy or climbing plant. Pollard - Lapsed / Mature stems. Shedding limb / limbs - Historic. Unable to gain access to tree. Dbh estimated. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	706.9	15.0	20-40	B	1 2
T1651	1	*Salix fragilis* Crack Willow	16.0	3	102	N E S W 11.0 10.0 11.0 7.0	3.5	4.0	Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Decay / structural defect - Suspected. Ivy or climbing plant. Multi-stemmed. Poor past pruning. Pruning wounds - Decayed. Shedding limb / limbs - Historic. Unable to gain access to tree. Dbh estimated. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	475.2	12.3	20-40	B	1 2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1652	40 35 10 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Rosa canina* Dog-rose *Sambucus nigra* Elder	2.5	1	12	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Hedgerow - Maintained. DBH estimated due to dense undergrowth.	6.5	1.4	20-40	C	2
G1653	150 50 25	*Crataegus monogyna* Common Hawthorn/Quick/May *Salix caprea* Goat Willow/Great Sallow *Sambucus nigra* Elder	8.0	1	35	N 3.0 E 3.0 S 3.0 W 3.0	1.5	2.0	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Decline - Evident / observed. Multi-stemmed. Natural regeneration. Twin-stemmed. Unable to gain access to trees to undertake full detailed assessment. DBH estimated. Off site railway embankment trees.	55.4	4.2	20-40	C	2
G1654	80 35 25	*Salix caprea* Goat Willow/Great Sallow *Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder	7.0	1	35	N 3.0 E 3.0 S 3.0 W 3.0	1.5	2.0	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Decline - Evident / observed. Multi-stemmed. Natural regeneration. Twin-stemmed. Unable to gain access to trees to undertake full detailed assessment. DBH estimated. Off site railway embankment trees.	55.4	4.2	20-40	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1655	17	*Quercus robur* English Oak	17.0	1	85	N E S W 6.0 8.0 6.0 8.0	1.5	3.0	Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Competition - Adjacent trees. Epicormic growth - Bole / principal stems. No significant faults observed. Suppressed crown - Minor. DBH estimated due to dense undergrowth. Boundary feature of early mature to mature oak.	326.9	10.2	40+	A	2
H1656	80 30	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder	3.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Hedgerow - Neglected / overgrown. DBH estimated due to dense undergrowth	4.5	1.2	20-40	C	2
T1657	1	*Aesculus hippocastanum* Horse Chestnut	12.0	3	50	N E S W 6.0 7.0 7.0 7.0	1.5	1.5	Semi Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Competition - Adjacent trees. Fork - Suspected structurally sound. No significant faults observed. Shedding limb / limbs - Historic. DBH estimated due to dense vegetation.	115.3	6.1	20-40	B	1 2
T1658	1	*Quercus robur* English Oak	12.0	1	46	N E S W 7.0 3.0 5.0 7.0	2.0	2.5	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Dense crown. Epicormic growth - Crown. Ivy or climbing plant. DBH estimated due to dense vegetation.	95.7	5.5	20-40	B	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)				Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
						N	E	S	W										
H1659	30	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	8	0.5	0.5	0.5	0.5	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Hedgerow - Maintained. DBH estimated due to dense undergrowth	2.9	1.0	20-40	C	2
	15	*Sambucus nigra* Elder																	

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1660	70	*Crataegus monogyna* Common Hawthorn/Quick/May	14.0	1	38	N 4.0 E 4.0 S 4.0 W 4.0	1.5	1.5	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Multi-stemmed. Suppressed crown - Minor. Twin-stemmed. DBH estimated due to dense undergrowth	65.3	4.6	20-40	B	2
	50	*Betula pubescens* Downy Birch														
	40	*Quercus cerris* Turkey Oak														
	30	*Pinus nigra subsp. laricio* Corsican Pine														
	30	*Acer campestre* Field Maple														
	20	*Malus sylvestris* Wild Crab														
	15	*Larix decidua* European Larch/Common Larch														
	10	*Euonymus sp.* Spindle														
	5	*Hippophae rhamnoides* Sea Buckthorn														
	1	*Elaeagnus angustifolia* Oleaster														

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1661	25 20 5 3	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus cerasifera* Cherry Plum (Myrobalan) *Elaeagnus angustifolia* Oleaster *Quercus robur* English Oak	6.0	1	16	N 2.0 E 2.0 S 2.0 W 2.0	0.5	0.5	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Multi-stemmed. Natural regeneration. Suppressed crown - Minor. Twin-stemmed. DBH estimated due to dense undergrowth	11.6	1.9	20-40	C	2
G1662	100 100 100 50 50 50 30	*Corylus avellana* Common Hazel *Betula pendula* Silver Birch *Acer campestre* Field Maple *Salix caprea* Goat Willow/Great Sallow *Crataegus monogyna* Common Hawthorn/Quick/May *Alnus glutinosa* Common Alder *Quercus robur* English Oak	14.0	1	22	N 2.0 E 2.0 S 2.0 W 2.0	0.5	0.5	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Multi-stemmed. Suppressed crown - Minor. Twin-stemmed. Young planted tree / trees. DBH estimated due to dense undergrowth Roadside verge plantation.	21.9	2.6	20-40	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1663	1 1	*Acer campestre* Field Maple *Salix caprea* Goat Willow/Great Sallow	4.0	1	15	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Multi-stemmed. Natural regeneration. DBH estimated due to no access to trees.	10.2	1.8	20-40	C	2
T1664	1	*Salix caprea* Goat Willow/Great Sallow	3.0	6	24	N E S W 1.5 1.5 1.5 0.5	0.0	0.5	Semi Mature	Good	Access to inspect base - Not possible. Multi-stemmed. Natural regeneration. DBH estimated due to no access to tree.	27.1	2.9	20-40	C	1
T1665	1	*Salix caprea* Goat Willow/Great Sallow	3.0	7	26	N E S W 2.0 2.0 2.0 0.5	0.0	0.5	Semi Mature	Good	Access to inspect base - Not possible. Multi-stemmed. Natural regeneration. DBH estimated due to no access to tree.	31.7	3.2	20-40	C	1
T1666	1	*Salix caprea* Goat Willow/Great Sallow	1.5	7	15	N E S W 1.0 1.0 1.0 0.5	0.0	0.5	Semi Mature	Good	Access to inspect base - Not possible. Multi-stemmed. Natural regeneration. DBH estimated due to no access to tree.	11.4	1.9	20-40	C	1
T1667	1	*Quercus robur* English Oak	9.0	1	53	N E S W 5.0 6.0 6.0 6.0	0.5	1.0	Early Mature	Good	Epicormic growth - Bole / principal stems. Form - Low canopy. No significant faults observed. Poor past pruning. Flailed lower canopy	127.1	6.4	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1668	120 50 40 20 20	*Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel *Acer campestre* Field Maple *Sambucus sp.* Elder sp. *Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** Remove a 25-m span. To facilitate development.	4.5	1.2	40+	C	2 3
T1669	1	*Quercus robur* English Oak	15.0	1	98	N 8.0 E 8.0 S 8.0 W 8.0	4.0	4.0	Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Major. Deadwood - Minor. Ivy or climbing plant.	434.5	11.8	40+	B	1
T1670	1	*Quercus robur* English Oak	15.0	1	54	N 6.0 E 6.0 S 6.0 W 6.0	5.0	4.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor. Ivy or climbing plant.	131.9	6.5	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1671	12 5 5 2 1	*Prunus spinosa* Blackthorn/Sloe *Acer campestre* Field Maple *Corylus avellana* Common Hazel *Salix caprea* Goat Willow/Great Sallow *Quercus robur* English Oak	6.0	1	16	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Semi Mature	Good	Hedgerow - Neglected / overgrown.	11.6	1.9	40+	C	2 3
H1672	85 35 25 25	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple *Corylus avellana* Common Hazel	3.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2 3
T1673	1	*Quercus robur* English Oak	16.0	1	125	N 8.0 E 8.0 S 8.0 W 8.0	4.0	3.0	Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Bark wound - Physical damage or vandalism. Deadwood - Major. Deadwood - Minor. Fire damage - Base / bole / principal stems. Ivy or climbing plant.	706.9	15.0	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1674	141 45 45 35 20	*Prunus spinosa* Blackthorn/Sloe *Acer campestre* Field Maple *Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Sambucus nigra* Elder	3.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** Remove a 103-m span. To facilitate development.	4.5	1.2	40+	C	2 3
T1675	1	*Quercus robur* English Oak	4.5	1	14	N 1.0 E 1.0 S 1.0 W 1.0	3.0	3.0	Young	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation.	8.9	1.7	40+	C	1
H1676	140 25 15 2	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder *Salix caprea* Goat Willow/Great Sallow	6.0	1	14	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Hedgerow - Neglected / overgrown. Maintained on roadside. **Fell - Ground level.** To facilitate development.	8.9	1.7	40+	C	2 3

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1677	1	*Acer campestre* Field Maple	6.0	1	16	N 2.0 E 2.0 S 2.0 W 2.0	3.0	3.0	Young	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. **Fell - Ground level.** To facilitate development.	11.6	1.9	40+	C	1
T1678	1	*Quercus robur* English Oak	4.5	1	14	N 1.0 E 1.0 S 1.0 W 1.0	3.0	3.0	Young	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. **Fell - Ground level.** To facilitate development.	8.9	1.7	40+	C	1
T1679	1	*Acer campestre* Field Maple	8.0	1	25	N 4.0 E 4.0 S 4.0 W 4.0	3.0	3.0	Young	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. **Fell - Ground level.** To facilitate development.	28.3	3.0	40+	B	1
G1680	2	*Quercus robur* English Oak	15.0	1	50	N 7.0 E 7.0 S 7.0 W 7.0	2.0	3.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor. Ivy or climbing plant.	113.1	6.0	40+	B	2 3
G1681	2	*Salix caprea* Goat Willow/Great Sallow	9.0	3	27	N 2.0 E 2.0 S 2.0 W 2.0	2.0	3.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor.	34.7	3.3	40+	C	2 3

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1682	6 3	*Quercus robur* English Oak *Salix caprea* Goat Willow/Great Sallow	17.0	1	55	N E S W 8.0 8.0 8.0 8.0	2.0	2.0	Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Major. Deadwood - Minor. Ivy or climbing plant.	136.8	6.6	40+	B	1 2
T1683	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	5	22	N E S W 2.0 2.0 2.0 2.0	0.0	0.5	Semi Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation.	22.6	2.7	20-40	C	1
T1684	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	5	22	N E S W 2.0 2.0 2.0 2.0	0.0	0.5	Semi Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation.	22.6	2.7	20-40	C	1
G1685	2 1	*Salix caprea* Goat Willow/Great Sallow *Quercus robur* English Oak	9.0	3	38	N E S W 3.0 3.0 3.0 3.0	2.0	3.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor.	65.7	4.6	40+	C	2 3
H1686	120 25	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	3.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	1 2
T1687	1	*Quercus robur* English Oak	4.0	1	16	N E S W 1.5 1.5 1.5 1.5	1.0	2.0	Young	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation.	11.6	1.9	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1688	1	*Quercus robur* English Oak	4.0	1	16	N 1.5 E 1.5 S 1.5 W 1.5	1.0	2.0	Young	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation.	11.6	1.9	40+	C	1
T1689	1	*Quercus robur* English Oak	4.0	1	16	N 1.5 E 1.5 S 1.5 W 1.5	1.0	2.0	Young	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation.	11.6	1.9	40+	C	1
T1690	1	*Quercus robur* English Oak	4.0	1	16	N 1.5 E 1.5 S 1.5 W 1.5	1.0	2.0	Young	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. **Fell - Ground level.** To facilitate development.	11.6	1.9	40+	C	1
T1691	1	*Quercus robur* English Oak	4.0	1	16	N 1.5 E 1.5 S 1.5 W 1.5	1.0	2.0	Young	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. **Fell - Ground level.** To facilitate development.	11.6	1.9	40+	C	1
T1692	1	*Quercus robur* English Oak	6.0	1	20	N 3.0 E 3.0 S 3.0 W 3.0	1.0	2.0	Semi Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation.	18.1	2.4	40+	C	1
T1693	1	*Quercus robur* English Oak	4.0	1	16	N 1.5 E 1.5 S 1.5 W 1.5	1.0	2.0	Young	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation.	11.6	1.9	40+	C	1
T1694	1	*Quercus robur* English Oak	4.0	1	16	N 1.5 E 1.5 S 1.5 W 1.5	1.0	2.0	Young	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation.	11.6	1.9	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1695	1	*Quercus robur* English Oak	4.0	1	16	N 1.5 E 1.5 S 1.5 W 1.5	1.0	2.0	Young	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation.	11.6	1.9	40+	C	1
T1696	1	*Quercus robur* English Oak	4.0	1	16	N 1.5 E 1.5 S 1.5 W 1.5	1.0	2.0	Young	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. **Fell - Ground level.** To facilitate development.	11.6	1.9	40+	C	1
T1697	1	*Quercus robur* English Oak	4.0	1	16	N 1.5 E 1.5 S 1.5 W 1.5	1.0	2.0	Young	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. **Fell - Ground level.** To facilitate development.	11.6	1.9	40+	C	1
T1698	1	*Quercus robur* English Oak	4.0	1	16	N 1.5 E 1.5 S 1.5 W 1.5	1.0	2.0	Young	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. **Fell - Ground level.** To facilitate development.	11.6	1.9	40+	C	1
T1699	1	*Quercus robur* English Oak	4.0	1	16	N 1.5 E 1.5 S 1.5 W 1.5	1.0	2.0	Young	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation.	11.6	1.9	40+	C	1
T1700	1	*Quercus robur* English Oak	4.0	1	16	N 1.5 E 1.5 S 1.5 W 1.5	1.0	2.0	Young	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation.	11.6	1.9	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1701	1	*Quercus robur* English Oak	4.0	1	16	N 1.5 E 1.5 S 1.5 W 1.5	1.0	2.0	Young	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. **Fell - Ground level.** To facilitate development.	11.6	1.9	40+	C	1
T1702	1	*Quercus robur* English Oak	4.0	1	16	N 1.5 E 1.5 S 1.5 W 1.5	1.0	2.0	Young	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. **Fell - Ground level.** To facilitate development.	11.6	1.9	40+	C	1
H1703	130	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	1 2
H1704			2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** To facilitate development.	4.5	1.2	40+	C	1 2
H1705			2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** To facilitate development.	4.5	1.2	40+	C	1 2
H1706			2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	1 2
T1707	1	*Quercus robur* English Oak	13.0	1	120	N 4.0 E 4.0 S 4.0 W 6.0	2.0	2.0	Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Major. Deadwood - Minor. Ivy or climbing plant.	651.4	14.4	40+	B	1 3

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1708	250	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** Remove a 25-m span. To facilitate development.	4.5	1.2	40+	C	1 2
H1709			2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. Sporadic gaps hedge.	4.5	1.2	40+	C	1 2
H1710	140 35	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	1 2
H1711			2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	1 2
T1712	1	*Fraxinus excelsior* Ash	18.0	1	95	N 8.0 E 8.0 S 8.0 W 8.0	4.0	5.0	Mature	Fair	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Decay / structural defect in crown limb / limbs - Open cavity / cavities. Deadwood - Major. Deadwood - Minor. Ivy or climbing plant.	408.3	11.4	20-40	B	1
T1713	1	*Fraxinus excelsior* Ash	14.0	1	58	N 7.0 E 7.0 S 7.0 W 7.0	1.0	1.5	Mature	Good	Arboricultural work - Historic. Deadwood - Minor.	152.2	7.0	20-40	B	1
G1714	8	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	1	20	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown.	18.1	2.4	20-40	C	1 2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1715	250	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** Remove a 25-m span. To facilitate development.	4.5	1.2	40+	C	1 2
T1716	1	*Quercus robur* English Oak	6.0	1	20	N E S W 3.0 3.0 3.0 3.0	3.0	3.0	Semi Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation.	18.1	2.4	40+	C	1
T1717	1	*Salix fragilis* Crack Willow	16.0	1	60	N E S W 8.0 8.0 5.0 8.0	2.0	1.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Crack - Longitudinal / shear crack. Deadwood - Minor. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	162.9	7.2	20-40	B	1
H1718	50 50 40 15 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel *Acer campestre* Field Maple *Sambucus nigra* Elder	4.0	1	12	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Sporadic gaps in hedge. **Fell - Ground level.** Remove a 25-m span. To facilitate development.	6.5	1.4	20-40	C	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1719	3 2	*Crataegus monogyna* Common Hawthorn/Quick/May *Acer pseudoplatanus* Sycamore	6.0	1	14	N E S W 1.5 1.5 1.5 1.5	0.0	0.0	Semi Mature	Good	Hedgerow - Neglected / overgrown.	8.9	1.7	20-40	C	1
H1720	160 20 15	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Sambucus nigra* Elder	3.0	1	14	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	8.9	1.7	20-40	C	1
T1721	1	*Acer pseudoplatanus* Sycamore	7.0	1	25	N E S W 3.0 3.0 3.0 3.0	3.0	3.0	Semi Mature	Fair	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Die-back - Upper crown. Deadwood - Minor.	28.3	3.0	20-40	C	1
G1722	5 3	*Salix fragilis* Crack Willow *Crataegus monogyna* Common Hawthorn/Quick/May	17.0	1	75	N E S W 8.0 8.0 8.0 8.0	0.0	1.0	Mature	Fair	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Branch - Broken. Branch - Suspended. Decay / structural defect - Base. Decay / structural defect - Major. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Bole. Natural regeneration. Pollard - Lapsed / Mature stems. Shedding limb / limbs - Minor. Shedding limb / limbs - Recent.	254.5	9.0	40+	B	1 2
T1723	1	*Acer pseudoplatanus* Sycamore	7.0	1	26	N E S W 4.0 4.0 2.0 4.0	3.0	3.5	Semi Mature	Fair	Measurements estimated.	30.6	3.1	20-40	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1724	1	*Malus sp.* Apple sp.	10.0	1	68	N E S W 6.0 6.0 6.0 6.0	2.0	3.5	Mature	Good	Arboricultural work - Historic. Measurements estimated.	209.2	8.2	40+	A	1
H1725	65	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	1 2
T1726	1	*Fraxinus excelsior* Ash	14.0	1	41	N E S W 5.0 5.0 5.0 5.0	4.0	1.0	Early Mature	Fair	Bark wound - Mechanical. Die-back - Throughout crown. Deadwood - Minor. Epicormic growth - Bole / principal stems.	76.0	4.9	10-20	C	1
T1727	1	*Fraxinus excelsior* Ash	12.0	2	47	N E S W 5.5 5.5 5.5 5.5	4.0	1.0	Early Mature	Fair	Bark wound - Mechanical. Die-back - Throughout crown. Deadwood - Minor. Epicormic growth - Bole / principal stems.	102.1	5.7	10-20	C	1
T1728	1	*Crataegus monogyna* Common Hawthorn/Quick/May	11.0	1	36	N E S W 3.0 3.0 1.0 3.0	1.0	1.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Bole / principal stems.	58.6	4.3	20-40	C	1
T1729	1	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	5	26	N E S W 2.5 2.5 2.5 2.5	0.0	0.0	Early Mature	Fair	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation.	32.6	3.2	20-40	C	1
T1730	1	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	5	26	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Early Mature	Fair	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation.	32.6	3.2	20-40	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1731	8 1 1	*Prunus spinosa* Blackthorn/Sloe *Acer campestre* Field Maple *Alnus glutinosa* Common Alder	7.0	1	16	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Semi Mature	Good	Hedgerow - Neglected / overgrown.	11.6	1.9	20-40	C	1 2
H1732	45	*Crataegus monogyna* Common Hawthorn/Quick/May	9.0	1	20	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown. Sporadic gaps in hedge.	18.1	2.4	40+	C	1 2
H1733	10 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple	9.0	1	20	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown. Sporadic gaps in hedge.	18.1	2.4	40+	C	1 2
H1734	20 12 1	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Ulmus sp.* Elm sp.	6.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Neglected / overgrown. Sporadic gaps in hedge.	4.5	1.2	40+	C	1 2
T1735	1	*Fraxinus excelsior* Ash	17.0	1	68	N 8.0 E 8.0 S 8.0 W 8.0	5.0	6.0	Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor. Epicormic growth - Base. Ivy or climbing plant.	209.2	8.2	20-40	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1736	1	*Fraxinus excelsior* Ash	17.0	1	74	N E S W 8.5 8.5 8.5 8.5	5.0	2.0	Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor. Epicormic growth - Base. Ivy or climbing plant. Shedding limb / limbs - Minor. Shedding limb / limbs - Recent.	247.7	8.9	20-40	B	1
G1737	25 20 15 8 4 3 2	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Ulmus sp.* Elm sp. *Acer campestre* Field Maple *Acer pseudoplatanus* Sycamore *Salix caprea* Goat Willow/Great Sallow *Corylus avellana* Common Hazel	11.0	1	22	N E S W 2.5 2.5 2.5 2.5	0.0	0.0	Early Mature	Good	Arboricultural work - Historic. Hedgerow - Neglected / overgrown. Sporadic gaps in hedge. Hv terminal pole located in northerner section of group.	21.9	2.6	40+	B	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1738	30 15 12 8 6	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Ulmus sp.* Elm sp. *Corylus avellana* Common Hazel *Fraxinus excelsior* Ash	8.0	1	12	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Semi Mature	Good	Hedgerow - Neglected / overgrown.	6.5	1.4	20-40	C	1 2
G1739	8 3 2 2	*Prunus spinosa* Blackthorn/Sloe *Fraxinus excelsior* Ash *Corylus avellana* Common Hazel *Sambucus nigra* Elder	14.0	1	22	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Semi Mature	Fair	Hedgerow - Neglected / overgrown.	21.9	2.6	40+	C	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1740	120 35 15 10 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel *Sambucus sp.* Elder sp. *Sambucus nigra* Elder	2.5	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	1 2
T1741	1	*Quercus robur* English Oak	15.0	1	58	N 8.0 E 8.0 S 8.0 W 8.0	3.0	3.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor.	152.2	7.0	40+	B	1
T1742	1	*Acer pseudoplatanus* Sycamore	14.0	1	42	N 5.0 E 5.0 S 7.0 W 5.0	1.0	4.0	Early Mature	Good	Access to inspect base - Not possible. Arboricultural work - Historic. Base / stems obscured - Vegetation.	79.8	5.0	40+	B	1
T1743	1	*Acer pseudoplatanus* Sycamore	16.0	4	64	N 5.0 E 5.0 S 7.0 W 6.0	4.0	0.0	Early Mature	Good	Access to inspect base - Not possible. Arboricultural work - Historic. Base / stems obscured - Vegetation.	185.3	7.7	40+	B	1
T1744	1	*Quercus cerris* Turkey Oak	18.0	3	90	N 6.0 E 12.0 S 10.0 W 10.0	5.0	1.0	Early Mature	Good	Access to inspect base - Not possible. Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor. Rubbing limbs.	367.0	10.8	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1745	12 3	*Fraxinus excelsior* Ash *Quercus cerris* Turkey Oak	18.0	1	45	N E S W 7.0 7.0 7.0 7.0	4.0	1.0	Early Mature	Good	Access to inspect base - Not possible. Arboricultural work - Historic. Base / stems obscured - Vegetation. Bark wound - Mechanical. Deadwood - Minor. Epicormic growth - Base / bole / principal stems.	91.6	5.4	40+	B	1
H1746	150 20 12 10 3	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Fraxinus excelsior* Ash *Quercus robur* English Oak *Cerasus avium* Wild Cherry	9.0	1	18	N E S W 2.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Height unmanaged.	14.7	2.2	40+	C	1 2
T1747	1	*Fraxinus excelsior* Ash	17.0	3	58	N E S W 6.0 6.0 9.0 8.0	1.0	1.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Recent. Base / stems obscured - Vegetation. Deadwood - Major. Deadwood - Minor.	153.3	7.0	20-40	B	1
H1748	7	*Crataegus monogyna* Common Hawthorn/Quick/May	7.0	1	12	N E S W 1.5 1.5 1.5 1.5	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown.	6.5	1.4	20-40	C	1 2
H1749	3	*Crataegus monogyna* Common Hawthorn/Quick/May	7.0	1	12	N E S W 1.5 1.5 1.5 1.5	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown.	6.5	1.4	20-40	C	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1750	1	*Fraxinus excelsior* Ash	17.0	5	62	N E S W 7.0 7.0 7.0 7.0	2.0	1.0	Early Mature	Fair	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Die-back - Upper crown. Deadwood - Minor. Decay / structural defect - Minor. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Bole. Multi-stemmed.	177.3	7.5	20-40	B	1
H1751	250 100 50 15	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Prunus spinosa* Blackthorn/Sloe *Sambucus nigra* Elder	2.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	1 2
T1752	1	*Acer campestre* Field Maple	17.0	1	52	N E S W 5.5 5.5 5.5 5.5	5.0	1.5	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base.	122.3	6.2	40+	B	1
T1753	1	*Acer campestre* Field Maple	17.0	2	70	N E S W 5.5 5.5 5.5 7.0	4.0	0.5	Early Mature	Poor	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Die-back - Throughout crown. Decline - Evident / observed. Deadwood - Major. Deadwood - Minor. Epicormic growth - Base.	226.2	8.5	10-20	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1754	75 15 8	*Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple *Sambucus nigra* Elder	9.0	1	14	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown. Sporadic gaps in hedge.	8.9	1.7	40+	C	1 2
T1755	1	*Fraxinus excelsior* Ash	17.0	1	55	N E S W 7.0 7.0 7.0 7.0	5.0	6.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor. Ivy or climbing plant.	136.8	6.6	20-40	B	1
G1756	4	*Fraxinus excelsior* Ash	18.0	1	65	N E S W 8.0 8.0 8.0 8.0	4.0	2.0	Mature	Good	Access to inspect base - Not possible. Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Die-back - Mid crown. Deadwood - Major. Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Ivy or climbing plant.	191.1	7.8	20-40	B	1 2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1757	65 10 8 4 4	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel *Acer campestre* Field Maple *Fraxinus excelsior* Ash	10.0	1	18	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Early Mature	Fair	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Die-back - Upper crown. Dead tree / trees. Deadwood - Minor. Epicormic growth - Base / bole / principal stems.	14.7	2.2	40+	C	1 2
T1758	1	*Fraxinus excelsior* Ash	17.0	5	67	N 6.0 E 6.0 S 6.0 W 6.0	3.0	0.0	Early Mature	Fair	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Die-back - Upper crown. Deadwood - Major. Deadwood - Minor. Epicormic growth - Base. Ivy or climbing plant.	203.6	8.0	20-40	C	1
T1759	1	*Salix fragilis* Crack Willow	20.0	1	74	N 9.0 E 9.0 S 9.0 W 4.0	0.0	3.0	Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Epicormic growth - Crown. Ivy or climbing plant. Pruning wounds - Historic. Shedding limb / limbs - Historic. Shedding limb / limbs - Major.	247.7	8.9	20-40	B	1
T1760	1	*Salix fragilis* Crack Willow	20.0	4	110	N 9.0 E 9.0 S 9.0 W 6.0	0.0	0.0	Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Epicormic growth - Crown. Ivy or climbing plant. Multi-stemmed. Pruning wounds - Historic.	547.4	13.2	20-40	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1761	1	*Populus tremula* Aspen	24.0	1	74	N 9.0 E 7.0 S 6.0 W 6.0	5.0	8.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Ivy or climbing plant.	247.7	8.9	40+	B	1
T1762	1	*Populus tremula* Aspen	24.0	1	74	N 9.0 E 5.0 S 9.0 W 9.0	5.0	8.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Ivy or climbing plant.	247.7	8.9	40+	B	1
T1763	1	*Populus tremula* Aspen	24.0	1	82	N 9.0 E 10.0 S 9.0 W 5.0	5.0	5.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Ivy or climbing plant. Leaning trunk - Minor.	304.2	9.8	40+	B	1
T1764	1	*Populus tremula* Aspen	22.0	1	85	N 10.0 E 6.0 S 10.0 W 10.0	5.0	8.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Ivy or climbing plant.	326.9	10.2	40+	B	1
T1765	1	*Fraxinus excelsior* Ash	18.0	3	51	N 5.0 E 5.0 S 5.0 W 5.0	4.0	1.0	Early Mature	Fair	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Die-back - Throughout crown. Deadwood - Minor. Ivy or climbing plant.	122.1	6.2	10-20	C	1
T1766	1	*Fraxinus excelsior* Ash	19.0	2	43	N 6.0 E 6.0 S 6.0 W 6.0	5.0	1.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Deadwood - Minor. Ivy or climbing plant.	86.9	5.3	20-40	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1767	150 45 25 15 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel *Fraxinus excelsior* Ash *Acer campestre* Field Maple	9.0	1	14	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown.	8.9	1.7	40+	C	1 2
T1768	1	*Crataegus monogyna* Common Hawthorn/Quick/May	8.0	1	30	N 4.0 E 4.0 S 4.0 W 3.0	0.0	1.0	Mature	Fair	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Die-back - Upper crown. Epicormic growth - Base / bole / principal stems. Ivy or climbing plant.	40.7	3.6	20-40	C	1
T1769	1	*Acer campestre* Field Maple	12.0	1	42	N 6.0 E 6.0 S 6.0 W 6.0	0.0	2.0	Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems. Ivy or climbing plant.	79.8	5.0	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1770	25 20 12	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Sambucus nigra* Elder	2.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** Remove a 10-m span. To facilitate development.	4.5	1.2	40+	C	1 2
T1771	1	*Acer campestre* Field Maple	9.0	1	42	N E S W 3.0 7.0 7.0 7.0	0.0	2.0	Mature	Fair	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Die-back - Upper crown. Epicormic growth - Base / bole / principal stems. Ivy or climbing plant. Suppressed crown - Minor.	79.8	5.0	20-40	C	1
T1772	1	*Quercus robur* English Oak	22.0	1	98	N E S W 10.0 12.0 12.0 12.0	5.0	7.0	Mature	Good	Arboricultural work - Historic. Deadwood - Major. Deadwood - Minor. Ivy or climbing plant.	434.5	11.8	40+	A	1
T1773	1	*Quercus robur* English Oak	20.0	1	85	N E S W 9.0 10.0 7.0 10.0	5.0	3.5	Mature	Good	Arboricultural work - Historic. Deadwood - Major. Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Fungal fruiting body - structural decay suspected. Ivy or climbing plant. Potential ganoderma brackets located on eastern side of base.	326.9	10.2	40+	B	1
T1774	1	*Quercus robur* English Oak	17.0	1	85	N E S W 7.0 7.0 7.0 6.0	5.0	3.5	Mature	Good	Arboricultural work - Historic. Deadwood - Major. Deadwood - Minor. Decay / structural defect - Base. Decay / structural defect - Major. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Bole. Epicormic growth - Base / bole / principal stems. Ivy or climbing plant.	326.9	10.2	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1775	1	*Quercus robur* English Oak	15.0	1	78	N E S W 5.0 8.0 8.0 8.0	5.0	3.5	Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor. Decay / structural defect - Localised. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Bole. Epicormic growth - Base / bole / principal stems. Ivy or climbing plant.	275.2	9.4	40+	B	1
T1776	1	*Quercus robur* English Oak	15.0	1	82	N E S W 7.0 7.0 5.0 7.0	5.0	4.0	Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Major. Deadwood - Minor. Decay / structural defect - Base. Decay / structural defect - Localised. Decay / structural defect - Open cavity / cavities. Epicormic growth - Base / bole / principal stems. Ivy or climbing plant.	304.2	9.8	40+	B	1
T1777	1	*Quercus robur* English Oak	22.0	1	115	N E S W 13.0 13.0 13.0 13.0	5.0	4.0	Mature	Good	Arboricultural work - Historic. Deadwood - Major. Deadwood - Minor. Fungal fruiting body - structural decay suspected. Ivy or climbing plant. Potential ganoderma brackets on eastern side of stem.	598.3	13.8	40+	A	1
T1778	1	*Alnus glutinosa* Common Alder	7.0	1	30	N E S W 2.5 0.0 1.0 1.0	1.0	1.0	Early Mature	Fair	Base / stems obscured - Vegetation. Deadwood - Minor. Decay / structural defect - Base. Decay / structural defect - Extensive. Decay / structural defect - Major. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Principal stems. Decay / structural defect - Bole. Epicormic growth - Base / bole / principal stems.	40.7	3.6	10-20	B	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1779	3 1 1 1 1 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple *Alnus glutinosa* Common Alder *Fraxinus excelsior* Ash *Malus sylvestris* Wild Crab *Sambucus nigra* Elder	15.0	1	60	N 5.0 E 9.0 S 5.0 W 6.0	3.0	1.0	Mature	Fair	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Bark exudation. Base / stems obscured - Vegetation. Die-back - Upper crown. Deadwood - Major. Deadwood - Minor. Decay / structural defect - Localised. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Bole. Epicormic growth - Base / bole / principal stems.	162.9	7.2	20-40	B	1 2
T1780	1	*Quercus robur* English Oak	19.0	1	96	N 12.0 E 12.0 S 12.0 W 12.0	4.0	4.0	Mature	Good	Arboricultural work - Historic. Branch - Suspended. Deadwood - Major. Deadwood - Minor. Fungal fruiting body - structural decay suspected. Ivy or climbing plant. Shedding limb / limbs - Minor. Shedding limb / limbs - Recent.	416.9	11.5	40+	A	1
G1781	6	*Quercus robur* English Oak	22.0	1	85	N 10.0 E 10.0 S 10.0 W 10.0	4.0	3.0	Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Major. Deadwood - Minor. Decay / structural defect - Localised. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Bole. Epicormic growth - Base / bole / principal stems. Shedding limb / limbs - Minor. Shedding limb / limbs - Recent. Woodpecker holes.	326.9	10.2	40+	A	1 2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1782	120 20 5 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder *Quercus robur* English Oak *Fraxinus excelsior* Ash	3.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Sporadic gaps in hedge.	4.5	1.2	40+	C	1 2
T1783	1	*Fraxinus excelsior* Ash	14.0	4	50	N 6.0 E 6.0 S 6.0 W 6.0	4.0	1.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Die-back - Upper crown. Decline - Evident / observed. Deadwood - Minor. Epicormic growth - Base / bole / principal stems.	113.1	6.0	10-20	C	1
G1784	2	*Quercus robur* English Oak	20.0	1	78	N 9.0 E 9.0 S 9.0 W 9.0	2.0	2.5	Mature	Good	Arboricultural work - Historic. Deadwood - Major. Deadwood - Minor. Epicormic growth - Base / bole / principal stems.	275.2	9.4	40+	A	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1785	75 15 8 6 4	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Sambucus nigra* Elder *Fraxinus excelsior* Ash *Acer pseudoplatanus* Sycamore	3.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	1
T1786	1	*Quercus robur* English Oak	17.0	1	65	N 10.0 E 10.0 S 10.0 W 10.0	4.0	4.0	Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Ivy or climbing plant.	191.1	7.8	40+	B	1
T1787	1	*Quercus robur* English Oak	23.0	1	92	N 12.0 E 12.0 S 12.0 W 12.0	2.0	5.0	Mature	Good	Arboricultural work - Historic. Bark exudation. Deadwood - Major. Deadwood - Minor. Fungal fruiting body - structural decay suspected. Foreign object - Ingrown metal. Ivy or climbing plant. Shedding limb / limbs - Minor. Shedding limb / limbs - Recent.	382.9	11.0	40+	A	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1788	130 40 10 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Prunus spinosa* Blackthorn/Sloe *Sambucus nigra* Elder	3.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. Sporadic gaps in hedge.	4.5	1.2	40+	C	1
T1789	1	*Crataegus monogyna* Common Hawthorn/Quick/May	11.0	1	43	N 7.0 E 7.0 S 7.0 W 7.0	0.0	1.0	Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems.	83.6	5.2	40+	A	1
T1790	1	*Acer campestre* Field Maple	14.0	4	60	N 7.0 E 7.0 S 7.0 W 7.0	0.0	0.0	Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems. Multi-stemmed.	162.9	7.2	40+	B	1
T1791	1	*Fraxinus excelsior* Ash	19.0	3	51	N 8.0 E 8.0 S 8.0 W 8.0	2.0	0.0	Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Multi-stemmed. Shedding limb / limbs - Minor. Shedding limb / limbs - Recent.	122.1	6.2	20-40	B	1
T1792	1	*Fraxinus excelsior* Ash	19.0	1	56	N 8.0 E 8.0 S 8.0 W 8.0	2.0	4.0	Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Shedding limb / limbs - Minor. Shedding limb / limbs - Recent.	141.9	6.7	20-40	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1793	1	*Fraxinus excelsior* Ash	18.0	1	40	N 8.0 E 8.0 S 6.0 W 5.0	4.0	5.0	Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Shedding limb / limbs - Minor. Shedding limb / limbs - Recent.	72.4	4.8	20-40	B	1
T1794	1	*Fraxinus excelsior* Ash	18.0	1	38	N 8.0 E 5.0 S 6.0 W 8.0	4.0	5.0	Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Shedding limb / limbs - Minor. Shedding limb / limbs - Recent.	65.3	4.6	20-40	B	1
T1795	1	*Fraxinus excelsior* Ash	15.0	2	35	N 4.0 E 4.0 S 4.0 W 4.0	0.0	1.0	Early Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems.	56.5	4.2	40+	C	1
T1796	1	*Fraxinus excelsior* Ash	18.0	2	45	N 8.0 E 7.0 S 7.0 W 5.0	4.0	0.0	Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor. Epicormic growth - Base.	92.6	5.4	20-40	B	1
T1797	1	*Fraxinus excelsior* Ash	18.0	1	36	N 8.0 E 5.0 S 7.0 W 7.0	4.0	5.0	Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Shedding limb / limbs - Minor. Shedding limb / limbs - Recent.	58.6	4.3	20-40	B	1
G1798	3 2	*Acer pseudoplatanus* Sycamore *Fraxinus excelsior* Ash	15.0	1	24	N 6.0 E 6.0 S 6.0 W 6.0	3.0	0.0	Early Mature	Fair	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Die-back - Upper crown. Deadwood - Minor. Epicormic growth - Base / bole / principal stems.	26.1	2.9	20-40	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1799	45 10 8 5 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Fraxinus excelsior* Ash *Acer pseudoplatanus* Sycamore *Corylus avellana* Common Hazel	6.0	1	14	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Hedgerow - Neglected / overgrown.	8.9	1.7	40+	C	1 2
H1800	65 8 5 4	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Sambucus nigra* Elder *Acer pseudoplatanus* Sycamore	2.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1801	6 4 4	*Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple *Prunus spinosa* Blackthorn/Sloe	9.0	1	20	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Early Mature	Fair	Access to inspect base - Not possible. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems.	18.1	2.4	20-40	C	1 2
G1802	6 2	*Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple	10.0	1	25	N 4.0 E 4.0 S 4.0 W 4.0	0.0	0.0	Early Mature	Good	Access to inspect base - Not possible. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems.	28.3	3.0	40+	C	1 2
T1803	1	*Crataegus monogyna* Common Hawthorn/Quick/May	7.0	2	2	N 4.0 E 4.0 S 4.0 W 4.0	0.0	0.0	Mature	Good	Access to inspect base - Not possible. Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems.	0.4	0.3	40+	B	1
G1804	2	*Quercus robur* English Oak	15.0	1	56	N 9.0 E 9.0 S 9.0 W 9.0	4.0	4.0	Early Mature	Good	Arboricultural work - Historic. Deadwood - Minor. **Reduce lateral limb / limbs.** Prune southern aspect of crowns back by 3 m. To facilitate development.	141.9	6.7	40+	B	1
T1805	1	*Quercus robur* English Oak	20.0	1	120	N 12.0 E 9.0 S 11.0 W 12.0	3.0	4.0	Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Major. Deadwood - Minor. Ivy or climbing plant. Shedding limb / limbs - Historic. Shedding limb / limbs - Minor.	651.4	14.4	40+	A	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1806	1	*Quercus robur* English Oak	19.0	1	94	N E S W 8.0 6.0 10.0 5.0	3.0	3.0	Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Ivy or climbing plant. Shedding limb / limbs - Historic. Shedding limb / limbs - Minor.	399.7	11.3	40+	B	1
T1807	1	*Acer campestre* Field Maple	14.0	1	30	N E S W 2.0 2.0 3.0 2.0	0.0	2.0	Early Mature	Fair	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems. Ivy or climbing plant. Suppressed crown - Minor.	40.7	3.6	20-40	C	1
G1808	1 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash	7.0	1	30	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Die-back - Upper crown. Deadwood - Major. Deadwood - Minor. Epicormic growth - Base / bole / principal stems.	40.7	3.6	40+	C	1
T1809	1	*Fraxinus excelsior* Ash	10.0	1	30	N E S W 3.5 3.5 3.5 3.5	3.0	1.5	Semi Mature	Good	Arboricultural work - Historic. Epicormic growth - Base.	40.7	3.6	20-40	C	1
T1810	1	*Fraxinus excelsior* Ash	10.0	1	20	N E S W 3.0 3.0 3.0 3.0	3.0	4.0	Semi Mature	Good	Arboricultural work - Historic. Epicormic growth - Base.	18.1	2.4	20-40	C	1
T1811	1	*Fraxinus excelsior* Ash	10.0	1	34	N E S W 3.5 3.5 3.5 3.5	3.0	3.0	Semi Mature	Fair	Arboricultural work - Historic. Epicormic growth - Base.	52.3	4.1	10-20	C	1
T1812	1	*Acer campestre* Field Maple	11.0	1	40	N E S W 5.0 5.0 5.0 5.0	2.0	2.0	Early Mature	Good	Arboricultural work - Historic. Epicormic growth - Base.	72.4	4.8	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1813	6 1 1	*Fraxinus excelsior* Ash *Quercus robur* English Oak *Sambucus nigra* Elder	11.0	1	20	N E S W 3.0 3.0 3.0 3.0	2.0	1.5	Semi Mature	Fair	Access to inspect base - Not possible. Arboricultural work - Historic. Die-back - Upper crown. Epicormic growth - Base / bole / principal stems. Affected by ash dieback.	18.1	2.4	20-40	C	1
G1814	6 1	*Acer pseudoplatanus* Sycamore *Quercus robur* English Oak	14.0	3	43	N E S W 5.0 5.0 5.0 5.0	0.0	0.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor. Epicormic growth - Base.	84.8	5.2	40+	B	1 2
T1815	1	*Quercus robur* English Oak	15.0	1	96	N E S W 10.0 7.0 10.0 9.0	0.0	1.0	Mature	Good	Arboricultural work - Historic. Deadwood - Major. Deadwood - Minor. Decay / structural defect - Base. Decay / structural defect - Localised. Decay / structural defect - Open cavity / cavities. Fungal fruiting body - structural decay suspected. Shedding limb / limbs - Minor. Unable to identify fungal bracket located at a cavity at the base on the south side. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	416.9	11.5	40+	B	1
T1816	1	*Corylus avellana* Common Hazel	3.0	12	20	N E S W 1.5 1.5 1.5 1.5	0.0	0.0	Semi Mature	Good	Natural regeneration.	19.5	2.5	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1817	4 3	*Corylus avellana* Common Hazel *Salix caprea* Goat Willow/Great Sallow	7.0	8	22	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base.	23.2	2.7	40+	C	1 2
T1818	1	*Quercus robur* English Oak	17.0	1	62	N E S W 8.0 8.0 8.0 8.0	2.0	3.0	Early Mature	Good	Arboricultural work - Historic. Deadwood - Major. Deadwood - Minor. Shedding limb / limbs - Minor.	173.9	7.4	40+	B	1
G1819	2 1 1	*Acer pseudoplatanus* Sycamore *Fraxinus excelsior* Ash *Quercus robur* English Oak	18.0	3	45	N E S W 5.0 5.0 5.0 5.0	0.0	0.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Arboricultural work - Recent. Base / stems obscured - Vegetation. Deadwood - Minor. Epicormic growth - Base.	91.7	5.4	40+	B	1 2
G1820	1 1 1	*Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	5.0	1	25	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems.	28.3	3.0	40+	C	1
G1821	1 1	*Fraxinus excelsior* Ash *Acer pseudoplatanus* Sycamore	16.0	2	35	N E S W 5.0 5.0 5.0 5.0	3.0	1.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Die-back - Upper crown. Epicormic growth - Base / bole / principal stems. Affected by ash dieback, 80% of canopy remains.	56.5	4.2	20-40	C	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1822	1	*Quercus robur* English Oak	16.0	1	62	N E S W 9.0 8.0 12.0 10.0	4.0	4.0	Early Mature	Good	Arboricultural work - Historic. Deadwood - Major. Deadwood - Minor. Epicormic growth - Base.	173.9	7.4	40+	B	1
T1823	1	*Acer pseudoplatanus* Sycamore	9.0	8	33	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Early Mature	Fair	Arboricultural work - Historic. Base / stems obscured - Vegetation. Coppice stool - Coppice origin / Mature stems. Deadwood - Minor. Epicormic growth - Base.	52.1	4.1	20-40	C	1
T1824	1	*Acer pseudoplatanus* Sycamore	9.0	8	33	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Early Mature	Fair	Arboricultural work - Historic. Base / stems obscured - Vegetation. Coppice stool - Coppice origin / Mature stems. Deadwood - Minor. Epicormic growth - Base.	52.1	4.1	20-40	C	1
G1825	4 1	*Corylus avellana* Common Hazel *Acer pseudoplatanus* Sycamore	9.0	8	28	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Coppice stool - Coppice origin / Mature stems. Epicormic growth - Base / bole / principal stems.	36.2	3.4	20-40	C	1
T1826	1	*Quercus robur* English Oak	2.5	1	14	N E S W 1.5 1.5 1.5 1.5	1.0	1.0	Young	Good	Natural regeneration. **Fell - Ground level.** To facilitate development.	8.9	1.7	40+	C	1
G1827	20	*Prunus spinosa* Blackthorn/Sloe	4.0	1	6	N E S W 3.0 3.0 3.0 3.0	0.0	1.0	Semi Mature	Good	Base / stems obscured - Vegetation. Natural regeneration. **Fell - Ground level.** To facilitate development.	1.6	0.7	10-20	C	1
G1828	5	*Fraxinus excelsior* Ash	9.0	8	28	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Early Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base.	36.2	3.4	40+	C	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1829	2 2 1	*Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May *Malus sylvestris* Wild Crab	11.0	1	18	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Semi Mature	Fair	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor.	14.7	2.2	10-20	C	1
T1830	1	*Acer pseudoplatanus* Sycamore	11.5	4	58	N E S W 5.0 5.0 5.0 5.0	1.0	0.0	Early Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base.	152.2	7.0	40+	B	1
T1831	1	*Corylus avellana* Common Hazel	4.0	8	16	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic.	13.0	2.0	40+	C	1
T1832	1	*Fraxinus excelsior* Ash	12.0	2	63	N E S W 7.0 7.0 7.0 7.0	1.0	1.0	Early Mature	Good	Arboricultural work - Historic. Die-back - Upper crown. Epicormic growth - Base. Dieback. Chalara ash dieback suspected.	181.0	7.6	20-40	B	1
G1833	4 4 1 1	*Acer pseudoplatanus* Sycamore *Fraxinus excelsior* Ash *Corylus avellana* Common Hazel *Malus sylvestris* Wild Crab	13.0	1	44	N E S W 7.0 7.0 7.0 7.0	2.0	0.0	Early Mature	Fair	Arboricultural work - Historic. Base / stems obscured - Vegetation. Die-back - Upper crown. Deadwood - Minor. Epicormic growth - Base. Affected by ash dieback.	87.6	5.3	20-40	B	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1834	1	*Acer pseudoplatanus* Sycamore	15.0	4	120	N E S W 8.0 8.0 8.0 8.0	2.0	0.0	Early Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor. Epicormic growth - Base.	651.4	14.4	40+	B	1
G1835	4 4 2	*Quercus robur* English Oak *Sambucus nigra* Elder *Corylus avellana* Common Hazel	11.0	1	53	N E S W 7.0 7.0 7.0 7.0	3.0	1.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Deadwood - Minor. Epicormic growth - Base.	127.1	6.4	40+	B	1 2
G1836	6 1	*Corylus avellana* Common Hazel *Salix caprea* Goat Willow/Great Sallow	6.0	10	25	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Epicormic growth - Base.	29.0	3.0	40+	C	1 2
G1837	3	*Corylus avellana* Common Hazel	5.0	8	22	N E S W 2.0 2.0 2.0 2.0	1.0	0.0	Semi Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base.	23.2	2.7	40+	C	1 2
T1838	1	*Quercus robur* English Oak	10.0	1	59	N E S W 7.0 7.0 7.0 7.0	2.0	2.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base.	157.5	7.1	40+	B	1
T1839	1	*Corylus avellana* Common Hazel	7.0	9	24	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base.	26.1	2.9	20-40	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1840	1	*Corylus avellana* Common Hazel	7.0	9	24	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base.	26.1	2.9	20-40	C	1
T1841	1	*Corylus avellana* Common Hazel	9.0	12	13	N 5.0 E 5.0 S 5.0 W 5.0	2.0	0.0	Early Mature	Poor	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Decline - Evident / observed. Epicormic growth - Base.	8.7	1.7	10-20	C	1
T1842	1	*Corylus avellana* Common Hazel	9.0	12	20	N 5.0 E 5.0 S 5.0 W 5.0	2.0	0.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base.	19.5	2.5	20-40	C	1
T1843	1	*Corylus avellana* Common Hazel	7.0	9	24	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base.	26.1	2.9	20-40	C	1
T1844	1	*Quercus robur* English Oak	10.0	1	48	N 9.0 E 5.0 S 5.0 W 5.0	0.0	1.5	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base.	104.2	5.8	40+	B	1
T1845	1	*Quercus robur* English Oak	9.0	1	67	N 7.0 E 7.0 S 7.0 W 7.0	1.0	2.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base.	203.1	8.0	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1846	1	*Fraxinus excelsior* Ash	11.0	6	44	N E S W 5.0 5.0 5.0 5.0	3.0	0.0	Early Mature	Fair	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Die-back - Upper crown. Deadwood - Minor. Epicormic growth - Base. Canopy in decline, affected by hymenoscyphus fraxineus (ash dieback).	87.9	5.3	10-20	C	1
H1847	45 12 4	*Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May	8.0	8	22	N E S W 2.5 2.5 2.5 2.5	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown.	23.2	2.7	40+	C	1 2
G1848	4 4 3 3	*Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Salix caprea* Goat Willow/Great Sallow	11.0	4	40	N E S W 3.5 3.5 3.5 3.5	0.0	0.0	Early Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base. Hedgerow - Neglected / overgrown.	72.4	4.8	40+	C	1 2
T1849	1	*Quercus robur* English Oak	16.0	1	72	N E S W 10.0 10.0 10.0 10.0	4.0	3.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Major. Deadwood - Minor. Epicormic growth - Base.	234.5	8.6	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1850	15 2 2 2	*Corylus avellana* Common Hazel *Salix caprea* Goat Willow/Great Sallow *Quercus robur* English Oak *Crataegus monogyna* Common Hawthorn/Quick/May	9.0	1	18	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown.	14.7	2.2	40+	C	1 2
G1851	45 10 6 5	*Populus tremula* Aspen *Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Quercus robur* English Oak	18.0	1	25	N 7.0 E 7.0 S 7.0 W 7.0	3.0	0.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Deadwood - Minor. Epicormic growth - Base.	28.3	3.0	40+	B	1 2
H1852	12 3 3	*Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May *Salix caprea* Goat Willow/Great Sallow	8.0	8	22	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown.	23.2	2.7	40+	C	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1853	1	*Corylus avellana* Common Hazel	6.0	12	27	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Semi Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base.	34.7	3.3	40+	C	1
G1854	2	*Quercus robur* English Oak	5.0	1	20	N E S W 3.0 3.0 3.0 3.0	1.0	0.5	Semi Mature	Good	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems.	18.1	2.4	40+	C	1 2
T1855	1	*Quercus robur* English Oak	14.0	1	45	N E S W 8.0 9.0 0.0 5.0	2.0	4.0	Early Mature	Fair	Access to inspect base - Restricted / obscured. Arboricultural work - Historic. Base / stems obscured - Vegetation. Decay / structural defect - Base. Decay / structural defect - Extensive. Decay / structural defect - Major. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Bole. Epicormic growth - Base. Unbalanced crown - Major. Southern stem has failed and exposed central heartwood. Half the stem and canopy remain.	91.6	5.4	40+	C	1
T1856	1	*Quercus robur* English Oak	6.0	1	20	N E S W 3.0 3.0 3.0 3.0	0.0	1.0	Semi Mature	Good	Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base.	18.1	2.4	40+	C	1
G1857	3 1	*Quercus robur* English Oak *Crataegus monogyna* Common Hawthorn/Quick/May	15.0	1	60	N E S W 8.0 8.0 8.0 8.0	2.0	3.0	Early Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Deadwood - Major. Deadwood - Minor. Epicormic growth - Base / bole / principal stems.	162.9	7.2	40+	B	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1858	1	*Quercus robur* English Oak	17.0	1	78	N 9.0 E 8.0 S 9.0 W 9.0	4.0	4.0	Mature	Good	Deadwood - Major. Deadwood - Minor. Decay / structural defect - Localised. Decay / structural defect - Open cavity / cavities. Epicormic growth - Bole / principal stems. Excavation within root zone - Burrowing. **Fell - Ground level.** To facilitate development.	275.2	9.4	40+	A	1
T1859	1	*Quercus robur* English Oak	17.0	1	74	N 6.0 E 7.0 S 8.0 W 8.0	4.0	4.0	Mature	Good	Deadwood - Major. Deadwood - Minor. Epicormic growth - Bole / principal stems.	247.7	8.9	40+	B	1
T1860	1	*Quercus robur* English Oak	16.0	1	97	N 7.0 E 7.0 S 7.0 W 8.0	1.0	2.5	Mature	Good	Deadwood - Major. Deadwood - Minor. Epicormic growth - Bole / principal stems. **Fell - Ground level.** To facilitate development.	425.7	11.6	40+	B	1
T1861	1	*Quercus robur* English Oak	16.0	1	74	N 6.0 E 7.0 S 6.0 W 7.0	1.0	2.0	Mature	Good	Deadwood - Major. Deadwood - Minor. Epicormic growth - Bole / principal stems. **Fell - Ground level.** To facilitate development.	247.7	8.9	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1862	15 10 10 8 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Salix caprea* Goat Willow/Great Sallow *Betula pendula* Silver Birch *Acer pseudoplatanus* Sycamore	9.0	1	20	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Not possible. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems. **Fell - Ground level.** To facilitate development.	18.1	2.4	40+	C	1 2
T1863	1	*Fraxinus excelsior* Ash	18.0	1	66	N 9.0 E 9.0 S 9.0 W 9.0	3.0	6.0	Mature	Fair	Arboricultural work - Historic. Die-back - Upper crown. Deadwood - Major. Deadwood - Minor. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Bole. Epicormic growth - Base / bole / principal stems. Fungal fruiting body - structural decay suspected. Fallen inonotus fungal brackets at base. Dieback in crown. **Fell - Ground level.** To facilitate development.	197.1	7.9	20-40	B	1 2
H1864	8	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	1	25	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Mature	Good	Hedgerow - Maintained. Height unmanaged. **Fell - Ground level.** To facilitate development.	28.3	3.0	20-40	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1865	10	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	20	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Mature	Good	Hedgerow - Maintained. Height unmanaged. **Fell - Ground level.** To facilitate development.	18.1	2.4	40+	C	1 2
H1866	120 8	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder	3.0	1	16	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** Remove a 45-m span. To facilitate development.	11.6	1.9	20-40	C	1 2
T1867	1	*Quercus robur* English Oak	10.0	1	60	NW NE SE SW 7.0 4.0 5.0 4.0	3.0	3.5	Early Mature	Good	Arboricultural work - Historic. Epicormic growth - Bole / principal stems. Ivy or climbing plant.	162.9	7.2	40+	B	1
H1868	25 5 2 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Viburnum opulus* Guelder Rose *Prunus spinosa* Blackthorn/Sloe *Fraxinus excelsior* Ash	3.0	1	5	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** Remove a 25-m span. To facilitate development.	1.1	0.6	40+	C	2
H1869	5 3	*Crataegus monogyna* Common Hawthorn/Quick/May *Viburnum opulus* Guelder Rose	3.0	1	5	NW NE SE SW 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	1.1	0.6	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1870	20 1 1 1 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple *Quercus robur* English Oak *Swida sanguinea* Common Dogwood *Corylus avellana* Common Hazel	4.0	1	10	NW NE SE SW 2.0 2.0 2.0 2.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** Remove a 25-m span. To facilitate development.	4.5	1.2	40+	C	2
G1871	30 10 10	*Tilia cordata* Small Leaved Lime *Cerasus avium* Wild Cherry *Populus x canadensis* Hybrid Black Poplars	16.0	1	30	NW NE SE SW 4.0 4.0 4.0 4.0	2.0	3.0	Semi Mature	Good	Branch - Broken. Branch - Suspended. Epicormic growth - Bole / principal stems.	40.7	3.6	40+	B	2
T1872	1	*Corylus avellana* Common Hazel	6.0	15	58	NW NE SE SW 3.0 3.0 3.0 3.0	0.0	0.0	Early Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Multi-stemmed.	152.7	7.0	40+	C	1
H1873	15 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel	3.0	1	10	NW NE SE SW 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1874	3 1 1	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel	3.0	8	14	NW NE SE SW 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	9.0	1.7	40+	C	2
H1875	20 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	3.0	1	10	NW NE SE SW 1.0 2.0 2.0 2.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
G1876	2 2	*Quercus robur* English Oak *Fraxinus excelsior* Ash	18.0	1	91	N E S W 9.0 9.0 9.0 9.0	1.0	2.0	Mature	Good	Arboricultural work - Historic. Die-back - Upper crown. Deadwood - Major. Epicormic growth - Bole / principal stems. Pruning wounds - Historic. The ash have symptoms associated with Hymenoscyphus fraxineus (ash die-back) - Health class 1. There is an understory of semi- mature common hawthorn beneath the Eastern most ash.	374.6	10.9	40+	B	1 2
H1877	20 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder	4.0	1	12	NW NE SE SW 1.0 2.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	6.5	1.4	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1878	30	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	15	NW NE SE SW 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Gapping up of this hedge line has taken place at the southwestern end. **Fell - Ground level.** Remove a 25-m span. To facilitate development.	10.2	1.8	40+	C	2
	5	*Acer campestre* Field Maple														
	5	*Corylus avellana* Common Hazel														
	1	*Malus sylvestris* Wild Crab														
	1	*Quercus robur* English Oak														
	1	*Swida sanguinea* Common Dogwood														
H1879	50	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	5	NW NE SE SW 3.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	1.1	0.6	40+	C	2
	3	*Acer pseudoplatanus* Sycamore														
	3	*Tilia cordata* Small Leaved Lime														
	2	*Fraxinus excelsior* Ash														

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1880	1	*Tilia cordata* Small Leaved Lime	10.0	2	42	NW 5.0 NE 3.0 SE 3.0 SW 2.0	0.0	0.0	Early Mature	Good	Access to inspect base - Not possible. Epicormic growth - Base / bole / principal stems. **Prune from adjacent structure.** Prune northeastern crown back by 2 m to clear cable corridor.	81.4	5.1	40+	C	1
H1881	20 15 15 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Acer campestre* Field Maple *Swida sanguinea* Common Dogwood	4.0	1	10	NW 3.0 NE 3.0 SE 3.0 SW 3.0	0.0	0.0	Semi Mature	Good	Hedgerow - Neglected / overgrown. **Fell - Ground level.** Remove 6-m span. To facilitate development.	4.5	1.2	40+	C	2
H1882	50 2 2 2 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple *Corylus avellana* Common Hazel *Quercus robur* English Oak *Sambucus nigra* Elder	3.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** Remove a 25-m span. To facilitate development.	4.5	1.2	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1883	1	*Quercus robur* English Oak	12.0	1	50	N E S W 5.0 5.0 6.0 6.0	3.0	2.0	Semi Mature	Good	Arboricultural work - Historic. Form - Low canopy vehicle damage.	113.1	6.0	40+	B	1
H1884	7	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
	6	*Acer campestre* Field Maple														
	2	*Corylus avellana* Common Hazel														
	1	*Malus sylvestris* Wild Crab														
	1	*Swida sanguinea* Common Dogwood														
H1885	20	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	15	N E S W 1.0 1.0 2.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	10.2	1.8	40+	C	2
	4	*Corylus avellana* Common Hazel														
	3	*Swida sanguinea* Common Dogwood														
	2	*Prunus spinosa* Blackthorn/Sloe														
T1886	1	*Quercus robur* English Oak	16.0	1	99	N E S W 4.0 6.0 8.0 5.0	0.5	2.0	Mature	Good	Deadwood - Major. Deadwood - Minor. Pruning wounds - Decayed. Pruning wounds - Historic.	443.4	11.9	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1887	1	*Quercus robur* English Oak	17.0	1	120	N E S W 8.0 8.0 9.0 8.0	3.0	4.0	Mature	Good	Arboricultural work - Historic. Deadwood - Minor. Epicormic growth - Bole / principal stems. Ivy or climbing plant.	651.4	14.4	40+	A	1
T1888	1	*Quercus robur* English Oak	18.0	1	120	N E S W 7.0 11.0 12.0 8.0	4.0	3.0	Mature	Good	Deadwood - Minor. Ivy or climbing plant.	651.4	14.4	40+	A	1
T1889	1	*Fraxinus excelsior* Ash	15.0	1	60	N E S W 6.0 8.0 9.0 8.0	4.0	4.0	Mature	Fair	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Die-back - Throughout crown. Deadwood - Minor. Ivy or climbing plant. Physiological / cambial damage - Fungal. Physiological / cambial damage - Unconfirmed. This tree has symptoms associated with Hymenoscyphus fraxineus (ash die-back) - Health class 2.	162.9	7.2	20-40	C	1
H1890	9 8 5 3	*Corylus avellana* Common Hazel *Acer campestre* Field Maple *Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	4.0	1	15	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown.	10.2	1.8	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1891	4 4 2 1	*Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple *Rosa canina* Dog-rose	3.0	1	4	N 1.0 E 1.0 S 2.0 W 2.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	0.7	0.5	40+	C	2
H1892	5 5 2	*Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple	4.0	20	22	N 1.0 E 1.0 S 2.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** Remove a 25-m span. To facilitate development.	22.6	2.7	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1893	1	*Quercus robur* English Oak	21.0	1	151	N E S W 12.0 13.0 15.0 15.0	3.0	5.0	Mature	Good	Buttresses / buttress roots - Major adaptive growth / strong development. Deadwood - Major. Decay / structural defect - Base. Decay / structural defect - Open cavity / cavities. Form - Large sail area / crown extent. Form - Spreading crown. Pruning wounds - Decayed. Pruning wounds - Historic. Rare or notable specimen. Root damage - Mechanical. Reaction wood / Adaptive growth - Base. Reaction wood / Adaptive growth - Stem / stems. Senescent Ganoderma brackets to the east and south. Pseudoinonotus dryadeus brackets to the northeast. All brackets are between major buttress roots that tap solid with the sounding hammer and show good reaction growth.	706.9	15.0	40+	A	1 2
T1894	1	*Quercus robur* English Oak	12.0	1	102	N E S W 6.0 6.0 6.0 5.0	1.0	2.0	Ancient or Veteran	Good	Buttresses / buttress roots - Major adaptive growth / strong development. Die-back - Upper crown. Decay / structural defect in crown limb / limbs - Localised. Deadwood - Major. Deadwood - Minor. Decay / structural defect - Open cavity / cavities. Habitat - High value. Hollow trunk - Open cavity. Reaction wood / Adaptive growth - Base. Reaction wood / Adaptive growth - Limb / limbs. Reaction wood / Adaptive growth - Stem / stems.	470.7	12.2	40+	B	1
T1895	1	*Fraxinus excelsior* Ash	13.0	1	58	N E S W 6.0 3.0 7.0 10.0	3.0	3.0	Early Mature	Fair	Arboricultural work - Historic. Physiological / cambial damage - Fungal. Tree has symptoms associated with Hymenoscyphus fraxineus (ash die-back).	152.2	7.0	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1896	10 5 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Acer campestre* Field Maple	8.0	1	20	N E S W 2.0 2.0 3.0 2.0	0.0	0.0	Mature	Good	Hedgerow - Neglected / overgrown. Hyacinthanoides non-scripta (common bluebells) and mature field maple present on the western edge of this hedge, shows its significant age.	18.1	2.4	40+	C	2 3
T1897	1	*Acer campestre* Field Maple	14.0	1	59	N E S W 7.0 7.0 7.0 7.0	1.5	4.0	Mature	Good	Deadwood - Minor. Decay / structural defect - Localised. Decay / structural defect - Bole.	157.5	7.1	40+	B	1
H1898	10 10 4 1	*Acer campestre* Field Maple *Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Quercus robur* English Oak	3.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** Remove a 25-m span. To facilitate development.	4.5	1.2	40+	C	2
T1899	1	*Quercus robur* English Oak	5.0	1	120	N E S W 0.0 0.0 0.0 0.0	0.0	0.0	Mature	Dead	Dead tree / trees. Monolith.			0-10	U	
T1900	1	*Crataegus monogyna* Common Hawthorn/Quick/May	12.0	1	45	N E S W 4.0 4.0 4.0 4.0	3.0	3.0	Mature	Fair	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Die-back - Throughout crown. Deadwood - Minor.	91.6	5.4	20-40	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1901	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	2	25	N 3.0 E 3.0 S 3.0 W 3.0	1.0	2.0	Mature	Good	Deadwood - Minor. Epicormic growth - Base. Twin-stemmed. **Fell - Ground level.** - To facilitate development.	28.3	3.0	40+	B	1
H1902	10 2 2 1	*Ligustrum ovalifolium* Privet/Garden Privet *Crataegus monogyna* Common Hawthorn/Quick/May *Malus sp.* Apple sp. *Sambucus nigra* Elder	6.0	1	20	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. Neatly managed 2 metre high privet with unmanaged hawthorn and apple standing above.	18.1	2.4	40+	B	2
H1903	20	*Ligustrum ovalifolium* Privet/Garden Privet	2.0	5	6	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	2.0	0.8	40+	C	2
T1904	1	*Trachycarpus fortunei* Chusan Palm	5.0	1	20	N 0.5 E 0.5 S 0.5 W 0.5	3.0	3.0	Semi Mature	Good		18.1	2.4	20-40	C	1
T1905	1	*Salix fragilis* Crack Willow	10.0	1	20	N 5.0 E 4.0 S 3.0 W 4.0	2.0	2.0	Semi Mature	Good		18.1	2.4	40+	B	1
T1906	1	*Viburnum lantana* Wayfaring Tree	1.5	10	15	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Semi Mature	Good	Form - Small sail area / crown extent.	11.3	1.9	40+	C	1
H1907	10	*Taxus baccata* Yew	3.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1908	25	*Populus tremula* Aspen	17.0	1	25	N 6.0 E 6.0 S 6.0 W 6.0	0.0	1.0	Semi Mature	Good		28.3	3.0	40+	B	2
T1909	1	*Alnus glutinosa* Common Alder	5.0	2	10	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.5	Young	Fair	Foliar / bud damage - Insect. Agelastica alni (Alder leaf beetle) present in crown.	5.1	1.3	40+	C	1
T1910	1	*Corylus avellana* Common Hazel	2.0	5	6	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Foreign object - Ingrown metal. Multi-stemmed.	2.0	0.8	40+	C	1
T1911	1	*Corylus avellana* Common Hazel	4.0	15	11	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Form - Low canopy. Multi-stemmed.	6.1	1.4	40+	C	1
T1912	1	*Corylus avellana* Common Hazel	3.0	15	11	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Semi Mature	Good	Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Form - Low canopy. Multi-stemmed.	6.1	1.4	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1913	5 3 2 2 1 1	*Corylus avellana* Common Hazel *Quercus robur* English Oak *Sorbus aria* Whitebeam *Fraxinus excelsior* Ash *Betula pendula* Silver Birch *Alnus glutinosa* Common Alder	10.0	1	20	N 4.0 E 4.0 S 4.0 W 4.0	0.0	0.0	Semi Mature	Good	Form - Low canopy. Sheltered crown. **Reduce lateral limb / limbs.** Prune back from north by 2.5 m. To facilitate development.	18.1	2.4	40+	B	2
T1914	1	*Quercus robur* English Oak	14.0	1	79	N 7.0 E 7.0 S 6.0 W 6.0	1.5	4.0	Mature	Good	Die-back - Upper crown. Deadwood - Minor. Epicormic growth - Bole / principal stems. Pruning wounds - Historic.	282.3	9.5	40+	B	1
T1915	1	*Sambucus nigra* Elder	2.0	6	29	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.5	Semi Mature	Good	Arboricultural work - Recent. Crown reduction - Recent.	39.1	3.5	20-40	C	1
H1916	6	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	20	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Hedgerow - Maintained.	18.1	2.4	40+	C	2
T1917	1	*Quercus robur* English Oak	12.0	1	45	N 6.0 E 6.0 S 6.0 W 6.0	3.0	5.0	Early Mature	Good	Epicormic growth - Bole / principal stems.	91.6	5.4	40+	B	1
T1918	1	*Quercus robur* English Oak	13.0	1	60	N 6.0 E 8.0 S 7.0 W 6.0	3.0	5.0	Early Mature	Good	Form - Spreading crown.	162.9	7.2	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1919	1	*Quercus robur* English Oak	12.0	1	50	N E S W 5.0 8.0 8.0 5.0	1.0	5.0	Early Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Epicormic growth - Bole / principal stems.	113.1	6.0	40+	B	1
T1920	1	*Fraxinus excelsior* Ash	12.5	2	41	N E S W 6.0 7.0 5.0 7.0	1.5	2.0	Semi Mature	Good	Die-back - Throughout crown. Deadwood - Minor. Physiological / cambial damage - Fungal. Symptoms associated with Hymenoscyphus fraxineus (ash die-back) - Health class 1. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	76.2	4.9	20-40	C	1
T1921	1	*Quercus robur* English Oak	12.0	1	60	NW NE SE SW 8.0 8.0 7.0 8.0	1.0	4.0	Early Mature	Good	Access to inspect base - Not possible. Arboricultural work - Historic. Base / stems obscured - Structure. Base / stems obscured - Vegetation. Crown reduction - Historic. Ivy or climbing plant. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	162.9	7.2	40+	B	1
T1922	1	*Sambucus nigra* Elder	4.0	7	39	NW NE SE SW 1.0 4.0 1.0 4.0	0.0	1.0	Early Mature	Fair	Arboricultural work - Recent. Crown reduction - Recent.	71.3	4.8	10-20	C	1
T1923	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	5	33	NW NE SE SW 1.0 4.0 1.0 4.0	0.0	0.5	Mature	Fair	Arboricultural work - Recent. Crown reduction - Recent. Die-back - Upper crown. Deadwood - Minor. Hedgerow - Historic.	50.9	4.0	20-40	C	1
T1924	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	20	NW NE SE SW 1.0 3.0 1.0 3.0	0.0	0.5	Mature	Good	Arboricultural work - Recent. Crown reduction - Recent. Dense crown. Epicormic growth - Crown. Hedgerow - Historic.	18.1	2.4	20-40	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1925	30	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	NW 1.0 NE 1.0 SE 1.0 SW 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. **Reduce lateral limb / limbs.** Prune western end back by 2 m. To facilitate development.	4.5	1.2	40+	B	2
T1926	1	*Quercus robur* English Oak	14.0	4	73	N 6.0 E 6.0 S 6.0 W 6.0	3.0	1.0	Semi Mature	Good	Branch - Broken. Branch - Suspended. Epicormic growth - Bole / principal stems. Fork - Suspected structurally sound.	247.2	8.9	40+	B	1
T1927	1	*Salix fragilis* Crack Willow	15.0	3	61	N 6.0 E 9.0 S 7.0 W 3.0	3.0	4.0	Early Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Deadwood - Minor. Ivy or climbing plant. Leaning trunk - Minor.	173.0	7.4	40+	B	1
T1928	1	*Salix fragilis* Crack Willow	11.0	3	34	N 3.0 E 6.0 S 4.0 W 1.0	1.5	1.5	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Crown conflict - Structure / boundary / wire / tree. Epicormic growth - Bole / principal stems. Leaning trunk - Major.	54.3	4.2	40+	C	1
T1929	1	*Salix fragilis* Crack Willow	12.0	1	30	N 3.0 E 4.0 S 5.0 W 3.0	5.0	5.0	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Epicormic growth - Crown. Leaning trunk - Minor.	40.7	3.6	40+	C	1
T1930	1	*Salix fragilis* Crack Willow	10.0	1	40	N 3.0 E 7.0 S 3.0 W 1.0	5.0	4.0	Early Mature	Good	Access to inspect base - Not possible. Arboricultural work - Historic. Base / stems obscured - Vegetation. Epicormic growth - Crown. Leaning trunk - Major.	72.4	4.8	40+	C	1
G1931	7	*Salix fragilis* Crack Willow	14.0	2	56	N 5.0 E 5.0 S 5.0 W 5.0	3.0	4.0	Early Mature	Good	Competition - Adjacent trees. Leaning trunk - Minor.	144.8	6.8	40+	B	1
T1932	1	*Fraxinus excelsior* Ash	15.0	12	83	N 7.0 E 7.0 S 7.0 W 7.0	1.0	2.0	Semi Mature	Good	Coppice stool - Coppice origin / Mature stems.	312.7	10.0	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1933	50 10 10	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Salix cinerea* Grey Sallow	6.0	5	11	N E S W 3.0 1.0 1.0 1.0	0.0	0.0	Mature	Good	Hedgerow - Maintained.	5.7	1.3	40+	B	2
H1934	30	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	15	N E S W 2.0 2.0 2.0 3.0	0.0	0.0	Mature	Good	Hedgerow - Neglected / overgrown.	10.2	1.8	40+	B	2
H1935	10	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	20	N E S W 2.0 3.0 2.0 3.0	0.0	0.0	Mature	Good	Hedgerow - Layed. Hedgerow - Neglected / overgrown.	18.1	2.4	40+	B	2
H1936	5 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Salix fragilis* Crack Willow	4.0	1	20	N E S W 2.0 3.0 2.0 3.0	0.0	0.0	Mature	Good	Hedgerow - Layed. Hedgerow - Neglected / overgrown.	18.1	2.4	40+	B	2
T1937	1	*Fraxinus excelsior* Ash	12.0	1	35	N E S W 5.0 5.0 5.0 5.0	3.0	4.0	Semi Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Structure. Base / stems obscured - Vegetation. Deadwood - Minor. Decay / structural defect - Localised. Decay / structural defect - Bole. Epicormic growth - Crown. Reaction wood / Adaptive growth - Stem / stems. Chalara (ash dieback) present. Minor symptoms.	55.4	4.2	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1938	1	*Quercus robur* English Oak	16.0	1	95	N E S W 13.0 12.0 13.0 11.0	4.0	3.0	Mature	Good	Buttresses / buttress roots - Major adaptive growth / strong development. Deadwood - Minor. Form - Spreading crown. Shedding limb / limbs - Historic.	408.3	11.4	40+	A	1
T1939	1	*Fraxinus excelsior* Ash	9.0	1	105	NW NE SE SW 2.0 2.0 4.0 2.0	4.0	6.0	Ancient or Veteran	Good	Decay / structural defect in crown limb / limbs - Open cavity / cavities. Deadwood - Major. Hollow trunk - Open cavity. Topped.	498.8	12.6	20-40	B	3
T1940	1	*Fraxinus excelsior* Ash	9.0	1	80	NW NE SE SW 4.0 4.0 4.0 4.0	4.0	6.0	Mature	Good	Arboricultural work - Recent. Decay / structural defect in crown limb / limbs - Open cavity / cavities. Epicormic growth - Crown. Topped.	289.5	9.6	20-40	B	3
H1941	50 5 2 1 1	*Prunus insititia* Damson/Bullace *Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel *Crataegus laevigata* Midland Hawthorn *Crataegus monogyna* Common Hawthorn/Quick/May	6.0	1	7	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Mature	Good	Hedgerow - Neglected / overgrown.	2.2	0.8	40+	B	2 3
T1942	1	*Quercus robur* English Oak	9.0	2	49	N E S W 6.0 4.0 6.0 4.0	0.0	1.0	Semi Mature	Good	Form - Spreading crown.	110.8	5.9	40+	B	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1943	11 2	*Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash	5.0	3	20	N E S W 2.0 2.0 2.0 2.0	0.0	0.5	Early Mature	Good	Hedgerow - Neglected / overgrown.	19.5	2.5	40+	C	2
T1944	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	2	16	N E S W 3.0 3.0 2.0 1.0	0.0	1.0	Early Mature	Good	Epicormic growth - Bole / principal stems. Form - Low canopy.	13.0	2.0	40+	C	1
T1945	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	2	17	N E S W 2.0 2.0 2.0 2.0	0.0	1.0	Semi Mature	Good	Dense crown. Form - Low canopy.	13.1	2.0	40+	C	1
T1946	1	*Acer pseudoplatanus* Sycamore	12.0	9	60	N E S W 4.0 4.0 4.0 4.0	3.0	3.0	Early Mature	Good	Growing on North Bank of ditch.	162.9	7.2	40+	C	1
T1947	1	*Fraxinus excelsior* Ash	18.0	2	60	N E S W 9.0 9.0 6.0 8.0	3.0	3.0	Early Mature	Fair	Die-back - Throughout crown. Ash dieback - moderate symptoms. Growing on North Bank of ditch.	164.0	7.2	10-20	C	1
T1948	1	*Salix caprea* Goat Willow/Great Sallow	7.0	5	55	N E S W 1.0 8.0 3.0 0.5	0.0	0.0	Early Mature	Good		141.4	6.7	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1949	8 7 6 1	*Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash	7.0	1	20	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Mature	Good	Hedgerow - Neglected / overgrown.	18.1	2.4	40+	C	2
T1950	1	*Quercus robur* English Oak	11.0	4	97	N 7.0 E 6.0 S 7.0 W 7.0	3.0	2.0	Mature	Good	Growing on South bank of ditch.	426.6	11.7	40+	B	1 2
T1951	1	*Fraxinus excelsior* Ash	11.0	6	73	N 7.0 E 7.0 S 7.0 W 7.0	3.0	2.0	Mature	Good	Coppice stool - Coppice origin / Mature stems. Growing on South	244.3	8.8	20-40	B	1 3
T1952	1	*Fraxinus excelsior* Ash	11.0	3	64	N 7.0 E 6.0 S 7.0 W 3.0	3.0	5.0	Mature	Good	Coppice stool - Coppice origin / Mature stems. Growing on South bank of ditch. Ash dieback minor symptoms.	185.5	7.7	20-40	C	1 3
T1953	1	*Fraxinus excelsior* Ash	11.0	5	55	N 4.0 E 2.0 S 3.0 W 6.0	3.0	5.0	Mature	Fair	Coppice stool - Coppice origin / Mature stems. Growing on South bank of ditch. Ash dieback moderate symptoms.	141.4	6.7	10-20	C	1
T1954	1	*Fraxinus excelsior* Ash	11.0	2	53	N 3.0 E 3.0 S 3.0 W 6.0	5.0	5.0	Mature	Fair	Coppice stool - Coppice origin / Mature stems. Growing on South bank of ditch. Ash dieback minor symptoms.	131.0	6.5	20-40	C	1
T1955	1	*Salix caprea* Goat Willow/Great Sallow	9.0	12	103	N 5.0 E 9.0 S 3.0 W 9.0	0.0	1.0	Mature	Good	One stem has failed. Flailed to South. Growing on South bank of ditch.	488.6	12.5	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1956	7 6 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Prunus spinosa* Blackthorn/Sloe	5.0	1	20	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Mature	Fair	Hedgerow - Neglected / overgrown. **Fell - Ground level.** Remove a 13.5-m span. To facilitate development.	18.1	2.4	40+	C	2
G1957	80 10 10 3	*Quercus robur* English Oak *Crataegus monogyna* Common Hawthorn/Quick/May *Viburnum opulus* Guelder Rose *Salix cinerea* Grey Sallow	15.0	1	49	N 3.0 E 9.0 S 3.0 W 6.0	4.0	5.0	Early Mature	Good	Branch - Broken. Branch - Suspended. Deadwood - Major. Deadwood - Minor. Epicormic growth - Bole / principal stems. Oak shelter belt on a bank with a notable herbaceous layer and scattered understory - Hyacinthoides non-scripta, Lonicera periclymenum, Ulex europaeus, Rubus fruticosus and Rosa arvensis. As far as I could see the northern part of group has Pteridium aquilinum only. Edges of the strip have a scattering of understory. Meles meles sett within this strip. Some lower branches broken, presumably from farm machinery.	108.6	5.9	40+	B	2 3
H1958	3	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	2	21	N 1.0 E 3.0 S 1.0 W 3.0	0.0	0.0	Mature	Good	Hedgerow - Maintained.	20.4	2.5	40+	C	2
T1959	1	*Quercus robur* English Oak	10.0	1	53	N 2.0 E 3.0 S 2.0 W 6.0	1.0	0.5	Early Mature	Good	Arboricultural work - Historic. Form - Low canopy.	127.1	6.4	40+	B	1
T1960	1	*Crataegus monogyna* Common Hawthorn/Quick/May	10.0	2	42	N 2.0 E 3.0 S 2.0 W 2.0	0.0	0.0	Mature	Good	Dense crown. Epicormic growth - Bole / principal stems.	82.6	5.1	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1961	1	*Quercus robur* English Oak	9.0	1	60	N E S W 3.0 7.0 3.0 5.0	4.0	4.0	Mature	Fair	Decay / structural defect in crown limb / limbs - Major. Decay / structural defect in crown limb / limbs - Open cavity / cavities. Deadwood - Major. Decay / structural defect - Bole. Epicormic growth - Crown. Reaction wood / Adaptive growth - Stem / stems. Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Canopy is made up of epicormic only. Tree is located in ditch surrounded by nettles.	162.9	7.2	10-20	C	1
H1962	7	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	2	18	N E S W 1.0 3.0 1.0 3.0	0.0	0.0	Mature	Good	Hedgerow - Maintained.	14.7	2.2	40+	C	2
T1963	1	*Crataegus monogyna* Common Hawthorn/Quick/May	7.0	1	25	N E S W 2.0 2.0 2.0 3.0	1.0	1.0	Mature	Fair	Deadwood - Minor. Decay / structural defect - Extensive. Decay / structural defect - Major. Decay / structural defect - Open cavity / cavities. Epicormic growth - Crown. Epicormic growth - Bole / principal stems. Tree is in the ditch surrounded by nettles.	28.3	3.0	10-20	C	1
T1964	1	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	2	28	N E S W 1.0 4.0 1.0 4.0	0.0	1.0	Mature	Good	Hedgerow - Maintained.	36.2	3.4	10-20	C	1
T1965	1	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	25	N E S W 1.0 4.0 1.0 4.0	0.0	1.0	Mature	Good	Hedgerow - Maintained.	28.3	3.0	10-20	C	1
T1966	1	*Populus x canadensis* Hybrid Black Poplars	25.0	1	88	NW NE SE SW 8.0 8.0 10.0 8.0	3.0	5.0	Mature	Good	Epicormic growth - Base / bole / principal stems.	350.3	10.6	40+	B	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1967	30	*Crataegus monogyna* Common Hawthorn/Quick/May	1.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
H1968	100	*Acer campestre* Field Maple	1.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. **Reduce lateral limb / limbs.** Prune northern side back by 1-2 m. To facilitate development.	4.5	1.2	40+	C	2
T1969	1	*Populus x canadensis* Hybrid Black Poplars	25.0	1	71	NW NE SE SW 6.0 6.0 6.0 6.0	3.0	4.0	Mature	Good	Epicormic growth - Base / bole / principal stems.	228.0	8.5	40+	B	1 2
T1970	1	*Populus x canadensis* Hybrid Black Poplars	20.0	1	29	NW NE SE SW 3.0 3.0 3.0 3.0	2.0	3.0	Semi Mature	Good	Epicormic growth - Base / bole / principal stems.	38.0	3.5	40+	C	1 2
T1971	1	*Populus x canadensis* Hybrid Black Poplars	25.0	1	78	NW NE SE SW 7.0 7.0 7.0 7.0	3.0	5.0	Mature	Good	Epicormic growth - Base / bole / principal stems.	275.2	9.4	40+	B	1 2
G1972	3 1	*Quercus robur* English Oak *Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	3	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Young	Good	Natural regeneration.	0.4	0.4	20-40	C	1
T1973	1	*Populus x canadensis* Hybrid Black Poplars	25.0	1	103	NW NE SE SW 10.0 10.0 10.0 10.0	2.0	3.0	Mature	Good	Epicormic growth - Base / bole / principal stems.	479.9	12.4	40+	B	1 2
T1974	1	*Acer campestre* Field Maple	6.0	2	21	N E S W 1.5 1.5 1.5 1.5	3.0	2.0	Early Mature	Good	**Fell - Ground level.** - To facilitate development.	20.4	2.5	40+	C	1
T1975	1	*Acer campestre* Field Maple	8.0	1	52	NW NE SE SW 2.0 3.0 2.0 2.0	2.0	2.0	Early Mature	Good		122.3	6.2	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1976	1	*Acer campestre* Field Maple	6.0	1	28	NW 2.0 NE 2.0 SE 2.0 SW 2.0	2.0	2.0	Early Mature	Good		35.5	3.4	40+	C	1
T1977	1	*Acer campestre* Field Maple	6.0	1	34	NW 2.0 NE 2.0 SE 2.0 SW 2.0	2.0	1.0	Early Mature	Good		52.3	4.1	40+	C	1
H1978	50 20 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple *Swida sanguinea* Common Dogwood	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** Remove a 25-m span. To facilitate development.	4.5	1.2	40+	C	2
T1979	1	*Fraxinus excelsior* Ash	14.0	1	35	NW 3.0 NE 3.0 SE 3.0 SW 2.0	3.0	5.0	Early Mature	Fair	Base / stems obscured - Vegetation. Chalara (ash dieback) present. Moderate symptoms. Growing on north bank of ditch.	55.4	4.2	10-20	C	1
T1980	1	*Fraxinus excelsior* Ash	14.0	1	45	NW 6.0 NE 4.0 SE 4.0 SW 3.0	3.0	3.0	Early Mature	Fair	Base / stems obscured - Vegetation. Chalara (ash dieback) present. Moderate symptoms. Growing on north bank of ditch.	91.6	5.4	10-20	C	1
G1981	5 3 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Acer pseudoplatanus* Sycamore	7.0	6	29	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Early Mature	Good	Multi-stemmed. Chalara (ash dieback) present. Moderate symptoms. Measurements represent average for larger trees in group.	39.1	3.5	40+	C	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1982	4	*Fraxinus excelsior* Ash	10.0	6	48	N 5.0 E 5.0 S 5.0 W 5.0	1.0	1.0	Early Mature	Fair	Multi-stemmed. Chalara (ash dieback) present. Moderate symptoms.	108.6	5.9	10-20	C	1
G1983	2	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	5	11	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Semi Mature	Good		5.7	1.3	40+	C	1
G1984			2.0	5	11	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Semi Mature	Good		5.7	1.3	40+	C	1
T1985	1	*Populus x canadensis* Hybrid Black Poplars	25.0	1	63	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Good	Woodland wedge specimen plotted to establish RPA for woodland plantation.	179.6	7.6	40+	B	1 2
T1986	1	*Populus x canadensis* Hybrid Black Poplars	25.0	1	65	N 5.0 E 5.0 S 5.0 W 5.0	3.0	3.0	Early Mature	Good	Woodland wedge specimen plotted to establish RPA for woodland plantation.	191.1	7.8	40+	B	1 2
H1987	7 5 5 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Acer campestre* Field Maple *Fraxinus excelsior* Ash	4.0	1	10	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Semi Mature	Good	Hedgerow - Neglected / overgrown. Hedge remnant.	4.5	1.2	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H1988	10 10 10 5	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Sambucus nigra* Elder	4.0	1	25	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Mature	Good	Hedgerow - Neglected / overgrown.	28.3	3.0	40+	C	2
T1989	1	*Sambucus nigra* Elder	3.0	1	10	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Semi Mature	Fair	Hedge remnant.	4.5	1.2	40+	C	2
H1990	3 3 2 1 1 1	*Fraxinus excelsior* Ash *Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder *Ribes rubrum* Redcurrant *Quercus robur* English Oak	4.0	1	35	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Mature	Good	Hedgerow - Neglected / overgrown.	55.4	4.2	40+	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T1991	1	*Corylus avellana* Common Hazel	6.0	25	25	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Early Mature	Fair	Coppice stool - Regrown.	28.3	3.0	40+	C	1
T1992	1	*Quercus robur* English Oak	15.0	1	104	NW NE SE SW 8.0 8.0 9.0 7.0	0.5	0.5	Mature	Good	Epicormic growth - Bole / principal stems.	489.3	12.5	40+	A	1
G1993	9 2	*Corylus avellana* Common Hazel *Quercus robur* English Oak	6.0	20	8	NW NE SE SW 2.0 2.0 2.0 2.0	0.0	0.0	Semi Mature	Fair	**Fell - Ground level.** To facilitate development.	3.6	1.1	40+	C	2
G1994	14 1	*Quercus robur* English Oak *Fraxinus excelsior* Ash	12.0	3	51	NW NE SE SW 4.0 4.0 4.0 4.0	0.0	1.0	Early Mature	Good	Coppice stool - Coppice origin / Mature stems. Growing on south bank of ditch.	122.1	6.2	40+	B	2
H1995	10	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	1	5	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Semi Mature	Good	Hedgerow - Neglected / overgrown. Some recently planted specimens.	1.1	0.6	40+	C	2
G1996	10 3 2	*Crataegus monogyna* Common Hawthorn/Quick/May *Quercus robur* English Oak *Alnus glutinosa* Common Alder	12.0	1	58	NW NE SE SW 4.0 6.0 4.0 4.0	1.0	0.5	Early Mature	Good	Infill hawthorn planting.	152.2	7.0	40+	B	2
H1997	5	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	5	17	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown. Recently planted.	14.5	2.1	40+	C	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G1998	2 2 2 1	*Acer campestre* Field Maple *Alnus glutinosa* Common Alder *Quercus robur* English Oak *Fraxinus excelsior* Ash	11.0	5	44	NW 4.0 NE 6.0 SE 4.0 SW 4.0	2.0	0.5	Early Mature	Good	Understorey of hawthorn, elder, blackthorn and field maple.	90.5	5.4	40+	B	2
G1999	15 10	*Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May	3.0	5	22	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. Occasional grown out specimens.	22.6	2.7	40+	C	2
T2000	1	*Alnus glutinosa* Common Alder	14.0	6	85	NW 5.0 NE 5.0 SE 4.0 SW 5.0	3.0	2.5	Early Mature	Good	Decay / structural defect - Localised. Decay / structural defect - Bole. Root damage - Mechanical.	332.5	10.3	40+	B	1 2
T2001	1	*Alnus glutinosa* Common Alder	14.0	6	85	NW 3.0 NE 5.0 SE 5.0 SW 5.0	3.0	3.0	Early Mature	Good	Decay / structural defect - Localised. Decay / structural defect - Bole. Root damage - Mechanical.	332.5	10.3	40+	B	1 2
H2002	100	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	8	N 1.0 E 1.0 S 1.0 W 1.0	0.5	0.5	Semi Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** Remove a 122-m span. To facilitate development.	2.9	1.0	40+	C	2
H2003	15	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	5	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained.	1.1	0.6	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2004	15	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	5	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Neglected / overgrown.	1.1	0.6	40+	C	1
T2005	1	*Cerasus avium* Wild Cherry	9.0	1	40	N 5.0 E 5.0 S 5.0 W 5.0	1.5	1.5	Early Mature	Good	**Fell - Ground level.** To facilitate development.	72.4	4.8	40+	C	1
T2006	1	*Cerasus avium* Wild Cherry	9.0	1	30	N 5.0 E 3.0 S 4.0 W 4.0	1.5	1.5	Early Mature	Good	**Fell - Ground level.** To facilitate development.	40.7	3.6	40+	C	1
T2007	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	2	35	N 2.0 E 3.0 S 2.0 W 2.0	0.0	0.0	Mature	Fair	Growing on West bank of ditch.	56.5	4.2	40+	C	1
T2008	1	*Fraxinus excelsior* Ash	14.0	4	59	N 7.0 E 7.0 S 5.0 W 6.0	0.5	1.0	Early Mature	Poor	Coppice stool - Regrown. Die-back - Throughout crown. Chalara (ash dieback) present. Moderate symptoms. Growing on East bank of ditch.	162.2	7.2	10-20	C	1
T2009	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	1	25	N 2.0 E 3.0 S 2.0 W 2.0	0.0	0.0	Early Mature	Fair	Base / stems obscured - Vegetation. Growing on West bank of ditch.	28.3	3.0	40+	C	1
T2010	1	*Cerasus avium* Wild Cherry	9.0	1	35	N 4.0 E 4.0 S 4.0 W 4.0	1.5	1.0	Early Mature	Good	Growing on west bank of ditch.	55.4	4.2	40+	C	1
T2011	1	*Salix fragilis* Crack Willow	9.0	3	75	N 5.0 E 8.0 S 5.0 W 5.0	0.5	1.0	Early Mature	Poor	Branch - Broken. Coppice stool - Regrown. Die-back - Throughout crown. Fallen tree / trees - Partial collapse. Growing on east bank of ditch.	259.0	9.1	10-20	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G2012	4 2 2	*Corylus avellana* Common Hazel *Salix fragilis* Crack Willow *Crataegus monogyna* Common Hawthorn/Quick/May	8.0	20	13	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Early Mature	Fair	Coppice stool - Regrown.	8.1	1.6	20-40	C	1
T2013	1	*Quercus robur* English Oak	10.0	1	77	N E S W 4.0 4.0 8.0 8.0	0.5	2.0	Early Mature	Good	Branch - Broken. Deadwood - Major. Ivy or climbing plant.	268.2	9.2	40+	B	1
H2014	15	*Corylus avellana* Common Hazel	2.5	6	12	NW NE SE SW 0.5 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Growing on West bank of ditch.	6.8	1.5	40+	C	2
H2015	40 15	*Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel	2.5	6	12	NW NE SE SW 0.5 2.0 2.0 2.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Growing on West bank of ditch.	6.8	1.5	40+	C	2
T2016	1	*Acer campestre* Field Maple	4.0	2	43	N E S W 3.0 3.0 2.0 0.5	0.5	0.0	Early Mature	Good	Managed as part of hedge.	83.7	5.2	40+	C	1
T2017	1	*Quercus robur* English Oak	14.0	1	86	N E S W 6.0 6.0 6.0 6.0	4.0	3.0	Early Mature	Good	Deadwood - Minor. Epicormic growth - Bole / principal stems. **Fell - Ground level.** To facilitate development.	334.6	10.3	40+	B	1
T2018	1	*Acer campestre* Field Maple	2.5	3	32	N E S W 3.0 2.0 3.0 0.5	0.5	0.0	Early Mature	Good	Managed as part of hedge.	46.4	3.8	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2019	1	*Acer campestre* Field Maple	8.0	5	44	N E S W 8.0 4.0 8.0 2.0	0.0	0.0	Early Mature	Good	Epicormic has formed a hedge. **Fell - Ground level.** To facilitate development.	90.5	5.4	40+	C	1
H2020	5 3 3	*Salix sp.* Willow sp. *Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel	2.5	6	12	NW NE SE SW 0.5 1.0 2.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Growing on West bank of ditch. **Fell - Ground level.** To facilitate development.	6.8	1.5	40+	C	2
T2021	1	*Fraxinus excelsior* Ash	14.0	4	73	N E S W 4.0 4.0 4.0 4.0	1.0	2.0	Early Mature	Fair	Coppice stool - Coppice origin / Mature stems. Chalara (ash dieback) present. Minor symptoms.	242.0	8.8	10-20	C	1
H2022	2	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	15	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Early Mature	Good	Hedge remnant.	10.2	1.8	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G2023	15 7 5 3 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash *Salix caprea* Goat Willow/Great Sallow *Acer campestre* Field Maple *Quercus robur* English Oak	11.0	3	60	N 4.0 E 4.0 S 4.0 W 4.0	0.0	2.5	Early Mature	Good	Measurements represent average for larger trees in group. Chalara (ash dieback) present. Minor symptoms. Grown out hedge. **Fell - Ground level.** Remove c. 5-6 trees/a 25-m span from western third. To facilitate development.	166.3	7.3	40+	B	2
H2024	30 10	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown.	4.5	1.2	40+	C	2
H2025	10 3 3 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Ribes rubrum* Redcurrant *Sambucus nigra* Elder	1.5	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown. Hedge remnant. **Fell - Ground level.** Remove a 27-m span. To facilitate development.	4.5	1.2	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2026	20 3 2 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash *Acer campestre* Field Maple *Salix caprea* Goat Willow/Great Sallow	4.0	5	22	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown. Multi-stemmed.	22.6	2.7	40+	C	2
T2027	1	*Quercus robur* English Oak	9.0	1	30	N 4.0 E 4.0 S 4.0 W 4.0	1.0	1.0	Semi Mature	Good	Good long-term potential.	40.7	3.6	40+	C	1
G2028	8 4	*Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash	9.0	1	30	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.5	Early Mature	Poor	Die-back - Throughout crown. Chalara (ash dieback) present. Moderate symptoms.	40.7	3.6	10-20	C	2
T2029	1	*Fraxinus excelsior* Ash	12.0	1	25	N 3.0 E 3.0 S 3.0 W 3.0	1.0	1.0	Semi Mature	Poor	Die-back - Throughout crown. Chalara (ash dieback) present. Severe symptoms.			0-10	U	
T2030	1	*Fraxinus excelsior* Ash	12.0	1	15	N 2.0 E 2.0 S 2.0 W 2.0	1.0	1.0	Semi Mature	Poor	Die-back - Throughout crown. Chalara (ash dieback) present. Moderate symptoms.	10.2	1.8	10-20	C	1
H2031	8	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	10	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown. Gappy.	4.5	1.2	20-40	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2032	1	*Quercus robur* English Oak	14.0	1	90	N E S W 9.0 9.0 9.0 8.0	2.0	2.0	Mature	Good		366.4	10.8	40+	A	1
H2033	10	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	10	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown.	4.5	1.2	40+	C	2
G2034	10 3	*Crataegus monogyna* Common Hawthorn/Quick/May *Quercus robur* English Oak	8.0	1	20	N E S W 3.0 3.0 3.0 3.0	0.5	0.0	Semi Mature	Good	Growing on West bank of ditch. Only partial access.	18.1	2.4	40+	C	2
H2035	100 10 5 1 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Swida sanguinea* Common Dogwood *Salix caprea* Goat Willow/Great Sallow *Cerasus avium* Wild Cherry	2.5	1	7	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Young	Good	Hedgerow - Maintained. On neighbouring land (garden).	2.2	0.8	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G2036	4 2 1 1	*Salix caprea* Goat Willow/Great Sallow *Sambucus sp.* Elder sp. *Ulmus sp.* Elm sp. *Betula pendula* Silver Birch	8.0	5	55	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Early Mature	Good	Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems. Multi-stemmed. Wall to east. Measurements represent average for larger trees in group.	141.4	6.7	40+	C	1 2
T2037	1	*Fraxinus excelsior* Ash	12.0	1	35	NW NE SE SW 3.0 6.0 4.0 5.0	5.0	2.0	Early Mature	Fair	Base / stems obscured - Vegetation. Die-back - Throughout crown. Chalara (ash dieback) present. Moderate symptoms. Mature epicormic stems from base. **Fell - Ground level.** To facilitate development.	55.4	4.2	10-20	C	1
T2038	1	*Fraxinus excelsior* Ash	13.0	1	70	NW NE SE SW 6.0 7.0 5.0 5.0	0.0	2.0	Mature	Fair	Base / stems obscured - Vegetation. Die-back - Throughout crown. Deadwood - Minor. Ivy or climbing plant. Shedding limb / limbs - Major. Shedding limb / limbs - Recent. **Fell - Ground level.** To facilitate development.	221.7	8.4	10-20	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2039	25 10 2 2	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Malus sylvestris* Wild Crab *Acer campestre* Field Maple	4.0	1	10	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown. **Fell - Ground level.** To facilitate development.	4.5	1.2	40+	C	2
H2040	25	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.5	0.5	Semi Mature	Fair	Hedgerow - Maintained. Gappy.	4.5	1.2	40+	C	2
H2041	3	*Sambucus nigra* Elder	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedge remnant. **Fell - Ground level.** To facilitate development.	4.5	1.2	40+	C	2
H2042	20 2	*Crataegus monogyna* Common Hawthorn/Quick/May *Salix caprea* Goat Willow/Great Sallow	2.5	1	25	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown.	28.3	3.0	40+	C	2
T2043	1	*Salix caprea* Goat Willow/Great Sallow	2.0	2	42	N 1.0 E 3.0 S 1.0 W 2.0	0.5	0.5	Early Mature	Fair	Topped and flailed.	81.4	5.1	40+	C	2
T2044	1	*Salix caprea* Goat Willow/Great Sallow	5.0	5	78	N 2.0 E 4.0 S 2.0 W 3.0	0.5	0.5	Early Mature	Fair	Topped and flailed.	277.1	9.4	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G2045	2	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Hedge remnant.			0-10	U	
T2046	1	*Salix caprea* Goat Willow/Great Sallow	4.0	2	56	N 2.0 E 2.0 S 2.0 W 2.0	0.5	0.5	Early Mature	Fair	Topped and flailed.	144.8	6.8	40+	C	2
T2047	1	*Salix caprea* Goat Willow/Great Sallow	9.0	3	75	N 4.0 E 10.0 S 3.0 W 6.0	0.5	0.5	Mature	Fair	Growing on bank of ditch.	255.6	9.0	40+	C	2
H2048	8	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	25	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown. Hedge remnant.	28.3	3.0	40+	C	2
T2049	1	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	3	37	N 4.0 E 1.0 S 3.0 W 1.5	0.5	0.5	Early Mature	Good	Hedge remnant. Flailed.	64.5	4.5	40+	C	1
T2050	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	25	N 2.0 E 0.5 S 2.0 W 0.5	0.5	0.5	Early Mature	Good	Hedge remnant. Flailed.	28.3	3.0	40+	C	1
T2051	1	*Fraxinus excelsior* Ash	11.0	2	60	N 8.0 E 4.0 S 6.0 W 3.0	0.0	1.0	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Flailed. Growing on bank of ditch. Chalara (ash dieback) present. Minor symptoms.	167.7	7.3	10-20	C	1
T2052	1	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	6	29	N 2.0 E 0.5 S 2.0 W 0.5	0.5	0.5	Early Mature	Good	Multi-stemmed. Hedge remnant. Flailed.	39.1	3.5	40+	C	1
T2053	1	*Salix alba* White Willow	10.0	3	58	N 7.0 E 8.0 S 4.0 W 4.0	3.0	1.0	Early Mature	Good	Epicormic growth - Bole / principal stems. Low crown break.	153.8	7.0	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2054	5 2	*Sambucus nigra* Elder *Crataegus monogyna* Common Hawthorn/Quick/May	2.0	5	22	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Mature	Fair	Hedgerow - Maintained. Hedge remnant.	22.6	2.7	40+	C	2
H2055	2	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	5	26	N E S W 2.0 1.0 2.0 1.0	0.0	0.0	Early Mature	Fair	Hedge remnant. Flailed.	32.6	3.2	40+	C	2
T2056	1	*Salix alba* White Willow	8.0	1	70	N E S W 4.0 1.0 3.0 2.0	0.0	2.0	Mature	Poor	Epicormic growth - Base / bole / principal stems. Main stem has snapped at c. 4 m.	221.7	8.4	10-20	C	1
T2057	1	*Salix alba* White Willow	16.0	3	73	N E S W 3.0 3.0 4.0 3.0	3.5	3.0	Early Mature	Good	Decay / structural defect - Base. Epicormic growth - Bole / principal stems. Shedding limb / limbs - Major. Shedding limb / limbs - Recent. Growing on West bank of ditch. Stem damaged by ditch scouring. One stem has failed.	245.4	8.8	40+	C	1
T2058	1	*Salix alba* White Willow	13.0	2	78	N E S W 4.0 6.0 3.0 7.0	3.5	3.0	Mature	Good	Base / stems obscured - Vegetation. Decay / structural defect - Base. Epicormic growth - Bole / principal stems. Fungal fruiting body - structural decay suspected. Shedding limb / limbs - Major. Shedding limb / limbs - Recent. Low crown break. Growing on West bank of ditch. Stem damaged by ditch scouring. Phellinus Ignatius bracket at base.	276.0	9.4	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2059	1	*Salix alba* White Willow	14.0	2	78	N E S W 6.0 7.0 4.0 7.0	3.5	3.0	Mature	Good	Base / stems obscured - Vegetation. Decay / structural defect - Base. Epicormic growth - Bole / principal stems. Shedding limb / limbs - Major. Shedding limb / limbs - Recent. Growing on west bank of ditch. Stem damaged by ditch scouring.	276.0	9.4	40+	C	1
T2060	1	*Salix alba* White Willow	9.0	1	65	N E S W 4.0 3.0 3.0 5.0	0.0	3.0	Mature	Good	Base / stems obscured - Vegetation. Decay / structural defect - Base. Epicormic growth - Bole / principal stems. Shedding limb / limbs - Major. Shedding limb / limbs - Recent. Growing on east bank of ditch. Stem damaged by ditch scouring. Topped.	191.1	7.8	40+	C	1
H2061	10 1 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Salix alba* White Willow *Corylus avellana* Common Hazel	3.0	1	15	N E S W 1.5 1.5 1.5 1.5	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown. Growing on west bank of ditch.	10.2	1.8	40+	C	2
T2062	1	*Crataegus monogyna* Common Hawthorn/Quick/May	7.0	1	20	N E S W 1.5 0.5 1.5 1.0		0.5	Mature	Fair	Hedge remnant. Flailed.	18.1	2.4	40+	C	1
T2063	1	*Alnus glutinosa* Common Alder	13.0	1	45	N E S W 6.0 6.0 6.0 6.0	4.0	4.0	Early Mature	Good	Growing on West bank of ditch.	91.6	5.4	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2064	20 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Quercus robur* English Oak	5.0	1	20	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Mature	Fair	Die-back - Throughout crown. Growing on west bank of ditch.	18.1	2.4	20-40	C	2
H2065	30 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder	1.5	1	15	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	10.2	1.8	40+	C	2
H2066	30 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder	2.5	5	22	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Early Mature	Good		22.6	2.7	40+	C	2
H2067	10	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	5	22	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Early Mature	Good		22.6	2.7	40+	C	2
H2068	30	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown. Hedge remnant. **Fell - Ground level.** Remove a 51-m span. To facilitate development.	4.5	1.2	40+	C	2
G2069	4	*Fraxinus excelsior* Ash	8.0	1	25	N 2.0 E 2.0 S 2.0 W 2.0	1.0	1.0	Semi Mature	Dead	Dead tree / trees.			0-10	U	
T2070	1	*Sambucus nigra* Elder	4.0	5	22	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Semi Mature	Fair	No access, surveyed from afar.	22.6	2.7	10-20	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2071	1	*Salix caprea* Goat Willow/Great Sallow	6.0	1	25	N 2.0 E 2.0 S 2.0 W 2.0	1.0	1.0	Semi Mature	Poor	Decline - Evident / observed. No access, surveyed from afar.			0-10	U	
H2072	40	*Crataegus monogyna* Common Hawthorn/Quick/May	1.5	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. No access; surveyed from afar. **Fell - Ground level.** Remove a 25-m span. To facilitate development.	4.5	1.2	40+	C	2
H2073	15	*Crataegus monogyna* Common Hawthorn/Quick/May	1.5	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Poor	Hedgerow - Maintained. No access; surveyed from afar. Very gappy. **Fell - Ground level.** Remove a 25-m span. To facilitate development.	4.5	1.2	40+	C	2
H2074	50 2	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel	1.5	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. No access; surveyed from afar. **Fell - Ground level.** Remove a 25-m span. To facilitate development.	4.5	1.2	40+	C	2
T2075	1	*Fraxinus excelsior* Ash	13.0	1	33	N 4.0 E 4.0 S 4.0 W 4.0	3.0	2.0	Early Mature	Fair	Epicormic growth - Bole / principal stems. Chalara (ash dieback) present. Minor symptoms.	49.3	4.0	10-20	C	1
T2076	1	*Acer pseudoplatanus* Sycamore	13.0	2	42	N 3.0 E 3.0 S 3.0 W 3.0	0.5	1.5	Early Mature	Good	Epicormic growth - Bole / principal stems. Flailed to West.	81.4	5.1	40+	C	1
T2077	1	*Acer campestre* Field Maple	9.0	1	31	N 4.0 E 2.0 S 3.0 W 3.0	0.5	0.5	Early Mature	Good	Low crown break. Flailed to West.	43.5	3.7	40+	C	1
T2078	1	*Tilia x vulgaris* Common Lime	13.0	1	48	N 4.0 E 4.0 S 4.0 W 2.0	0.0	0.5	Early Mature	Good	Low crown break. Flailed to West.	104.2	5.8	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2079	25	*Crataegus monogyna* Common Hawthorn/Quick/May	1.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Gappy. **Fell - Ground level.** Remove a 25-m span. To facilitate development.	4.5	1.2	20-40	C	2
T2080	1	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	1	20	N E S W 2.0 2.0 2.0 2.0	0.5	0.5	Early Mature	Fair	Hedge remnant.	18.1	2.4	20-40	C	1
W2081	300 150	*Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash	15.0	1	30	N E S W 3.0 3.0 3.0 3.0	1.0	1.0	Early Mature	Fair	Plantation of predominantly Ash. Deep ditch along south Western boundary. Chalara (ash dieback) present. Minor symptoms. Future of plantation threatened by Ash dieback.	40.7	3.6	10-20	C	2
T2082	1	*Salix alba* White Willow	20.0	1	83	NW NE SE SW 5.0 5.0 7.0 5.0	8.0	8.0	Mature	Fair	Deadwood - Minor. Decay / structural defect - Localised. Decay / structural defect - Bole. Fungal fruiting body - structural decay suspected. Large fruiting body of possible Laetiporous sulphureous on wound to north. Sparse crown.	311.7	10.0	20-40	B	1 3
G2083	10	*Salix alba* White Willow	19.0	1	35	N E S W 5.0 5.0 5.0 5.0	1.0	1.5	Early Mature	Good	Multi-stemmed. Inaccessible. Some fallen stems.	55.4	4.2	40+	C	2
G2084	80 35 20	*Fraxinus excelsior* Ash *Acer pseudoplatanus* Sycamore *Crataegus monogyna* Common Hawthorn/Quick/May	12.0	1	15	N E S W 2.0 2.0 2.0 2.0	1.0	1.0	Semi Mature	Fair	Planted shelterbelt. Chalara (ash dieback) present. Moderate symptoms. Future of group threatened by Ash dieback.	10.2	1.8	10-20	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2085	80	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	1	15	N E S W 2.0 2.0 2.0 2.0	0.5	0.5	Mature	Fair	Hedgerow - Neglected / overgrown. Growing on North bank of ditch. Being shaded out by plantation. Numbers approximate.	10.2	1.8	20-40	C	2
G2086	5 1	*Fraxinus excelsior* Ash *Malus sp.* Apple sp.	3.0	1	8	N E S W 2.0 2.0 2.0 2.0	0.0	0.5	Young	Good	Natural regeneration. Growing on railway embankment	2.9	1.0	40+	C	1
T2087	1	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	5	22	N E S W 2.0 0.5 2.0 2.0	0.0	0.0	Early Mature	Good	Hedge remnant. Growing on west bank of ditch. Flailed to east.	22.6	2.7	40+	C	1
T2088	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	5	26	N E S W 2.0 1.0 2.0 1.0	0.0	0.0	Early Mature	Good	Hedge remnant. Growing on east bank of ditch. Flailed to east.	32.6	3.2	40+	C	1
T2089	1	*Quercus robur* English Oak	11.0	1	64	N E S W 6.0 8.0 6.0 7.0	3.0	2.0	Early Mature	Good	Deadwood - Major. Epicormic growth - Base / bole / principal stems. Shedding limb / limbs - Historic. Growing on east bank of ditch.	185.3	7.7	40+	B	1 2
T2090	1	*Quercus robur* English Oak	9.0	1	48	N E S W 4.0 4.0 6.0 6.0	3.0	2.5	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Suppressed crown - Major. Growing on east bank of ditch. Flailed to east.	104.2	5.8	40+	B	1 2
T2091	1	*Fraxinus excelsior* Ash	18.0	1	93	N E S W 9.0 6.0 9.0 4.0	3.0	4.0	Early Mature	Poor	Die-back - Throughout crown. Deadwood - Major. Decay / structural defect - Localised. Decay / structural defect - Bole. Chalara (ash dieback) present. Moderate symptoms. Growing on east bank of ditch.	391.3	11.2	10-20	C	1 2
T2092	1	*Quercus robur* English Oak	14.0	1	76	N E S W 9.0 7.0 9.0 8.0	4.0	2.5	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Growing on east bank of ditch. Flailed to east.	261.3	9.1	40+	B	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2093	1	*Quercus robur* English Oak	11.0	1	48	N 5.0 E 4.0 S 7.0 W 7.0	3.0	2.5	Early Mature	Good	Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Growing on east bank of ditch. Flailed to east.	104.2	5.8	40+	B	1 2
T2094	1	*Quercus robur* English Oak	14.0	1	72	N 8.0 E 7.0 S 6.0 W 9.0	5.0	2.0	Early Mature	Good	Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Shedding limb / limbs - Minor. Shedding limb / limbs - Recent. Growing on east bank of ditch. Flailed to east.	234.5	8.6	40+	B	1 2
T2095	1	*Quercus robur* English Oak	14.0	1	47	N 2.0 E 4.0 S 6.0 W 6.0	5.0	3.0	Early Mature	Good	Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Suppressed crown - Minor. Growing on east bank of ditch. Flailed to east.	99.9	5.6	40+	B	1 2
T2096	1	*Quercus robur* English Oak	14.0	1	80	N 8.0 E 8.0 S 7.0 W 8.0	5.0	4.0	Early Mature	Good	Deadwood - Minor. Epicormic growth - Bole / principal stems. Growing on west bank of ditch. Flailed to east.	289.5	9.6	40+	B	1 2
T2097	1	*Quercus robur* English Oak	14.0	1	85	N 10.0 E 8.0 S 10.0 W 8.0	5.0	4.0	Early Mature	Good	Deadwood - Minor. Epicormic growth - Bole / principal stems. Ivy or climbing plant. Inaccessible. Measurements estimated.	326.9	10.2	40+	A	1 2
T2098	1	*Quercus robur* English Oak	14.0	1	70	N 9.0 E 7.0 S 10.0 W 6.0	3.0	3.0	Early Mature	Good	Deadwood - Minor. Epicormic growth - Bole / principal stems. Growing on east bank of ditch. Flailed to east.	221.7	8.4	40+	B	1 2
T2099	1	*Quercus robur* English Oak	14.0	1	70	N 5.0 E 8.0 S 10.0 W 8.0	3.0	3.0	Early Mature	Good	Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Growing on east bank of ditch. Flailed to east.	221.7	8.4	40+	B	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2100	1	*Quercus robur* English Oak	14.0	1	70	N E S W 6.0 8.0 6.0 8.0	3.0	2.5	Early Mature	Fair	Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Growing on east bank of ditch. Flailed to east. Slightly sparse crown.	221.7	8.4	40+	B	1 2
T2101	1	*Quercus robur* English Oak	14.0	1	72	N E S W 8.0 9.0 6.0 8.0	6.0	2.0	Early Mature	Fair	Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Twin-stemmed. Growing on east bank of ditch. Flailed to east.	234.5	8.6	40+	B	1 2
T2102	1	*Quercus robur* English Oak	14.0	2	45	N E S W 2.0 8.0 6.0 7.0	5.0	1.5	Early Mature	Fair	Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Twin-stemmed. Growing on east bank of ditch. Flailed to east.	92.6	5.4	40+	B	1 2
T2103	1	*Quercus robur* English Oak	14.0	1	35	N E S W 7.0 8.0 2.0 7.0	6.0	3.0	Early Mature	Fair	Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Growing on east bank of ditch. Flailed to east.	55.4	4.2	40+	B	1 2
T2104	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	5	26	N E S W 2.0 1.5 2.5 1.0	0.0	0.5	Early Mature	Fair	Die-back - Throughout crown. Growing on west bank of ditch. Flailed to east and west. Hedge remnant.	32.6	3.2	10-20	C	1
T2105	1	*Quercus robur* English Oak	14.0	2	76	N E S W 8.0 9.0 7.0 8.0	4.0	2.5	Early Mature	Fair	Deadwood - Minor. Epicormic growth - Base / bole / principal stems. Twin-stemmed. Growing on east bank of ditch. Flailed to east and pruned to west.	263.5	9.2	40+	B	1 2
H2106	15 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder	3.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Growing on north bank of ditch. Numbers approximate.	4.5	1.2	20-40	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2107	60 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder	4.0	1	10	N E S W 1.5 1.5 1.5 1.5	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Growing on north bank of ditch. Numbers approximate.	4.5	1.2	20-40	C	2
H2108	5 4 2	*Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple	3.0	10	3	N E S W 1.0 1.5 1.5 1.5	0.0	0.0	Semi Mature	Good	Coppice stool - Regrown. Hedgerow - Neglected / overgrown. Hedge remnant. Growing on south bank of ditch.	0.5	0.4	40+	C	2
T2109	1	*Ilex aquifolium* Holly	8.0	10	31	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Semi Mature	Poor	Base / stems obscured - Vegetation. Die-back - Throughout crown.	45.2	3.8	10-20	C	1
T2110	1	*Acer campestre* Field Maple	3.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.5	Young	Good		4.5	1.2	40+	C	1
T2111	1	*Acer pseudoplatanus* Sycamore	14.0	1	50	N E S W 4.0 4.0 4.0 4.0	2.5	2.5	Early Mature	Good	Base / stems obscured - Vegetation. Woodland edge specimen. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	113.1	6.0	40+	B	2
T2112	1	*Acer pseudoplatanus* Sycamore	14.0	1	35	N E S W 2.0 4.0 3.0 1.0	2.5	2.5	Early Mature	Good	Base / stems obscured - Vegetation. Unbalanced crown - Minor. Woodland edge specimen.	55.4	4.2	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
W2113	25 3 3	*Acer pseudoplatanus* Sycamore *Fagus sylvatica* Common Beech *Fraxinus excelsior* Ash	14.0	1	35	N 4.0 E 4.0 S 4.0 W 4.0	2.5	2.5	Early Mature	Good	Edge species in plantation woodland overhanging road. Stems c. 4 m from road edge. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	55.4	4.2	40+	B	2
T2114	1	*Acer pseudoplatanus* Sycamore	8.0	1	20	N 3.0 E 3.0 S 3.0 W 3.0	2.5	2.5	Semi Mature	Good	Growing in hedge. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	18.1	2.4	40+	C	1
T2115	1	*Acer pseudoplatanus* Sycamore	8.0	1	20	N 3.0 E 3.0 S 3.0 W 3.0	2.5	2.5	Semi Mature	Good	Growing in hedge. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	18.1	2.4	40+	C	1
T2116	1	*Acer pseudoplatanus* Sycamore	8.0	1	25	N 4.0 E 4.0 S 4.0 W 4.0	2.5	2.5	Semi Mature	Good	Growing in hedge. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	28.3	3.0	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2117	50 10 5 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Quercus robur* English Oak *Sambucus nigra* Elder *Acer pseudoplatanus* Sycamore	2.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	B	2
T2118	1	*Quercus robur* English Oak	8.0	1	75	N E S W 5.0 3.0 4.0 4.0	5.0	2.0	Early Mature	Poor	Bark wound - Physical damage or vandalism. Decay / structural defect - Base. Poor past pruning. Topped. Cambial dieback on wounds.	254.5	9.0	10-20	C	1
T2119	1	*Quercus robur* English Oak	16.0	1	90	N E S W 7.0 7.0 7.0 7.0	5.0	2.5	Mature	Good	Epicormic growth - Base / bole / principal stems. Growing in hedge on verge, deep ditch to west.	366.4	10.8	40+	A	1
T2120	1	*Acer pseudoplatanus* Sycamore	8.0	1	30	N E S W 3.0 3.0 3.0 3.0	2.5	3.0	Semi Mature	Good	Growing in hedge. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	40.7	3.6	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2121	15 5 5 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash *Acer pseudoplatanus* Sycamore *other* Other	1.0	1	10	N E S W 0.5 0.5 0.5 0.5	0.0	0.0	Early Mature	Fair	Semi managed road boundary hedge. 06/10/25 Felled. Some plants have sprouted back.	4.5	1.2	20-40	C	2
T2122	1	*Fraxinus excelsior* Ash	9.0	1	28	N E S W 3.5 3.5 3.5 3.5	4.0	2.5	Semi Mature	Good	Growing in hedge. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	35.5	3.4	40+	C	1
T2123	1	*Populus x canadensis* Hybrid Black Poplars	18.0	1	20	N E S W 3.0 3.0 3.0 2.0	2.0	2.0	Semi Mature	Good		18.1	2.4	40+	C	1
T2124	1	*Tilia cordata* Small Leaved Lime	10.0	1	47	N E S W 4.0 4.0 4.0 4.0	4.0	3.0	Early Mature	Good	Growing in hedge. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	99.9	5.6	40+	B	2
T2125	1	*Tilia cordata* Small Leaved Lime	12.0	1	40	N E S W 4.0 4.0 4.0 4.0	4.0	3.0	Early Mature	Good	Growing in hedge. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	72.4	4.8	40+	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2126	1	*Fagus sylvatica* Common Beech	12.0	1	34	N 4.0 E 4.0 S 4.0 W 4.0	4.0	3.0	Early Mature	Good	Growing in hedge. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	52.3	4.1	40+	B	2
T2127	1	*Acer pseudoplatanus* Sycamore	9.0	1	38	N 5.0 E 4.0 S 5.0 W 5.0	4.0	2.5	Early Mature	Good	Growing in hedge. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	65.3	4.6	40+	B	2
T2128	1	*Tilia cordata* Small Leaved Lime	11.0	1	38	N 5.0 E 5.0 S 5.0 W 5.0	4.0	2.5	Early Mature	Good	Growing in hedge. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	65.3	4.6	40+	B	2
T2129	1	*Fagus sylvatica* Common Beech	9.0	1	27	N 3.0 E 3.0 S 3.0 W 3.0	4.0	2.5	Semi Mature	Good	Growing in hedge. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	33.0	3.2	40+	C	2
T2130	1	*Tilia cordata* Small Leaved Lime	9.0	1	40	N 3.0 E 3.0 S 3.0 W 3.0	4.0	1.5	Early Mature	Good	Fork - Weak with included bark. Growing in hedge. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	72.4	4.8	40+	B	2
T2131	1	*Tilia cordata* Small Leaved Lime	9.0	1	35	N 4.0 E 4.0 S 4.0 W 4.0	4.0	2.5	Semi Mature	Good	Growing in hedge. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	55.4	4.2	40+	C	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2132	100 20 10 10 5 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Acer pseudoplatanus* Sycamore *Sambucus nigra* Elder *Corylus avellana* Common Hazel *Quercus robur* English Oak *Fraxinus excelsior* Ash	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Older hedge gapped up. Still gappy in places.	4.5	1.2	40+	B	2
W2133	5 3 1	*Acer pseudoplatanus* Sycamore *Fraxinus excelsior* Ash *Acer campestre* Field Maple	15.0	1	30	N 6.0 E 6.0 S 6.0 W 6.0	4.0	4.0	Early Mature	Good	Woodland edge specimens. Stems c. 2 m from highway edge. Hawthorn/blackthorn hedge beneath.	40.7	3.6	40+	C	2
T2134	1	*Acer campestre* Field Maple	10.0	1	25	N 4.0 E 4.0 S 4.0 W 4.0	4.0	2.5	Early Mature	Good	Growing in hedge.	28.3	3.0	40+	B	2
T2135	1	*Quercus robur* English Oak	20.0	1	86	NW 4.0 NE 4.0 SE 5.0 SW 4.0	6.0	4.0	Mature	Poor	Die-back - Throughout crown. Deadwood - Major. Poor past pruning. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	334.6	10.3	10-20	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2136	1	*Aesculus hippocastanum* Horse Chestnut	17.0	1	102	N 6.0 E 6.0 S 6.0 W 6.0	6.0	2.5	Late Mature	Good	Decay / structural defect in crown limb / limbs - Localised. Pruning wounds - Decayed. Pruning wounds - Historic. Growing on verge. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	470.7	12.2	40+	B	1
H2137	40 30	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
H2138	100	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
H2139	60	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	B	2
T2140	1	*Ilex x altaclerensis* Highclere Holly	11.0	1	40	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Early Mature	Good	Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems. **Fell - Ground level.** To facilitate development.	72.4	4.8	40+	C	1
H2141	10	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	10	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Early Mature	Good		4.5	1.2	40+	C	2
H2142	20	*Cupressocyparis leylandii* Leyland Cypress	2.5	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Young	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2143	1	*Sambucus nigra* Elder	6.0	2	32	NW 4.0 NE 1.5 SE 2.0 SW 2.0	2.0	1.0	Mature	Fair		46.4	3.8	10-20	C	1
T2144	1	*Salix cinerea* Grey Sallow	6.0	1	40	NW 3.0 NE 3.0 SE 4.0 SW 3.0	1.0	1.0	Early Mature	Good	Leaning trunk - Major.	72.4	4.8	40+	C	1
T2145	1	*Corylus avellana* Common Hazel	7.0	20	53	NW 3.0 NE 4.0 SE 3.0 SW 3.0	0.5	0.0	Mature	Fair	Bark wound - Mammal. Coppice stool - Regrown. Stock damage to base.	130.3	6.4	20-40	C	1
W2146	25	*Pinus sylvestris* Scots Pine	19.0	1	30	N 3.0 E 3.0 S 3.0 W 3.0	9.0	9.0	Early Mature	Good	Edge of larger plantation woodland. Numbers approximate. **Fell - Ground level.** Remove c. 2-3 trees from southern end. To facilitate development.	40.7	3.6	40+	B	2
T2147	1	*Acer campestre* Field Maple	7.0	1	27	N 2.0 E 2.0 S 2.0 W 2.0	1.0	0.5	Semi Mature	Good	Low crown break.	33.0	3.2	40+	C	1
G2148	5	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	1	20	N 2.0 E 2.0 S 1.0 W 2.0	0.0	0.0	Early Mature	Good	**Fell - Ground level.** To facilitate development.	18.1	2.4	40+	C	2
T2149	1	*Populus balsamifera* Balsam Poplar	20.0	1	42	N 3.0 E 3.0 S 3.0 W 3.0	1.5	1.0	Semi Mature	Fair	Die-back - Throughout crown. One of a planted row.	79.8	5.0	20-40	C	1 2
T2150	1	*Populus balsamifera* Balsam Poplar	20.0	1	40	N 3.0 E 3.0 S 3.0 W 3.0	1.5	1.0	Semi Mature	Fair	Die-back - Throughout crown. One of a planted row.	72.4	4.8	20-40	C	1 2
H2151	20 2	*Corylus avellana* Common Hazel *Crataegus monogyna* Common Hawthorn/Quick/May	2.5	10	15	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown. Hedge remnant.	11.3	1.9	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2152	1	*Quercus robur* English Oak	16.0	1	102	NW 11.0 NE 10.0 SE 11.0 SW 11.0	3.0	3.0	Early Mature	Good		470.7	12.2	40+	A	1
H2153	7 5 4	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Sambucus nigra* Elder	3.0	10	15	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Early Mature	Fair	Hedge remnant. **Fell - Ground level.** Remove a 12-m span. To facilitate development.	11.3	1.9	40+	C	2
T2154	1	*Corylus avellana* Common Hazel	6.0	30	27	N 4.0 E 4.0 S 4.0 W 4.0	0.0	0.0	Early Mature	Good	Coppice stool - Regrown.	33.9	3.3	40+	C	1
T2155	1	*Quercus robur* English Oak	15.0	1	65	N 6.0 E 6.0 S 6.0 W 6.0	1.0	1.0	Early Mature	Good	Growing on north bank of ditch.	191.1	7.8	40+	B	1
T2156	1	*Alnus glutinosa* Common Alder	13.0	3	61	N 4.0 E 4.0 S 4.0 W 4.0	1.0	2.0	Mature	Good	Multi-stemmed. Growing on north bank of ditch.	168.5	7.3	40+	B	1 2
T2157	1	*Alnus glutinosa* Common Alder	18.0	3	76	N 5.0 E 5.0 S 5.0 W 5.0	1.0	2.5	Mature	Good	Epicormic growth - Base / bole / principal stems. Multi-stemmed. Growing on north bank of ditch.	264.6	9.2	40+	B	1 2
T2158	1	*Alnus glutinosa* Common Alder	18.0	6	73	N 7.0 E 7.0 S 7.0 W 7.0	1.0	1.5	Mature	Good	Base / stems obscured - Vegetation. Epicormic growth - Base / bole / principal stems. Multi-stemmed. Growing on north bank of ditch.	244.3	8.8	40+	B	1 2
G2159	2	*Alnus glutinosa* Common Alder	15.0	5	55	N 5.0 E 5.0 S 5.0 W 5.0	1.0	1.0	Early Mature	Good	Multi-stemmed.	141.4	6.7	40+	B	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2160	1	*Quercus robur* English Oak	9.0	2	58	NW 4.0 NE 6.0 SE 5.0 SW 5.0	3.0	1.5	Early Mature	Good	Growing on west bank of ditch.	153.8	7.0	40+	B	1
T2161	1	*Quercus robur* English Oak	11.0	1	45	NW 5.0 NE 4.0 SE 5.0 SW 6.0	3.0	2.0	Early Mature	Good	Pruning wounds - Recent. Growing on west bank of ditch.	91.6	5.4	40+	B	1
T2162	1	*Quercus robur* English Oak	11.0	4	51	NW 3.0 NE 5.0 SE 3.0 SW 5.0	2.0	1.5	Early Mature	Good	Multi-stemmed. Growing on west bank of ditch.	117.8	6.1	40+	C	1
T2163	1	*Fraxinus excelsior* Ash	8.0	5	33	NW 5.0 NE 4.0 SE 1.0 SW 3.0	2.0	2.0	Semi Mature	Fair	Multi-stemmed. Suppressed crown - Minor. Growing on west bank of ditch.	50.9	4.0	20-40	C	1
G2164	10 5 1 1	*Quercus robur* English Oak *Fraxinus excelsior* Ash *Salix cinerea* Grey Sallow *Crataegus monogyna* Common Hawthorn/Quick/May	13.0	5	44	N 4.0 E 4.0 S 4.0 W 4.0	2.0	0.0	Early Mature	Good	Multi-stemmed. Growing on banks of drain. Outgrown hedge. **Fell - Ground level.** Remove a 99-m span. To facilitate development.	90.5	5.4	40+	B	2
G2165	7 3 1	*Salix fragilis* Crack Willow *Alnus glutinosa* Common Alder *Corylus avellana* Common Hazel	18.0	5	67	N 5.0 E 5.0 S 5.0 W 5.0	1.0	1.0	Early Mature	Good	Deadwood - Minor. Leaning trunk - Major. Multi-stemmed. Growing on bank of ditch.	203.6	8.0	40+	B	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G2166	2	*Corylus avellana* Common Hazel	6.0	10	31	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Early Mature	Good		45.2	3.8	40+	C	2
G2167	2	*Corylus avellana* Common Hazel	6.0	10	31	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Early Mature	Good		45.2	3.8	40+	C	2
G2168	2	*Corylus avellana* Common Hazel	6.0	10	31	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Early Mature	Good		45.2	3.8	40+	C	2
T2169	1	*Quercus robur* English Oak	17.0	1	84	N 5.0 E 8.0 S 8.0 W 7.0	4.0	4.0	Early Mature	Good	Epicormic growth - Bole / principal stems.	319.2	10.1	40+	B	1 2
T2170	1	*Quercus robur* English Oak	17.0	1	97	N 9.0 E 9.0 S 9.0 W 9.0	4.0	4.0	Mature	Good	Epicormic growth - Bole / principal stems.	425.7	11.6	40+	B	1 2
T2171	1	*Quercus robur* English Oak	16.0	1	90	N 6.0 E 6.0 S 6.0 W 6.0	1.0	1.0	Mature	Good	Growing on east bank of ditch. Significant soil erosion at base. Stilt roots.	366.4	10.8	40+	B	1
W2172	25 5	*Quercus robur* English Oak *Pinus sylvestris* Scots Pine	20.0	1	55	N 4.0 E 4.0 S 4.0 W 4.0	3.0	4.0	Early Mature	Good	Edge of plantation woodland	136.8	6.6	40+	B	2
T2173	1	*Quercus robur* English Oak	16.0	1	96	N 7.0 E 7.0 S 9.0 W 7.0	3.0	6.0	Mature	Good	Growing on east bank of ditch.	416.9	11.5	40+	B	1
W2174	30 2	*Pinus sylvestris* Scots Pine *Fagus sylvatica* Common Beech	20.0	1	35	N 3.0 E 3.0 S 3.0 W 3.0	3.0	4.0	Early Mature	Good	Edge of plantation woodland.	55.4	4.2	40+	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G2175	5 1	*Cerasus avium* Wild Cherry *Quercus robur* English Oak	9.0	1	30	N E S W 2.0 2.0 2.0 2.0	3.0	3.0	Semi Mature	Good	On neighbouring land. Growing in managed hedge of hawthorn and hazel.	40.7	3.6	40+	C	2
G2176	7	*Betula pendula* Silver Birch	14.0	1	25	N E S W 3.0 3.0 3.0 3.0	4.0	4.0	Semi Mature	Good		28.3	3.0	40+	C	2
T2177	1	*Ilex x altaclerensis* Highclere Holly	9.0	1	30	N E S W 3.0 3.0 3.0 3.0	4.0	2.5	Semi Mature	Fair	Base / stems obscured - Vegetation. Die-back - Upper crown. Swathed in ivy. **Fell - Ground level.** To facilitate development.			10-20	U	
T2178	1	*Juglans regia* Walnut	9.0	2	32	NW NE SE SW 3.0 4.0 3.0 3.0	5.0	2.0	Semi Mature	Good	**Fell - Ground level.** To facilitate development.	46.4	3.8	40+	C	1
T2179	1	*Ilex aquifolium* Holly	7.0	1	20	N E S W 2.0 2.0 2.0 2.0	2.5	2.5	Semi Mature	Good	**Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	18.1	2.4	40+	C	1
T2180	1	*Juglans regia* Walnut	8.0	1	25	NW NE SE SW 3.0 3.0 3.0 3.0	3.0	1.5	Semi Mature	Good	**Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	28.3	3.0	40+	C	1
T2181	1	*Acer campestre* Field Maple	10.0	1	45	N E S W 5.0 5.0 5.0 5.0	4.0	1.5	Early Mature	Good	**Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	91.6	5.4	40+	B	1
T2182	1	*Populus x canadensis* Hybrid Black Poplars	25.0	1	59	N E S W 4.0 4.0 4.0 4.0	7.0	5.0	Early Mature	Good	**Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	157.5	7.1	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2183	1	*Acer campestre* Field Maple	10.0	1	43	N E S W 5.0 5.0 5.0 5.0	4.0	1.5	Early Mature	Good	**Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	83.6	5.2	40+	B	1
T2184	1	*Acer campestre* Field Maple	10.0	1	31	N E S W 5.0 5.0 5.0 5.0	4.0	2.0	Early Mature	Good		43.5	3.7	40+	B	1
T2185	1	*Acer campestre* Field Maple	10.0	1	43	N E S W 5.0 5.0 5.0 5.0	4.0	2.0	Early Mature	Good		83.6	5.2	40+	B	1
T2186	1	*Ilex aquifolium* Holly	7.0	1	20	N E S W 2.0 2.0 2.0 2.0	2.5	2.5	Semi Mature	Good		18.1	2.4	40+	C	1
G2187	6	*Acer campestre* Field Maple	12.0	1	45	N E S W 4.0 4.0 4.0 4.0	6.0	3.0	Early Mature	Good		91.6	5.4	40+	B	2
H2188	50	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
T2189	1	*Juglans regia* Walnut	9.0	2	25	NW NE SE SW 2.0 2.0 2.0 2.0	4.0	1.5	Semi Mature	Good	**Fell - Ground level.** To facilitate development.	28.3	3.0	40+	C	1
T2190	1	*Castanea sativa* Sweet Chestnut	9.0	1	48	N E S W 5.0 5.0 5.0 5.0	3.0	2.0	Semi Mature	Good	**Fell - Ground level.** To facilitate development.	104.2	5.8	40+	C	1
T2191	1	*Acer campestre* Field Maple	9.0	5	33	N E S W 2.0 2.0 2.0 2.0	6.0	2.0	Semi Mature	Good		50.9	4.0	40+	C	1
G2192	3 1	*Quercus robur* English Oak *Ilex aquifolium* Holly	10.0	1	45	N E S W 5.0 5.0 5.0 5.0	5.0	2.5	Early Mature	Good		91.6	5.4	40+	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G2193	2 1	*Quercus robur* English Oak *Acer campestre* Field Maple	10.0	1	45	N E S W 5.0 5.0 5.0 5.0	5.0	2.5	Early Mature	Good		91.6	5.4	40+	B	2
T2194	1	*Quercus robur* English Oak	10.0	1	45	NW NE SE SW 5.0 5.0 5.0 3.0	5.0	3.0	Early Mature	Good		91.6	5.4	40+	B	1 2
G2195	2 1 1	*Quercus robur* English Oak *Ilex aquifolium* Holly *Betula pendula* Silver Birch	9.0	1	25	N E S W 3.0 3.0 3.0 3.0	4.0	2.5	Semi Mature	Good		28.3	3.0	40+	C	2
H2196	50	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
T2197	1	*Fraxinus excelsior* Ash	13.0	1	35	N E S W 3.0 3.0 3.0 3.0	6.0	2.5	Early Mature	Good		55.4	4.2	40+	C	1
T2198	1	*Acer campestre* Field Maple	10.0	1	30	N E S W 2.0 2.0 2.0 2.0	5.0	1.5	Semi Mature	Good		40.7	3.6	40+	C	1
H2199	20 10 5	*Rubus fruticosus s.* Blackberry/Bramble *Prunus cerasifera* Cherry Plum (Myrobalan) *Rosa canina* Dog-rose	2.0	1	5	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Semi Mature	Good		1.1	0.6	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2200	1	*Quercus robur* English Oak	20.0	1	65	N 6.0 E 6.0 S 6.0 W 6.0	5.5	7.0	Early Mature	Good	On neighbouring land (garden).	191.1	7.8	40+	B	1 2
T2201	1	*Quercus robur* English Oak	23.0	1	65	N 6.0 E 6.0 S 6.0 W 6.0	13.0	13.0	Early Mature	Good	On neighbouring land (garden).	191.1	7.8	40+	B	1 2
T2202	1	*Quercus robur* English Oak	20.0	1	65	N 3.0 E 6.0 S 7.0 W 6.0	5.5	7.0	Early Mature	Good	On neighbouring land (garden).	191.1	7.8	40+	B	1 2
T2203	1	*Quercus robur* English Oak	20.0	1	90	N 10.0 E 10.0 S 10.0 W 10.0	4.0	7.0	Early Mature	Good	On neighbouring land (garden). **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	366.4	10.8	40+	A	1 2
T2204	1	*Quercus robur* English Oak	12.0	1	30	N 5.0 E 3.0 S 6.0 W 5.0	4.0	3.0	Semi Mature	Good	On neighbouring land (garden). **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	40.7	3.6	40+	C	1 2
T2205	1	*Quercus robur* English Oak	17.0	1	90	N 10.0 E 10.0 S 10.0 W 10.0	4.0	7.0	Early Mature	Good	On neighbouring land (garden). **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	366.4	10.8	40+	A	1 2
T2206	1	*Quercus robur* English Oak	6.0	1	20	N 4.0 E 4.0 S 4.0 W 4.0	2.5	3.0	Semi Mature	Good	On neighbouring land (garden). **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	18.1	2.4	40+	C	1 2
T2207	1	*Cerasus avium* Wild Cherry	12.0	1	60	N 6.0 E 5.0 S 6.0 W 5.0	4.0	2.5	Early Mature	Fair	**Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	162.9	7.2	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2208	1	*Acer campestre* Field Maple	12.0	1	55	N E S W 4.0 4.0 4.0 4.0	5.0	2.0	Mature	Good		136.8	6.6	40+	B	1
T2209	1	*Betula pendula* Silver Birch	19.0	1	29	N E S W 2.0 2.0 2.0 2.0	3.0	2.5	Early Mature	Good	**Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	38.0	3.5	40+	C	1
T2210	1	*Acer pseudoplatanus* Sycamore	16.0	1	35	N E S W 4.0 5.0 5.0 5.0	5.0	2.0	Early Mature	Good		55.4	4.2	40+	B	1
T2211	1	*Acer pseudoplatanus* Sycamore	18.0	1	55	N E S W 4.0 5.0 5.0 5.0	5.0	2.5	Early Mature	Good		136.8	6.6	40+	B	1
T2212	1	*Fraxinus excelsior* Ash	15.0	1	45	N E S W 4.0 4.0 4.0 4.0	3.0	5.0	Early Mature	Fair	Base / stems obscured - Vegetation.	91.6	5.4	10-20	C	1
G2213	4 1	*Juglans regia* Walnut *Quercus robur* English Oak	12.0	1	50	N E S W 5.0 5.0 5.0 5.0	3.0	2.5	Early Mature	Good	Hanging low over road.	113.1	6.0	40+	B	2
T2214	1	*Carpinus betulus* Hornbeam	10.0	1	49	N E S W 6.0 6.0 6.0 6.0	4.0	2.0	Early Mature	Good	Growing at edge of municipal field. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	108.6	5.9	40+	B	1
T2215	1	*Acer campestre* Field Maple	13.0	1	47	N E S W 5.0 5.0 5.0 5.0	4.0	2.0	Early Mature	Good	Growing at edge of municipal field. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	99.9	5.6	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2216	1	*Alnus glutinosa* Common Alder	13.0	1	37	N E S W 4.0 4.0 4.0 4.0	4.0	3.5	Early Mature	Good	Leaning trunk - Minor. Growing at edge of municipal field. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	61.9	4.4	40+	B	1
T2217	1	*Acer pseudoplatanus* Sycamore	13.0	1	40	N E S W 4.0 4.0 4.0 4.0	4.0	2.0	Early Mature	Good	Growing at edge of municipal field. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	72.4	4.8	40+	B	1
T2218	1	*Betula pendula* Silver Birch	17.0	1	45	NW NE SE SW 5.0 4.0 4.0 4.0	4.0	3.5	Early Mature	Good	Ivy or climbing plant. Growing at edge of municipal field. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	91.6	5.4	40+	B	1
H2219	65 20 10 10	*Ulmus procera* English Elm *Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple *Corylus avellana* Common Hazel	2.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good		4.5	1.2	40+	B	2
T2220	1	*Carpinus betulus* Hornbeam	9.0	1	25	N E S W 3.0 3.0 3.0 3.0	2.5	1.5	Semi Mature	Good	Growing in Park. Does not overhang road.	28.3	3.0	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2221	1	*Quercus robur* English Oak	22.0	1	110	NW 9.0 NE 7.0 SE 5.0 SW 9.0	8.0	7.0	Mature	Good	Growing in Park. Does not overhang road.	547.4	13.2	40+	A	1
T2222	1	*Quercus robur* English Oak	20.0	1	85	NW 3.0 NE 4.0 SE 5.0 SW 5.0	8.0	3.0	Mature	Good	Growing in Park. Does not overhang road.	326.9	10.2	40+	B	1
T2223	1	*Acer pseudoplatanus* Sycamore	14.0	1	45	N 4.0 E 4.0 S 4.0 W 4.0	2.5	2.5	Early Mature	Good	Growing in Park. Does not overhang road.	91.6	5.4	40+	B	1
T2224	1	*Carpinus betulus* Hornbeam	6.0	1	12	N 3.0 E 3.0 S 3.0 W 3.0	3.0	1.5	Young	Good	Growing in Park. Does not overhang road. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	6.5	1.4	40+	C	1
T2225	1	*Fagus sylvatica* Common Beech	10.0	1	35	NW 4.0 NE 4.0 SE 2.0 SW 5.0	4.0	1.5	Early Mature	Fair	Growing on highway verge. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	55.4	4.2	20-40	C	1
T2226	1	*Fagus sylvatica* Common Beech	10.0	1	35	NW 2.0 NE 4.0 SE 5.0 SW 4.0	4.0	2.0	Early Mature	Fair	Growing on highway verge. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	55.4	4.2	20-40	C	1
T2227	1	*Quercus robur* English Oak	11.0	5	33	NW 3.0 NE 3.0 SE 3.0 SW 2.0	4.0	3.0	Semi Mature	Fair	Growing on highway verge. **Fell - Ground level.** To facilitate development.	50.9	4.0	20-40	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2228	1	*Carpinus betulus* Hornbeam	6.0	1	25	NW 1.0 NE 3.0 SE 3.0 SW 3.0	3.0	2.0	Young	Good	Growing in Park. Does not overhang road. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	28.3	3.0	40+	C	1
T2229	1	*Quercus robur* English Oak	15.0	1	55	NW 8.0 NE 7.0 SE 6.0 SW 7.0	3.0	2.5	Early Mature	Good	Growing in park. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	136.8	6.6	40+	B	1
T2230	1	*Cerasus avium* Wild Cherry	11.0	2	28	NW 2.0 NE 4.0 SE 3.0 SW 3.0	3.0	1.5	Early Mature	Good	Growing in park.	36.2	3.4	40+	C	1
T2231	1	*Cerasus avium* Wild Cherry	13.0	1	93	NW 6.0 NE 7.0 SE 5.0 SW 5.0	3.0	1.5	Mature	Good	Growing in park. Does not overhang road.	391.3	11.2	40+	B	1
T2232	1	*Cerasus avium* Wild Cherry	13.0	1	70	NW 5.0 NE 7.0 SE 4.0 SW 7.0	3.0	1.5	Mature	Good	Growing in park. Does not overhang road.	221.7	8.4	40+	B	1
T2233	1	*Fagus sylvatica* Common Beech	16.0	1	70	NW 5.0 NE 8.0 SE 4.0 SW 6.0	1.0	1.0	Mature	Good	Growing in park. Does not overhang road.	221.7	8.4	40+	B	1
T2234	1	*Quercus robur* English Oak	25.0	1	126	N 12.0 E 12.0 S 12.0 W 10.0	4.0	5.0	Late Mature	Good	Fungal fruiting body - structural decay suspected. Growing at edge of park c. 1.5 m from tarmac edge of road. Ganoderma bracket at base.	706.9	15.0	40+	A	1
T2235	1	*Fraxinus excelsior* Ash	16.0	2	40	N 6.0 E 6.0 S 3.0 W 5.0	6.0	6.0	Early Mature	Fair	Die-back - Throughout crown. Growing on highway verge. Chalara (ash dieback) present. Moderate symptoms.	73.5	4.8	10-20	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2236	1	*Quercus robur* English Oak	18.0	1	96	N E S W 7.0 8.0 7.0 8.0	4.0	6.5	Mature	Good	Deadwood - Minor. Decay / structural defect - Extensive. Decay / structural defect - Bole. Growing on highway verge.	416.9	11.5	40+	A	1 3
T2237	1	*Quercus robur* English Oak	15.0	1	55	N E S W 6.0 7.0 5.0 7.0	6.0	3.5	Early Mature	Good	Growing in park. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	136.8	6.6	40+	B	1
T2238	1	*Quercus robur* English Oak	20.0	1	98	N E S W 7.0 8.0 10.0 9.0	8.0	10.0	Late Mature	Good	Ivy or climbing plant. Growing at edge of park c. 2.5 m from tarmac edge of road.	434.5	11.8	40+	A	1
T2239	1	*Quercus robur* English Oak	14.0	1	80	N E S W 6.0 6.0 6.0 6.0	3.0	4.0	Mature	Fair	Bark wound - Mechanical. Pollard - Regrown. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	289.5	9.6	40+	B	1
G2240	1 1 1	*Quercus robur* English Oak *Cerasus avium* Wild Cherry *Acer platanoides* Norway Maple	14.0	2	57	N E S W 6.0 5.0 5.0 5.0	5.0	2.0	Early Mature	Good	Growing in park. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	147.0	6.8	40+	B	1
T2241	1	*Fraxinus excelsior* Ash	8.0	4	40	N E S W 3.0 3.0 3.0 3.0	4.0	2.5	Early Mature	Fair	Bark wound - Mechanical. Chalara (ash dieback) present. Minor symptoms. Growing in hedge.	72.4	4.8	20-40	C	1
H2242	50	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	10	N E S W 1.0 0.5 1.0 1.0	0.0	0.0	Early Mature	Good	Flailed to East.	4.5	1.2	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G2243	100	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	1	10	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Young	Fair	Odd hawthorn plantation.	4.5	1.2	20-40	C	1
H2244	3	*Crataegus monogyna* Common Hawthorn/Quick/May	1.5	1	10	N E S W 0.5 0.5 0.5 0.5	0.0	0.0	Early Mature	Poor	Hedge remnant. Flailed.	4.5	1.2	10-20	C	1
T2245	1	*Fraxinus excelsior* Ash	17.0	1	75	NW NE SE SW 6.0 11.0 11.0 11.0	4.0	7.0	Mature	Good	Deadwood - Major. Epicormic growth - Base / bole / principal stems. Ivy or climbing plant. Deadwood over road. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	254.5	9.0	20-40	B	1
T2246	1	*Ulmus sp.* Elm sp.	9.0	1	50	NW NE SE SW 4.0 4.0 4.0 4.0	5.0	2.0	Early Mature	Fair	Die-back - Throughout crown. Epicormic growth - Base / bole / principal stems. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	113.1	6.0	20-40	C	1
T2247	1	*Populus nigra 'Italica'* Lomardy Poplar	24.0	4	90	N E S W 2.5 2.5 2.5 2.5	1.0	1.0	Early Mature	Good	Base / stems obscured - Vegetation. **Fell - Ground level.** To facilitate development.	366.4	10.8	40+	C	1 2
T2248	1	*Populus nigra 'Italica'* Lomardy Poplar	24.0	1	65	N E S W 2.5 2.5 2.5 2.5	1.0	1.0	Early Mature	Good	Base / stems obscured - Vegetation. **Fell - Ground level.** To facilitate development.	191.1	7.8	40+	C	1 2
T2249	1	*Fraxinus excelsior* Ash	14.0	8	70	N E S W 4.0 4.0 4.0 4.0	4.0	4.0	Early Mature	Fair	Coppice stool - Coppice origin / Mature stems. Exposed roots at road edge.	226.2	8.5	20-40	C	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2250	1	*Fraxinus excelsior* Ash	14.0	11	66	N E S W 4.0 4.0 4.0 4.0	4.0	3.0	Early Mature	Fair	Coppice stool - Coppice origin / Mature stems.	199.1	8.0	20-40	C	1 2
T2251	1	*Acer pseudoplatanus* Sycamore	12.0	4	80	N E S W 4.0 4.0 4.0 4.0	4.0	2.0	Early Mature	Good	Coppice stool - Coppice origin / Mature stems. Epicormic growth - Base / bole / principal stems.	291.8	9.6	40+	C	1
H2252	20 1 1	*Prunus spinosa* Blackthorn/Sloe *Sambucus nigra* Elder *Corylus avellana* Common Hazel	2.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Gappy.	4.5	1.2	40+	C	2
H2253	20	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
H2254	50	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	5	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	1.1	0.6	40+	C	2
T2255	1	*Prunus cerasifera* Cherry Plum (Myrobalan)	7.0	4	30	N E S W 3.0 3.0 3.0 3.0	2.5	2.0	Early Mature	Good	On neighbouring land.	40.7	3.6	40+	C	1
T2256	1	*Populus x canadensis* Hybrid Black Poplars	16.0	1	25	N E S W 3.0 3.0 3.0 3.0	3.0	2.5	Semi Mature	Good	On neighbouring land (garden). **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	28.3	3.0	40+	C	1
H2257	20	*Thuja plicata* Western Red Cedar	6.0	1	20	N E S W 2.0 2.0 2.0 1.0	0.0	0.0	Early Mature	Fair	Flailed on road side. On neighbouring land (garden).	18.1	2.4	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2258	1	*Cerasus avium* Wild Cherry	9.0	5	89	NW 4.0 NE 4.0 SE 4.0 SW 4.0	5.0	3.0	Early Mature	Fair	On neighbouring land (garden).	361.9	10.7	20-40	C	1
T2259	1	*Acer platanoides 'Crimson King'* Red Norway Maple	10.0	1	45	NW 4.0 NE 4.0 SE 4.0 SW 3.0	4.0	1.0	Early Mature	Good	On neighbouring land (garden). **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	91.6	5.4	40+	C	1
G2260	2 1 1	*Fraxinus excelsior* Ash *Fagus sylvatica* Common Beech *Acer pseudoplatanus* Sycamore	15.0	1	35	N 4.0 E 4.0 S 4.0 W 4.0	4.0	3.0	Early Mature	Good	On neighbouring land. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	55.4	4.2	40+	C	2
T2261	1	*Quercus robur* English Oak	14.0	1	70	NW 5.0 NE 5.0 SE 5.0 SW 5.0	3.0	3.0	Early Mature	Good	Fungal fruiting body - structural decay suspected. Pruning wounds - Historic. Grifola frondosa bracket at base. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	221.7	8.4	40+	B	1
T2262	1	*Fraxinus excelsior* Ash	15.0	1	83	N 6.0 E 6.0 S 6.0 W 6.0	4.0	3.0	Mature	Fair	Die-back - Upper crown. Deadwood - Minor. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Bole. Epicormic growth - Base / bole / principal stems. Chalara (ash dieback) present. Minor symptoms. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	311.7	10.0	20-40	B	1 3

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
W2263	15 10 5 1	*Fraxinus excelsior* Ash *Betula pendula* Silver Birch *Acer campestre* Field Maple *Salix caprea* Goat Willow/Great Sallow	13.0	1	25	N 3.0 E 3.0 S 3.0 W 3.0	3.0	3.0	Semi Mature	Good	Edge group of plantation woodland. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	28.3	3.0	40+	B	2
G2264	7 1	*Fraxinus excelsior* Ash *Salix fragilis* Crack Willow	16.0	3	69	N 4.0 E 4.0 S 4.0 W 4.0	3.0	4.0	Early Mature	Good	Growing on West bank of ditch. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	217.1	8.3	40+	B	2
T2265	1	*Quercus cerris* Turkey Oak	18.0	1	85	N 8.0 E 8.0 S 8.0 W 8.0	4.0	2.0	Mature	Good	**Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	326.9	10.2	40+	B	1 2
T2266	1	*Quercus robur* English Oak	18.0	1	81	N 10.0 E 7.0 S 9.0 W 8.0	7.0	7.0	Mature	Good	Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Road side low branches pruned off.	296.8	9.7	40+	B	1 2
T2267	1	*Quercus robur* English Oak	18.0	1	70	NW 9.0 NE 9.0 SE 8.0 SW 7.0	4.0	3.0	Mature	Good	Epicormic growth - Base / bole / principal stems. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	221.7	8.4	40+	B	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2268	1	*Fraxinus excelsior* Ash	16.0	1	77	NW 5.0 NE 8.0 SE 5.0 SW 5.0	5.0	8.0	Mature	Fair	Bark wound - Major. Bark wound - Mechanical. Decay / structural defect - Extensive. Decay / structural defect - Bole.	268.2	9.2	20-40	C	1
T2269	1	*Acer pseudoplatanus* Sycamore	17.0	5	44	NW 6.0 NE 4.0 SE 2.0 SW 6.0	6.0	6.0	Semi Mature	Good	Epicormic growth - Base / bole / principal stems.	90.5	5.4	40+	B	1 2
T2270	1	*Quercus robur* English Oak	18.0	1	75	NW 6.0 NE 9.0 SE 8.0 SW 8.0	3.5	3.0	Mature	Good	Epicormic growth - Base / bole / principal stems. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	254.5	9.0	40+	B	1 2
T2271	1	*Fraxinus excelsior* Ash	16.0	3	78	NW 6.0 NE 5.0 SE 7.0 SW 6.0	5.0	5.0	Early Mature	Fair	Chalara (ash dieback) present. Minor symptoms.	277.1	9.4	20-40	C	2
G2272	5 2	*Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash	5.0	1	15	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Early Mature	Good	Hedge remnant.	10.2	1.8	40+	C	2
T2273	1	*Quercus robur* English Oak	14.0	1	73	NW 6.0 NE 6.0 SE 6.0 SW 6.0	4.0	4.0	Mature	Good	Epicormic growth - Base / bole / principal stems. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	241.1	8.8	40+	B	1 2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2274	1	*Quercus robur* English Oak	14.0	1	73	NW 8.0 NE 8.0 SE 8.0 SW 8.0	3.5	5.0	Mature	Good	Epicormic growth - Base / bole / principal stems. Shedding limb / limbs - Historic. Shedding limb / limbs - Minor. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	241.1	8.8	40+	B	1 2
T2275	1	*Quercus robur* English Oak	14.0	1	75	NW 8.0 NE 8.0 SE 8.0 SW 8.0	4.0	6.0	Mature	Good	Epicormic growth - Base / bole / principal stems. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	254.5	9.0	40+	B	1 2
T2276	1	*Quercus robur* English Oak	14.0	1	75	NW 8.0 NE 8.0 SE 8.0 SW 8.0	5.0	5.0	Mature	Good	Epicormic growth - Base / bole / principal stems.	254.5	9.0	40+	B	1 2
T2277	1	*Quercus robur* English Oak	14.0	1	70	NW 7.0 NE 7.0 SE 7.0 SW 7.0	4.0	5.0	Mature	Good	Epicormic growth - Base / bole / principal stems. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	221.7	8.4	40+	B	1 2
T2278	1	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	20	NW 1.0 NE 1.0 SE 1.0 SW 1.0	0.5	0.0	Early Mature	Fair	Hedge remnant.	18.1	2.4	20-40	C	1
T2279	1	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	25	NW 2.0 NE 2.0 SE 2.0 SW 2.0	0.5	0.0	Early Mature	Fair	Hedge remnant.	28.3	3.0	20-40	C	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2280	1	*Quercus robur* English Oak	14.0	2	68	N E S W 6.0 5.0 6.0 7.0	3.0	1.5	Early Mature	Good	Epicormic growth - Base / bole / principal stems. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	209.2	8.2	40+	B	1 2
T2281	1	*Quercus robur* English Oak	10.0	1	44	N E S W 6.0 6.0 6.0 5.0	4.0	2.0	Early Mature	Good	Epicormic growth - Base / bole / principal stems. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	87.6	5.3	40+	B	1 2
T2282	1	*Fraxinus excelsior* Ash	16.0	9	90	N E S W 7.0 7.0 6.0 6.0	3.0	5.0	Early Mature	Good	Coppice stool - Coppice origin / Mature stems. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	366.4	10.8	40+	B	1
T2283	1	*Fraxinus excelsior* Ash	14.0	1	77	N E S W 9.0 7.0 7.0 7.0	3.0	1.5	Early Mature	Good	Epicormic growth - Base / bole / principal stems. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	268.2	9.2	40+	B	1
T2284	1	*Fraxinus excelsior* Ash	17.0	1	84	N E S W 7.0 7.0 7.0 7.0	7.0	6.0	Mature	Fair	Epicormic growth - Base. Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Chalara (ash dieback) present. Minor symptoms. Inonotus hispidus brackets on old wounds.	319.2	10.1	20-40	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2285	1	*Fraxinus excelsior* Ash	17.0	1	102	N E S W 9.0 9.0 9.0 7.0	5.0	5.0	Mature	Fair	Epicormic growth - Base. Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Chalara (ash dieback) present. Minor symptoms. Inonotus hispidus brackets on old wounds.	470.7	12.2	20-40	B	1
T2286	1	*Fraxinus excelsior* Ash	17.0	1	82	N E S W 7.0 9.0 8.0 8.0	6.0	4.0	Mature	Fair	Epicormic growth - Base. Shedding limb / limbs - Major. Chalara (ash dieback) present. Minor symptoms. Inonotus hispidus brackets on old wounds.	304.2	9.8	20-40	B	1
T2287	1	*Quercus robur* English Oak	18.0	1	90	N E S W 8.0 8.0 8.0 8.0	3.0	2.5	Mature	Good	**Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	366.4	10.8	40+	A	1 2
T2288	1	*Fraxinus excelsior* Ash	15.0	1	55	N E S W 6.0 6.0 6.0 6.0	5.0	2.0	Early Mature	Fair	Chalara (ash dieback) present. Moderate symptoms.	136.8	6.6	10-20	C	1
H2289	30 5 3 1 1 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Cerasus avium* Wild Cherry *Corylus avellana* Common Hazel *Sorbus aucuparia* Rowan/Mountain Ash *Sambucus nigra* Elder *Acer campestre* Field Maple	1.5	1	3	N E S W 0.5 0.5 0.5 0.5	0.0	0.0	Young	Fair		0.4	0.4	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G2290	5	*Salix fragilis* Crack Willow	18.0	5	100	N E S W 6.0 6.0 6.0 6.0	4.0	5.0	Early Mature	Fair	Multi-stemmed. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	458.0	12.1	20-40	C	2
T2291	1	*Fraxinus excelsior* Ash	9.0	1	60	NW NE SE SW 1.0 1.0 5.0 4.0	3.0	2.5	Early Mature	Poor	Crown missing on road side. Chalara (ash dieback) present. Severe symptoms.			0-10	U	
H2292	30	*Crataegus monogyna* Common Hawthorn/Quick/May	1.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
G2293	2	*Acer pseudoplatanus* Sycamore	10.0	10	63	N E S W 5.0 5.0 5.0 5.0	4.0	3.0	Semi Mature	Good	**Fell - Coppice.** To facilitate development.	181.0	7.6	40+	C	2
T2294	1	*Fraxinus excelsior* Ash	18.0	1	70	N E S W 6.0 6.0 6.0 6.0	4.0	7.0	Mature	Fair	Epicormic growth - Base / bole / principal stems. Chalara (ash dieback) present. Moderate symptoms. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	221.7	8.4	10-20	C	1
T2295	1	*Fagus sylvatica f. purpurea* Purple Beech	14.0	1	65	N E S W 6.0 6.0 6.0 6.0	4.0	4.0	Early Mature	Good	On neighbouring land.	191.1	7.8	40+	B	1
G2296	3 2	*Acer pseudoplatanus* Sycamore *Fraxinus excelsior* Ash	12.0	5	44	N E S W 4.0 4.0 4.0 4.0	4.0	3.0	Early Mature	Good	Multi-stemmed.	90.5	5.4	40+	C	1
T2297	1	*Salix fragilis* Crack Willow	18.0	4	101	N E S W 8.0 8.0 8.0 8.0	5.0	6.0	Early Mature	Fair	Base / stems obscured - Vegetation. Multi-stemmed.	468.2	12.2	20-40	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2298	1	*Salix fragilis* Crack Willow	18.0	2	63	N E S W 6.0 6.0 6.0 6.0	5.0	4.0	Mature	Fair	Base / stems obscured - Vegetation.	183.2	7.6	20-40	C	1
T2299	1	*Fraxinus excelsior* Ash	13.0	6	48	N E S W 4.0 4.0 4.0 4.0	4.0	4.0	Early Mature	Fair	Chalara (ash dieback) present. Minor symptoms.	108.6	5.9	20-40	C	2
T2300	1	*Fraxinus excelsior* Ash	13.0	6	48	N E S W 4.0 4.0 4.0 4.0	4.0	4.0	Early Mature	Fair	Chalara (ash dieback) present. Minor symptoms.	108.6	5.9	20-40	C	2
T2301	1	*Salix fragilis* Crack Willow	17.0	1	80	N E S W 9.0 9.0 9.0 9.0	4.0	4.0	Mature	Fair	Epicormic growth - Base / bole / principal stems. Fallen tree / trees - Partial collapse.	289.5	9.6	20-40	C	1
T2302	1	*Fraxinus excelsior* Ash	15.0	1	60	N E S W 4.0 4.0 4.0 4.0	5.0	5.0	Early Mature	Fair		162.9	7.2	20-40	C	1
H2303	40 10 10	*Corylus avellana* Common Hazel *Fraxinus excelsior* Ash *Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G2304	5 1 1 1	*Prunus spinosa* Blackthorn/Sloe *Salix alba* White Willow *Fraxinus excelsior* Ash *Corylus avellana* Common Hazel	10.0	3	63	NW 2.0 NE 2.0 SE 1.0 SW 2.0	0.0	1.0	Semi Mature	Fair	Flailed on road side. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	183.2	7.6	40+	C	2
T2305	1	*Fraxinus excelsior* Ash	17.0	1	78	N 7.0 E 7.0 S 7.0 W 7.0	4.0	4.0	Early Mature	Poor	Die-back - Throughout crown. Decay / structural defect - Open cavity / cavities. Decay / structural defect - Bole. Chalara (ash dieback) present. Moderate symptoms. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	275.2	9.4	10-20	C	1
G2306	2 1 1	*Fraxinus excelsior* Ash *Salix alba* White Willow *Acer campestre* Field Maple	13.0	1	45	N 4.0 E 2.0 S 4.0 W 4.0	3.0	5.0	Early Mature	Fair	**Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	91.6	5.4	20-40	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2307	1	*Fraxinus excelsior* Ash	13.0	10	47	N E S W 4.0 4.0 4.0 4.0	4.0	5.0	Early Mature	Fair	Coppice stool - Coppice origin / Mature stems. Chalara (ash dieback) present. Moderate symptoms. Growing on West bank of ditch. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	101.8	5.7	10-20	C	1
H2308	6 2	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel	2.0	1	15	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Hedge remnant.	10.2	1.8	40+	C	2
T2309	1	*Salix x sepulcralis* Weeping Willow	20.0	1	120	N E S W 8.0 9.0 9.0 11.0	1.0	4.0	Mature	Good	**Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	651.4	14.4	40+	A	1
G2310	2	*Quercus robur* English Oak	10.0	5	67	N E S W 5.0 5.0 5.0 5.0	1.0	1.5	Early Mature	Good	Coppice stool - Coppice origin / Mature stems.	203.6	8.0	40+	B	1 2
G2311	2	*Quercus robur* English Oak	12.0	5	67	N E S W 5.0 5.0 5.0 5.0	5.0	3.0	Early Mature	Good	Coppice stool - Coppice origin / Mature stems.	203.6	8.0	40+	C	1 2
T2312	1	*Salix fragilis* Crack Willow	18.0	5	89	N E S W 6.0 6.0 6.0 6.0	1.0	0.5	Early Mature	Fair	Coppice stool - Coppice origin / Mature stems. Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Shedding limb / limbs - Recent.	361.9	10.7	20-40	C	1
T2313	1	*Quercus robur* English Oak	13.0	1	58	N E S W 6.0 6.0 4.0 6.0	4.0	2.0	Early Mature	Good	**Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	152.2	7.0	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2314	1	*Quercus robur* English Oak	13.0	2	74	N E S W 8.0 8.0 8.0 8.0	4.0	2.0	Early Mature	Good	**Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	249.9	8.9	40+	B	1
G2315	3 1 1 1	*Salix cinerea* Grey Sallow *Quercus robur* English Oak *Fraxinus excelsior* Ash *Tilia cordata* Small Leaved Lime	10.0	1	30	N E S W 4.0 4.0 4.0 4.0	4.0	2.0	Semi Mature	Good		40.7	3.6	40+	C	1
T2316	1	*Fraxinus excelsior* Ash	11.0	9	45	N E S W 5.0 6.0 4.0 4.0	3.0	4.0	Early Mature	Fair	Coppice stool - Coppice origin / Mature stems. Chalara (ash dieback) present. Minor symptoms.	91.6	5.4	20-40	C	1
H2317	2 1 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Prunus spinosa* Blackthorn/Sloe	1.5	1	20	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Gappy. Hedge remnant.	18.1	2.4	20-40	C	1
T2318	1	*Fraxinus excelsior* Ash	13.0	1	30	N E S W 4.0 6.0 6.0 6.0	7.0	6.0	Early Mature	Fair	Shedding limb / limbs - Minor. Shedding limb / limbs - Recent. Chalara (ash dieback) present. Minor symptoms.	40.7	3.6	20-40	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2319	15	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	10	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown.	4.5	1.2	20-40	C	2
T2320	1	*Fraxinus excelsior* Ash	15.0	5	44	N 6.0 E 6.0 S 6.0 W 6.0	5.0	5.0	Early Mature	Fair	Coppice stool - Coppice origin / Mature stems. Chalara (ash dieback) present. Moderate symptoms.	90.5	5.4	10-20	C	1
G2321	2	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	6	29	N 2.0 E 2.0 S 2.0 W 2.0	1.0	0.5	Early Mature	Fair	Multi-stemmed.	39.1	3.5	40+	C	1
T2322	1	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	6	24	N 2.0 E 2.0 S 2.0 W 2.0	1.0	0.5	Early Mature	Fair		27.1	2.9	40+	C	1
T2323	1	*Quercus robur* English Oak	14.0	1	78	N 6.0 E 6.0 S 6.0 W 7.0	5.0	2.5	Mature	Good	Bark wound - Mechanical. Decay / structural defect - Bole. Hollow trunk - Suspected. Ivy or climbing plant. Pollard - Lapsed / Mature stems.	275.2	9.4	40+	B	1 3
T2324	1	*Quercus robur* English Oak	11.0	1	80	N 6.0 E 6.0 S 6.0 W 6.0	5.0	2.5	Early Mature	Good	Epicormic growth - Base / bole / principal stems.	289.5	9.6	40+	B	1
T2325	1	*Quercus robur* English Oak	12.0	1	82	N 6.0 E 6.0 S 6.0 W 6.0	6.0	2.0	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Pollard - Lapsed / Mature stems.	304.2	9.8	40+	B	1
T2326	1	*Quercus robur* English Oak	11.0	1	115	NW 7.0 NE 7.0 SE 7.0 SW 7.0	5.0	3.0	Mature	Good	Epicormic growth - Base / bole / principal stems. Pollard - Lapsed / Mature stems.	598.3	13.8	40+	B	1
T2327	1	*Quercus robur* English Oak	4.0	1	12	N 2.0 E 2.0 S 2.0 W 2.0	1.0	0.5	Young	Good		6.5	1.4	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2328	1	*Quercus robur* English Oak	9.0	1	73	NW 6.0 NE 6.0 SE 2.0 SW 6.0	1.0	1.0	Mature	Good	Pollard - Lapsed / Mature stems. Flailed on road side.	241.1	8.8	40+	B	1
T2329	1	*Fraxinus excelsior* Ash	14.0	7	52	NW 4.0 NE 5.0 SE 5.0 SW 5.0	5.0	4.0	Semi Mature	Poor	Chalara (ash dieback) present. Severe symptoms.			0-10	U	
T2330	1	*Quercus robur* English Oak	9.0	1	55	NW 4.0 NE 6.0 SE 6.0 SW 6.0	4.0	1.0	Early Mature	Good	Pollard - Regrown.	136.8	6.6	40+	B	1
G2331	3	*Picea abies* Norway Spruce	4.0	1	15	N 1.5 E 1.5 S 1.5 W 1.5	1.5	1.5	Young	Fair	Planted at field edge.	10.2	1.8	40+	C	1
T2332	1	*Quercus robur* English Oak	14.0	1	95	N 9.0 E 9.0 S 9.0 W 7.0	5.0	1.5	Mature	Good	Pollard - Lapsed / Mature stems.	408.3	11.4	40+	A	1
T2333	1	*Quercus robur* English Oak	14.0	1	115	N 10.0 E 10.0 S 10.0 W 9.0	5.0	2.5	Mature	Good	Pollard - Lapsed / Mature stems.	598.3	13.8	40+	A	1
T2334	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	6	36	N 2.5 E 2.5 S 2.5 W 2.5	1.5	1.5	Mature	Fair		61.1	4.4	20-40	C	1
T2335	1	*Quercus robur* English Oak	7.0	1	50	N 4.0 E 4.0 S 1.0 W 1.0	0.5	1.0	Early Mature	Good	Pollard - Regrown.	113.1	6.0	40+	C	1
T2336	1	*Fraxinus excelsior* Ash	9.0	1	50	N 4.0 E 2.0 S 4.0 W 4.0	2.0	1.5	Early Mature	Poor	Base / stems obscured - Vegetation. Die-back - Throughout crown. Chalara (ash dieback) present. Severe symptoms. On neighbouring land.			0-10	U	
T2337	1	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	1	20	N 3.0 E 3.0 S 2.0 W 3.0	0.0	0.0	Semi Mature	Good	Inaccessible. Measurements estimated.	18.1	2.4	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G2338	3	*Prunus spinosa* Blackthorn/Sloe	4.0	1	20	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Semi Mature	Fair	Inaccessible. Measurements estimated.	18.1	2.4	40+	C	1
H2339	10 2	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Gappy. Hedge remnant.	4.5	1.2	20-40	C	1
H2340	25	*Crataegus monogyna* Common Hawthorn/Quick/May	1.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
H2341	60	*Crataegus monogyna* Common Hawthorn/Quick/May	1.5	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
H2342	50 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus cerasifera* Cherry Plum (Myrobalan)	2.8	1	10	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
H2343	60	*Crataegus monogyna* Common Hawthorn/Quick/May	1.5	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
G2344	3	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	15	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Semi Mature	Good	Multi-stemmed. Hedge remnant. **Fell - Ground level.** To facilitate development.	10.2	1.8	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2345	1	*Fraxinus excelsior* Ash	10.0	5	67	N E S W 6.0 6.0 4.0 6.0	0.0	0.0	Early Mature	Fair	Coppice stool - Coppice origin / Mature stems. Chalara (ash dieback) present. Minor symptoms.	203.6	8.0	20-40	C	1
H2346	50 50	*Crataegus monogyna* Common Hawthorn/Quick/May *Acer campestre* Field Maple	1.5	1	10	N E S W 0.5 0.5 0.5 0.5	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
G2347	2	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	15	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Poor	Die-back - Throughout crown. Hedge remnant. **Fell - Ground level.** To facilitate development.			0-10	U	
T2348	1	*Fraxinus excelsior* Ash	11.0	1	50	N E S W 6.0 3.0 7.0 5.0	1.0	2.0	Early Mature	Fair	Die-back - Throughout crown. Chalara (ash dieback) present. Moderate symptoms.	113.1	6.0	10-20	C	1
T2349	1	*Quercus robur* English Oak	11.0	1	85	N E S W 7.0 4.0 6.0 6.0	5.0	3.0	Early Mature	Good		326.9	10.2	40+	B	1
T2350	1	*Quercus robur* English Oak	11.0	1	95	N E S W 9.0 8.0 8.0 5.0	5.0	2.5	Early Mature	Good	Base / stems obscured - Vegetation.	408.3	11.4	40+	B	1
T2351	1	*Acer pseudoplatanus* Sycamore	8.0	2	25	N E S W 2.0 3.0 1.0 0.0	5.0	4.0	Semi Mature	Poor				0-10	U	
T2352	1	*Quercus robur* English Oak	12.0	1	90	N E S W 9.0 7.0 9.0 8.0	5.0	3.0	Early Mature	Good	Base / stems obscured - Vegetation.	366.4	10.8	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2353	1	*Quercus robur* English Oak	12.0	1	90	N E S W 9.0 7.0 9.0 8.0	6.0	2.0	Early Mature	Good	Base / stems obscured - Vegetation. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	366.4	10.8	40+	B	1
H2354	50 50	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May	1.0	1	10	N E S W 0.5 0.5 0.5 0.5	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** Remove a 26-m span. To facilitate development.	4.5	1.2	40+	C	2
H2355	100 100 25 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Acer campestre* Field Maple *Sambucus nigra* Elder	1.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Gappy.	4.5	1.2	40+	C	2
T2356	1	*Quercus robur* English Oak	11.0	1	65	N E S W 5.0 5.0 5.0 5.0	5.0	4.0	Early Mature	Poor	Die-back - Throughout crown. On neighbouring land.	191.1	7.8	20-40	C	1
T2357	1	*Fraxinus excelsior* Ash	8.0	1	75	N E S W 4.0 4.0 2.0 2.0	4.0	4.0	Early Mature	Poor	Top has snapped out in recent storm. Flailed on road side.	254.5	9.0	10-20	C	1
T2358	1	*Fraxinus excelsior* Ash	13.0	1	60	N E S W 4.0 4.0 4.0 3.0	4.0	3.0	Early Mature	Fair	Chalara (ash dieback) present. Moderate symptoms.	162.9	7.2	10-20	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2359	1	*Salix cinerea* Grey Sallow	9.0	1	50	N E S W 3.0 3.0 3.0 3.0	3.0	3.0	Early Mature	Fair	Access to inspect base - Not possible. Pollard - Regrown. On neighbouring land (garden).	113.1	6.0	20-40	C	1
T2360	1	*Quercus robur* English Oak	9.0	1	75	N E S W 8.0 8.0 7.0 7.0	4.0	2.0	Mature	Good		254.5	9.0	40+	B	1
H2361	25	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown.	4.5	1.2	40+	C	2
T2362	1	*Fraxinus excelsior* Ash	16.0	2	77	N E S W 8.0 7.0 10.0 8.0	6.0	4.0	Mature	Fair	Chalara (ash dieback) present. Minor symptoms. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	273.7	9.3	20-40	B	1
T2363	1	*Fraxinus excelsior* Ash	11.0	2	43	N E S W 5.0 5.0 6.0 4.0	6.0	3.0	Semi Mature	Fair	Epicormic growth - Base / bole / principal stems. Chalara (ash dieback) present. Minor symptoms. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	83.7	5.2	20-40	C	1
H2364	10	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	10	N E S W 1.5 1.5 1.5 1.5	0.0	0.0	Early Mature	Fair	Hedgerow - Neglected / overgrown. Gappy. **Fell - Ground level.** Remove a 18-m span. To facilitate development.	4.5	1.2	20-40	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2365	1	*Salix fragilis* Crack Willow	6.0	1	120	N E S W 1.0 0.5 8.0 3.0	0.0	0.0	Mature	Poor	Decay / structural defect - Extensive. Decay / structural defect - Open cavity / cavities. Fallen tree / trees - Partial collapse. Tree has recently collapsed. **Fell - Ground level.** To facilitate development.			0-10	U	
G2366	3	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	1	25	N E S W 2.0 2.0 2.0 2.0	1.0	0.0	Early Mature	Good	Hedge remnant.	28.3	3.0	40+	C	1
T2367	1	*Fraxinus excelsior* Ash	16.0	1	73	N E S W 8.0 7.0 11.0 8.0	5.0	2.0	Early Mature	Fair	Chalara (ash dieback) present. Moderate symptoms. One half of crown failed historically. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	241.1	8.8	10-20	C	1
T2368	1	*Quercus robur* English Oak	15.0	1	60	N E S W 7.0 7.0 7.0 6.0	7.0	5.0	Early Mature	Good	On neighbouring land (garden).	162.9	7.2	40+	B	1
T2369	1	*Fraxinus excelsior* Ash	16.0	1	75	N E S W 7.0 9.0 7.0 7.0	5.0	2.0	Early Mature	Fair	Chalara (ash dieback) present. Moderate symptoms. One half of crown failed historically.	254.5	9.0	10-20	C	1
H2370	5	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	10	N E S W 1.5 1.5 1.5 1.5	0.0	0.0	Early Mature	Fair	Hedge remnant. **Fell - Ground level.** Remove a 8-m span. To facilitate development.	4.5	1.2	20-40	C	2
H2371	20	*Crataegus monogyna* Common Hawthorn/Quick/May	1.0	1	10	N E S W 0.5 0.5 0.5 0.5	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** Remove a 22-m span. To facilitate development.	4.5	1.2	40+	C	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2372	20 15 10 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Swida sanguinea* Common Dogwood *Ulmus sp.* Elm sp. *Ligustrum ovalifolium* Privet/Garden Privet	1.5	1	10	N E S W 0.5 0.5 0.5 0.5	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Ornamental hedge.	4.5	1.2	40+	C	2
G2373	20 20	*Salix fragilis* Crack Willow *Betula pendula* Silver Birch	8.0	1	15	N E S W 2.0 2.0 2.0 2.0	1.0	1.0	Young	Good	Shelterbelt.	10.2	1.8	40+	C	2
H2374	120	*Crataegus monogyna* Common Hawthorn/Quick/May	1.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
G2375	3	*Quercus robur* English Oak	12.0	1	65	N E S W 7.0 7.0 6.0 7.0	5.0	2.0	Mature	Good	Growing on north bank of ditch. **Reduce lateral limb / limbs.** Prune southern side back by 2-3 m. To facilitate development.	191.1	7.8	40+	B	1 2
G2376	6	*Alnus glutinosa* Common Alder	15.0	1	45	N E S W 4.0 4.0 4.0 4.0	5.0	3.0	Early Mature	Good	Growing on south bank of ditch.	91.6	5.4	40+	B	2
T2377	1	*Alnus glutinosa* Common Alder	11.0	3	80	N E S W 3.0 4.0 4.0 4.0	5.0	2.0	Early Mature	Good	Growing on south bank of ditch.	296.3	9.7	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2378	20	*Crataegus monogyna* Common Hawthorn/Quick/May	1.0	1	10	N 0.5 E 0.5 S 0.5 W 0.5	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Gappy.	4.5	1.2	20-40	C	2
T2379	1	*Fraxinus excelsior* Ash	11.0	8	56	N 3.0 E 3.0 S 3.0 W 3.0	5.0	4.0	Semi Mature	Good	Multi-stemmed. Growing on south bank of ditch.	144.8	6.8	40+	C	2
H2380	15	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	10	N 1.0 E 1.5 S 1.8 W 1.5	0.0	0.0	Early Mature	Fair	Flailed.	4.5	1.2	20-40	C	2
H2381	15	*Crataegus monogyna* Common Hawthorn/Quick/May	1.5	1	5	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. Hedge remnant.	1.1	0.6	40+	C	2
T2382	1	*Quercus robur* English Oak	12.0	1	50	N 6.0 E 6.0 S 7.0 W 6.0	4.0	2.0	Early Mature	Good	Pollard - Regrown.	113.1	6.0	40+	B	1
T2383	1	*Sambucus nigra* Elder	5.0	5	33	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Mature	Fair		50.9	4.0	20-40	C	1
T2384	1	*Acer pseudoplatanus* Sycamore	8.0	1	31	N 2.5 E 2.5 S 2.5 W 2.5	3.0	2.0	Semi Mature	Good	Planted in highway verge.	43.5	3.7	40+	C	1
T2385	1	*Fraxinus excelsior* Ash	9.0	1	43	N 4.0 E 4.0 S 4.0 W 4.0	4.0	1.0	Early Mature	Good	Planted in highway verge.	83.6	5.2	40+	C	1
T2386	1	*Fraxinus excelsior* Ash	10.0	1	48	N 4.0 E 4.0 S 4.0 W 4.0	4.0	1.0	Early Mature	Fair	Planted in highway verge. Chalara (ash dieback) present. Minor symptoms.	104.2	5.8	20-40	C	1
T2387	1	*Fraxinus excelsior* Ash	11.0	1	48	N 3.0 E 3.0 S 3.0 W 3.0	4.0	3.0	Early Mature	Fair	Planted in highway verge. Chalara (ash dieback) present. Minor symptoms.	104.2	5.8	20-40	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2388	1	*Cupressocyparis leylandii* Leyland Cypress	11.0	1	90	N E S W 5.0 5.0 5.0 5.0	3.0	2.5	Mature	Fair	Topped. Growing in cemetery. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	366.4	10.8	40+	C	1
T2389	1	*Cupressocyparis leylandii* Leyland Cypress	11.0	1	90	N E S W 4.0 4.0 3.0 3.0	3.0	2.5	Mature	Fair	Topped. Growing in cemetery.	366.4	10.8	40+	C	1
T2390	1	*Tilia x vulgaris* Common Lime	10.0	1	75	N E S W 5.0 5.0 5.0 5.0	3.0	1.5	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Growing in cemetery.	254.5	9.0	40+	B	1 2
T2391	1	*Tilia x vulgaris* Common Lime	10.0	2	71	N E S W 5.0 5.0 5.0 5.0	3.0	1.5	Early Mature	Good	Epicormic growth - Base / bole / principal stems. Growing in cemetery.	231.3	8.6	40+	B	1 2
G2392	3 1	*Quercus robur* English Oak *Fraxinus excelsior* Ash	12.0	1	65	N E S W 5.0 5.0 5.0 5.0	5.0	4.0	Mature	Good	Growing on west bank of ditch.	191.1	7.8	40+	B	1 2
G2393	60 30 10 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Acer pseudoplatanus* Sycamore *Quercus robur* English Oak *Fraxinus excelsior* Ash	16.0	1	40	N E S W 4.0 4.0 4.0 4.0	5.0	3.0	Early Mature	Good	Growing on east side of ditch. Measurements represent average for larger trees in group. Flailed to west. Hawthorn hedge beneath.	72.4	4.8	40+	B	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2394	1	*Quercus robur* English Oak	12.0	1	75	N E S W 5.0 5.0 5.0 5.0	5.0	3.0	Mature	Good	Growing on west bank of ditch.	254.5	9.0	40+	B	1
T2395	1	*Quercus robur* English Oak	8.0	1	100	NW NE SE SW 2.0 1.0 2.0 3.0	3.0	3.0	Mature	Good	Growing on west bank of ditch. Large bough carrying most of the crown has recently failed, leaving large scar.	452.4	12.0	40+	C	1
T2396	1	*Taxus baccata* Yew	8.0	1	45	N E S W 3.0 1.0 2.0 3.0	6.0	5.0	Early Mature	Good	On neighbouring land (garden). Pruned back to boundary on road side.	91.6	5.4	40+	C	1
T2397	1	*Taxus baccata* Yew	8.0	1	45	N E S W 3.0 1.0 2.0 3.0	6.0	5.0	Early Mature	Good	On neighbouring land (garden). Pruned back to boundary on road side.	91.6	5.4	40+	C	1
T2398	1	*Acer pseudoplatanus* Sycamore	6.0	1	25	N E S W 2.5 2.5 2.5 2.5	3.0	2.0	Semi Mature	Good	On neighbouring land (garden).	28.3	3.0	40+	C	1
G2399	2 1 1	*Syringa vulgaris* Common Lilac *Malus sp.* Apple sp. *Cerasus avium* Wild Cherry	6.0	3	45	N E S W 1.0 2.5 2.5 2.5	2.0	2.0	Early Mature	Fair	On neighbouring land (garden). Pruned back to boundary on road side.	92.0	5.4	20-40	C	1
T2400	1	*Acer pseudoplatanus* Sycamore	8.0	1	25	N E S W 2.5 2.5 2.5 2.5	2.0	1.5	Semi Mature	Good	Natural regeneration.	28.3	3.0	40+	C	1
H2401	10	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N E S W 10.0 10.0 10.0 10.0	0.0	0.0	Semi Mature	Good	Hedgerow - Neglected / overgrown. Growing on North bank of ditch.	4.5	1.2	40+	C	2
T2402	1	*Taxus baccata* Yew	3.0	1	5	N E S W 0.5 0.5 0.5 0.5	1.5	1.5	Young	Fair	Staked tree / trees. Young planted tree / trees.	1.1	0.6	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2403	1	*Cerasus avium* Wild Cherry	4.0	1	5	N 1.0 E 1.0 S 1.0 W 1.0	1.5	1.5	Young	Fair	Staked tree / trees. Young planted tree / trees.	1.1	0.6	40+	C	1
T2404	1	*Cerasus avium* Wild Cherry	4.0	1	5	N 1.0 E 1.0 S 1.0 W 1.0	1.5	1.5	Young	Fair	Die-back - Upper crown. Staked tree / trees. Young planted tree / trees.	1.1	0.6	40+	C	1
T2405	1	*Betula pendula* Silver Birch	3.0	1	5	N 1.0 E 1.0 S 1.0 W 1.0	1.5	1.5	Young	Fair	Staked tree / trees. Young planted tree / trees.	1.1	0.6	40+	C	1
T2406	1	*Quercus robur* English Oak	15.0	1	90	N 8.0 E 8.0 S 8.0 W 8.0	5.0	2.0	Mature	Good	Pollard - Lapsed / Mature stems. Growing on East Bank of ditch. Low branches on road side pruned off. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	366.4	10.8	40+	B	1
T2407	1	*Quercus robur* English Oak	12.0	1	45	N 5.0 E 5.0 S 5.0 W 5.0	5.0	5.0	Early Mature	Good	Growing on East bank of ditch.	91.6	5.4	40+	B	1
G2408	2	*Quercus robur* English Oak	10.0	1	40	N 4.0 E 4.0 S 4.0 W 4.0	4.0	5.0	Early Mature	Good		72.4	4.8	40+	C	1
T2409	1	*Quercus robur* English Oak	12.0	1	90	N 7.0 E 7.0 S 7.0 W 7.0	5.0	4.0	Mature	Good	Epicormic growth - Base / bole / principal stems. Growing on East bank of ditch. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	366.4	10.8	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2410	1	*Fraxinus excelsior* Ash	12.0	1	70	N 7.0 E 7.0 S 5.0 W 7.0	5.0	4.0	Mature	Fair	Epicormic growth - Base / bole / principal stems. Growing on East bank of ditch. Chalara (ash dieback) present. Moderate symptoms. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	221.7	8.4	10-20	C	1
T2411	1	*Quercus robur* English Oak	12.0	1	50	N 7.0 E 7.0 S 7.0 W 7.0	4.0	2.5	Early Mature	Good	Growing on East bank of ditch. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	113.1	6.0	40+	B	1
T2412	1	*Quercus robur* English Oak	10.0	1	80	N 5.0 E 5.0 S 5.0 W 5.0	4.0	2.5	Mature	Good	Growing on East bank of ditch. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	289.5	9.6	40+	B	1
T2413	1	*Quercus robur* English Oak	10.0	1	60	N 7.0 E 7.0 S 7.0 W 7.0	5.0	4.0	Early Mature	Good	Growing on East bank of ditch. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	162.9	7.2	40+	B	1
T2414	1	*Quercus robur* English Oak	8.0	1	50	NW 4.0 NE 4.0 SE 3.0 SW 4.0	4.0	2.0	Early Mature	Good	Growing on West bank of ditch.	113.1	6.0	40+	B	1
H2415	200	*Crataegus monogyna* Common Hawthorn/Quick/May	1.5	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
T2416	1	*Fraxinus excelsior* Ash	13.0	1	35	N 3.0 E 5.0 S 4.0 W 4.0	0.5	1.0	Semi Mature	Fair	Chalara (ash dieback) present. Minor symptoms. Growing on North Bank of ditch.	55.4	4.2	10-20	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2417	1	*Fraxinus excelsior* Ash	13.0	5	33	N 1.5 E 3.0 S 3.0 W 3.0	0.5	1.0	Semi Mature	Fair	Chalara (ash dieback) present. Minor symptoms. Growing on North Bank of ditch.	50.9	4.0	10-20	C	1
H2418	5 3	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Fair	Hedge remnant.	4.5	1.2	20-40	C	2
H2419	3	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	3	17	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Early Mature	Good	Growing on North bank of ditch. Deadwood over low target area. Hedge remnant.	13.6	2.1	40+	C	2
T2420	1	*Quercus robur* English Oak	9.0	1	35	N 6.0 E 6.0 S 6.0 W 4.0	4.0	1.5	Semi Mature	Good	Growing on east bank of ditch.	55.4	4.2	40+	C	1
T2421	1	*Acer pseudoplatanus* Sycamore	9.0	7	39	N 4.0 E 3.0 S 4.0 W 2.0	4.0	2.5	Semi Mature	Good	Growing on east bank of ditch.	71.3	4.8	40+	C	1
T2422	1	*Quercus robur* English Oak	9.0	1	40	N 6.0 E 6.0 S 6.0 W 6.0	4.0	3.0	Semi Mature	Good	Growing on east bank of ditch.	72.4	4.8	40+	C	1
H2423	20 10	*Prunus spinosa* Blackthorn/Sloe *Acer pseudoplatanus* Sycamore	1.5	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Fair	Hedgerow - Maintained. Gappy.	4.5	1.2	20-40	C	1
T2424	1	*Quercus robur* English Oak	14.0	1	45	N 6.0 E 6.0 S 6.0 W 6.0	2.0	2.0	Early Mature	Good	On neighbouring land (garden).	91.6	5.4	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2425	25 15 1	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Acer pseudoplatanus* Sycamore	2.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
G2426	3 1	*Fraxinus excelsior* Ash *Crataegus monogyna* Common Hawthorn/Quick/May	17.0	3	60	N E S W 4.0 4.0 4.0 4.0	5.0	4.0	Early Mature	Fair	Chalara (ash dieback) present. Minor symptoms. On neighbouring land (garden).	166.3	7.3	20-40	B	2
T2427	1	*Salix x sepulcralis* Weeping Willow	16.0	1	60	N E S W 10.0 9.0 10.0 10.0	5.0	2.0	Early Mature	Good	Growing on highway verge. Ownership uncertain.	162.9	7.2	40+	B	1
T2428	1	*Salix x sepulcralis* Weeping Willow	16.0	1	85	N E S W 10.0 10.0 9.0 12.0	5.0	4.0	Early Mature	Good	Branch - Suspended. Growing on highway verge. Ownership uncertain. Pruned back over road to 5.5 m	326.9	10.2	40+	B	1
G2429	4 1	*Acer pseudoplatanus* Sycamore *Quercus robur* English Oak	12.0	1	35	N E S W 4.0 4.0 4.0 4.0	3.0	2.0	Semi Mature	Good		55.4	4.2	40+	C	2
H2430	25	*Crataegus monogyna* Common Hawthorn/Quick/May	1.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2431	10 10 5 5 1	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Quercus robur* English Oak *Fraxinus excelsior* Ash *Salix caprea* Goat Willow/Great Sallow	5.0	1	10	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Semi Mature	Fair	Hedgerow - Neglected / overgrown. Gappy.	4.5	1.2	20-40	C	2
H2432	3	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	1	20	N 2.0 E 2.0 S 2.0 W 2.0	1.0	1.0	Early Mature	Fair	Hedge remnant. **Fell - Ground level.** To facilitate development.	18.1	2.4	20-40	C	2
G2433	10	*Populus x canadensis* Hybrid Black Poplars	13.0	1	20	N 2.0 E 2.0 S 2.0 W 2.0	1.0	1.0	Young	Good	No access; surveyed from afar.	18.1	2.4	40+	C	2
T2434	1	*Fraxinus excelsior* Ash	13.0	2	49	N 5.0 E 5.0 S 5.0 W 5.0	5.0	3.0	Early Mature	Good	Epicormic growth - Base / bole / principal stems. No access, surveyed from afar.	110.8	5.9	40+	B	1
T2435	1	*Fraxinus excelsior* Ash	13.0	5	67	N 5.0 E 5.0 S 5.0 W 5.0	4.0	3.0	Early Mature	Fair	Epicormic growth - Base / bole / principal stems. Multi-stemmed. No access, surveyed from afar. Chalara (ash dieback) present. Moderate symptoms.	203.6	8.0	10-20	C	1
T2436	1	*Quercus robur* English Oak	15.0	1	45	N 5.0 E 5.0 S 5.0 W 5.0	4.0	4.0	Early Mature	Good	Epicormic growth - Base / bole / principal stems. No access, surveyed from afar.	91.6	5.4	10-20	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2437	1	*Sorbus intermedia* Swedish Whitebeam	6.0	1	35	N 2.0 E 2.0 S 2.0 W 2.0	1.5	1.0	Early Mature	Good	On neighbouring land.	55.4	4.2	40+	C	1
T2438	1	*Sorbus intermedia* Swedish Whitebeam	6.0	1	35	N 2.0 E 2.0 S 2.0 W 2.0	1.5	1.0	Early Mature	Good	On neighbouring land.	55.4	4.2	40+	C	1
T2439	1	*Sorbus intermedia* Swedish Whitebeam	6.0	1	35	N 2.0 E 2.0 S 2.0 W 2.0	1.5	1.0	Early Mature	Good	On neighbouring land.	55.4	4.2	40+	C	1
T2440	1	*Sorbus intermedia* Swedish Whitebeam	6.0	1	35	N 2.0 E 2.0 S 2.0 W 2.0	1.5	1.0	Early Mature	Good	On neighbouring land.	55.4	4.2	40+	C	1
T2441	1	*Sorbus intermedia* Swedish Whitebeam	6.0	1	35	N 2.0 E 2.0 S 2.0 W 2.0	1.5	1.0	Early Mature	Good	On neighbouring land.	55.4	4.2	40+	C	1
T2442	1	*Sorbus intermedia* Swedish Whitebeam	6.0	1	35	N 2.0 E 2.0 S 2.0 W 2.0	1.5	1.0	Early Mature	Good	Bark wound - Major. Bark wound - Mechanical. On neighbouring land.	55.4	4.2	40+	C	1
G2443	2	*Salix fragilis* Crack Willow	12.0	1	30	N 6.0 E 6.0 S 6.0 W 6.0	1.0	2.0	Semi Mature	Good	On neighbouring land (garden).	40.7	3.6	40+	C	1
G2444	2 2	*Fraxinus excelsior* Ash *Castanea sativa* Sweet Chestnut	12.0	1	30	N 5.0 E 5.0 S 5.0 W 5.0	1.0	1.0	Early Mature	Good	On neighbouring land (garden). Measurements represent average for larger trees in group.	40.7	3.6	40+	C	1
H2445	20	*Cupressocyparis leylandii* Leyland Cypress	4.0	1	15	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Young	Good	Ornamental hedge.	10.2	1.8	40+	C	2
T2446	1	*Acer pseudoplatanus* Sycamore	18.0	1	50	N 6.0 E 6.0 S 6.0 W 6.0	5.0	3.0	Early Mature	Good		113.1	6.0	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2447	1	*Acer pseudoplatanus* Sycamore	18.0	1	50	N 5.0 E 5.0 S 5.0 W 5.0	5.0	5.0	Early Mature	Good		113.1	6.0	40+	B	1
T2448	1	*Sambucus nigra* Elder	6.0	3	25	N 1.0 E 1.0 S 1.0 W 1.0	2.0	1.5	Early Mature	Poor	Branch - Broken.			0-10	U	
T2449	1	*Acer pseudoplatanus* Sycamore	16.0	3	63	N 7.0 E 7.0 S 7.0 W 7.0	4.0	3.0	Early Mature	Fair	Sparse crown. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	183.2	7.6	10-20	C	1
T2450	1	*Acer pseudoplatanus* Sycamore	3.0	1	35	N 0.0 E 0.0 S 0.0 W 0.0	3.0	3.0	Early Mature	Poor	Epicormic growth - Base. Stump / stumps.			0-10	U	
T2451	1	*Acer pseudoplatanus* Sycamore	9.0	2	15	N 2.0 E 2.0 S 2.0 W 2.0	2.0	2.0	Young	Good		11.0	1.9	40+	C	1
T2452	1	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	1	20	N 2.0 E 3.0 S 2.0 W 3.0	0.0	0.0	Early Mature	Good		18.1	2.4	40+	C	1
T2453	1	*Corylus avellana* Common Hazel	3.0	20	8	N 1.0 E 2.0 S 1.0 W 2.0	0.0	0.0	Semi Mature	Good	Coppice stool - Regrown.	3.6	1.1	40+	C	1
T2454	1	*Fagus sylvatica f. purpurea* Purple Beech	9.0	1	55	N 6.0 E 6.0 S 6.0 W 6.0	3.0	2.5	Early Mature	Good	On neighbouring land (garden).	136.8	6.6	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2455	50 1	*Corylus avellana* Common Hazel *Prunus cerasifera* Cherry Plum (Myrobalan)	2.0	10	9	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. **Reduce lateral limb / limbs.** Prune northern side back by c. 1 m. To facilitate development. **Fell - Coppice.** Coppice hazel.	4.1	1.1	40+	C	2
H2456	5 4 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder *Corylus avellana* Common Hazel	1.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good		4.5	1.2	40+	C	2
T2457	1	*Cerasus serrulata* Japanese Cherry	6.0	1	45	NW NE SE SW 3.0 4.0 5.0 6.0	3.0	1.0	Early Mature	Fair	Topped. Growing on highway verge.	91.6	5.4	20-40	C	1
T2458	1	*Quercus robur* English Oak	11.0	1	50	N E S W 5.0 5.0 5.0 5.0	3.0	4.0	Early Mature	Good		113.1	6.0	40+	B	1
H2459	50 5	*Prunus spinosa* Blackthorn/Sloe *Swida sanguinea* Common Dogwood	2.5	1	5	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Young	Good	Hedgerow - Neglected / overgrown. **Fell - Ground level.** To facilitate development.	1.1	0.6	40+	C	2
T2460	1	*Fraxinus excelsior* Ash	15.0	2	39	N E S W 3.0 3.0 3.0 3.0	4.0	4.0	Semi Mature	Fair	Chalara (ash dieback) present. Moderate symptoms. **Fell - Ground level.** To facilitate development.	69.0	4.7	20-40	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2461	1	*Fraxinus excelsior* Ash	11.0	1	45	N 4.0 E 4.0 S 4.0 W 4.0	4.0	4.0	Semi Mature	Fair	Chalara (ash dieback) present. Moderate symptoms.	91.6	5.4	20-40	C	1
G2462	20	*Salix caprea* Goat Willow/Great Sallow	7.0	1	25	N 3.0 E 3.0 S 3.0 W 3.0	0.0	1.0	Semi Mature	Good	Shelterbelt. Does not overhang track.	28.3	3.0	40+	C	2
	20	*Prunus spinosa* Blackthorn/Sloe														
	20	*Crataegus monogyna* Common Hawthorn/Quick/May														
	15	*Fraxinus excelsior* Ash														
	5	*Sambucus nigra* Elder														
	5	*Malus x soulardii* Crab Apple														
H2463	30	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	1	25	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Mature	Fair	Hedgerow - Neglected / overgrown. Does not overhang track.	28.3	3.0	40+	B	2
	10	*Fraxinus excelsior* Ash														
	5	*Sambucus nigra* Elder														
	1	*Salix caprea* Goat Willow/Great Sallow														

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2464	25 5 2 1 1	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Malus sylvestris* Wild Crab *Fraxinus excelsior* Ash *Sambucus nigra* Elder	5.0	1	15	N 1.5 E 1.5 S 1.5 W 1.5	0.0	0.0	Early Mature	Good	Hedgerow - Neglected / overgrown.	10.2	1.8	40+	B	2
W2465	150 50 50	*Fraxinus excelsior* Ash *Pinus sylvestris* Scots Pine *Quercus robur* English Oak	18.0	1	50	N 6.0 E 6.0 S 6.0 W 6.0	1.0	1.0	Early Mature	Good	.No access; surveyed from afar. Everything estimated. Likely a plantation.	113.1	6.0	40+	B	2 3
G2466	3 1	*Acer pseudoplatanus* Sycamore *Fraxinus excelsior* Ash	18.0	1	55	N 5.0 E 5.0 S 5.0 W 5.0	5.0	4.0	Early Mature	Good	Epicormic growth - Base.	136.8	6.6	40+	B	2
H2467	20	*Crataegus monogyna* Common Hawthorn/Quick/May	1.0	1	10	N 0.5 E 0.5 S 0.5 W 0.5	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. Hedge remnant. **Fell - Ground level.** To facilitate development.	4.5	1.2	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2468	1	*Fraxinus excelsior* Ash	16.0	1	70	N E S W 6.0 4.0 4.0 4.0	5.0	5.0	Mature	Fair	Chalara (ash dieback) present. Minor symptoms.	221.7	8.4	20-40	B	1
H2469	50	*Crataegus monogyna* Common Hawthorn/Quick/May	1.0	1	3	N E S W 0.5 0.5 0.5 0.5	0.0	0.0	Young	Good		0.4	0.4	40+	C	2
T2470	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	10	N E S W 1.0 1.0 1.0 1.0	1.0	1.0	Young	Good		4.5	1.2	40+	C	1
H2471	250 50 25 10	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Rosa canina* Dog-rose *Acer pseudoplatanus* Sycamore	1.0	1	10	N E S W 0.5 0.5 0.5 0.5	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
T2472	1	*Fraxinus excelsior* Ash	15.0	5	44	N E S W 6.0 6.0 6.0 6.0	6.0	7.0	Early Mature	Fair	Chalara (ash dieback) present. Minor symptoms.	90.5	5.4	20-40	C	1
T2473	1	*Fraxinus excelsior* Ash	15.0	3	34	N E S W 6.0 6.0 6.0 6.0	6.0	7.0	Early Mature	Fair	Chalara (ash dieback) present. Minor symptoms.	54.3	4.2	20-40	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2474	5 5 5	*Ulmus procera* English Elm *Swida sanguinea* Common Dogwood *Crataegus monogyna* Common Hawthorn/Quick/May	5.0	1	15	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.0	Early Mature	Good	Dutch elm disease. Some dead elm.	10.2	1.8	40+	C	2
G2475	4	*Salix fragilis* Crack Willow	17.0	2	49	N 6.0 E 6.0 S 6.0 W 6.0	2.0	2.0	Early Mature	Good	Growing at bottom of bank. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	110.8	5.9	40+	C	2
G2476	10 5 3 3	*Crataegus monogyna* Common Hawthorn/Quick/May *Fraxinus excelsior* Ash *Sambucus nigra* Elder *Salix fragilis* Crack Willow	6.0	1	15	N 2.0 E 2.0 S 2.0 W 2.0	0.0	1.0	Semi Mature	Good	**Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	10.2	1.8	40+	C	2
T2477	1	*Fraxinus excelsior* Ash	18.0	1	95	N 7.0 E 8.0 S 9.0 W 8.0	5.0	5.0	Mature	Poor	Base / stems obscured - Vegetation. Die-back - Throughout crown. Deadwood - Major. Chalara (ash dieback) present. Moderate symptoms. Growing on south bank of ditch. Pruned back from road.	408.3	11.4	10-20	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
W2478	100 50 50 50	*Fraxinus excelsior* Ash *Salix fragilis* Crack Willow *Quercus robur* English Oak *Acer campestre* Field Maple	16.0	1	20	N E S W 3.0 3.0 3.0 3.0	4.0	4.0	Semi Mature	Good		18.1	2.4	40+	B	2
T2479	1	*Salix caprea* Goat Willow/Great Sallow	9.0	10	79	NW NE SE SW 12.1 6.0 8.0 8.0	1.0	0.5	Early Mature	Good		282.7	9.5	40+	C	2
G2480	3 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Pyrus communis* Garden Pear	5.0	1	15	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Semi Mature	Good		10.2	1.8	40+	C	2
T2481	1	*Prunus cerasifera* Cherry Plum (Myrobalan)	5.0	1	12	N E S W 2.0 2.0 2.0 2.0	0.5	0.5	Young	Good		6.5	1.4	40+	C	1
G2482	6	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	15	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Semi Mature	Good		10.2	1.8	40+	C	2
H2483	100	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	8	N E S W 1.0 1.0 1.0 1.0	0.5	0.5	Semi Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** Remove a 115-m span. To facilitate development.	2.9	1.0	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2484	1	*Quercus robur* English Oak	12.0	1	40	N 4.0 E 4.0 S 4.0 W 3.0	0.0	0.5	Early Mature	Good	Growing on highway embankment. Inaccessible. Measurements estimated.	72.4	4.8	40+	C	1
T2485	1	*Quercus robur* English Oak	5.0	1	20	N 2.0 E 2.0 S 2.0 W 2.0	1.5	1.0	Young	Good		18.1	2.4	40+	C	1
T2486	1	*Tilia platyphyllos* Large Leaved Lime	6.0	1	25	N 2.0 E 2.0 S 2.0 W 2.0	0.5	1.0	Semi Mature	Good		28.3	3.0	40+	C	1
T2487	1	*Tilia platyphyllos* Large Leaved Lime	5.0	1	20	N 2.0 E 2.0 S 2.0 W 2.0	0.0	0.5	Young	Good		18.1	2.4	40+	C	1
T2488	1	*Quercus robur* English Oak	8.0	1	30	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Semi Mature	Good		40.7	3.6	40+	B	1
T2489	1	*Quercus robur* English Oak	4.0	1	16	N 2.0 E 2.0 S 2.0 W 2.0	1.5	2.0	Young	Good	Access to inspect base - Not possible. Base / stems obscured - Structure. Young planted tree / trees. DBH estimated due to dense vegetation. **Fell - Ground level.** To facilitate development.	11.6	1.9	20-40	C	1
T2490	1	*Quercus robur* English Oak	11.0	1	70	N 7.0 E 7.0 S 5.0 W 7.0	4.0	2.0	Early Mature	Good	Pollard - Lapsed / Mature stems.	221.7	8.4	40+	B	1
T2491	1	*Fraxinus excelsior* Ash	10.0	4	40	N 3.0 E 3.0 S 3.0 W 3.0	0.0	1.0	Early Mature	Fair	Base / stems obscured - Vegetation. Chalara (ash dieback) present. Minor symptoms. **Fell - Ground level.** To facilitate development.	72.4	4.8	20-40	C	1
T2492	1	*Pyrus sp.* Pear sp.	7.0	5	44	N 3.0 E 3.0 S 3.0 W 3.0	3.0	3.0	Early Mature	Good	Multi-stemmed.	90.5	5.4	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2493	1	*Fraxinus excelsior* Ash	13.0	7	52	N E S W 5.0 5.0 5.0 1.5	4.0	2.0	Early Mature	Good	Coppice stool - Coppice origin / Mature stems. Pruned back from road edge,.	126.7	6.3	40+	C	1
G2494	2 1	*Acer campestre* Field Maple *Corylus avellana* Common Hazel	10.0	10	47	N E S W 3.0 3.0 3.0 3.0	1.0	1.0	Early Mature	Good	Multi-stemmed.	101.8	5.7	40+	C	2
T2495	1	*Quercus robur* English Oak	11.0	1	35	N E S W 6.0 3.0 6.0 6.0	4.0	2.5	Early Mature	Good	**Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	55.4	4.2	40+	B	1
H2496	50 20 10	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus spinosa* Blackthorn/Sloe *Corylus avellana* Common Hazel	2.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained. c. 3 m tall at northern end. **Fell - Ground level.** To facilitate development.	4.5	1.2	40+	C	2
T2497	1	*Fraxinus excelsior* Ash	10.0	1	35	N E S W 4.0 4.0 4.0 4.0	3.0	2.0	Early Mature	Fair	Base / stems obscured - Vegetation. Chalara (ash dieback) present. Minor symptoms.	55.4	4.2	20-40	C	1
T2498	1	*Quercus robur* English Oak	12.0	1	40	N E S W 6.0 6.0 5.0 6.0	2.0	2.5	Early Mature	Good	Access to inspect base - Not possible. Base / stems obscured - Vegetation. Dense crown. Epicormic growth - Crown. Ivy or climbing plant. DBH estimated due to dense vegetation.	72.4	4.8	20-40	B	1 2
T2499	1	*Quercus robur* English Oak	10.0	1	45	N E S W 4.0 5.0 5.0 5.0	3.0	1.0	Early Mature	Good		91.6	5.4	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G2500	2 1	*Fraxinus excelsior* Ash *Corylus avellana* Common Hazel	8.0	6	48	N E S W 3.0 3.0 3.0 3.0	0.0	0.0	Early Mature	Good	Multi-stemmed.	108.6	5.9	40+	C	2
T2501	1	*Fraxinus excelsior* Ash	12.5	1	35	N E S W 3.0 5.0 5.0 5.0	1.5	2.0	Semi Mature	Good	Die-back - Throughout crown. Deadwood - Minor. Physiological / cambial damage - Fungal. Symptoms associated with Hymenoscyphus fraxineus (ash die-back) - Health class 1. **Fell - Ground level.** To facilitate development.	55.4	4.2	20-40	C	1
T2502	1	*Quercus robur* English Oak	11.0	1	50	N E S W 5.0 6.0 6.0 6.0	4.0	2.5	Early Mature	Good	**Fell - Ground level.** To facilitate development.	113.1	6.0	40+	B	1
T2503	1	*Quercus robur* English Oak	11.0	1	50	N E S W 4.0 5.0 5.0 5.0	4.0	2.5	Early Mature	Good	**Fell - Ground level.** To facilitate development.	113.1	6.0	40+	B	1
T2504	1	*Ilex aquifolium* Holly	6.0	5	33	N E S W 2.0 2.0 2.0 2.0	0.0	0.0	Early Mature	Fair	**Fell - Ground level.** To facilitate development.	50.9	4.0	20-40	C	1
T2505	1	*Quercus robur* English Oak	10.0	1	35	N E S W 3.0 4.0 4.0 4.0	3.0	2.5	Semi Mature	Good		55.4	4.2	40+	C	1
G2506	3	*Fraxinus excelsior* Ash	9.0	6	48	N E S W 4.0 4.0 4.0 4.0	0.0	0.0	Semi Mature	Good		108.6	5.9	40+	C	2
T2507	1	*Sambucus nigra* Elder	4.0	1	15	NW NE SE SW 2.0 2.0 1.0 2.0	0.0	0.0	Early Mature	Fair		10.2	1.8	20-40	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2508	1	*Fraxinus excelsior* Ash	9.0	6	36	NW 4.0 NE 4.0 SE 3.0 SW 4.0	0.0	0.0	Early Mature	Fair	Coppice stool - Regrown.	61.1	4.4	20-40	C	1
H2509	3	*Crataegus monogyna* Common Hawthorn/Quick/May	1.5	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. Hedge remnant.	4.5	1.2	40+	C	1
G2510	10	*Cerasus avium* Wild Cherry	8.0	1	25	N 3.0 E 3.0 S 3.0 W 3.0	1.0	1.0	Semi Mature	Good		28.3	3.0	40+	C	2
T2511	1	*Quercus rubra* Red Oak	14.0	1	30	NW 4.0 NE 4.0 SE 4.0 SW 4.0	3.0	3.0	Semi Mature	Good	On neighbouring land (garden).	40.7	3.6	40+	C	1
T2512	1	*Quercus rubra* Red Oak	14.0	1	30	N 6.0 E 3.0 S 6.0 W 6.0	3.0	1.5	Semi Mature	Good	On neighbouring land (garden).	40.7	3.6	40+	C	1
T2513	1	*Quercus rubra* Red Oak	14.0	1	30	N 4.0 E 3.0 S 4.0 W 5.0	3.0	1.5	Semi Mature	Good	On neighbouring land (garden).	40.7	3.6	40+	C	1
H2514	50	*Fagus sylvatica* Common Beech	2.0	1	6	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	On neighbouring land (garden). Ornamental hedge.	1.6	0.7	40+	C	2
T2515	1	*Quercus robur* English Oak	12.0	1	65	N 6.0 E 5.0 S 6.0 W 6.0	2.0	2.5	Early Mature	Good	On neighbouring land (garden).	191.1	7.8	40+	B	1
T2516	1	*Salix alba* White Willow	15.0	2	134	N 10.0 E 7.0 S 10.0 W 10.0	5.0	1.0	Mature	Good	Base / stems obscured - Vegetation. On neighbouring land (garden).	706.9	15.0	40+	B	1
T2517	1	*Populus x canadensis* Hybrid Black Poplars	25.0	1	50	N 7.0 E 7.0 S 7.0 W 7.0	5.0	2.0	Early Mature	Good		113.1	6.0	40+	B	1

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2518	1	*Quercus robur* English Oak	13.0	1	70	N E S W 5.0 6.0 6.0 6.0	1.0	1.0	Mature	Good	Pollard - Lapsed / Mature stems. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	221.7	8.4	40+	B	1
T2519	1	*Cerasus avium* Wild Cherry	8.0	1	41	N E S W 3.0 3.0 1.0 0.5	4.0	2.5	Semi Mature	Poor	Die-back - Throughout crown.			0-10	U	
G2520	5 4	*Acer campestre* Field Maple *Cerasus avium* Wild Cherry	8.0	1	45	N E S W 4.0 4.0 4.0 4.0	4.0	2.5	Semi Mature	Good	Growing in hedge. Measurements represent average for larger trees in group. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	91.6	5.4	40+	C	2
T2521	1	*Populus x canadensis* Hybrid Black Poplars	19.0	2	49	N E S W 5.0 5.0 5.0 5.0	6.0	3.5	Early Mature	Good	Edge specimens of linear row of poplar	110.8	5.9	40+	C	2
H2522	50	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	B	2
W2523	12	*Pinus sylvestris* Scots Pine	16.0	1	45	N E S W 4.0 4.0 4.0 4.0	4.0	5.0	Early Mature	Good	Edge specimens of linear pine plantation. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	91.6	5.4	40+	C	2
W2524	13	*Pinus sylvestris* Scots Pine	16.0	1	40	N E S W 4.0 4.0 4.0 4.0	4.0	5.0	Early Mature	Good	Edge specimens of linear pine plantation. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	72.4	4.8	40+	C	2

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2525	1	*Salix fragilis* Crack Willow	10.0	2	53	N E S W 4.0 5.0 6.0 6.0	3.0	3.0	Early Mature	Good	Pollard - Regrown. Growing in hedge.	127.8	6.4	40+	C	1
H2526	150	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	B	2
T2527	1	*Fagus sylvatica f. purpurea* Purple Beech	16.0	1	65	N E S W 7.0 7.0 7.0 9.0	1.5	2.0	Early Mature	Good	On neighbouring land.	191.1	7.8	40+	B	1
T2528	1	*Acer pseudoplatanus* Sycamore	14.0	1	35	N E S W 4.0 4.0 4.0 4.0	2.8	2.5	Early Mature	Good	On neighbouring land.	55.4	4.2	40+	C	1
G2529	1 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Salix cinerea* Grey Sallow	6.0	1	35	N E S W 3.0 3.0 3.0 3.0	1.0	1.0	Early Mature	Fair	Branch - Broken.	55.4	4.2	20-40	C	2
H2530	50 25 3	*Prunus spinosa* Blackthorn/Sloe *Crataegus monogyna* Common Hawthorn/Quick/May *Ilex aquifolium* Holly	2.0	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
T2531	1	*Acer pseudoplatanus* Sycamore	12.0	3	36	N E S W 3.0 3.0 3.0 3.0	4.0	3.0	Semi Mature	Good	**Fell - Coppice.** To facilitate development.	61.9	4.4	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G2532	8	*Acer pseudoplatanus* Sycamore	12.0	1	80	N 7.0 E 7.0 S 7.0 W 7.0	3.0		Mature	Good	On neighbouring land.	289.5	9.6	40+	A	2
T2533	1	*Acer pseudoplatanus* Sycamore	12.0	1	33	N 3.0 E 3.0 S 3.0 W 3.0	4.0	3.0	Semi Mature	Good		49.3	4.0	40+	C	1
G2534	4	*Ilex aquifolium* Holly	10.0	4	30	N 3.0 E 3.0 S 3.0 W 3.0	4.0	2.0	Semi Mature	Fair	Outgrown hedge plants. **Reduce lateral limb / limbs.** Prune eastern side back by 2 m. To facilitate development.	40.7	3.6	20-40	C	1
G2535	3 3	*Quercus robur* English Oak *Picea sitchensis* Sitka Spruce	12.0	1	50	N 4.0 E 4.0 S 4.0 W 4.0	4.0	2.0	Early Mature	Good	On neighbouring land. Inaccessible. Measurements estimated.	113.1	6.0	40+	B	2
H2536	4 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Prunus cerasifera* Cherry Plum (Myrobalan)	3.0	4	21	N 2.0 E 1.0 S 2.0 W 2.0	0.0	0.5	Mature	Poor	Die-back - Throughout crown. Ivy or climbing plant. Hedge remnant. Pruned back to road edge.	20.1	2.5	10-20	C	2
G2537	3	*Quercus robur* English Oak	10.0	5	55	N 6.0 E 6.0 S 6.0 W 6.0	3.5	2.5	Early Mature	Good	Multi-stemmed. Growing on highway embankment. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	141.4	6.7	40+	B	1 2
T2538	1	*Quercus robur* English Oak	12.0	1	65	N 5.0 E 5.0 S 5.0 W 5.0	1.5	2.0	Early Mature	Good		191.1	7.8	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2539	1	*Ilex aquifolium* Holly	10.0	1	35	N 3.0 E 3.0 S 3.0 W 3.0	4.0	2.5	Early Mature	Good	Growing in hedge.	55.4	4.2	40+	C	1
H2540	20 3 2 1	*Crataegus monogyna* Common Hawthorn/Quick/May *Ulmus sp.* Elm sp. *Corylus avellana* Common Hazel *Acer pseudoplatanus* Sycamore	3.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	C	2
T2541	1	*Ilex x altaclerensis* Highclere Holly	6.0	1	35	N 3.0 E 3.0 S 3.0 W 3.0	2.0	2.0	Early Mature	Fair	On neighbouring land (garden).	55.4	4.2	20-40	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2542	10 10 5 5 5 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Corylus avellana* Common Hazel *Salix fragilis* Crack Willow *Salix caprea* Goat Willow/Great Sallow *Quercus robur* English Oak *Ilex aquifolium* Holly	6.0	1	30	N 3.0 E 3.0 S 3.0 W 3.0	0.0	1.5	Mature	Good	Outgrown hedge. Some fallen stems.	40.7	3.6	40+	B	2
T2543	1	*Quercus robur* English Oak	18.0	1	115	N 10.0 E 10.0 S 10.0 W 10.0	5.0	4.0	Mature	Good		598.3	13.8	40+	A	1
T2544	1	*Castanea sativa* Sweet Chestnut	7.0	1	20	N 3.0 E 3.0 S 3.0 W 3.0	1.5	2.5	Young	Good	On neighbouring land (garden).	18.1	2.4	40+	C	1
T2545	1	*Fagus sylvatica* Common Beech	7.0	1	20	N 2.0 E 2.0 S 2.0 W 2.0	1.5	2.5	Young	Good	On neighbouring land (garden).	18.1	2.4	40+	C	1
G2546	8 4	*Salix caprea* Goat Willow/Great Sallow *Salix fragilis* Crack Willow	9.0	1	30	N 3.0 E 3.0 S 3.0 W 3.0	4.0	3.0	Semi Mature	Fair	Leaning trunk - Minor.	40.7	3.6	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2547	1	*Quercus robur* English Oak	12.0	1	70	N E S W 5.0 6.0 6.0 6.0	3.0	1.5	Mature	Good		221.7	8.4	20-40	B	1
G2548	6	*Quercus robur* English Oak	13.0	1	85	N E S W 6.0 10.0 10.0 10.0	6.0	4.0	Early Mature	Good		326.9	10.2	40+	B	1 2
W2549	30 20 5	*Pinus sylvestris* Scots Pine *Quercus robur* English Oak *Acer pseudoplatanus* Sycamore	14.0	1	40	NW NE SE SW 3.0 3.0 3.0 4.0	3.0	3.0	Early Mature	Good	Edge of plantation woodland. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	72.4	4.8	40+	B	2
W2550	100 5	*Pinus sylvestris* Scots Pine *Acer pseudoplatanus* Sycamore	12.0	1	25	N E S W 3.0 3.0 3.0 3.0	2.0	2.0	Semi Mature	Good	Plantation woodland.	28.3	3.0	40+	C	2
H2551	60	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good		4.5	1.2	40+	B	2
T2552	1	*Quercus robur* English Oak	14.0	1	89	N E S W 7.0 7.0 7.0 7.0	5.0	1.5	Mature	Good	Shedding limb / limbs - Historic. Shedding limb / limbs - Major. Large tearout wound on stem	358.3	10.7	40+	B	1
T2553	1	*Cerasus avium* Wild Cherry	13.0	1	35	N E S W 6.0 6.0 6.0 6.0	0.0	1.0	Early Mature	Good		55.4	4.2	40+	C	1
T2554	1	*Quercus robur* English Oak	13.0	1	35	N E S W 6.0 6.0 6.0 6.0	1.0	1.0	Early Mature	Good		55.4	4.2	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2555	50	*Crataegus monogyna* Common Hawthorn/Quick/May	2.5	1	10	N E S W 1.0 1.0 1.0 1.0	0.0	0.0	Early Mature	Good	Hedgerow - Maintained.	4.5	1.2	40+	B	2
T2556	1	*Fraxinus excelsior* Ash	11.0	1	40	N E S W 6.0 6.0 6.0 6.0	3.0	3.0	Early Mature	Fair	On neighbouring land (garden).	72.4	4.8	20-40	C	1
T2557	1	*Chamaecyparis lawsoniana* Lawson Cypress	12.0	1	35	N E S W 2.0 2.0 2.0 2.0	2.0	1.5	Early Mature	Good	On neighbouring land (garden).	55.4	4.2	40+	C	1
T2558	1	*Chamaecyparis lawsoniana* Lawson Cypress	12.0	1	35	N E S W 2.0 2.0 2.0 2.0	2.0	1.5	Early Mature	Good	On neighbouring land (garden).	55.4	4.2	40+	C	1
G2559	2 2 1 1	*Tilia cordata* Small Leaved Lime *Betula pendula* Silver Birch *Salix caprea* Goat Willow/Great Sallow *Ilex aquifolium* Holly	8.0	1	20	N E S W 3.0 3.0 3.0 3.0	0.0	0.5	Semi Mature	Good		18.1	2.4	40+	C	2
G2560	2 1	*Acer campestre* Field Maple *Prunus spinosa* Blackthorn/Sloe	8.0	2	49	N E S W 4.0 4.0 4.0 4.0	2.0	1.0	Early Mature	Good		110.8	5.9	40+	C	1
T2561	1	*Quercus robur* English Oak	15.0	1	95	N E S W 7.0 7.0 7.0 7.0	1.0	2.0	Mature	Good	No access, surveyed from afar.	408.3	11.4	40+	A	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2562	1	*Fraxinus excelsior* Ash	10.0	2	46	N 4.0 E 3.0 S 1.0 W 3.0	2.0	2.5	Semi Mature	Fair		96.1	5.5	20-40	C	1
T2563	1	*Acer campestre* Field Maple	6.0	5	44	N 3.0 E 3.0 S 3.0 W 3.0	0.5	1.0	Early Mature	Good	Coppice stool - Regrown. No access, surveyed from afar.	90.5	5.4	40+	C	1
T2564	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	15	N 1.8 E 1.8 S 1.8 W 1.8	0.5	0.5	Early Mature	Good	Hedge remnant. No access, surveyed from afar.	10.2	1.8	40+	C	1
T2565	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	1	25	N 4.0 E 4.0 S 4.0 W 4.0	1.0	1.0	Mature	Good	No access, surveyed from afar. Hedge remnant.	28.3	3.0	40+	C	1
T2566	1	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	1	25	N 3.0 E 3.0 S 3.0 W 3.0	1.0	1.0	Mature	Good	No access, surveyed from afar. Hedge remnant.	28.3	3.0	40+	C	1
T2567	1	*Crataegus monogyna* Common Hawthorn/Quick/May	7.0	1	30	N 5.0 E 5.0 S 5.0 W 5.0	0.0	0.5	Mature	Good	No access, surveyed from afar. Hedge remnant.	40.7	3.6	40+	B	1
T2568	1	*Quercus robur* English Oak	10.0	1	65	N 6.0 E 6.0 S 6.0 W 6.0	1.0	1.5	Early Mature	Good	No access, surveyed from afar.	191.1	7.8	40+	B	1
G2569	3	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	1	25	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Mature	Fair	Some storm damage. No access; surveyed from afar.	28.3	3.0	40+	C	2
G2570	3	*Fraxinus excelsior* Ash	18.0	1	65	N 8.0 E 8.0 S 8.0 W 8.0	0.0	1.0	Mature	Good	No access; surveyed from afar. Possibly just a single large tree.	191.1	7.8	40+	B	1 2
G2571	10	*Crataegus monogyna* Common Hawthorn/Quick/May	6.0	1	30	N 4.0 E 4.0 S 4.0 W 4.0	0.0	0.0	Mature	Fair	No access; surveyed from afar.	40.7	3.6	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
G2572	3	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	1	25	N 3.0 E 3.0 S 3.0 W 3.0	0.0	0.0	Mature	Fair	No access; surveyed from afar.	28.3	3.0	40+	C	2
H2573	9	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	1	25	N 2.0 E 2.0 S 2.0 W 2.0	0.5	0.5	Mature	Fair	Gappy. Hedge remnant. No access; surveyed from afar.	28.3	3.0	20-40	C	2
T2574	1	*Quercus robur* English Oak	11.0	1	55	N 6.0 E 6.0 S 6.0 W 6.0	2.0	2.0	Early Mature	Good	No access, surveyed from afar.	136.8	6.6	40+	B	1
T2575	1	*Quercus robur* English Oak	8.0	1	45	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.0	Early Mature	Good	Bark wound - Major. No access, surveyed from afar.	91.6	5.4	40+	B	1
T2576	1	*Quercus robur* English Oak	9.0	2	60	N 5.0 E 5.0 S 5.0 W 5.0	2.0	2.0	Early Mature	Good	Bark wound - Major. No access, surveyed from afar.	164.0	7.2	40+	B	1
T2577	1	*Acer campestre* Field Maple	6.0	1	30	N 2.5 E 2.5 S 2.5 W 2.5	2.0	2.0	Early Mature	Good	Stock damage. No access, surveyed from afar.	40.7	3.6	40+	C	1
T2578	1	*Acer campestre* Field Maple	7.0	2	42	N 2.5 E 2.5 S 2.5 W 2.5	2.0	2.0	Early Mature	Good	Stock damage. No access, surveyed from afar.	81.4	5.1	40+	C	1
T2579	1	*Fraxinus excelsior* Ash	7.0	1	55	N 1.0 E 1.0 S 1.0 W 1.0	5.0	5.0	Early Mature	Good	Decay / structural defect - Major. Stock damage. No access, surveyed from afar. Most of tree has failed, only tuft left.	136.8	6.6	40+	C	1
T2580	1	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	1	25	N 3.0 E 3.0 S 3.0 W 3.0	1.0	1.0	Mature	Good	No access, surveyed from afar. Hedge remnant.	28.3	3.0	40+	C	1
T2581	1	*Acer campestre* Field Maple	6.0	1	30	N 2.5 E 2.5 S 2.5 W 2.5	2.0	2.0	Early Mature	Good	Stock damage. No access, surveyed from afar.	40.7	3.6	40+	C	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2582	4	*Crataegus monogyna* Common Hawthorn/Quick/May	5.0	5	33	N 2.0 E 2.0 S 2.0 W 2.0	0.5	0.5	Mature	Fair	Multi-stemmed. Gappy. Hedge remnant. No access; surveyed from afar.	50.9	4.0	20-40	C	2
T2583	1	*Crataegus monogyna* Common Hawthorn/Quick/May	3.0	5	33	N 3.0 E 3.0 S 3.0 W 3.0	1.0	1.0	Mature	Good	Multi-stemmed. No access, surveyed from afar. Hedge remnant.	50.9	4.0	40+	C	1
H2584	25 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder	2.5	1	12	N 1.0 E 1.0 S 1.0 W 1.0	0.5	0.0	Early Mature	Good	Hedgerow - Maintained. **Fell - Ground level.** Remove a 15-m span. To facilitate development.	6.5	1.4	40+	C	2
H2585	25 5	*Crataegus monogyna* Common Hawthorn/Quick/May *Sambucus nigra* Elder	2.5	1	12	N 1.0 E 1.0 S 1.0 W 1.0	0.5	0.0	Early Mature	Good	Hedgerow - Maintained.	6.5	1.4	40+	C	2
T2586	1	*Crataegus monogyna* Common Hawthorn/Quick/May	4.0	1	25	N 2.0 E 2.0 S 2.0 W 2.0	0.5	0.5	Early Mature	Good	Hedge remnant. No access, surveyed from afar.	28.3	3.0	40+	C	1
T2587	1	*Salix alba* White Willow	20.0	6	110	N 10.0 E 10.0 S 10.0 W 10.0	2.0	1.0	Mature	Good	Multi-stemmed. Pollard - Lapsed / Mature stems. **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	549.7	13.2	40+	B	1

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2588	1	*Betula pendula* Silver Birch	17.0	1	40	NW 4.0 NE 5.0 SE 4.0 SW 4.0	4.0	2.5	Early Mature	Good	On neighbouring land (garden). **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	72.4	4.8	40+	B	1
T2589	1	*Prunus cerasifera 'Atropurpurea'* Cherry Plum (Myrobalan)	6.0	2	25	NW 2.0 NE 1.0 SE 2.0 SW 2.0	1.0	1.5	Early Mature	Good	On neighbouring land (garden). Does not overhang road.	28.3	3.0	40+	C	1
T2590	1	*Fagus sylvatica f. purpurea* Purple Beech	14.0	1	50	N 6.0 E 6.0 S 6.0 W 6.0	3.0	2.0	Early Mature	Good	One of a pair either side of junction. On neighbouring land (garden). **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	113.1	6.0	40+	B	1 2
T2591	1	*Fagus sylvatica f. purpurea* Purple Beech	14.0	1	50	N 6.0 E 6.0 S 6.0 W 6.0	3.0	1.0	Early Mature		One of a pair either side of junction. On neighbouring land (garden). **Lift low canopy - Highways clearance.** Crown raise to c. 5 m above road/access. To facilitate development.	113.1	6.0	40+	B	1 2
T2592	1	*Salix matsudana 'Tortuosa'* Corkscrew Willow	12.0	1	60	N 6.0 E 6.0 S 6.0 W 6.0	4.0	1.0	Early Mature	Good	On neighbouring land (garden).	162.9	7.2	40+	B	1
G2593	2	*Acer pseudoplatanus* Sycamore	14.0	7	52	N 4.0 E 4.0 S 4.0 W 4.0	2.0	0.0	Early Mature	Good	Base / stems obscured - Vegetation. Multi-stemmed. **Reduce lateral limb / limbs.** Prune south-eastern side back by 2 m. To facilitate development.	126.7	6.3	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
T2594	1	*Fraxinus excelsior* Ash	14.0	1	45	N 5.0 E 5.0 S 5.0 W 5.0	4.0	3.0	Early Mature	Good	Tree plotted as desktop exercise from photos supplied by project ecologist. All measurements estaimated. **Lift low canopy - Highways clearance.** Lift canopy to give 5.5 m clearance over highway.	91.6	5.4	40+	B	1
T2595	1	*Quercus robur* English Oak	9.0	1	25	N 4.0 E 4.0 S 4.0 W 4.0	2.0	2.5	Semi Mature	Good	Tree plotted as desktop exercise from photos supplied by project ecologist. All measurements estaimated. **Lift low canopy - Highways clearance.** Lift canopy to give 5.5 m clearance over highway.	28.3	3.0	40+	C	1
H2596			1.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedgerow - Maintained. Hedge plotted as desktop exercise from photos supplied by project ecologist. All measurements estaimated. Recently laid.	4.5	1.2	40+	C	2
T2597	1	*Fraxinus excelsior* Ash	16.0	1	70	NW 6.0 NE 6.0 SE 6.0 SW 3.0	6.0	5.0	Early Mature	Good	Tree plotted as desktop exercise from photos supplied by project ecologist. All measurements estaimated. Sided up on road side.	221.7	8.4	40+	B	1
H2598	15	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedge plotted as desktop exercise from photos supplied by project ecologist. All measurements estaimated.	4.5	1.2	40+	C	2
H2599	60	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedge plotted as desktop exercise from photos supplied by project ecologist. All measurements estaimated.	4.5	1.2	40+	C	2

Generated By MyTREES tree management software

Light Valley Solar
Tree Survey BS5837-2012

Treework Environmental Practice

Tree/Group Reference	Tree Count	Species	Height (m)	Stem Count	Stem Diameter (cm)	Crown Radius (m)	Crown Clearance Height (m)	Lowest Branch Height (m)	Life Stage	Physiological Condition	Observations and Recommendations	RPA (m^2)	RPR (m)	Remaining Contribution (Years)	Retention Category	Retention Sub-category
H2600	20	*Crataegus monogyna* Common Hawthorn/Quick/May	2.0	1	10	N 1.0 E 1.0 S 1.0 W 1.0	0.0	0.0	Semi Mature	Good	Hedge plotted as desktop exercise from photos supplied by project ecologist. All measurements estaimated.	4.5	1.2	40+	C	2
H2601	15	*Fagus sylvatica* Common Beech	0.5	1	3	N 0.5 E 0.5 S 0.5 W 0.5	0.0	0.0	Young	Fair	Hedge plotted as desktop exercise from photos supplied by project ecologist. All measurements estimated.	0.4	0.4	40+	C	2

Generated By MyTREES tree management software

Tree Schedule Key

Treework Environmental Practice


Tree/Group Reference	Reference number for individual trees or groups of trees, prefixed by T (Tree), G (Group), W (Woodland), H (Hedge) or S (Shrub) to indicate the type of feature.
Tree Count	Number of trees of a particular species recorded within a group feature, with the default value of 1 for single trees.
Species	Scientific name followed by common name (where available).
Height (m)	Tree height to the nearest metre, either measured with a device or estimated. Tree height for group records refers to the estimated average height of trees within the group (unrepresentative trees may be excluded from this estimate).
Stem Count	Number of stems. Stem count indicates whether the tree is single-stemmed or multi-stemmed and informs the RPA calculation.
Stem Diameter (cm)	Stem diameter, measured at 1.5m above ground level in accordance with Annex C of BS5837:2012. Diameters of multi-stemmed trees are presented as a combined stem diameter calculated in accordance with the formulae in Section 4.6.1 of BS5837:2012. Stem diameter for group records refers to the estimated average stem diameter of trees within the group (unrepresentative trees may be excluded from this estimate).
Crown Radius (m)	Distance from stem position to crown periphery in either the four cardinal or four ordinal directions, estimated to the nearest half metre. Crown spreads for group records refer to the estimated average spreads of trees within the group (unrepresentative trees may be excluded from this estimate).
Crown Clearance Height (m)	Distance between the ground and the lowest point of the crown periphery, estimated to the nearest half metre.
Lowest Branch Height (m)	Height of the lowest branch, the removal of which is considered likely to have a significant negative effect on the tree in terms of physiology or in terms of the size of wound created.
Life Stage	Young, Semi-mature, Early Mature, Mature, Late Mature, Ancient or Veteran.
Physiological Condition	Good, Fair, Poor, Dead.
Observations	General description of the tree or tree group, including basic features and morphology, structural and physiological condition, growing conditions and surroundings.
Recommendations	Management recommendations for tree works to address immediate unacceptable risks, or to facilitate development proposals.
RPA (m^2)	Minimum area around a tree deemed to contain sufficient roots and rooting soil volume to maintain the tree's viability, in which the protection of roots and soil structure is treated as a priority. Calculated from the stem diameter according to the formulae in BS5837:2012. RPA for group records is based on the estimated average stem diameter of trees within the group (unrepresentative trees may be excluded from this estimate).
RPR (m)	Radius of the RPA, in metres, when this is plotted as a circle around the tree stem.
Remaining Contribution (years)	Estimated number of years for which the tree will continue to make a positive contribution to the site, banded as < 10, 10-20, 20-40, 40 +.
Retention Category	Quality and value category (**A**, **B**, **C** or **U**) as defined in Table 1 of BS5837: 2012 (reproduced below), where **A** = high quality and value; **B** = moderate quality and value; **C** = low quality and value and **U** = tree identified for removal due to poor condition regardless of development proposals.
Retention Sub-category	One or more sub-categories (1-3) as defined in Table 1 of BS5837: 2012 (reproduced below), assigned for Categories **A**, **B** or **C** where 1 = arboricultural qualities, 2 = landscape qualities and 3 = conservation and cultural value.


Table 1 **Cascade chart for tree quality assessment**


Category and definition	Criteria (including subcategories where appropriate)			Identification on plan
Trees unsuitable for retention (see Note)				
Category U Those in such a condition that they cannot realistically be retained as living trees in the context of the current land use for longer than 10 years	• Trees that have a serious, irremediable, structural defect, such that their early loss is expected due to collapse, including those that will become unviable after removal of other category U trees (e.g. where, for whatever reason, the loss of companion shelter cannot be mitigated by pruning) • Trees that are dead or are showing signs of significant, immediate, and irreversible overall decline • Trees infected with pathogens of significance to the health and/or safety of other trees nearby, or very low quality trees suppressing adjacent trees of better quality *NOTE Category U trees can have existing or potential conservation value which it might be desirable to preserve; see 4.5.7.*			See Table 2
	1 Mainly arboricultural qualities	**2 Mainly landscape qualities**	**3 Mainly cultural values, including conservation**	
Trees to be considered for retention				
Category A **Trees of high quality** with an estimated remaining life expectancy of at least 40 years	Trees that are particularly good examples of their species, especially if rare or unusual; or those that are essential components of groups or formal or semi-formal arboricultural features (e.g. the dominant and/or principal trees within an avenue)	Trees, groups or woodlands of particular visual importance as arboricultural and/or landscape features	Trees, groups or woodlands of significant conservation, historical, commemorative or other value (e.g. veteran trees or wood-pasture)	See Table 2
Category B **Trees of moderate quality** with an estimated remaining life expectancy of at least 20 years	Trees that might be included in category A, but are downgraded because of impaired condition (e.g. presence of significant though remediable defects, including unsympathetic past management and storm damage), such that they are unlikely to be suitable for retention for beyond 40 years; or trees lacking the special quality necessary to merit the category A designation	Trees present in numbers, usually growing as groups or woodlands, such that they attract a higher collective rating than they might as individuals; or trees occurring as collectives but situated so as to make little visual contribution to the wider locality	Trees with material conservation or other cultural value	See Table 2
Category C **Trees of low quality** with an estimated remaining life expectancy of at least 10 years, or young trees with a stem diameter below 150 mm	Unremarkable trees of very limited merit or such impaired condition that they do not qualify in higher categories	Trees present in groups or woodlands, but without this conferring on them significantly greater collective landscape value; and/or trees offering low or only temporary/transient landscape benefits	Trees with no material conservation or other cultural value	See Table 2


© The British Standards Institution 2012

Annex B - Tree Protection Plan









Topographical Survey 251028_OS Master Mapping	28.10.2025
Site Layout/Design	
LVS - Draft Layout Trackers New Sub 08-10-25WIP_cleaned	28.10.2025
LVS DRAFT CableRoute	28.10.2025
LVS_DRAFT_ConstructionCompounds	28.10.2025
P6045_WIP_HDDAvoidanceArea	28.10.2025
P6045_WIP_CableAccessPoint	28.10.2025
P6045_WIP_PermissivePaths	28.10.2025
P6045_WIP_SiteAccess	28.10.2025
P6045_WIP_SiteConstructionCompounds	28.10.2025

Date:
December 2025

Scale:
1:5000 @ A0


Project Name:
Light Valley Solar

Drawing Title:
Tree Protection Plan

Drawing Number:
251209-1.1-LVS-MASTER TPP-NC

Treework Environmental Practice

Treework Environmental Practice
2nd Floor
10-12 Bourlet Close
London
W1W 7BR
Tel: 0117 244 0012
Web: www.treeworks.co.uk
Email: info@treeworks.co.uk







Topographical Survey 251028_OS Master Mapping	28.10.2025
Site Layout /Design	
LVS - Draft Layout Trackers New Sub 08-10-25WIP_cleaned	28.10.2025
LVS DRAFT CableRoute	28.10.2025
LVS_DRAFT_ConstructionCompounds	28.10.2025
P6045_WIP_HDDAvoidanceArea	28.10.2025
P6045_WIP_CableAccessPoint	28.10.2025
P6045_WIP_PermissivePaths	28.10.2025
P6045_WIP_SiteAccess	28.10.2025
P6045_WIP_SiteConstructionCompounds	28.10.2025

Date:
December 2025

Scale:
1:5000 @ A0

Project Name:
Light Valley Solar


Drawing Title:
Tree Protection Plan

Drawing Number:
251209-1.1-LVS-MASTER TPP-NC


Treework Environmental Practice

Treework Environmental Practice
2nd Floor
10-12 Bourlet Close
London
W1W 7BR

Tel: 0117 244 0012
Web: www.treeworks.co.uk
Email: info@treeworks.co.uk







Topographical Survey 251209_OS Master Mapping	28.10.2025
Site Layout/Design LVS - Draft Layout Trackers New Sub 08-10-25WIP_cleaned LVS DRAFT CableRoute LVS_DRAFT_ConstructionCompounds P6045_WIP_HDDAvoidanceArea P6045_WIP_CableAccessPoint P6045_WIP_PermissivePaths P6045_WIP_SiteAccess P6045_WIP_SiteConstructionCompounds	28.10.2025 28.10.2025 28.10.2025 28.10.2025 28.10.2025 28.10.2025 28.10.2025 28.10.2025

Date:
December 2025

Scale:
1:5000 @ A0

Project Name:
Light Valley Solar


Drawing Title:
Tree Protection Plan


Drawing Number:
251209-1.1-LVS-MASTER TPP-NC

Treework Environmental Practice

Treework Environmental Practice
2nd Floor
10-12 Bourlet Close
London
W1W 7BR

Tel: 0117 244 0012
Web: www.treeworks.co.uk
Email: info@treeworks.co.uk


N
W
E
S
T1
T2
T3
A1
A2
A3
A4
A5
A6
A7
A8
A9
A10
A11
A12
A13
A14
A15
A16
A17
A18
A19
A20
A21
A22
A23
A24
A25
A26
A27
A28
A29
A30
A31
A32
A33
A34
A35
A36
A37
A38
A39
A40



Topographical Survey 251028_OS Master Mapping	28.10.2025
Site Layout/Design LVS - Draft Layout Trackers New Sub 08-10-25WIP_cleaned LVS DRAFT CableRoute LVS_DRAFT_ConstructionCompounds P6045_WIP_HDDAvoidanceArea P6045_WIP_CableAccessPoints P6045_WIP_PermissivePaths P6045_WIP_SiteAccess P6045_WIP_SiteConstructionCompounds	28.10.2025 28.10.2025 28.10.2025 28.10.2025 28.10.2025 28.10.2025 28.10.2025 28.10.2025

Date:
December 2025

Scale:
1:5000 @ A0


Project Name:
Light Valley Solar

Drawing Title:
Tree Protection Plan

Drawing Number:
251209-1.1-LVS-MASTER TPP-NC

Treework Environmental Practice

Treework Environmental Practice
2nd Floor
10-12 Bourlet Close
London
W1W 7BR
Tel: 0117 244 0012
Web: www.treeworks.co.uk
Email: info@treeworks.co.uk



Tree or Group Reference Number

Tree Protection Fencing

Tree Stem Position A Category Tree

Initial Tree Protection Fencing

Tree Stem Position B Category Tree

Ground Protection

Tree Stem Position C Category Tree

Special Engineering /Supervised Excavations

Tree Stem Position U Category Tree

Construction Exclusion Zone

Tree Crown

Pruning/Tree Removal

Root Protection Area

Order Limits

Ancient and Veteran Tree/Ancient Woodland Buffer Zone

Topographical Survey

Design Proposals

Cable Route Line

Access Tracks

C2

Access Points

Security/Tree Protection Fencing

Access Tracks

Main Panel Area Construction Compounds

Cable Construction Compounds

Draft HDD Areas

Topographical Survey 251028_OS Master Mapping	28.10.2025
Site Layout /Design	
LVS - Draft Layout Trackers New Sub 08-10-25WIP_cleaned	28.10.2025
LVS DRAFT CableRoute	28.10.2025
LVS_DRAFT_ConstructionCompounds	28.10.2025
P6045_WIP_HDDAvoidanceArea	28.10.2025
P6045_WIP_CableAccessPoint	28.10.2025
P6045_WIP_PermissivePaths	28.10.2025
P6045_WIP_SiteAccess	28.10.2025
P6045_WIP_SiteConstructionCompounds	28.10.2025

Date:
December 2025

Scale:
1:5000 @ A0

Project Name:
Light Valley Solar


Drawing Title:
Tree Protection Plan


Drawing Number:
251209-1.1-LVS-MASTER TPP-NC

Treework Environmental Practice

Treework Environmental Practice
2nd Floor
10-12 Bourlet Close
London
W1W 7BR

Tel: 0117 244 0012
Web: www.treeworks.co.uk
Email: info@treeworks.co.uk







Topographical Survey 251028_OS Master Mapping	28.10.2025
Site Layout/Design	
LVS - Draft Layout Trackers New Sub 08-10-25WIP_cleaned	28.10.2025
LVS DRAFT CableRoute	28.10.2025
LVS_DRAFT_ConstructionCompounds	28.10.2025
P6045_WIP_HDDAvoidanceArea	28.10.2025
P6045_WIP_CableAccessPoint	28.10.2025
P6045_WIP_PermissivePaths	28.10.2025
P6045_WIP_SiteAccess	28.10.2025
P6045_WIP_SiteConstructionCompounds	28.10.2025

Date:
December 2025

Scale:
1:5000 @ A0

Project Name:
Light Valley Solar

Drawing Title:
Tree Protection Plan

Drawing Number:
251209-1.1-LVS-MASTER TPP-NC

Treework Environmental Practice

Treework Environmental Practice
2nd Floor
10-12 Bourlet Close
London
W1W 7BR

Tel: 0117 244 0012
Web: www.treeworks.co.uk
Email: info@treeworks.co.uk

Annex C - Tree Protection Specifications

Technical Measures to Prevent Tree Damage

Tree Pruning

Tree pruning will be carried out where the design and/or planned site operations encroach into the crowns of trees and where these encroachments can be accommodated through facilitation pruning without significantly reducing the landscape value and/or viability of the tree.

Tree pruning operations will:

- be specified by the arboricultural consultant
- be in accordance with current best practice
- be carried out by a suitably experienced and qualified arborist

Tree Protection Fencing


Tree protection fencing will be located at the edge of the Construction Exclusion Zone (CEZ) and will be suitably robust to provide sufficient protection for trees. The performance requirement for fencing will be determined by the type of activity that will take place in the area around the CEZ.

Typically the performance requirement for the Tree Protection Fencing will be:

- Tree Protection Fencing will be installed prior to commencement of activity on the site.
- Tree Protection Fencing will only be removed once all works associated with the development have been completed.
- The Tree Protection Fencing will be installed and removed without causing damage to retained trees.
- Installation, removal and, where required, replacement of Tree Protection Fencing will be supervised and signed off by the Arboricultural Consultant.
- The Tree Protection Fencing will be stable and robust (typical construction method, in accordance with BS5837: 2012, see below).
- The area between the Tree Protection Fencing and the tree will be a Construction Exclusion Zone (CEZ)
- Fence panels will be made of mesh (e.g.: Heras fencing) or, if solid, will have 30cm windows cut into enough panels to enable conditions within the CEZ to be viewed.
- The CEZ will be clearly identified (see Construction Exclusion Zone sign example below)




Example Tree Protection Fencing Sign




Key

1 Standard scaffold poles
2 Heavy gauge 2 m tall galvanized tube and welded mesh infill panels
3 Panels secured to uprights and cross-members with wire ties
4 Ground level
5 Uprights driven into the ground until secure (minimum depth 0.6 m)
6 Standard scaffold clamps

BS5837: 2012 - Figure 2 – Tree Protective Barrier



BS5837: 2012 - Figure 3 – Examples of Above Ground Stabilisation Systems



Examples of specification fencing that may be appropriate for areas of low-intensity activity

No-dig Construction and Special Engineering Measures

No-dig construction methods and special engineering measures will be employed to enable the construction of roads and other built features within the RPAs of trees without damaging tree roots. Installation of built features using no-dig and special engineering measures will meet the following performance criteria:

- Ensure that tree roots are not damaged.
  - *For the roots of the trees to remain undamaged there must be no excavation, soil stripping or site grading within the rooting areas – in other words NO DIGGING.*
- Ensure that soil is not compacted.
- Ensure that no spilled toxic materials seep into the soil.
- Ensure that sufficient rain water reaches tree roots.
- Ensure that gaseous exchange can take place within the soil around tree roots.
- All operations will be supervised and signed off by the Arboricultural Consultant.

Annex D - Tree Survey Method and Limitations

Treework Environmental Practice

Tree Survey Method and Limitations

Tree Survey Method

1. The tree survey was conducted from ground level aided by the Visual Tree Assessment method (Mattheck and Breloer, 1994) and in accordance with BS5837: 2012.

2. All trees on the site with a stem diameter of over 75 mm (measured at 1.5 m above ground) were included in the survey.

3. Offsite trees within influencing distance of the site (typically those located within a distance of up to 12 times their stem diameter away from the site) were included in the survey.

4. Data collected included:

   - a designated tree number
   - type of feature (trees, group, woodland, hedge)
   - number of trees in group
   - tree species
   - height (metres)
   - number of stems
   - stem diameter (in centimetres, as measured at 1.5 m above ground)
   - crown clearance (height of periphery of crown spread above ground level in metres)
   - height of lowest branch (metres),
   - branch spread (to N, S, E and W)
   - age class
   - physiological condition
   - useful life expectancy
   - structural condition
   - BS5837 retention category (A, B, C or U)
   - site notes (where this has a bearing on the present or future health or structural condition of the tree)
   - preliminary management recommendations.

5. All measurements were made in metric using measuring devices where applicable. Estimated stem diameters (e.g., due to lack of access or dense undergrowth) were recorded as such and are shown in the Tree Schedule in bold (see the key at the end of the Tree Schedule table at Appendix A for an explanation of the measurements and codes presented therein).

6. While the appraisals of the surveyed trees are not tree risk assessments, they nonetheless take into account observed structural defects in drawing conclusions about the trees' retentive worth.

Survey Limitations

1. The survey was a preliminary assessment from ground level and observations were made solely from visual inspection for the purposes of an assessment relevant to planning and development. Only binoculars, trowel, mallet and fine manual metal probe were used to aid tree assessment, where necessary. No invasive or other detailed internal decay detection devices were used in assessing trunk condition.

2. The conclusions relate to conditions found at the time of survey. Any significant alteration to the site that may affect the trees that are present or have a bearing on the planning implications (including level changes, hydrological changes, extreme climatic events or other site works) will require a re-assessment of the trees and the site.

3. This survey is not a tree safety inspection. It is carried out in order to inform the planning process. Where clear and obvious hazards have been observed, these have been addressed in the recommendations (see Appendix A - Tree Schedule). A full assessment of the levels of risk posed by trees would need to consider site use together with tree hazards.

Light Valley
Solar

W: Lightvalleysolar.co.uk
E: info@lightvalleysolar.co.uk