

Additional site inspection is needed along Church Hill, Saxlingham Nethergate as the passage of the abnormal load and proposed road widening affects a Grade 2 star listed wall running behind/below the hedge along Church Hill, and mainly invisible as it is covered by the hedge. The hedge is a site for nesting birds. The retaining wall needs to be inspected. It can be examined from the public highway but needs inspection in person. If necessary inspectors may request an on site visit at the property. A letter objecting to demolition of the wall has been submitted from the Sir John Soane Museum. Additional site inspection in person of the route (in this conservation area) of the abnormal load along Church Hill is also needed as the passage may affect the War Memorial, a listed building of special historic interest, as well as other notable listed buildings and houses some of which because of their age do not have modern underpinnings. The pipes under the road need to be examined which may require additional procedures but is needed as pipes under the road surface may be significantly affected by the abnormally heavy load.