

Submission ID: SD94F37C8

A site visit is required -

The positioning of pylons TB217 to TB222 mean Chase Farm Airfield will no longer be able to operate. AN Obstacle Limitation Surfaces Assessment has been provided by an aviation consultant who has identified that the pylon placement would pose a critical safety risk. The Airfield would no longer be able to operate.