

Submission ID: SD75F0A60

Site inspection between A1060 and A 414 and in the vicinity of TB 166 and 167 suggested to view how minor realignment and straightening can 1) save a turning pylon 2) mitigate harmful impacts on listed lane and buildings & 3) reduce injurious affection. NG were invited to inspect but could not be bothered!