

The Grand Union Canal Transfer

Section 51 Advice Log Version: 06 November 2025

There is a statutory duty under ['section 51 \(s51\) of the Planning Act 2008'](#) for The Planning Inspectorate to record the advice that it gives in relation to an application or potential application, and to make this publicly available.

This document comprises a record of the advice that has been provided by The Planning Inspectorate to the applicant (Affinity Water and Severn Trent Water) and their consultants during the pre-application stage. It will be updated by The Planning Inspectorate after every interaction with the applicant during which s51 has been provided. The applicant will always be given the opportunity to comment on The Planning Inspectorate's draft record of advice before it is published.

The applicant will use this advice log as the basis for demonstrating regard to s51 advice within the application.

The Grand Union Canal Transfer s51 Advice Log - Index	
Date of meeting	Meeting overview
<u>28 October 2025</u>	<ul style="list-style-type: none"> Email – Pre-application Prospectus

The Grand Union Canal Transfer - s51 Advice Library

Topic	Email (advice): 28 October 2025
Pre-application prospectus	<p>The Inspectorate has advised that, following a six-month review, the Pre-application Prospectus has been updated. Applicants with live projects at the pre-application stage should familiarise themselves with the revised document and consider any implications for their engagement with the Inspectorate.</p> <p>Key updates include:</p> <ul style="list-style-type: none"> • The establishment of land and rights negotiations tracking as a core service feature. All applicants are now expected to develop and share a tracker using one of two standard templates, regardless of service tier. • Clarified expectations for applicants ahead of meetings with the Inspectorate. This includes confirmation that the Inspectorate may delay or refuse service where pre-meeting requirements, such as the timely submission of an updated programme or issues tracker, are not met.