From: To: Subject: Date: Louiser bank South
Responses to ExQ1 questions - J L White & Son
04 June 2025 22:59:45
image:004.ong
image:003.ong
image:003.ong
image:010-000 - LVIA page 11 (1).odf



Dear Sirs

We would like to submit the following responses to questions that were asked of our client, J L White and Son, in the ExA's ExQ1 questions of 28 Feb 2025.

Question LUA 1.6: Sterilised and impractical land

For the purpose of answering this question we have not identified areas of agricultural land that will be temporarily unfarmable due to the scheme as this can sensibly be dealt with through compensation.

In respect of areas made impractical or sterilised permanently the attached Indicative Landscape Plan ("ILP") shows three areas highlighted orange and marked A, B and C. These areas form part of or adjoin plot 18-010 of the applicants Land Plans and, if the ILP is assumed to be correct the areas left sterilised by the proposed project are the following sizes:

- A 0.58Ha (approx, 20m wide
- B 0.48Ha (approx. 25m wide)
- C 0.30Ha (approx. 25m wide)

All three of these areas currently form part of larger arable fields and will be severed due to the project. The size of modern agricultural machinery leaves these areas completely impractical to farm following completion of the project.


I should also like to point out the area D on the attached plan is forms part of plot 18-010 which is included within the book of reference as being required for freehold acquisition. The ILP suggests that the majority of this area will be returned to agriculture but parts of this area could result in being impractical to farm due to final arrangement on the ground.



Tom Julian BSc (Hons) MRICS FAAV - Rural



DISCLAME: The information in this -mail and any stationments as continential and is intended single by the use of the inflended recipient(s), if you will receive the semant in entire, please advise the sended returns —mail and detel all copies of this intended. The semant is not provided a control of visuals, however the recipient should be that entire and is an advised to the semant of visuals. Whyets accepts no liability for any damagic caused by any virus transmitted by this email. Any views or opinions presented in this email are solely those of the author and do not necessarily represent those of the company.





Legend:

Onshore Substation Zone

Existing utilities

Area of underground cables

Proposed meadow grassland

Proposed woodland meadow

Existing woodland to be retained

Proposed native woodland Existing hedgerow to be retained

Proposed native hedgerow

Proposed native hedgerow with trees

Enhancement of existing watercourse vegetation

Area for SUDs (indicative)

Area to be returned to agriculture

Maintained access through planting

Area of earthworks to be re-seeded with grassland

Public Right of Way
Public Right of Way diversion

P08	25/10/2024	Suitable for Information	SH	EH	РМ
P07	06/03/2024	Suitable for Information	SH	EH	РМ
P07	27/02/2024	Suitable for Information	SH	EH	PM
P06	22/11/2023	Suitable for Information	SH	EH	PM
P02	22/03/2023	Suitable for Information	HS	TH	PM
REV	DATE	DESCRIPTION	DRW	CHK	APR
	P07 P07 P06 P02	P07 06/03/2024 P07 27/02/2024 P06 22/11/2023 P02 22/03/2023	P07 27/02/2024 Suitable for Information P06 22/11/2023 Suitable for Information P02 22/03/2023 Suitable for Information	P07 06/03/2024 Suitable for Information SH P07 27/02/2024 Suitable for Information SH P06 22/11/2023 Suitable for Information SH P02 22/03/2023 Suitable for Information HS	P07 06/03/2024 Suitable for Information SH EH P07 27/02/2024 Suitable for Information SH EH P06 22/11/2023 Suitable for Information SH EH P02 22/03/2023 Suitable for Information HS TH

Indicative Landscape Plan

Figure: 23-6	Drawing No: Po	C2340_LUC_O	N_ZZ_D	R_Z_23_6
Co-ordinate sys	stem: National Grid	Page Size:	Scale: 1:6,000	DO NOT SCALE
Project:		Report:		

Dogger Bank South Offshore Wind Farms

Dogger Bank South: Environmental Statement

