Submission ID: 35934

The applicant has not made enough provision to prevent potential flooding and farmland degradation due to the certain destruction of the land drainage systems north of the village of Scopwick during the construction process , also the lack of external supervision (no external agency or resident engineer employed) during the installation of these panels