

On examining the site inspections members of the ExA have made to date we note that there has not been a site inspection of the B1119 from its junction with Mill Road along Rendham Road, Chapel Road and Fairfield Road to the B1121 at North Entrance.

We understand SCC generally requires A or B roads to be used for signed diversion route and thus for northbound A12 traffic when the B1121 is closed at Benhall Bridge for A1L passage to the Fromus valley access road this section of road will most probably be part of the diversion route. You have inspected the B1119 from the A12 to Mill Road already but your route diverted off the B1119 along the unclassified Mill Road to the traffic lights on the B1121 junction with the eastbound B1119. The B1119 east of its junction with Mill Road is markedly different to the B1119 west of Mill Road with tight bends, narrow carriageways and considerable on street parking. It poses a difficulty for diversion traffic particularly any HGV and larger LGVs and thus in our view is a material consideration