From:
 Great Yarmouth Third River Cross

 Cc:
 Subject:

 Date:
 14 January 2020 15:24:03

Please see below GYPC's answers to the 2 questions posed.

2.0.4	Note the concern about bridge failure to open and the request for an emergency lay-
	by berth. Has GYPC identified where such a facility could be located?
	NO. The locations identified by GYPC following the vessel simulations might well be at
	Berth 33 (or alternatively at Berth 10) but ultimately it will depend upon a number of
	$factors, for \ example \ land \ ownership, \ competing \ uses, \ dredging \ and \ navigational \ safety \ .$
	A scope of work would be required to be completed to make any berth fit for purpose
	and to maintain a minimum depth.
2.0.5	With regard to the suggestion that the bridge may need to open before certain
	vessels enter the port, is it known roughly what percentage of the time all berths on
	the approach to the bridge would be occupied?
	No. There is very little (if any) time that all berths are likely to be unoccupied.
	Our confidence level to predict, beyond a 3-hour horizon, when any particular berth
	will be occupied is Low.
	Unless a dedicated emergency lay-by berth exists, then identification of a <i>suitable</i> berth
	introduces further uncertainty and adds complexity to plan vessel movements in the harbour.
	In determining a suitable berth, full consideration must be given to:
	Does it comprise a straight line, of sufficient length for any likely Vessel, have immediate and adequate access to secure alongside (clear of obstructions/other vessels), deep enough to remain alongside and for a period of up to 12 hours across all tide cycle? Additionally, will the Berth Owner become compromised (operationally and/or financially) and give consent for an unexpected arrival OR will the Harbour Authority have to intervene and act/direct in order to ensure safety? Further, will the Vessel as a consequence of now being in an unscheduled position, adversely affect other Vessels in transit or manoeuvring in proximity?



Nicholas Brown Partner and Parliamentary Agent



For and on behalf of BDB Pitmans LLP 50 Broadway London SW1H 0BL

WARNING – This email and any files transmitted with it are confidential and may also be privileged. If you are not the intended recipient, you should not copy, forward or use any part of it or disclose its contents to any person. If you have received it in error please notify our system manager immediately on +44 (0)20 7783 3555 or +44 (0)345 222 9222. This email and any automatic copies should be deleted after you have contacted the system manager.

This email is sent from the offices of BDB Pitmans LLP, a limited liability partnership authorised and regulated by the Solicitors Regulation Authority (SRA ID number 448617) and registered in England and Wales with registered number OC320798. Its registered office and principal place of business is 50 Broadway, London SW1H 0BL. A full list of members, referred to as partners by the firm, is available for inspection on request. BDB Pitmans LLP accepts no responsibility for software viruses and you should check for viruses before opening any attachments.

Cybercrime Alert: If you receive an email purporting to be from someone at this firm and telling you that we have changed our bank details, it is likely to be from a criminal. Please do not reply to that email – instead ring the person you have been dealing with as soon as possible to check whether the change is genuine.

Internet communications are not secure and therefore BDB Pitmans LLP does not provide any guarantee or warranty that this message or any attachments shall remain confidential. To ensure client service levels and business continuity BDB Pitmans LLP operates a policy whereby emails can be read by its employees or partners other than the addressee. This policy complies with the Telecommunications (Lawful Business Practice) (Interception of Communications) Regulations 2000.